

INS CASE OWNER:

Bernard

CC 4, AIG 1.802803, Gfa39

LKK:

IDAC:

Surveyor:

Xhr

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 28/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

19/3

CPL

4/4/2019

Spoke to OI (Lin), confirmed BOLA q, informed TP claim and MCP issue. OI agree to settle and aware MCP will be affected. send letter to OI.

After repair photo ✓

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 4/4/2019

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

17/3/2019

Sent By:

HMK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 3,250.00

(4 days)

Reduction:

44.60

%

Email

Call

FINAL SETTLEMENT

Date/Time:

15/4/2019

Confirm with:

Jimmy Buey

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

9

Repair Cost:

S\$ 3,250.00

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 120.00

(\$20.00 x 6

days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 3,370.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 3,370.00

Name 1:

JC Motors Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

16/4/19

ASS. REC. BY:

REF: CS/AIG/8021803/G

Special Instruction:

Surveyor:

Gao (Cao)

ASSIGNMENT (Office)

From (Person):

Chan Yoke Shi

of

AIG

Date/Time:

4/12/18 10:31am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 1390E

Insured:

SJE 930X

at Workshop m/s

JC Motors

Tel:

9889 5190 (Roy Mechanic)

of

13 Kaki Bkf Rd 4 #01-16

07433222

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/11/18

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11:17am 4/12/18

Person Contacted:

Jimmy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBL 1390E - X

SJE 930X - X

V

DATE/TIME

Ref: AIG

5534J

ASSIGNMENT

From: Date: 4/12/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: FBL 1390E

at Workshop n/s JC Motors

of 13 kaki Bkt Rd 4 #01-16

Insured: Burtley Biz Centre

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Roy@ 98895190

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 14 days Res. Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted

Vehicle: IN / OUT

Veh No:

FBL 1390E

Yr Regd: 22 Jun 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Burgman 200

Make:

Suzuki UH 200AL6 200

Colour:

Black

A/C: Insured / Std / NI / NA

Sp Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ML CC 911219.040 2640

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/90-13

R:

130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

mm

L/Bal:

mm

D.O.A.

D.O.I.

04-12-18

Survey held at:

w/s

3:35pm

Des. of Damages: Front / Rear / D/S / U/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

01/3

Final but \$3250 with Boss

w/s want to check liability do direct settlement

L/S \$3250.00 (Ref: 2,616.20 / 44.60%)

Order/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Order/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) 10 + 100 10

2) Photos:

3) Other:

TOTAL:

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp: (\$)

☐

Interview: (\$)

☐

Tech. Invs: (\$)

☐

Weekend: (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5534J
Vehicle Details	
Vehicle No.:	FBL1390E
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2018
Vehicle Make:	SUZUKI
Vehicle Model:	UH200AL6 BURGMAN 200 ABS
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	H405402640
Chassis No.:	MLCC91121G0402640
Maximum Power Output:	-
Open Market Value:	\$4,268.00
Original Registration Date:	22 Jun 2016
First Registration Date:	22 Jun 2016
Transfer Count:	1
Actual ARF Paid:	\$641.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,302.00
COE Rebate Amount:	\$4,754.00
Total Rebate Amount:	\$4,754.00

The information contained herein is correct as at 05 Dec 2018

OK

JC MOTORS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-16
S'pore 417807
Tel 65846914 Fax 65846912

LKK Auto Care

the Repairer

- To resurvey before start of repair
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE December 1, 2018

Quotation # FBL1390E

Quotation valid until: December 5, 2018

Prepared by: Jimmy Boey

Make/Model : SUZUKI BURGMAN 200

S/No	Part	Price	Discount	Price
1	Number Plate (Front)	\$15.00	Na	\$15.00 (SN)
1	Front fender	\$180.00	10%	\$162.00
1	Front Fork Assy	\$480.00	10%	\$432.00
1	View Mirror 1 set	\$80.00	10%	\$72.00
1	Handle Bar Balancer	\$60.00	10%	\$54.00
1	Handle Bar	\$110.00	10%	\$99.00
1	Exhaust Muffler protector A/B	\$190.00	10%	\$171.00
1	Battery	\$120.00	10%	\$108.00
1	Exhaust Muffler Assy	\$750.00	10%	\$675.00
1	Exhaust Muffler Gasket	\$20.00	10%	\$18.00
1	Front Brake Lever	\$40.00	10%	\$36.00
1	Front lower Pandel	\$120.00	10%	\$108.00
1	Handle Bar Cover (Top/ Lower)	\$200.00	10%	\$180.00
1	Front Meter Dashboard Inner	\$280.00	10%	\$252.00
1	Front Windshield	\$550.00	10%	\$495.00
1	Windshield Inner Pandel	\$220.00	10%	\$198.00
1	windshield Front Lip	\$110.00	10%	\$99.00
1	Lower Pandel	\$280.00	10%	\$252.00
1	Front lower Pandel	\$240.00	10%	\$216.00
1	Lower Side Cowling RH/LH	\$180.00	10%	\$162.00
1	Rear Footrest Pandel RH/LH	\$90.00	10%	\$81.00
1	Rear Side Cowling LH	\$200.00	10%	\$180.00
1	Steering Cone	\$100.00	10%	\$90.00
1	Rear Box	\$520.00	10%	\$468.00
1	Check and Repair Body Frame	\$400.00	10%	\$360.00

		Sub-Total	\$4,983.00	
QTY	Description	UNIT PRICE	DISCOUNT	LINE TOTAL
1	Service			
1	Paint-Work with Burgman Logo	\$650.00	NA	\$585.00
1	Labour 7 Days	\$800.00	NA	\$800.00
1	Towing 3 Times	\$150.00	NA	\$150.00
		Total	\$6,518.00	
		10%	\$ 5,866.20	

Completion Time : 14 Days.

4-5 Days.

Gino Qiang - 82880282 / 520% 3250

(LKK)

04/12/18.

pat by pat.

Before / After paint photos.

- Pre repair inspection request - FBL1390E VS SJE930X (OI) DOA 25/11/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKAUTO.COM, Admin A
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Hor, Yinnul
Sent: 4/12/2018 10:31:26 AM
Attachments: attachment.Ledf

Hi,

Please refer to the enclosed request from **JC Motors (Pte. Ltd)** via telecommunication.

Claim no : 9819441622SG003
Case Owner : BERNARD JI QIAN LER

If you have any queries/concerns, please let us know.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
yokeshi.chan@aig.com | www.aig.com

From: Chan, Yoke Shi
Sent: Monday, December 03, 2018 5:00 PM
To: jimmy@jcmotorspl.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Hor, Yinnul
Subject: aigencrypt - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJE930X AND FBL1390E ON 25/11/2018

Without Prejudice

Your Reference : SC.GMW.2053.18.02
Our Reference : 9819441622SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

yokeshi.chan@aig.com | www.aig.com

From: Gerald Martin Wee [mailto:gerald@singhnco.com]

Sent: Monday, December 03, 2018 3:23 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; jimmy@jcmotorspl.com; Chan, Yoke Shi; Kaur, Baljit

Subject: NEW MATTER - ACCIDENT ON 25.11.2018 BETWEEN FBL1390E AND SJE930X

Our Ref: SC.GMW.2053.18.02

Your Ref: SJE930X

PRE-REPAIR INSPECTION NOTICE

Dear Sirs,

CLAIM BY KUA TECK HENG, NRIC NO. S6845534J

OWNER/RIDER/DRIVER OF FBL1390E AGAINST DRIVER OF SJE930X

We act for Kua Teck Heng the owner and rider of FBL1390E that was damaged as a result of the above accident.

Attached is our client's Report of the Accident for your attention and records.

Please take note that our client's motorcycle is presently located at his repairer's workshop.

JC Motors (Pte. Ltd.)

13, Kaki Bukit Road 4, #01-16

Bartley Biz Centre

Singapore 417807

Tel: 9743-3222

Email: jimmy@jcmotorspl.com

Attn: Jimmy Boey

In the circumstances, **kindly let us know within 2 (two) working days from your receipt of this Notice if you will be conducting a pre-repair inspection of our client's vehicle.** You may liaise directly with Jimmy Boey who has been copied on this e-mail at his contact details stated above.

As provided by the NIMA Protocol, take notice that **our client shall proceed to appoint his own surveyor and repair his vehicle without any further reference to you, if we do not hear from you within the next 2 (two) days.**

Yours faithfully,
Gerald Martin Wee

SINGH & CO.
77, High Street, #10-09,
High Street Plaza,
Singapore 179433.

Tel: +65 6338 3766
Fax: +65 6338 3762

Thank You & Best Regards,
Gerald Martin Wee

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Poh Kin (LKKAUTO)

From: jimmy@jcmotorspl.com
Sent: Tuesday, 16 April 2019 3:39 PM
To: Poh Kin (LKKAUTO)
Cc: gerald@singhnco.com
Subject: RE: RTA involving vehicle nos. SJE 930X and FBL 1390E on 25/112/2018
Attachments: FBL1390DOC.pdf

Hi Poh Kin .this is the document u need.

Thank you.

Best regards,
Jimmy Boey

JC Motors (Pte. Ltd.)
13 Kaki Bukit Road 4
#01-16 Bartley Biz Centre
Singapore 417807
Tel: 6584 6914 Fax: 6584 6912
General Email: enquiries@jcmotorspl.com

CONFIDENTIALITY CAUTION:

This message is intended only for the use of the individual/entity to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient of this message, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify the writer immediately by return e-mail and delete the original message. Thank you.

From: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Sent: Monday, 15 April 2019 15:23
To: jimmy@jcmotorspl.com
Subject: RE: RTA involving vehicle nos. SJE 930X and FBL 1390E on 25/112/2018

Dear Jimmy,

Scan a copy to us enough.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.


In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Monday, 15 April 2019 2:50 PM
To: jimmy@jcmotorspl.com
Cc: Admin A
Subject: RTA involving vehicle nos. SJE 930X and FBL 1390E on 25/112/2018
Attachments: DV FBL 1390E.pdf

Importance: High

WITHOUT PREJUDICE

SAVE AS TO COSTS

Our Ref: CC4/AIG18021803/Gfb3
Your Ref: FBL 1390E

Dear Jimmy,

We refer to the above matter and our tele conversation.

Towards an amicable settlement and without admission of liability to our Insured's part, we hereby confirmed settlement as below:

1. Cost of Repair	S\$ 3,250.00
2. Loss of Use (\$20.00 x 6 days)	<u>S\$ 120.00</u>
	<u>S\$ 3,370.00</u>

Please duly sign the **DV** attached and return with **Letter of Demand**(tax invoice, Authorization to Act) to us (**LKK**) for payment processing.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

JC MOTORS PTE LTD

Blk 13 KAKI BUKIT ROAD 4
#01-16 Bartley Biz Centre
Singapore 417807
Email : jimmy@jcmotorspl.com
HP : 977433222 Fax : 65846912

AIG Asia Pacific Insurance Pte Ltd
No 78 Shenton Way #07-16
Singapore 079120

Date : 15/04/2019

Attn : Claims Department

Claimant: Kua Tek Heng

Accident involving SUE930X & FBL1390E & along Tanjong Katong Road on 25/11/2018 at 14.10pm

We were instructed by the abovenamed to claim damages against you in connection with a road traffic accident on 25/11/2018 at 14.10pm Along Tanjong Katong Road involving our client's motor vehicle FBL1390E and motor vehicle SUE930X driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged. He has been put to loss and expenses, particulars of which are as follows:

a) Lum Sum Repair	S\$3250.00
b) Lost of use (4 days)	S\$120.00
TOTAL	S\$3370.00

Please note that if you are insured and wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you and your insurer should send us an acknowledgement of the receipt of this letter within 14 days of your receipt of this letter. If you or your insurer wishes to have our client examined by your own medical expert, this should be stated in your acknowledgement of receipt. Please also advise within 14 days of the acknowledgement of receipt where and when the examination of our client is to take place so that we may arrange for our client to attend.

Should you fail to acknowledge receipt of this letter within 14 days, our client can commence court proceedings against you without further notice to you or your insurer.

Yours faithfully,




Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18021803/Gfa3

08 APRIL 2019

LIN ZHENGYUAN
BLK 411B FERNVALE ROAD
#09-66
SINGAPORE 792411

Dear Sir/Madam,

ACCIDENT INVOLVING SJE 930X AND FBL 1390E ON 25/11/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORISATION


Accident involving FBL1390E And SJE930X on 25/11/2018 at 14.10pm
At/Along Tanjong Katong Road
I/We KUA TECK HENG, am/are the registered owner of
Reg No FBL1390E

I/we hereby authorize you to release all compensation monies pertaining to the above
Mentioned accident to **JC MOTORS PTE LTD** and forward your settlement cheque to
JC MOTORS PTE LTD whom I had authorized to collect the said compensation monies

Thanks You



Signature of Claimant



Witness By Jimmy Boey
S7228943I

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, JC Motors Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor with respect to the amount claimed for S\$3,250.00 (Repair Cost), S\$120.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. FBL 1390E that was damaged pursuant to the accident which occurred on 25/11/2018 (date) along TANJONG KATONG ROAD (location) involving vehicle no/s SJE 930X. This is pursuant to the inspection conducted on 04/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KUA TECK HENG ("the third party claimant") of vehicle no. FBL 1390E make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to FBL 1390E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 (day) of APR (month) 2019 (year)

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.



Signed by appointed surveyor



Signed by "the workshop" (with chop)

JC Motors Pte Ltd
BLK 13 Kaki Bukit Road 4
#01-16 Bartley Biz Centre
Singapore 417807
Tel : 65846914 Fax : 65846912

INVOICE : JCM18/1930

DATE: APRIL 15, 2019

Bill To : AIG Asia Pacific Insurance Pte Ltd
Address : No 78 Shenton Way
#07-16
Singapore 079120

Accident Date/ Location : 25/ 11/ 2018
Tanjong Katong Road
Involve Vehicle : SJE930X And FBL1390E

OWNER NAME	MOTOR NUMBER	MAKE/MODEL
Kua Teck Heng	FBL1390E	SUZUKI

S/N	QTY	DESCRIPTION	UNIT PRICE \$	DISCOUNT	LINE TOTAL \$
1	1	Lum-Sum Repair	\$3250.00	NA	\$3250.00
2	1	Loss of Use	\$120.00	NA	\$120.00
GOODS SOLD ARE NOT RETURNABLE			TOTAL AMOUNT	NA	\$3370.00



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Nov 2018 Edit Reg		04 Dec 2018 00:00 Edit Adj Rpt	\$53,250.00 Edit Estimates	\$53,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LIN ZHENGYUAN, ID: S8315176E		
Main Claimant:	KUA TECK HENG, ID: S6845534J		
Vehicle Reg. No.:	FBL1390E	Date of Loss:	25/11/2018 14:00 - :59 [29 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9819441622SG	Policy/Cover Note No.:	1700084826 (Comprehensive) Coverage: 30/11/2017 - 29/11/2018
Vehicle Reg. No. (Insured):	SJE930X	Policy No. (Claimant):	5081567610-02TPFT
		Excess:	
Repairer:	Jc Motors Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4 #01-16 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/12/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (05/12/2018): Request to upload TP GIA Report














































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBL1390E (9819441622SG)
[SJE930X]
TP
KUA TECK HENG
Nov 25 2018 2:00PM
[LIN ZHENGYUAN]
Jc Motors Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Letters/Correspondences														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown											1	Edit			
Photos/Images														3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
2	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
3	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
4	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
5	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
6	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
7	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
8	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
9	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
10	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
11	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
12	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
13	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
14	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
15	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
16	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
17	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
18	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
19	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
20	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
21	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
22	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
23	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
24	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
25	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
26	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
27	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
28	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
29	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
30	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
31	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
32	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
33	05/03/19 11:23	General View											1	Load JPG	<input checked="" type="checkbox"/>		
34	05/03/19 11:23	General View											1	Load JPG			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
36	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
37	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
38	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
39	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
40	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
41	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
42	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
43	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
44	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
45	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
46	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
47	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
48	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
49	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
50	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
51	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
52	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
53	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
54	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
55	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
56	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
57	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
58	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
59	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
60	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
61	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
62	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
63	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
64	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
65	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
66	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
67	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
68	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
69	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
70	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
71	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
72	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
73	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
74	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
75	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
76	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
77	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
78	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
79	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
80	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
81	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
82	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
83	05/03/19 11:23	General View		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
85	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
86	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
87	05/03/19 11:23	General View		<input checked="" type="checkbox"/>
88	05/03/19 11:24	Dismantled Parts		<input checked="" type="checkbox"/>
89	05/03/19 11:24	Dismantled Parts		<input checked="" type="checkbox"/>
90	05/03/19 11:24	Dismantled Parts		<input checked="" type="checkbox"/>
91	05/03/19 11:24	Dismantled Parts		<input checked="" type="checkbox"/>
92	05/03/19 11:24	Dismantled Parts		<input checked="" type="checkbox"/>
93	05/03/19 11:24	Dismantled Parts		<input checked="" type="checkbox"/>
94	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
95	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
96	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
97	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
98	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
99	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
100	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
101	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
102	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
103	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
104	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
105	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
106	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
107	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
108	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
109	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
110	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
111	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
112	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
113	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
114	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
115	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
116	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
117	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
118	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
119	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
120	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
121	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
122	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
123	05/03/19 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/03/19 09:45	EMAIL FROM AIG DD 04.12.2018		
2	12/03/19 09:45	TP GIA REPORT		
3	17/03/19 20:49	TP ESTIMATE - MARKED		
4	16/04/19 15:15	LETTER TO OI		
5	26/04/19 11:57	WORKSHOP INVOICE		
6	26/04/19 11:57	Release Voucher		
7	26/04/19 11:57	AUTHORISATION TO ACT FORM		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/12/18 11:27	OI GIA REPORT		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJE930X (Insd veh)	Model:	SUZUKI UH200AL6
	FBL1390E (TP veh)		BURGMAN 200CC ABS
Date of Accident:	25/11/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$		6,518.00
Final Repair Cost	: \$		3,250.00
Loss of Use	: \$		120.00
			6.00 days at \$20.00 per day
Rental (if any)	: \$		0.00
			days
LTA / GIA Search Fee	: \$		0.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		3,370.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	JC Motors Pte Ltd	: \$	3,370.00
2)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

26 Apr
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021803/GFA3Q2

Date: 26/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700084826
Claimant Vehicle No : FBL1390E **Insured Vehicle No :** SJE930X
 Date of Loss: 25/11/2018 Nature of Claim: TP Claim No: 9819441622SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL1390E**
 Make & Model: SUZUKI UH200AL6 BURGMAN, 200cc ABS Engine No: H405402640
 Reg. Date: 22/06/2016 (Man. Year: 2016) Chassis No: MLCC91121G0402640
 Colour: Black Odometer: 0 km
 Engine Capacity: 200 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/90-13 Rear Tyre Size: 130/70-12
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,983.00	3,372.00	1,611.00	32.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,535.00	700.00	835.00	54.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,518.00	4,072.00	2,446.00	37.53
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	6,518.00	3,250.00	3,268.00	50.14
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Nett Liability (S\$)		3,370.00		

INSPECTION

Date of Assignment: 04/12/2018
 Date Inspected: 04/12/2018 Inspected At: Jc Motors Pte Ltd (HQ)
 13 KAKI BUKIT ROAD 4 #01-16 BARTLEY
 BIZ CENTRE
 Singapore 417807
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE (FRONT)	Torn	15.00 FS	*15.00 FS
2	1		*FRONT FENDER	Cut	180.00 FL	*180.00 FL
3	1		*FRONT FORK ASSY	Bent	480.00 FL	*480.00 FL
4	1		*SET VIEW MIRROR	Scratched	80.00 FL	*80.00 FL
5	1		*HANDLE BAR BALANCER	Cut	60.00 FL	*60.00 FL
6	1		*HANDLE BAR	Bent	110.00 FL	*110.00 FL
7	1		*EXHAUST MUFFER PROTECTOR A/B	Cut	190.00 FL	*190.00 FL
8	1		*BATTERY	Not Necessary	120.00 FL	*- FL
9	1		*EXHAUST MUFFER ASSY	Repair	750.00 FL	*- FL
10	1		*EXHAUST MUFFER GASKET	Necessary	20.00 FL	*20.00 FL
11	1		*FRONT BRAKE LEVER	Scratched	40.00 FL	*40.00 FL
12	1		*FRONT LOWER PANDEL	Cut	120.00 FL	*120.00 FL
13	1		*HANDLE BAR COVER (TOP/LOWER)	Cracked	200.00 FL	*200.00 FL
14	1		*FRONT METER DASHBOARD INNER	Cut	280.00 FL	*280.00 FL
15	1		*FRONT WINDSHIELD	Cracked	550.00 FL	*550.00 FL
16	1		*WINDSHIELD INNER PANDEL	Cut	220.00 FL	*220.00 FL
17	1		*WINDSHIELD FRONT LIP	Cracked	110.00 FL	*110.00 FL
18	1		*LOWER PANDEL	Cut	280.00 FL	*280.00 FL
19	1		*FRONT LOWER PANDEL	Cut	240.00 FL	*240.00 FL
20	2		*LOWER SIDE COWLING RH/LH	Cut	180.00 FL	*180.00 FL
21	2		*REAR FOOTREST PANDEL RH/LH	Cut	90.00 FL	*90.00 FL
22	1		*REAR SIDE COWLING LH	Cut	200.00 FL	*200.00 FL
23	1		*STEERING CONE	Necessary	100.00 FL	*100.00 FL
24	1		*REAR BOX	Not Necessary	520.00 FL	*- FL
25	1		*CHECK AND REPAIR BODY FRAME	Not Necessary	400.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	5,535.00	3,745.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	552.00	373.00
Total Parts (\$\$)	4,983.00	3,372.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PAINT -WORK WITH BURGMAN LOGO	New	585.00	400.00
2	LABOUR 7 DAYS	New	800.00	250.00
3	TOWING 3 TIMES	New	150.00	50.00
Gross Labour Cost (S\$)			1,535.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >