

12/07/2018

SS. REP. BY:

REF: (S3/Asm18012521/Gtz462)

Special Instruction:

SUITABILITY

Smart claim

612

ASSIGNMENT (Office)

From (Person):

Johnny Yong

of ASM

Date/Time: 09/07/2018 4:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 5698E

Insured:

XE 252S

at Workshop m/s

Autowerke Automotive

Tel:

9630 1281

of

8 Kgki Bukit Aie 4 #05-01/02

Policy No:

Claim No:

SSMOON6D

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 03072018

CA / REV / REP. / REV 24 HRS wpi

Date/Time: 10/07/2018 10:23am

Person Contacted:

Aly

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJT 5698E - X
	XE 252S - X 054480
10/7/18	Dismantled.
13/7/18	After repair

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s **Auto werke**
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: **\$18K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SJT 5698E** Yr Regn: **19 Oct 2009**
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Nissan latia 1.5**
 Colour: **Black** A/C Insured / Std / NI / NA
 Sp. Reading: **131622** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JN1BAACU2-0021524**
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD / Air Rim or
 Tyre Size: F: **195/60 R15**
 R: **11**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Hankook**
 Front _____ Rear _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. _____ D.O.I. **10-07-18**
 Survey held at **w/s** **3pm**
 Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/7/18	submit PRS report

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$) _____
☐ Interview (\$) _____
☐ Tech Invz (\$) _____
☐ Wagon (\$) _____

Survey Fee:

Transportation:

\$ + RT \$ _____

Rides _____

Other _____

TOTAL

100
100

Catherine Chong (LKK Auto)

From: June@seahong.com.sg
Sent: Friday, 30 November, 2018 12:23 PM
To: 'Catherine Chong (LKK Auto)'
Cc: 'Chee Kiong'; samson@seahong.com.sg; amanda@seahong.com.sg; xinyi@seahong.com.sg
Subject: REF : 18.25687 - VEHICLE NUMBER : SJT 5698E
Attachments: LOD to AXA 15082018 (Part 1).pdf; LOD to AXA 15082018 (Part 2).pdf

Dear Sirs,

CLAIMANT : KOH MOAL WI
VEHICLE NUMBER : SJT 5698E
ALLEGED ACCIDENT DATE : 3 JULY 2018
AXA VEHICLE NUMBER : XE 525S

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.

Please let us hear from you on the following: -

- a. If you have conducted post-repair inspection already, please let us have your survey report urgently.
- b. If you have not conducted post-repair inspection, please let us arrange for inspection with the claimant's solicitor and let us have your survey report in due course.

May we hear from you on the above soonest.

Regards,
Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Tel: 6536 5369
Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

Satwant Singh
Priyam Singh
Khong Zi-Wei

SATWANT ASSOCIATES

AN OFFICIAL MEMBER OF THE LAWYER NETWORK, AN INTERNATIONAL NETWORK OF LAW FIRMS

CONVEYANCING OFFICE:
450 Lorong 6 Toa Payoh
#02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114
Fax: 6266 6925
www.satwantlaw.com.sg
(Fax not for service
of documents)

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying)

Your Ref: To be advised

Our Ref: PD/DL/1801213 (ml) – Toa Payoh Office
(margaretlim@satwantlaw.com.sg)

15 August 2018

WITHOUT PREJUDICE

AXA Insurance Pte Ltd

8 Shenton Way
#24-01 AXA Tower
Singapore 068811

BY HAND & EMAIL

Attention: Motor Claims Department

Dear Sirs,

**ACCIDENT INVOLVING SJT5698E & XE525S ALONG JURONG WEST AVE 2
TOWARDS BULIN AVENUE ON 03/07/2018 @ 16:25**

We act for Mr Koh Niak Wu, whose motor vehicle No. SJT5698E was damaged in the above accident by your insured motor vehicle No. XE525S.

Our investigation reveals that you are the Insurers of motor vehicle No. XE525S at the material time of the accident and that the said accident was caused solely by the negligence of the driver of your insured motor vehicle.

We enclose herewith copy each of the following: -

1. GIA Report;
2. LTA search and invoice;
3. Surveyor Report and invoice;
4. Rental Agreement and invoice.

We are instructed to claim the following: -

1. Cost of Repair	\$ 6,900.00
2. Rental (\$120.00 x 1 day)	\$ 120.00
3. Loss of Use (\$200.00 x 9 days)	\$ 1,800.00
4. GIA search and report fees	\$ 30.00
5. LTA search	\$ 8.00
6. Surveyor report fees	\$ 455.00
7. Costs (at this stage)	\$ 800.00

Total: \$10,113.00

MAIN OFFICE:
3 Jalan Bingka
Singapore 588896
Tel: 6299 9470 Fax: 6299 5541

CONVEYANCING BRANCH OFFICE:
450 Lorong 6 Toa Payoh #02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114 Fax: 6266 6925

This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

Kindly let us know whether you are prepared to settle our client's claim amicably by 28 August 2018, failing which we shall commence legal proceedings without further reference to you as instructed.

We look forward to hearing from you.

Yours faithfully,

A handwritten signature in black ink, appearing to read 'Satwant & Associates', is written over a horizontal line.

SATWANT & ASSOCIATES

encs
cc. client

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	00901
Vehicle Details	
Vehicle No.:	SJT5698E
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L AT ABS D/AIRBAG 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	HR15110998B
Chassis No.:	JN1BAAC11Z0021524
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,833.00
Original Registration Date:	19 Oct 2009
First Registration Date:	19 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$17,833.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Oct 2019
PARF Rebate Amount:	\$9,808.00
Intended COE Registration Details	
COE Expiry Date:	18 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,201.00
COE Rebate Amount:	\$2,051.00
Total Rebate Amount:	\$11,859.00

The information contained herein is correct as at 12 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/07/2018 17:04
Date Of Accident	03/07/2018 16:25
Exact Location Of Accident	JURONG WEST AVE 2 TWDS BULIN AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT5698E
Insured/Policyholder	
Name Of Registered Owner	KOH NIAK WU
NRIC No	S80600901
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96522517
Alternative Phone No	OFFICE-96522517

Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100329819

Cover Note Number

Driver

Name of Driver	KOH NIAK WU
NRIC No	S80600901
Date Of Birth	22/08/1980
Occupation	OUTDOOR
Date Of Driving Pass	14/12/2006
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96522517
Fax Number	
Contact Number	OFFICE-96522517
Email Address	NOEMAIL

Address	BLK 1 GHIM MOH ROAD #05-386
Postcode	270001
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, (SJT5698E) WAS ON THE FIRST LANE STATIONARY WAITING FOR THE TRAFFIC TO TURN GREEN FOR ME TO TURN RIGHT. WHEN THE TRAFFIC TURNED GREEN FOR ME TO TURN RIGHT, I WAS STILL STATIONARY WHEN I FELT 3 CONTINUOUS BUMP AT MY REAR SIDE. I ALIGHTED FROM MY VEHICLE TO SEE THAT IT WAS VEHICLE B (XE525S) WHO BUMPED INTO ME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE525S
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	KOH NIAK WU
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJT5698E
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (1) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (2) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (3) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (4) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (5) the information so collected under (2) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Autowaree

SKETCH PLAN

Jurong West Ave 2 towards Bulim Ave



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated time and date, I (SJT5698E), was on first lane, stationaried waiting for the traffic to turn green for me to turn right. When the traffic turned green for me to turn right, I was still stationary when I felt three continuous bumps at my rear side. I alighted from my vehicle to see that it was Veh B (XE252S), who bumped into me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 4/7/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
(Name)
NRIC/PIV No.:

Identification Card



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S80600901



Name

KOH NIAK WU

许立宇

Race

CHINESE

Date of birth

12-08-1989

Country of birth


MALAYSIA

Sex

M




Driving License



55/1837



Card No. S80690901



Date of issue
06-03-2018

Address
APT BLK 1 GRM MOH ROAD
405-308
SINGAPORE 270003

INSURANCE

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM
12/1/2011 11:11 AM
12/1/2011 11:11 AM
12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM

12/1/2011 11:11 AM



12/1/2011 11:11 AM

12/1/2011 11:11 AM

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Enquire Vehicle & Owner Information (Vehicle No. XE525S As At 03 Jul 2018 / 16:25:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: PD/DL/1801213

Current Owner Details

Owner ID Type: Company
Owner ID: 201325787M
Owner Name: AAK LOGISTICS SERVICES PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 153
Registered Street Name: BUKIT BATOK STREET 11
Registered Unit No.: # 03 - 292
Registered Building Name: -
Registered Postal Code: 650153

Current Vehicle Details

Vehicle No.: XE525S
Make Description/Model: ISUZU / EXR52E
Insurance Company Name: AXA INSURANCE PTE LTD



THANK YOU

Satwant Singh S/o Sarban Singh has successfully logged out.

Your last login date and time was 09 Jul 2018, 15:44:04.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

SrNo	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$)
1	Vehicle	SK35706J	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
2	Vehicle	XE5255	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
3	Vehicle	SGJ5695B	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
4	Vehicle	PC447P	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

DREAM CARZ LEASING PTE LTD

Company Registration: 201433037R

8 Kakl Bukit Ave 4, #05-27, Premier, Singapore 415875 Tel: (65) 63845206 Fax: (65) 63845205 Email: dreamcarzleasing@gmail.com

INVOICE

5698

Koh Niak Wu
Blk 1 Ghim Moh Road
#05-366
Singapore 270001

Invoice No: 10374
Invoice Date: 4/7/2018
Due Date: 4/7/2018
VHA No: 1814

Description

Rental for	1	Days @	\$ 120.00 per Day	\$ 120.00
Vehicle No	SLX6414G			
Vehicle Description	KIA CERATO			
Rental Period	3/7/2018	to	4/7/2018	

Total Amount Payable \$ 120.00

4/1/18 RETURN

SGT 5698E

Kaki Bukit Ave 4 #05-27 Premier Singapore 415875

Email: dreamcarzleasing@gmail.com

Tel: +65 6384 5206 Fax: +65 6384 5205

DCL**DREAM CARZ LEASING**
PTE LTD

ROC No: 201433037R

VEHICLE RENTAL AGREEMENT

VHA No: 1814

HIRER'S PARTICULAR


Name: (as in I/C) Koh NIAK WU
 NRIC/PASSPORT No: S20600901
 Address (Res): Blk 1 Ghim Moh Rd #05-366
S270001

Name & Address of Employer:

Occupation: _____ Driving Exp: 3
 Driving Licence No: _____ D/L Type: Local / International
 Issue Date: 02/9/09 Date of Birth: 22/8/1980
 Tel: (O) _____ (R) 9652517 HP / PG _____

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) _____
 NRIC/PASSPORT No: _____
 Address (Res): _____
 Driving Licence No: _____ D/L Type: Local / International
 Issue Date: _____ Date of Birth: _____
 Occupation: _____ Driving Exp: _____

VEHICLE CHECK LIST**ACCESSORIES CHECK**

- ☐ Ashtray ☐ Cig Lighter ☐ S/Tyre
☐ STD Tools ☐ Jack ☐ Hub Caps
☐ Radio / Cass ☐ CD ☐ Cartridges

Vehicle No: SLX 644 G Replace Veh No: _____
 Mileage Out: _____ Mileage Out: _____

Make & Model: 1.8 CCEPT Auto / Manual
 Group: _____

Out: Date 3/1/18 Time: 6:30 PM

HIRE / PERIOD EXPIRY Time: _____

NON-WAIVER EXCESS = \$ 2000 / per

CHARGES

Daily	@ \$	per day
Weekly	@ \$	per week
Monthly	@ \$	per month
Hours	@ \$	per hour
Others	@ \$	
CDW	@ \$	per day/month
PAI	@ \$	per day/month

Delivery/ Collection Service

SUB-TOTAL \$**PETROL LEVEL**

Out	E	1/4	1/2	3/4	F
In	E	1/4	1/2	3/4	F

EXTENSION

Misc.

TOTAL CHARGES \$

Hirer's Signature

Additional Driver's
Signature

 Authorised Person
Signature

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/ credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/ credit card voucher. All information I have given Dream Carz Leasing Pte Ltd in connection with this agreement is true.

IMPORTANT

ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.

THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF COW AND/OR PAI WHERE APPLICABLE.

IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN CAR RENTAL.

ON RETURN OF VEHICLE, THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN SINGAPORE OF HIRER / DRIVER * FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
04/07/18				AUTOWORKS	

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: Winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

Our Ref: WG/TP/2018-239
Invoice No: TP/AW/2018-239
Vehicle No: SJT5698E
Attn: KOH NIAK WU
Company: AVIS MANAGEMENT PTE LTD
Address: 8 Kaki Bukit Ave 4, #05-01/02, Premier Building S415875

Date 26 July 2018

Invoice

Surveyor Fee:	S\$290
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$65/- (@ \$1 per photo, total 65 photos)
Total:	S\$455

Surveyor:
Signature:
Date:

Winsen Goh
26/7/2018



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: wimongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S KOH NIAK WU
C/O AVIS MANAGEMENT PTE LTD
8 Kaki Bukit Ave 4, #05-01/02
Premier Building S415875

Date : 26 July 2018
Our Ref : WG/TP/2018-239

REFERENCE PARTICULARS

Date of Accident : 03 July 2018
Date of Inspection : 04 July 2018

Type of Inspection : Third Party Claim
Date of Re-Inspr : 10 July 2018

VEHICLE PARTICULARS

Registration No : SJT5698E
Make : NISSAN
Model : LATI
Year : NA

Engine No : HR151498
Chassis No : JN1BAACJJ2005J524
Odometer : 131618km
Colour : Black

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near Side	Hankook	165/60R15
Front Off side	Hankook	165/60R15
Rear Near side	Hankook	165/60R15
Rear Off side	Hankook	165/60R15

Thread Balance
5mm
5mm
5mm
5mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$6,900.00** nett at lump sum basis (Subject to GST (if applicable))
Under normal circumstances, estimated period required for repairs : Ten (10) working days.

Enclosed Sixty-five (65) photographs depicting damage to the vehicle.

Inspection conducted at : AVIS MANAGEMENT PTE LTD
8 Kaki Bukit Ave 4, #05-01/02, Premier Building S415875.

In accordance to your instruction, we have **not** authorise repairs and inspection
was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

VEHICLE NO : SJT5698E
MODEL : LATIO

Our Ref : WG/TP/2018-239

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS		QTY	ASSESSED	ORIGINAL	REVISED
		PC/SET	CONDITION	QUOTATION	QUOTATION
1	REAR BUMPER	1	DEFORMED	\$ 609.90	\$ 609.90
2	REAR END PANEL	1	DENTED	\$ 542.60	\$ 542.60
3	REAR TAILLAMP PANEL	2	REPAIR	\$ 364.80	\$ -
4	REAR LH FENDER	1	DENTED	\$ 1,152.70	\$ 1,152.70
5	BOOTLID	1	DENTED	\$ 846.40	\$ 846.40
				\$ 3,516.40	\$ 3,151.60
				Less 30%	\$ 1,054.92
				\$ 2,461.48	\$ 2,206.12
6	REAR BUMPER SIDE RETAINER	2	NECESSARY	\$ 70.40	\$ 70.40
7	REAR BUMPER BRACKET	2	NECESSARY	\$ 57.60	\$ 57.60
8	REAR BUMPER SPONGE	1	CRACKED	\$ 35.60	\$ 35.60
9	REAR END PANEL TOP GARNISH	1	DEFORMED	\$ 103.10	\$ 103.10
10	END PANEL KEY ACCESS CONTROL	1	CRACKED	\$ 57.50	\$ 57.50
11	REAR TAILLAMP	2	CRACKED	\$ 534.84	\$ 534.84
12	REAR FENDER INNER TRIM	2	NOT NECESSARY	\$ 484.80	\$ -
13	REAR WINDSCREEN MOULDING	1	NECESSARY	\$ 130.10	\$ 130.10
14	BOOTLID WEATHERSTRIP	1	DEFORMED	\$ 69.90	\$ 69.90
15	BOOTLID EMBLEM	1	NECESSARY	\$ 45.60	\$ 45.60
16	BOOTLID OUTER CHROME	1	CRACKED	\$ 257.70	\$ 257.70
17	BOOTLID NUMBER PLATE	2	CRACKED	\$ 59.40	\$ 59.40
18	BOOTLID LOCK	1	JAMMED	\$ 97.90	\$ 97.90
19	BOOTLID LOCK STRIKER	1	BENT	\$ 50.00	\$ 50.00
20	BOOTLID HINGE	2	BENT	\$ 105.10	\$ 105.10
21	SPARE TYRE TOP BOARD	1	DEFORMED	\$ 495.00	\$ 495.00
				\$ 2,654.54	\$ 2,169.74
				Less 10%	\$ 265.45
				\$ 2,389.09	\$ 1,952.77
B) S/NETT ITEM					
22	REAR BUMPER CLIP	1 SET	NECESSARY	\$ 60.00	\$ 50.00
23	FENDER INNER TRIM CLIP	1 SET	NECESSARY	\$ 50.00	\$ 40.00
24	REAR REVERSE SENSOR	1 SET	MALFUNCTION	\$ 400.00	\$ 300.00
25	WINDSCREEN SEALANT	1	NECESSARY	\$ 150.00	\$ 120.00
26	JOINT SEALANT	1	NECESSARY	\$ 150.00	\$ 120.00
27	REAR NUMBER PLATE	1	BENT	\$ 70.00	\$ 60.00
				\$ 880.00	\$ 690.00
Parts Total :				\$ 5,730.57	\$ 4,848.89
C) LABOUR CHARGES & MISC					
28	CHECK REAR WIRING AND LIGHTNING SYSTEM			\$ 60.00	\$ 50.00
29	REMOVE AND REFIT LINING, TRIM AND GARNISH			\$ 200.00	\$ 180.00
30	REMOVE AND RENEW REAR REVERSE SENSOR			\$ 150.00	\$ 130.00
31	REMOVE AND STRAIGHTEN REAR EXHAUST ASSY			\$ 150.00	\$ 120.00
32	REMOVE AND REFIT REAR WINDSCREEN			\$ 150.00	\$ 120.00
33	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW			\$ 200.00	\$ 180.00
34	PANEL BEATING ON AFFECTED AREAS			\$ 1,800.00	\$ 1,500.00
35	SPRAY PAINTING ON AFFECTED AREAS			\$ 1,500.00	\$ 1,400.00
36	APPLY ANTI RUST ON AFFECTED AREAS			\$ 150.00	\$ 130.00
Labour Total :				\$ 4,360.00	\$ 3,810.00
Total Parts and Labours :				\$ 10,090.57	\$ 8,658.89
FINAL LUMP SUM ADJUSTMENT					\$ 6,900.00

7 days

POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$6,900.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES



Winson Goh
Automotive Appraiser



Your Ref: 18.25687

Date: 11th Dec 2018

Our Ref: CS3/ASM18012521/Gvbe2-1

M/s Axa Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJT 5698E

INSURED VEHICLE: XE 252S

ACCIDENT DATE: 03/07/2018

We thank you for your instruction on 30/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJT 5698E from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SJT 5698E.
- c) Colour damaged vehicle photographs of SJT 5698E.

Pre-Repair Inspection Date : 10/07/2018 at M/s : 8 Kaki Bukit Ave 4 #05-01, Repairer : Autowerke Automotive.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded:-

Registration Number	: SJT 5698E
Make & Model	: Nissan Latio 1.5L AT ABS D/Airbag 2WD 4DR
Year of Registration	: 2009
Chassis Number	: JN1BAAC11Z0021524
Engine Capacity	: 1498 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 5698E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	609.90	609.90
1	REAR END PANEL	DENTED	542.60	542.60
2	REAR TAILLAMP PANEL	TO REPAIR SEE LABOUR	364.80	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	1,152.70	-
1	BOOTLID	DENTED	846.40	846.40
	LESS 30% DISCOUNT		-1,054.92	-599.67
			2,461.48	1,399.23
<u>NETT ITEMS</u>				
2	REAR BUMPER SIDE RETAINER (N)	NECESSARY	70.40	70.40
2	REAR BUMPER BRACKET (N)	NECESSARY	57.60	57.60
1	REAR BUMPER SPONGE (N)	CRACKED	35.60	35.60
1	REAR END PANEL TOP GARNISH (N)	DEFORMED	103.10	103.10
1	END PANEL KEY ACCESS CONTROL (N)	NOT NECESSARY	57.50	-
2	REAR TAILLAMP (N)	CRACKED	534.84	534.84
2	REAR FENDER INNER TRIM (N)	NOT NECESSARY	484.80	-
1	REAR WINDSCREEN MOULDING (N)	NOT NECESSARY	130.10	-
1	BOOTLID WEATHERSTRIP (N)	DEFORMED	69.90	69.90
1	BOOTLID EMBLEM (N)	NECESSARY	45.60	45.60
1	BOOTLID OUTER CHROME (N)	CRACKED	257.70	257.70
2	BOOTLID NUMBER PLATE (N)	CRACKED	59.40	59.40
1	BOOTLID LOCK (N)	JAMMED	97.90	97.90
1	BOOTLID LOCK STRIKER (N)	BENT	50.00	50.00
2	BOOTLID HINGE (N)	BENT	105.10	105.10
1	SPARE TYRE TOP BOARD (N)	NOT NECESSARY	495.00	-
	LESS 10% DISCOUNT		-265.45	-148.71
			2,389.09	1,338.43
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	NECESSARY	400.00	200.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	50.00

Report Ref No. CS3/ASM18012521/Gvbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	JOINT SEALANT (SN)	NECESSARY	150.00	50.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	70.00	-
			880.00	330.00
	LABOUR			
	CHECK REAR WIRING AND LIGHTNING SYSTEM.		60.00	30.00
	REMOVE AND REFIT LINING, TRIM AND GARNISH.		200.00	60.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	50.00
	REMOVE AND STRAIGHTEN REAR EXHAUST ASSY.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR TAILLAMP PANEL AND REAR LH FENDER.		1,800.00	800.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,500.00	700.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	60.00
			4,360.00	1,760.00
	GRAND TOTAL		10,090.57	4,827.66
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,850.00

Report Ref No. CS3/ASM18012521/Gvbe2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.