



Your Ref: 18.25687

Date: 11th Dec 2018

Our Ref: CS3/ASM18012521/Gvbe2-1

M/s Axa Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJT 5698E
INSURED VEHICLE: XE 252S
ACCIDENT DATE: 03/07/2018**

We thank you for your instruction on 30/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJT 5698E from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SJT 5698E.
- c) Colour damaged vehicle photographs of SJT 5698E.

Pre-Repair Inspection Date : 10/07/2018 at M/s : 8 Kaki Bukit Ave 4 #05-01, Repairer : Autowerke Automotive.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJT 5698E
Make & Model	: Nissan Latio 1.5L AT ABS D/Airbag 2WD 4DR
Year of Registration	: 2009
Chassis Number	: JN1BAAC11Z0021524
Engine Capacity	: 1498 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.