

INSURANCE

INS. CASE OWNER:

DEANARD

CC 4/AIG1802

1829, KPM39

LKK:

IDAC:

Surveyor:

KORATH

DOI:

ASSIGNMENT
04/12/18

Date / Time:

21/1/18

Registered in Merimen:

21/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGW 288UG

Name of Insured:

KHOO LIM LIN WHEA HYN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

10/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: GEE KAD 7yr

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

:

224207088456

Policy No.:

:

20042214-03

Make / Model:

:

MERCEDES

Place of Accident:

:

GREENWICH VILLAGE 4

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SUA CLAIM

INSRS:
WSP:
Tel:
Liability:
RMKS:

SAH

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

5/1/18

717

16/05/19

30/05/19

SUA CLAIM - X SGW 288UG - Y

- INSTRUCTED
- TP LOD IN BY BULIL
- VIDEO FOOTAGE UPLOADED IN INFORMATION- FILE REVISED. OLD MOVING OFF
FROM CP LOT. VIDEO FOOTAGE IN.
SEND LETTER TO OI

- TP ACCEPTED OFFER.

- RECOVERED BY ALL BOSS IN OFFICE.
- TO CLOSE.

STAGE DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI: 16/05/19 - VIC

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost: P/P

S\$ 2,000.56 (3 days) Reduction: 16 %

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email: Call:

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: (w/lev)

S\$

3,000.10

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

210.00 x 60 x 4 (days)

Loss of Income (LOI):

S\$

(5 x days)

LOR only ☐ LOU only ☒

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search:

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

3,290.10

Global Sum S\$:

3,290.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email: Call:

Payee 1:

S\$

3,290.00

Name 1:

G L H MOTOR PTB LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

REF: ALG1

ASSIGNMENT

From: Date: 04/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLA 1101M
at Workshop mis: S & H Motor.
of: 160 Sim Ming Drive #07-02

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

10am - 12pm

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res: Yes or No

Lump Sum: 1.81 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLA 1101M Yr Regn: 02 16

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai A/Electro cc 1591

Colour: M. D. Grey A/C Insured / Std / NI / NA

Sp. Reading: 44486 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KM1101H 41CMGU 856773

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal: 8 mm

R/Bal: 8 mm

L/Bal: 8 mm

L/Bal: 8 mm

D.O.A. 10/11/18

D.O.I. 4/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/12 File pass to Cathman

\$ 2,850.56

(net: \$500.32/16%)

Date/Time: File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

I S+RS SI

I Price

I Other

I

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

The Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD
 BLK 78 #08-16
 SHENTON WAY
 CHARTIS BUILDING
 SINGAPORE 079120

File No :
 Date : 19-November-2018

Not Authored
Resurvey B4 paint
3 days

Estimated cost of repair for vehicle no: **SLA1101M** HYUNDAI ELANTRA
 Accident involving vehicle no: **SLA1101M** & **SGN2880G** on 10-November-2018

Description	Quantity	List Price
Front bumper	1 <i>440.50</i>	<i>\$ helum</i> 481.30 ✓
<i>LH</i> head lamp	1	<i>\$ G</i> 1,756.40 ✓
<i>LH</i> bumper focus lamp	1 <i>233.50</i>	<i>\$ G</i> 335.50 ✓
		\$ 2,573.20
	Less 10% <i>20%</i>	\$ 257.32
		\$ 2,315.88
RH bumper parking sensor	1	<i>SN \$ / S/L</i> 260.00 <i>18m</i>
To spray paint bonnet bumper and accident repair areas.	1	\$ 450.00 <i>400</i>
Labour charges to fixed and removed front bumper, head lamp, and install damaged areas.	1	\$ 380.00 <i>300</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	\$ 25.00 <i>200</i>
		<u>\$ 3,430.88</u>

T/Party: AIG ASIA PACIFIC INSURANCE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1649G

Vehicle Details

Vehicle No.: SLA1101M
Vehicle to be Exported: Yes
Intended Deregistration Date: 12 Nov 2018
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: G4GFUD68800
Chassis No.: KMHDH41CMGU656773
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$15,245.00
Original Registration Date: 23 Feb 2016
First Registration Date: 23 Feb 2016
Transfer Count: 0
Actual ARF Paid: \$15,245.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Feb 2026
PARF Rebate Amount: \$11,433.00

Intended COE Rebate Details

COE Expiry Date: 22 Feb 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$43,000.00
COE Rebate Amount: \$31,302.00
Total Rebate Amount: \$42,735.00

The information contained herein is correct as at 12 Nov 2018

OK

Our Ref : SH/2018/152/11/013/TP

Date : 02 April 2019

The Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD
BLK 78 #08-16
SHENTON WAY
CHARTIS BUILDING
SINGAPORE 079120

Dear Sir / Madam,

RE : Accident Involving SLA1101M & SGN2880G on 10.11.2018

I forward herewith copies of the following documents for claiming against your insured for my loss of use :-

Cost Of Repair - Invoice No: AR201903-0142	:	S\$ 3,050.10
Loss Of Use (\$ 100.00 x 4 days)	:	S\$ 400.00
		<u>S\$ 3,450.10</u>

Your co-operation and prompt settlement towards this matter are much appreciated.

Kindly acknowledge the receipt of this letter.

Thank you very much for your kind attention.

Yours faithfully,

encl



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

16 MAY 2019

**KHOO KIM LIN CLARA-ANN
23 FERNVALE LANE
#20-29
SINGAPORE 797501**

Dear Sir/Madam,

**OUR REF : CC4/AIG18021829/Khb3
YOUR REF : SGN 2880G
ACCIDENT INVOLVING SGN 2880G AND SLA 1101M ALONG GREENWICH MALL
CAR PARK ON 10.11.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLA 1101M against your motor insurance policy.

Based on the accident report, accident scenario and available evidence at hand, it was reported that your vehicle had collided to the Third-Party vehicle SLA 1101M. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Koh Li Chen ("the third party claimant")
of Blk 146 Saraca Rd, Saraca Gardens, S1407416 (address),
owner of SLA1101M (vehicle no.) hereby authorize
S & H Motor Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLA1101M that was
damaged pursuant to the accident which occurred on 10/11/2018 (date) along
Greenwich Mall Carpark (location)
involving vehicle no/s SGN288G ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 25 day of June (month) 2019 (year)

Signed by "the third party claimant"

Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **S & H MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,290.00** (Global Sum – all in) for vehicle no. **SLA 1101M** that was damaged pursuant to the accident which occurred on **10/11/2018** (date) along **GREENWICH MALL CAR PARK** (location) involving vehicle no/s **SGN 2880G**. This is pursuant to the inspection conducted on **04/12/2018** (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner **KHOO KIM LIN CLARA-ANN** ("the third party claimant") of vehicle no. **SLA 1101M** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLA 1101M** (vehicle no.) as a result of the accident.



We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of June (month) **2019** (year)

 KOC

Signed by appointed surveyor

 
Signed by "the workshop" (with chop)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2018 16:28		03 Dec 2018 17:20 Edit Adj Rpt	\$2,850.56 Edit Estimates	\$2,850.56 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	KHOO KIM LIN, CLARA-ANN , ID: S8733695F, Tel: +6593668938								
Main Claimant:	KOH LI CHEN , ID: S0001649G								
Vehicle Reg. No.:	SLA1101M	Date of Loss:	10/11/2018 17:00 - :59 [32 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3343510883SG	Policy/Cover Note No.:	2100432114 (Comprehensive) Coverage: 28/12/2017 - 27/12/2018						
Vehicle Reg. No. (Insured):	SGN2880G	Policy No. (Claimant):	VPA/P1727551						
		Excess:							
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/12/2018]								
Driver/Custodian (Insured):	SEE HAO JUN (32 / Male), NRIC: S8542434C, Tel: +6598419481 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA1101M (3343510883SG)
[SGN2880G]
TP
KOH LI CHEN
Nov 10 2018 5:00PM
[KHOO KIM LIN, CLARA-ANN]
S & H Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	23/11/18 16:52	Video - Accident <small>From:OD - Reg. No: SGN2880G, Claimant: KHOO KIM LIN, CLARA-ANN</small>		Load MP4	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	12/11/18 15:18	Video - Accident <small>[Linked Accident Report Documents]</small>		Load MP4	

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Assessment Reports

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	23/11/18 16:52	Accident Statement <small>From:OD - Reg. No: SGN2880G, Claimant: KHOO KIM LIN, CLARA-ANN</small>		Load HTM	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	12/11/18 15:20	Accident Statement		Load HTM	

Photos/Images

3 per page

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
2	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
3	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
4	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
5	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
6	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
7	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
8	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
9	12/11/18 15:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/06/19 11:36	Odometer Reading		Load JPG	
2	24/06/19 11:36	Chassis Number		Load JPG	
3	24/06/19 11:36	General View		Load JPG	
4	24/06/19 11:36	General View		Load JPG	
5	24/06/19 11:36	General View		Load JPG	
6	24/06/19 11:36	General View		Load JPG	
7	24/06/19 11:36	General View		Load JPG	
8	24/06/19 11:36	General View		Load JPG	
9	24/06/19 11:36	General View		Load JPG	
10	24/06/19 11:36	General View		Load JPG	
11	24/06/19 11:36	General View		Load JPG	
12	24/06/19 11:36	General View		Load JPG	
13	24/06/19 11:36	General View		Load JPG	
14	24/06/19 11:36	General View		Load JPG	
15	24/06/19 11:37	Reinspection Photo		Load JPG	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
16	24/06/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/11/18 16:29	Repair Estimate		<input checked="" type="checkbox"/>
2	23/11/18 17:07	Liability Established		<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/11/18 15:13	Sketch Plan [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
2	12/11/18 15:13	Sketch Plan #2 [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
3	12/11/18 15:13	Sketch Plan #3 [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
4	12/11/18 15:13	Sketch Plan #4 [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
5	12/11/18 15:13	Sketch Plan #5 [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 17:26	TP ESTIMATE- MARKED		<input checked="" type="checkbox"/>
2	24/06/19 11:53	LETTER TO OI		<input checked="" type="checkbox"/>
3	12/09/19 10:29	WORKSHOP INVOICE		<input checked="" type="checkbox"/>
4	12/09/19 10:29	AUTHORISATION TO ACT FORM		<input checked="" type="checkbox"/>
5	12/09/19 10:29	Release Voucher		<input checked="" type="checkbox"/>

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/11/18 15:18	Video - Accident		<input checked="" type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/11/18 15:20	Accident Statement		<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
2	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
3	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
4	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
5	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
6	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
7	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
8	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
9	12/11/18 15:12	Accident Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/11/18 15:13	Sketch Plan		<input checked="" type="checkbox"/>
2	12/11/18 15:13	Sketch Plan #2		<input checked="" type="checkbox"/>
3	12/11/18 15:13	Sketch Plan #3		<input checked="" type="checkbox"/>
4	12/11/18 15:13	Sketch Plan #4		<input checked="" type="checkbox"/>
5	12/11/18 15:13	Sketch Plan #5		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGN2880G (Insd veh)	Model:	HYUNDAI ELANTRA 1.6
	SLA1101M (TP veh)		ABS D/AB 2WD 4DR (A)
Date of Accident:	10/11/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	3,671.04
Final Repair Cost	:	\$	3,290.00
Loss of Use	:	\$	4.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,290.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	S & H Motor Pte Ltd	:	\$ 3,290.00
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

12 Sep
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021829/KHB3Q2

Date: 12/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100432114
 Claimant: SLA1101M Insured Vehicle No: SGN2880G
 Vehicle No: SLA1101M
 Date of Loss: 10/11/2018 Nature of Claim: TP Claim No: 3343510883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA1101M**
 Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A) Engine No: G4FGFU068800
 Reg. Date: 23/02/2016 (Man. Year: 2015) Chassis No: KMHDH41CMGU656773
 Colour: Metallic Dark Grey Odometer: 44496 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Hankook 8 mm Rear Left Side: Hankook 8 mm
 Front Right Side: Hankook 8 mm Rear Right Side: Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,575.88	2,130.56	445.32	17.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	855.00	720.00	135.00	15.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,430.88	2,850.56	580.32	16.91
+ GST 7.00/7.00% (S\$)	240.16	199.54	40.62	16.91
Nett Amount (S\$)	3,671.04	3,050.10	620.94	16.91
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		3,290.10		
Global Sum Settlement (S\$)		3,290.00		

INSPECTION

Date of Assignment: 03/12/2018
 Date Inspected: 04/12/2018 Inspected At: S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming
 AutoCity
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	481.30 FL	*448.30 FL
2	1		*LH HEADLAMP	Cut	1,756.40 FL	*1,756.40 FL
3	1		*LH BUMPER FOCUE LAMP	Cut	335.50 FL	*233.50 FL
4	1		*RH BUMPER PARKING SENSOR	Dented / Scratched	260.00 FS	*180.00 FS

F=Franchise part. S=SpchNett. L=ListItemDisc.

Sub Total (S\$)	2,833.20	2,618.20
- List Item Discount on L Items 10.00/20.00% (S\$)	257.32	487.64
Total Parts (S\$)	2,575.88	2,130.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SPRAY PAINT BONNET BUMPER AND ACCIDENT REPAIR AREAS	New	450.00	400.00
2	LABOUR CHARGES TO FIXED AND REMOVED FRONT BUMPER ,HEAD LAMP ,AND INSTALL DAMAGED AREAS	New	380.00	300.00
3	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY .TO FOCUS HEADLAMP	New	25.00	20.00
Gross Labour Cost (\$\$)			855.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >