



(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Am/**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 66717at Workshop m/s Rico

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: 6 Consistent? : Yes or NoEst. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time Action / Instruction LTA 355633/5 Rear ? consistent?\$ 6,300/-R (\$ 18,237.90 / 74%)Veh No: PC 66717 Yr Regn: 10:17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)Make: Toyota hiace super G.6cc 2982Colour: white A/C: Insured / Std / NI / NASp.Reading: 75/69 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KDM 211 8007479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

Front 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/11/18 D.O.I. 5/12/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s rear, 20/5/18

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                                           |                            |            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                        |                                                                                                           | Ref : CC4/AIG18021834/Ujb3 |            |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120                                                                             |                                                                                                           | Date : 04-12-2018          |            |  |
|                                                                                                                                           |                                                                                                           | Code : AIG                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                                           |                            |            |                                                                                     |
| Insured Veh.                                                                                                                              | GBH 6182C                                                                                                 | Veh. Inspected             | PC 6671T   |                                                                                     |
| Policy No.                                                                                                                                |                                                                                                           | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                                 |                                                                                                           | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                               |                                                                                                           | Assign Date                | 04/12/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                                           |                            |            |                                                                                     |
| Make & Model                                                                                                                              |                                                                                                           | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                                                    | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                                           | Colour                     |            |                                                                                     |
| Odometer                                                                                                                                  |                                                                                                           | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                    |                                                                                                           | Modification               |            |                                                                                     |
| General                                                                                                                                   |                                                                                                           |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                                           |                            |            |                                                                                     |
|                                                                                                                                           | Size                                                                                                      | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                                                           |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                                                           |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                                                           |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                                                           |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                                           |                            |            |                                                                                     |
|                                                                                                                                           |                                                                                                           |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                                           |                            |            |                                                                                     |
| Accident Date                                                                                                                             | 30/11/2018                                                                                                | Inspection Date            | 05/12/2018 |                                                                                     |
| Survey held at                                                                                                                            | RICO 60 AUTO SERVICES PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#02-24 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                                           |                            |            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                           |                            |            |                                                                                     |



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com  
Tel: 6286 6060 , FAX: 6286 7060  
VECHICLE NUM: PC 6671 T  
MAKE & MODEL: TOYOTA HIACE  
MILEAGE:  
TYRE:  
CHASSIS NUM:

4/5 \$6300/2

6 day not Agent  
note 5/11/18  
To be replaced

| NO. | DESCRIPTION - PARTS                           | QTY | PRICE      |         |
|-----|-----------------------------------------------|-----|------------|---------|
| 1   | FRONT BONNET <i>2 X</i>                       | 1   | \$549.60   | X       |
| 2   | FRONT BONNET LOGO <i>2 X</i>                  | 1   | \$54.90    | X       |
| 3   | FRONT BONNET HINGE L+R <i>1 X</i>             | 2   | \$242.80   | X       |
| 4   | FRONT BONNET RUBBER <i>1 X</i>                | 1   | \$108.40   | X       |
| 5   | FRONT BONNET LOCK <i>1 X</i>                  | 1   | \$135.40   | X       |
| 6   | FRONT GRILLE ASSY <i>1 X</i>                  | 1   | \$481.40   | X       |
| 7   | FRONT BUMPER <i>DIS</i>                       | 1   | \$681.40   | X       |
| 8   | FRONT BUMPER BEAM <i>DIS</i>                  | 1   | \$289.90   | X       |
| 9   | FRONT BUMPER REINFORCEMENT BAR <i>2 NN</i>    | 1   | \$381.40   | X       |
| 10  | FRONT BUMPER RETAINER L+R <i>DISC 1 PC</i>    | 2   | \$262.40   | X       |
| 11  | FRONT BUMPER BRACKET L+R <i>1 X</i>           | 2   | \$232.60   | X       |
| 12  | FRONT BUMPER TOWING COVER <i>1 X</i>          | 1   | \$41.20    | X       |
| 13  | FRONT BUMPER FOG LAMP <i>2 UN</i>             | 2   | \$282.60   | X       |
| 14  | FRONT BUMPER FOG LAMP GARNISH <i>SCN</i>      | 1   | \$134.20   | X       |
| 15  | FRONT HEADLAMP L+R <i>0/5/10 1 PC</i>         | 2   | \$1562.40  | X       |
| 16  | FRONT HEADLAMP PANEL RH <i>2 X</i>            | 1   | \$289.40   | X       |
| 17  | SIDE PANEL RH <i>SCN</i>                      | 1   | \$362.40   | X       |
| 18  | FRONT SUPPORT PANEL <i>2 X</i>                | 1   | \$482.40   | X       |
| 19  | FRONT BRACE PANEL <i>1 X</i>                  | 1   | \$161.20   | X       |
| 20  | WIRE HARNESS <i>1 X</i>                       | 1   | \$338.50   | X       |
| 20  | AIR CON CONDENSER <i>1 X</i>                  | 1   | \$1012.40  | X       |
| 21  | RADIATOR <i>1 X</i>                           | 1   | \$1514.50  | X       |
| 22  | RADIATOR SPARE TANK <i>1 X</i>                | 1   | \$387.40   | X       |
| 23  | TURBO COOLER <i>1 X</i>                       | 1   | \$2,142.00 | X       |
| 24  | WASHER TANK <i>1 X</i>                        | 1   | \$161.40   | X       |
| 25  | WASHER TANK MOTOR <i>1 X</i>                  | 1   | \$162.60   | X       |
| 26  | FRONT DOOR RH <i>NO/24</i>                    | 1   | \$1683.40  | X       |
| 27  | FRONT DOOR HINGE UP AND DOWN <i>1 X</i>       | 2   | \$248.30   | X       |
| 28  | FRONT DOOR CHECKER <i>1 X</i>                 | 1   | \$164.30   | X       |
| 29  | FRONT DOOR WINDOW MOULDING <i>1 X</i>         | 1   | \$124.30   | X       |
| 30  | FRONT DOOR LOWER STEP PANEL <i>2 X</i>        | 1   | \$246.50   | X       |
| 31  | FRONT DOOR LOWER STEP PANEL GARNISH <i>TO</i> | 1   | \$123.40   | X       |
| 32  | REAR FENDER RH <i>3.550</i>                   | 1   | \$1715.90  | X       |
| 33  | REAR FENDER GLASS MOULDING RH <i>1 X</i>      | 1   | \$135.80   | X       |
| 34  | REAR FENDER DOOR RAILING RH <i>25%</i>        | 1   | \$340.50   | X       |
|     | PARTS = \$6,635.2                             |     |            |         |
|     | LESS 25% = \$4976.40                          |     |            |         |
|     | SUBTOTAL                                      |     | \$         | 6296.4  |
|     | LESS 25%                                      |     | \$         | 4272.23 |
|     | PARTS TOTAL                                   |     | \$         | -       |


12312.20  
-25% 12987.90

| SPECIAL NETT                                           |        | QTY              | PRICE        |
|--------------------------------------------------------|--------|------------------|--------------|
| RADIATOR COOLANT                                       | 11 X   | 1                | \$ 120.00    |
| FRONT BUMPER CLIPS                                     | in 30  | 10               | \$ 100.00    |
| FRONT BUMPER LOWER SPOILER                             | in 800 | 1                | \$ 4,000.00  |
| REAR FENDER SEALANT                                    | 11 X   | 1                | \$ 120.00    |
| REAR FENDER GLASS SEALANT                              | in 40  | 1                | \$ 120.00    |
| SPECIAL NETT = \$870.                                  |        |                  |              |
| SPECIAL NETT TOTAL                                     |        |                  | \$ 4,460.00  |
| LABOUR                                                 |        | QTY              | PRICE        |
| 1 TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN | 1100   | 1                | \$ 3,000.00  |
| TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA            | 1000   | 1                | \$ 3,000.00  |
| TO RUST PROOF ACCIDENT AFFECTED AREA                   | 80     | 1                | \$ 120.00    |
| TO RNR FRONT DOOR MECHANISM                            | 60     | 1                | \$ 200.00    |
| TO RNR A/C CONDENSOR ASSY AND REFILL GAS               | 11 X   | 1                | \$ 250.00    |
| TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS              | 20     | 1                | \$ 150.00    |
| TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD     | 11 X   | 1                | \$ 250.00    |
| TO RNR REAR FENDER DOOR RAILING AND CHECK FUNCTION     | 80     | 1                | \$ 120.00    |
| LABOUR = \$2,340                                       |        |                  |              |
| GROSS TOTAL = \$8,186.4                                |        | LABOUR TOTAL     | \$ 7,090.00  |
| LESS 20% = \$6,650                                     |        | GRAND TOTAL COST | \$ 11,550.00 |

PAGE 2 OF 2

24537.90


? - 4722.30  
 S.N - 870.00  
 labour - 2340.00  
 -----  
 7932.30  
 6348



PC 6671 T  
TOYOTA HIACE

|       |  |
|-------|--|
| ATTN: |  |
|-------|--|

[illegible]

[illegible]

| SPECIAL NETT                                           |            | QTY | PRICE       |
|--------------------------------------------------------|------------|-----|-------------|
| RADIATOR COOLANT                                       | 11X        | 1   | S 120.00    |
| FRONT BUMPER CLIPS                                     | m 30       | 10  | S 100.00    |
| FRONT BUMPER LOWER SPOILER                             | cm 800     | 1   | S 4,000.00  |
| REAR FENDER SEALANT                                    | acc 40 m x | 1   | S 120.00    |
| REAR FENDER GLASS SEALANT                              | m 40       | 1   | S 120.00    |
| SPECIAL NETT TOTAL                                     |            |     | S 4,460.00  |
| LABOUR                                                 |            | QTY | PRICE       |
| 1 TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN | 1100       | 1   | S 3,000.00  |
| TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA            | 1000       | 1   | S 3,000.00  |
| TO RUST PROOF ACCIDENT AFFECTED AREA                   | 80         | 1   | S 120.00    |
| TO RNR FRONT DOOR MECHANISM                            | 60         | 1   | S 200.00    |
| TO RNR A/C CONDENSOR ASSY AND REFILL GAS               | 11X        | 1   | S 250.00    |
| TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS              | 20         | 1   | S 150.00    |
| TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD     | 11X        | 1   | S 250.00    |
| TO RNR REAR FENDER DOOR RAILING AND CHECK FUNCTION     | 80         | 1   | S 120.00    |
| LABOUR TOTAL                                           |            |     | S 7,090.00  |
| GRAND TOTAL COST                                       |            |     | S 11,550.00 |

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- Pre repair inspection request - PC6671T VS GBH6182C (OI) DOA 30/11/2018

From: Chan, Yoke Shi  
To: ASSIGNMENTS@LKKAUTO.COM, Admin A  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Azlan, Syazairdina, Hor, Yinnul  
Sent: Monday, 3 December, 2018 2:43:00 PM  
Attachments:  PRI Arrangement.pdf

Hi,

Please refer to the enclosed request from rico60.

Claim no : 69761469835G003  
Case Owner : CHAN KIAN MENG

If you have any queries/concerns, please let us know.  
Kindly assist to assign Marcus as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley  
AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com) | [www.aig.com](http://www.aig.com)

03-12-2018 @ 2:56pm  
Kelvin Keh in

**From:** claims@rico60.com [mailto:claims@rico60.com]  
**Sent:** Monday, December 03, 2018 2:38 PM  
**To:** Chan, Yoke Shi  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Hor, Yinnul  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBH6182C AND PC6671T ON 30/11/2018

Dear AIG,

Please have Marcus from Lkk survey the said vehicle.

**From:** Chan, Yoke Shi  
**Sent:** Mon, 3 Dec 2018 00:58:50 +0000  
**To:** Rico 60  
**Cc:** Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Azlan, Syazairdina, Hor, Yinnul  
**Subject:** - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBH6182C AND PC6671T ON 30/11/2018

Without Prejudice

Your Reference : PC6671T  
Our Reference : GBH6182C

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor         | Company Name                           |
|--------------------------|----------------------------------------|
| AIG In House Surveyor    | AIG Asia Pacific Insurance Pte Ltd     |
| Lawrence Ng Chun Kee     | Priority Services                      |
| Jeffrey Ong Leng Kiat    | Priority Services                      |
| Jimmy Lee                | Priority Services                      |
| EC Looi                  | Automobile Inspection Services Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd             |
| Ng You Han               | Formteam Adjusters Pte Ltd             |
| Soon Han Xin (Gary)      | Formteam Adjusters Pte Ltd             |

|                          |                              |
|--------------------------|------------------------------|
| Chow Bo Xiong            | Formteam Adjusters Pte Ltd   |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd   |
| Kalvin Ang               | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang           | LKK Auto Consultants Pte Ltd |
| Marcus Chua              | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh          | LKK Auto Consultants Pte Ltd |
| Adrian Ling              | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul           | LKK Auto Consultants Pte Ltd |
| Kenneth Kong             | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley  
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Enquiry [mailto:claims@rico60.com]

**Sent:** Saturday, December 01, 2018 9:43 AM

**To:** Lim, Sheng Yang; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Mithoosingh, Aashweenjeetkaur

**Subject:** PRI Arrangement for PC 6671 T

Dear All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – PC 6671 T  
Your Insured – GBH 6182 C  
DOA – 30/11/2018

Thank you.

Best Regards,  
Shanelle Lim



**RICO 60 AUTO SERVICES PTE. LTD.**

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: [claims@rico60.com](mailto:claims@rico60.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Print Received Message

This mail is associated with :

**\*PC6671T (6976146983SG)  
[GBH6182C]**

TP

GARY TAN TRANSPORT SERVICE

Nov 30 2018 12:00AM

[ONEBUILDER PTE LTD]

RICO 60 AUTO SERVICES PTE LTD

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 07/06/2019 17:00 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$8500.00) - PC6671T - Claim Handler: Chan, Kian-Meng

Approved:8500.00:COR: \$6,741.00 LOR: \$1,600.00 (8 days at \$200 per day) Search Fee: \$36.45 Please try to settle at best up to global sum \$8500.00 (all in)



**RICO 60 AUTO SERVICES PTE. LTD.**

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4

Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

Our Ref.: PC 6671 T  
Your Ref.: GBH 6182 C

Date: 15/1/2019

ATTN: Motor Claims Department  
INS: AIG Asia Pacific Insurance Pte. Ltd.

Dear Sir/Madam,

Accident Involving: PC 6671 T & GBH 6182 C  
Date of Accident: 30/11/2018  
Location: PIE (TUAS) AT BKE (SLE) ENTRANCE

We refer to the above-mentioned accident.

We are claiming as follows:

|                        |    |          |
|------------------------|----|----------|
| Cost of Repair:        | \$ | 6,794.50 |
| Rental                 |    |          |
| (\$260/Day x 10 Days): | \$ | 2,600.00 |
| 3rd Party Report:      | \$ | 29.00    |
| LTA Search:            | \$ | 7.45     |
| Grand Total:           | \$ | 9,430.95 |

The above-mentioned settlement is in respect for our client of damage pertaining to his/her motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his/her personal injuries.

Kindly take note that our office is located at **8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit, #02-24, Singapore 415875.**

For any further queries, please kindly contact Yvonne Teoh @ 6286 6060, or email to claims@rico60.com.

Thank You,

Yvonne Teoh

**RICO 60 AUTO SERVICES PTE. LTD.**

Co. &amp; GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4

Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

**TAX INVOICE**

AIG Asia Pacific Insurance Pte. Ltd.

6419 1000

Invoice No. : I201901406

Invoice Date : January 15, 2019

Vehicle No. : PC6671T

Make &amp; Model : TOYOTA HIACE

Chassis No. : KDH2118007479

Mileage : -

Terms : Due within 90 days

| NO. | DESCRIPTION                                                                                       | QUANTITY | PER UNIT (SGD) | AMOUNT (SGD) |
|-----|---------------------------------------------------------------------------------------------------|----------|----------------|--------------|
| 1   | To Carry Out Repair & Respray on Accident Corresponding to Supply on Spare Parts & Labour Charges | 1        | 6,350.00       | 6,350.00     |

|                                          |                   |
|------------------------------------------|-------------------|
| 7% GST                                   | \$444.50          |
| <b>GRAND TOTAL (INCLUSIVE OF 7% GST)</b> | <b>\$6,794.50</b> |
| Amount Paid                              | \$0.00            |
| Balance Due                              | \$6,794.50        |

Signature/Company Stamp

*I agree to the price as listed above and affirm that the goods are received in good condition.*

## Claim Documents

\*PC6671T (6976146983SG)  
[GBH6182C]  
TP  
GARY TAN TRANSPORT SERVICE  
Nov 30 2018 12:00AM  
[ONEBUILDER PTE LTD]  
RICO 60 AUTO SERVICES PTE LTD

|                                                                                                                                                             |                 |                                                    |                                                                                                                                    |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|----------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|-------|
| <a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a> |                 |                                                    | <b>View</b> <a href="#">View in Browser</a> ▼                                                                                      |       |
| <b>Letters/Correspondences</b>                                                                                                                              |                 |                                                    |                                                                                                                                    |       |
|                                                                                                                                                             |                 |                                                    | 1 per page ▼ <input checked="" type="checkbox"/>                                                                                   |       |
| No                                                                                                                                                          | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  | Thumbnail                                                                                                                          | Print |
| 1                                                                                                                                                           | (Draft)         | Third Party Express Settlement – Payment Breakdown |  Edit                                           |       |
| <b>Photos/Images</b>                                                                                                                                        |                 |                                                    |                                                                                                                                    |       |
|                                                                                                                                                             |                 |                                                    | 3 per page ▼ <input checked="" type="checkbox"/>                                                                                   |       |
| No                                                                                                                                                          | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  | Thumbnail                                                                                                                          | Print |
| 1                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/>   |       |
| 2                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/>   |       |
| 3                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/>   |       |
| 4                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/>   |       |
| 5                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/>   |       |
| 6                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 7                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 8                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 9                                                                                                                                                           | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 10                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 11                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 12                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 13                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 14                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 15                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 16                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 17                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 18                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 19                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 20                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 21                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 22                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 23                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 24                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 25                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 26                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 27                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 28                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 29                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 30                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 31                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |
| 32                                                                                                                                                          | 03/06/19 15:05  | General View                                       |  Load JPG <input checked="" type="checkbox"/> |       |

| Letters/Correspondences |                |                                   | 1 per page ▼                                                                                   | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 33                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                      | 03/06/19 15:05 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                      | 03/06/19 15:05 | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 52                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 53                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 54                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 55                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 56                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 57                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 58                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 59                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 60                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 61                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 63                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 64                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 65                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 66                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 67                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 68                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 69                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 70                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 71                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 72                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 73                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 74                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 75                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 76                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 77                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 78                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 79                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 80                      | 03/06/19 15:05 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                 |                                           | 1 per page                                                                                   | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|-------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                    | Print                               |
| 81                      | 03/06/19 15:05  | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 82                      | 03/06/19 15:05  | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 83                      | 03/06/19 15:06  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 84                      | 03/06/19 15:06  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 85                      | 03/06/19 15:06  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 86                      | 03/06/19 15:06  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 87                      | 03/06/19 15:06  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
|                         |                 |                                           |                                                                                              |                                     |
| Documentation           |                 |                                           | 1 per page                                                                                   | <input checked="" type="checkbox"/> |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                    | Print                               |
| 1                       | 04/12/18 18:00  | EMAIL FROM AIG DD 03122018                |  Load PDF |                                     |
| 2                       | 04/12/18 18:00  | NOTICE                                    |  Load PDF |                                     |
| 3                       | 07/12/18 08:51  | TP ESTIMATE- MARKED                       |  Load PDF |                                     |
| 4                       | 07/12/18 08:51  | TP GIA REPORT                             |  Load PDF |                                     |
| 5                       | 12/03/19 17:40  | GIA LTA SEARCH                            |  Load PDF |                                     |
| 6                       | 12/03/19 17:40  | RENTAL RECEIPT                            |  Load PDF |                                     |
| 7                       | 25/06/19 14:20  | LETTER TO OI                              |  Load PDF |                                     |
| 8                       | 25/06/19 14:20  | AUTHORISATION TO ACT                      |  Load PDF |                                     |
| 9                       | 25/06/19 14:20  | RELEASE VOUCHER                           |  Load PDF |                                     |
| 10                      | 25/06/19 14:20  | WORKSHOP INVOICE                          |  Load PDF |                                     |
| No                      | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail                                                                                    | Print                               |
| 1                       | 05/12/18 10:55  | OI GIA REPORT                             |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                |  | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|--|-------|------|-------|
| There are no document checklists configured.                                                                                                       |  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>                                                                                   |  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |  |       |      |       |

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'ed | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 03 Dec 2018<br><a href="#">Edit Reg</a> |               | 03 Dec 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$6,300.00</b><br><a href="#">Edit Estimates</a> | <b>S\$6,300.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                                                                                                                                                                                         | Reference                                                                                                                     | Claim Details          | Documents                                                                    | Show All |         |             |              |            |       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>                                                                                                                                                                                                                                                                      |                                                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| Insured:                                                                                                                                                                                                                                                                                                                                                     | ONEBUILDER PTE LTD, Co. Reg. No.: A200305666Z                                                                                 |                        |                                                                              |          |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                                                                                                                                                                                               | GARY TAN TRANSPORT SERVICE, Co. Reg. No.: 52859216E                                                                           |                        |                                                                              |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                                                                                                                                                                                                            | PC6671T                                                                                                                       | Date of Loss:          | 30/11/2018 00:00 - :59<br>[13 Months and 24 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                                                                                                                                                                                                                                                  | TP / 6976146983SG                                                                                                             | Policy/Cover Note No.: | 1800092945 (Comprehensive)                                                   |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                                                                                                                                                                                                  | GBH6182C                                                                                                                      | Policy No. (Claimant): | 5087461199-01                                                                |          |         |             |              |            |       |
|                                                                                                                                                                                                                                                                                                                                                              |                                                                                                                               | Excess:                |                                                                              |          |         |             |              |            |       |
| Repairer:                                                                                                                                                                                                                                                                                                                                                    | RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:             |                        |                                                                              |          |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                                                                                                                                                                                                            | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]<br>Kianmeng.Chan1@aig.com |                        |                                                                              |          |         |             |              |            |       |
| Claimant's Insurer:                                                                                                                                                                                                                                                                                                                                          | NTUC Income Insurance Co-operative Ltd (HQ) - Tel:                                                                            |                        |                                                                              |          |         |             |              |            |       |
| Adjuster:                                                                                                                                                                                                                                                                                                                                                    | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/12/2018]                |                        |                                                                              |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                                                                                                                                                                                                |                                                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (07/06/2019): Alert - Adj Mandate Approved (S\$8500.00) - PC6671T - Claim Handler: Chan, Kian-M...</li> <li>AIG_SG_EXPRESS (04/06/2019): Alert - Adj Mandate Approved (S\$8000.00) - PC6671T - Claim Handler: Chan, Kian-M...</li> <li>AIG_SG (05/12/2018): Request to upload TP GIA Report</li> </ul> |                                                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>                                                                                                                                                                                |                                                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| Due Date                                                                                                                                                                                                                                                                                                                                                     | Priority                                                                                                                      | Type                   | Task Group                                                                   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                                                                                                                                                                                                  |                                                                                                                               |                        |                                                                              |          |         |             |              |            |       |



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021834/UJB3S2

Date: 25/06/2019

## REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:           | 1800092945   |
| Claimant Vehicle No : | PC6671T                              | Insured Vehicle No : | GBH6182C     |
| Date of Loss:         | 30/11/2018                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 6976146983SG |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |               |
|-----------------------------|------------------------------|-------------|---------------|
| Reg No:                     | PC6671T                      | Engine No:  | 1KD2657603    |
| Make & Model:               | TOYOTA HIACE, 3.0 (A)        | Chassis No: | KDH2118007479 |
| Reg. Date:                  | 06/10/2017 (Man. Year: 2016) | Odometer:   | 75169 km      |
| Colour:                     | White                        |             |               |
| Engine Capacity:            | 2982 cc                      |             |               |
| Market Value/New Car Price: | N/A                          |             |               |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |               |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

## CONDITION OF TYRES

|                   |           |                  |           |
|-------------------|-----------|------------------|-----------|
| Front Tyre Size:  | 195 R15   | Rear Tyre Size:  | 195 R15   |
| Front Left Side:  | Toyo 6 mm | Rear Left Side:  | Toyo 6 mm |
| Front Right Side: | Toyo 6 mm | Rear Right Side: | Toyo 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's       | Adjuster's      | Difference       | Diff %       |
|-------------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                           | 17,447.90        | 5,398.35        | 12,049.55        | 69.06        |
| Miscellaneous Items                             | 0.00             | 0.00            | 0.00             |              |
| Labour                                          | 7,090.00         | 2,340.00        | 4,750.00         | 67.00        |
| Paintwork Labour                                | 0.00             | 0.00            | 0.00             |              |
| Towing                                          | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>24,537.90</b> | <b>7,738.35</b> | <b>16,799.55</b> | <b>68.46</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                  | <b>6,300.00</b> |                  |              |
| (S\$)                                           | 24,537.90        | 6,300.00        | 18,237.90        | 74.33        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | <b>1,717.65</b>  | <b>441.00</b>   | <b>1,276.65</b>  | <b>74.33</b> |
| <b>Nett Amount (S\$)</b>                        | <b>26,255.55</b> | <b>6,741.00</b> | <b>19,514.55</b> | <b>74.33</b> |
| <b>+ Car Rental (9.0 x S\$200.00/day) (S\$)</b> |                  | <b>1,800.00</b> |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | <b>36.45</b>    |                  |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>8,577.45</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>              |                  | <b>8,500.00</b> |                  |              |

## INSPECTION

Date of Assignment: 03/12/2018

Date Inspected: 05/12/2018 Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)  
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT  
Singapore 415875

Estimated Period of Repair: 6.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                        | Repair        | 549.60 FL   | *- FL        |
| 2   | 1   |          | *FRONT BONNET LOGO                   | Necessary     | 54.90 FL    | *54.90 FL    |
| 3   | 2   |          | *FRONT BONNET HINGE L+R              | Not Necessary | 242.80 FL   | *- FL        |
| 4   | 1   |          | *FRONT BONNET RUBBER                 | Not Necessary | 108.40 FL   | *- FL        |
| 5   | 1   |          | *FRONT BONNET LOCK                   | Not Necessary | 135.40 FL   | *- FL        |
| 6   | 1   |          | *FRONT GRILLE ASSY                   | Not Necessary | 481.40 FL   | *- FL        |
| 7   | 1   |          | *FRONT BUMPER                        | Distorted     | 681.40 FL   | *681.40 FL   |
| 8   | 1   |          | *FRONT BUMPER BEAM                   | Distorted     | 289.90 FL   | *289.90 FL   |
| 9   | 1   |          | *FRONT BUMPER REINFORCEMENT BAR      | Not Necessary | 381.40 FL   | *- FL        |
| 10  | 1   |          | *FRONT BUMPER RETAINER L+R           | O/s Cracked   | 262.40 FL   | *131.20 FL   |
| 11  | 2   |          | *FRONT BUMPER BRACKET L+R            | Not Necessary | 232.60 FL   | *- FL        |
| 12  | 1   |          | *FRONT BUMPER TOWING COVER           | Not Necessary | 41.20 FL    | *- FL        |
| 13  | 2   |          | *FRONT BUMPER FOG LAMP               | Not Necessary | 282.60 FL   | *- FL        |
| 14  | 1   |          | *FRONT BUMPER FOG LAMP GARNISH       | Scratched     | 134.20 FL   | *134.20 FL   |
| 15  | 1   |          | *FRONT HEADLAMP L+R                  | O/s Broken    | 1,562.40 FL | *781.40 FL   |
| 16  | 1   |          | *FRONT HEADLAMP PANEL RH             | Repair        | 289.40 FL   | *- FL        |
| 17  | 1   |          | *SIDE PANEL RH                       | Buckled       | 362.40 FL   | *362.40 FL   |
| 18  | 1   |          | *FRONT SUPPORT PANEL                 | Repair        | 482.40 FL   | *- FL        |
| 19  | 1   |          | *FRONT BRACE PANEL                   | Not Necessary | 161.20 FL   | *- FL        |
| 20  | 1   |          | *WIRE HARNESS                        | Not Necessary | 338.50 FL   | *- FL        |
| 21  | 1   |          | *AIR CON CONDENSER                   | Not Necessary | 1,012.40 FL | *- FL        |
| 22  | 1   |          | *RADIATOR                            | Not Necessary | 1,514.50 FL | *- FL        |
| 23  | 1   |          | *RADIATOR SPARE TANK                 | Not Necessary | 387.40 FL   | *- FL        |
| 24  | 1   |          | *TURBO COOLER                        | Not Necessary | 2,142.00 FL | *- FL        |
| 25  | 1   |          | *WASHER TANK                         | Not Necessary | 161.40 FL   | *- FL        |
| 26  | 1   |          | *WASHER TANK MOTOR                   | Not Necessary | 162.60 FL   | *- FL        |
| 27  | 1   |          | *FRONT DOOR RH                       | Dented / Bent | 1,683.40 FL | *1,683.40 FL |
| 28  | 2   |          | *FRONT DOOR HINGE UP AND DOWN        | Not Necessary | 248.30 FL   | *- FL        |
| 29  | 1   |          | *FRONT DOOR CHECKER                  | Not Necessary | 164.30 FL   | *- FL        |
| 30  | 1   |          | *FRONT DOOR WINDOW MOULDING          | Not Necessary | 124.30 FL   | *- FL        |
| 31  | 1   |          | *FRONT DOOR LOWER STEP PANEL         | Repair        | 246.50 FL   | *- FL        |
| 32  | 1   |          | *FRONT DOOR LOWER STEP PANEL GARNISH | Torn          | 123.40 FL   | *123.40 FL   |
| 33  | 1   |          | *REAR FENDER RH                      | Badly Dented  | 1,795.90 FL | *1,455.10 FL |
| 34  | 1   |          | *REAR FENDER GLASS MOULDING RH       | Not Necessary | 135.80 FL   | *- FL        |
| 35  | 1   |          | *REAR FENDER DOOR RAILING RH         | Bent          | 340.50 FL   | *340.50 FL   |
| 36  | 1   |          | *RADIATOR COOLER                     | Not Necessary | 120.00 FS   | *- FS        |
| 37  | 10  |          | *FRONT BUMPER CLIPS                  | Necessary     | 100.00 FS   | *30.00 FS    |
| 38  | 1   |          | *FRONT BUMPER LOWER SPOILER          | Cracked       | 4,000.00 FS | *800.00 FS   |
| 39  | 1   |          | *REAR FENDER SEALANT                 | Not Necessary | 120.00 FS   | *- FS        |
| 40  | 1   |          | *REAR FENDER GLASS SEALANT           | Necessary     | 120.00 FS   | *40.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>21,777.20</b> | <b>6,907.80</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 4,329.30         | 1,509.45        |

|                           |                  |                 |
|---------------------------|------------------|-----------------|
| <b>Total Parts (\$\$)</b> | <b>17,447.90</b> | <b>5,398.35</b> |
|---------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                | Lab.Type | Repairer's      | Amount          |
|--------------------------------|------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                            |          |                 |                 |
| 1                              | TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN. | New      | 3,000.00        | 1,100.00        |
| 2                              | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.               | New      | 3,000.00        | 1,000.00        |
| 3                              | TO RUST PROOF ACCIDENT AFFECTED AREA.                      | New      | 120.00          | 80.00           |
| 4                              | TO RNR FRONT DOOR MECHANISM.                               | New      | 200.00          | 60.00           |
| 5                              | TO RNR A/C CONDENSER ASSY AND REFILL GAS.                  | New      | 250.00          | 0.00            |
| 6                              | TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.                 | New      | 150.00          | 20.00           |
| 7                              | TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.        | New      | 250.00          | 0.00            |
| 8                              | TO RNR REAR FENDER DOOR RAILING AND CHECK FUNCTION.        | New      | 120.00          | 80.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                            |          | <b>7,090.00</b> | <b>2,340.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                      |
|-------------------|---------------------|--------|----------------------|
| Vehicle No:       | GBH6182C (Insd veh) | Model: | TOYOTA HIACE 3.0 (A) |
|                   | PC6671T (TP veh)    |        |                      |
| Date of Accident: | 30/11/2018          |        |                      |

|                                                                                                      |   |                                                 |     |           |                        |
|------------------------------------------------------------------------------------------------------|---|-------------------------------------------------|-----|-----------|------------------------|
| Global Sum Settlement                                                                                | : | [ X ]                                           | Yes | [ ]       | No                     |
| Repair Estimate                                                                                      | : | \$                                              |     | 26,255.55 |                        |
| Final Repair Cost                                                                                    | : | \$                                              |     | 8,500.00  |                        |
| Loss of Use                                                                                          | : | \$                                              |     |           | days at \$0.00 per day |
| Rental (if any)                                                                                      | : | \$                                              |     |           | 9 days                 |
| LTA / GIA Search Fee                                                                                 | : | \$                                              |     |           |                        |
| Others:                                                                                              | : | \$                                              |     |           |                        |
|                                                                                                      | : | \$                                              |     |           |                        |
| Final Settlement Sum (GLOBAL SUM)                                                                    | : | \$                                              |     | 8,500.00  |                        |
| Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)                     |   |                                                 |     |           |                        |
| A) For Non GIA Registered Workshop:                                                                  |   | Agreed Liability ____ 100 ____ (%)              |     |           |                        |
| B) For GIA Registered Workshop:                                                                      |   | BOLA Applicable: Yes/ No BOLA Scenario No: ____ |     |           |                        |
| BOLA Liability: ____ (%)                                                                             |   | Assessed Liability (*): ____ (%)                |     |           |                        |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. |   |                                                 |     |           |                        |
| Remarks _____                                                                                        |   |                                                 |     |           |                        |

| Payment Instruction: Payee's Breakdown |                                 |      |          |
|----------------------------------------|---------------------------------|------|----------|
| 1)                                     | RICO 60 AUTO SERVICES PTE. LTD. | : \$ | 8,500.00 |
| 2)                                     |                                 | : \$ |          |
| 3)                                     |                                 | : \$ |          |
| 4)                                     |                                 | : \$ |          |

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

25 Jun  
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))