

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

03 DEC 2018

Estimate No. : **b1 49316**
Date Estimated : **03/12/2018**
Prepared By : **Kevin Leong Wai Kit**Page No. : **1 of 5****- ESTIMATE REPAIR FOR -****Chan Chi Ping**
6 Sunrise Avenue**Singapore 806668****- ACCOUNT - 121****AIG Asia Pacific Insurance Pte. Ltd.**
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK8117G	J209695	30/08/2013	116iA/5	0

DESCRIPTIONVALUE

To replace rear right side panel, rear bumper & all attachments cause by accident.

4250 ~~5,950.00~~

Painting on rear right side panel, rear bumper & rear RH trunk floor.

2208 ~~2,454.00~~

To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.

451 ~~531.00~~

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 ~~873.00~~

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

451 ~~531.00~~

To replace tyre and wheel rim including balancing. (1x).

80 ~~94.00~~

To check electrical wiring systems at the rear section for proper function.

150 ~~177.00~~

To carry out body cavity preservation. (For cut panel).

451 ~~531.00~~

Sundries.

? ~~150.00~~Total Labour 1: **11,291.00**DESCRIPTIONQTYPRICVALUERR RH FENDER **PA****1** **1,328.35** **1,328.35**REINFORCEMENT PLATE C-PILLAR RH **?****1** **50.45** **50.45**REINFORCEMENT PLATE ROCKER PLATE RH **?****1** **50.45** **50.45**REINFORCEMENT PLATE UNIVERSAL **?****1** **28.45** **28.45**RR BUMPER RH SIDE GUIDE **?****1** **49.05** **49.05**REAR BUMPER PRIMED (LINES) **DE****1** **924.75** **924.75**REAR RH WHEEL HOUSING COVER **?****1** **131.10** **131.10**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49316
Date Estimated : 03/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK8117G	J209695	30/08/2013	116iA/5	0

DESCRIPTION	QTY	PRIC	VALUE
DECOUPLING RING PDC TORQUE CONVERTE ?	4	5.05	20.20
BLIND RIVET AVIBVLB <i>na</i>	7	0.55	3.85
SCREW (SF PLUS M5X15) <i>na</i>	3	0.55	1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	326.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	112.70
(DG) CLEANER R1 (100ML)	1	26.15	26.15
PUNCH RIVET N4	32	0.55	17.60
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 3,105.35

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 14/12/18 @ 1030 Excess S\$ _____

Surveyor's Name RPM Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	11,291.00
Parts	:	3,105.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,007.74
Grand Total	:	15,404.09

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **