

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MSLW/ CC3/MSL18021910/UTbnz

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

have 6.4 LTA19862 not 8138

Veh No:

S72 6851R

Yr Regn:

12/10

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (C/A)

Make:

Nissan Juke

o.c. 15.98

Colour:

Cng

A/C: Insured / Std / NI / NA

Sp. Reading

16684

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1FBAF152 000004

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55-217

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

4/12/18

D.O.I.

5/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

7/12 Revised GIA Report via email.  
 13/12/18 4/5 & 4300 confirmed with Alan.  
 (cred: 96161, 69%)

RECEIVED 14 DEC 2018

Date/Time, File Pass to?



: Prel. Report

14/12 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

) S + RS \$1



: Interview (\$

) Photos



: Tech. Invs (\$

) Others



: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$ 4300/-)

TOTAL

210

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 7 December 2018 9:18 AM  
**To:** 'Pang Xiu Shi'  
**Cc:** Accounts (LKKAuto); KKLau; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 4/12/2018, SJZ 6851R (TP VEHICLE), SLH 8186K (OI VEHICLE)  
**Attachments:** gia report.pdf

Dear Xiu Shi,

Please be informed that we had inspected the vehicle SJZ 6851R at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto)

**Sent:** Wednesday, 28 November 2018 3:31 PM

**To:** elaine\_ngu@sg.msig-asia.com; iryani\_amin@sg.msig-asia.com

**Cc:** KKLau <[kklau@lkkauto.com](mailto:kklau@lkkauto.com)>; Accounts (LKKAuto) <[account@lkkauto.com](mailto:account@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 27/11/2018, SLW 1253S (TP VEHICLE), SLU 130E (OI VEHICLE)

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6525F
<b>Vehicle Details</b>	
Vehicle No.:	SJZ6851R
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	JUKE 1.6 A/T ABS D/AIRBAG 2WD 5DR
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	HR16017205C
Chassis No.:	JN1FBAF15Z0000018
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$21,882.00
Original Registration Date:	18 Dec 2010
First Registration Date:	18 Dec 2010
Transfer Count:	1
Actual ARF Paid:	\$21,882.00 10941
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2020
PARF Rebate Amount:	\$13,129.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Dec 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$33,132.00
COE Rebate Amount:	\$6,733.00
<b>Total Rebate Amount:</b>	<b>\$19,862.00</b>

The information contained herein is correct as at 05 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/12/2018 11:02
Date Of Accident	04/12/2018 18:40
Exact Location Of Accident	PASIR RIS DRIVE 03 > PASIR RIS DRIVE 06
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ6851R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOCK LYE TIN STANLEY (LUO LITIAN)
NRIC No	S7826525F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81897301
Alternative Phone No	OTHERS-81897301

### Vehicle Particulars

Manufacturer	NISSAN
Model	JUKE 1.6 A/T ABS D/AIRBAG 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076639752-02
Cover Note Number	

### Driver

Name of Driver	GOH MEI CHENG(WU MEICHENG)
NRIC No	S8214471D
Date Of Birth	08/05/1982
Occupation	OUTDOOR
Date Of Driving Pass	31/05/2004
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97999512
Fax Number	
Contact Number	
Email Address	JIPSC_GG@HOTMAIL.COM

Address	BLK 405 PASIR RIS DRIVE 06 #06-483
Postcode	510405
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH8186K
Vehicle Make/Model/Colour	TOYOTA PRIUS HYBRID 1.8 CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOW YEW WANG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLR6402Y
Vehicle Make/Model/Colour	VOLKSWAGEN SHARAN 2.0 TSI 7N24MY

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name GOH MEI CHENG(WU MEICHENG)

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJZ6851R

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address BLK 405 PASIR RIS DRIVE 06 #06-483

Postcode 510405

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

04 DEC 2018

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

**IDAC KAKI BUKIT(VAC)**  
23 KAKI BUKIT AVE 4  
Singapore, 415933  
Reporting Centre Personal Signature  
Tel: 67416897  
Name:  
Fax: 67492305  
NRIC/FIN No.:  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)



# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I was driving along Pasir Ris Dr 3. I signal left & when the traffic light turned green, I stopped before the traffic junction to allow pedestrians to cross the road. Suddenly I felt an impact from the rear of my car. I alighted & realized I was involved in a 3 cars chain collision.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

04 DEC 2010

IDAC KAKI BUKIT(VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415933

Reporting Centre Person's Signature  
Name: Email: vackb@singnet.com.sg  
NRIC/FIN NO:



**FASTECH AUTO PTE LTD**  
**1 KAKI BUKIT AVENUE 6**

**#01-46/48/50**

**SINGAPORE 417883**

**VEHICLE NO: SJZ 68 SIR**

KK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To supply damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

not Arthur  
 4/5 = 4300  
 5/14/18

QTY	PARTICULAR (NETT ITEM)		
1 PCS	TAILGATE	11	\$966.00 X
1 PCS	TAILGATE INNER LOCK	11	\$188.00 X
1 PCS	TAILGATE WEATHERSTRIP	4m	\$219.00
1 PCS	REAR BUMPER	10/12	\$755.00
2 PCS	REAR BUMPER SIDE RETAINERS @ \$45.00 30 x 2 = 60	5/11	\$90.00
2 PCS	REAR BUMPER REFLECTORS @ \$85.00	11	\$170.00 X
1 SET	REAR BUMPER CLIPS 35	11	\$39.00
1 PCS	REAR BUMPER LOWER 305	12	\$611.00
1 PCS	REAR BUMPER SPONGE 185	10/11	\$311.00
1 PCS	REAR BUMPER REINFORCEMENT	11	\$250.00 X
1 PCS	REAR BUMPER 'JUKE' EMBLEM	11	\$68.00
1 PCS	REAR BUMPER EMBLEM O/S	11	\$65.00
1 PCS	REAR BUMPER TOW COVER	11	\$85.00
2 PCS	REAR BUMPER SIDE PROTECTORS @ \$215.00	0/11/11	\$430.00 PC
1 PCS	REAR END PANEL 520.30	30/100	\$899.00
1 PCS	REAR END PANEL TOP GARNISH 215	11	\$295.00
1 PCS	REAR FLOOR PANEL	11	\$981.00 X
1 PCS	REAR FLOOR PANEL TOP BOARD	11	\$650.00 X
2 PCS	TAILLAMPS @ \$850.00 320 x 2 = 640	11	\$1,700.00
1 PCS	REAR EXHAUST	11	\$629.00 X
2 PCS	REAR END PANEL AIR VENT @ \$110.00	11	\$220.00
1 PCS	REAR END PANEL SMARTS SENSOR 192	11	\$315.00
2 PCS	REAR BUMPER BRACKETS @ \$80.00	11	\$160.00 X
			\$10,096.00
	S.NETT		
1 SET	REAR BUMPER REVERSE SENSOR	11	\$280.00 200
1 PCS	REAR END PANEL SEALANT	11	\$50.00
1 PCS	REAR WINDSCREEN SEALANT	11	\$50.00 X
	LABOUR CHARGES:		
	TO CHECK WIRING		\$80.00 30
	TO DISMANTLE & REFIX REAR WINDSCREEN	11	\$150.00 X
	TO DISMANTLE & REFIX REAR EXHAUST	11	\$100.00 X
	TO SPRAY RUST PROOFING		\$100.00 50
	TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00 50
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY		\$150.00 80
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,280.00 700
	TO PUTTY & SPRAY PAINTING		\$1,500.00 1000
	<b>TOTAL</b>		<b>\$13,916.00</b>

102  
 3605-9

5401.88

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18021910/UTBN2  
Date: 18/12/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29069766MKF
Claimant Vehicle No :	SJZ6851R	Insured Vehicle No :	SLH8186K
Date of Loss:	04/12/2018	Nature of Claim:	TP
		Claim No:	578254

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJZ6851R	Engine No:	HR16017205C
Make & Model:	NISSAN JUKE, 1.6 (A)	Chassis No:	JN1FBAF15Z0000018
Reg. Date:	18/12/2010 (Man. Year: 2010)	Odometer:	166884 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,476.00	3,494.86	6,981.14	66.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	1,910.00	1,530.00	44.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,916.00</b>	<b>5,404.86</b>	<b>8,511.14</b>	<b>61.16</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,300.00</b>		
<b>(\$\$)</b>	13,916.00	4,300.00	9,616.00	69.10
<b>+ GST 7.00/7.00% (\$\$)</b>	974.12	301.00	673.12	69.10
<b>Nett Amount (\$\$)</b>	<b>14,890.12</b>	<b>4,601.00</b>	<b>10,289.12</b>	<b>69.10</b>

## INSPECTION

Date of Assignment:	08/12/2018	
Date Inspected:	05/12/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2018)
<b>Parts:</b> M1-SUV	NISSAN JUKE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJZ6851R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	966.00 F	*- FL
2	1		*TAILGATE INNER LOCK	Not Necessary	188.00 F	*- FL
3	1		*TAILGATE WEATHERSTRIP	Twisted	219.00 F	*219.00 FL
4	1		*REAR BUMPER	Dented/Deformed	755.00 F	*581.10 FL
5	2		*REAR BUMPER SIDE RETAINERS	Bent	90.00 F	*60.00 FL
6	2		*REAR BUMPER REFLECTORS	Not Necessary	170.00 F	*- FL
7	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*35.00 FL
8	1		*REAR BUMPER LOWER	Deformed	611.00 F	*305.00 FL
9	1		*REAR BUMPER SPONGE	Torn	311.00 F	*185.00 FL
10	1		*REAR BUMPER REINFORCEMENT	No such part	250.00 F	*- FL
11	1		*REAR BUMPER JUKE EMBLEM	Necessary	68.00 F	*68.00 FL
12	1		*REAR BUMPER EMBLEM O/S	Necessary	65.00 F	*65.00 FL
13	1		*REAR BUMPER TOW COVER	Twisted	85.00 F	*85.00 FL
14	1		*REAR BUMPER SIDE PROTECTORS	O/s Twisted	430.00 F	*215.00 FL
15	1		*REAR END PANEL	Badly Dented	899.00 F	*520.30 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	295.00 F	*215.00 FL
17	1		*REAR FLOOR PANEL	Repair	981.00 F	*- FL
18	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	650.00 F	*- FL
19	2		*TAILLAMPS	Cracked	1,700.00 F	*640.00 FL
20	1		*REAR EXHAUST	Not Necessary	629.00 F	*- FL
21	2		*REAR END PANEL AIR VENT	Torn	220.00 F	*220.00 FL
22	1		*REAR END PANEL SMARTS SENSOR	Cracked	315.00 F	*192.00 FL
23	2		*REAR BUMPER BRACKETS	Serviceable	160.00 F	*- FL
24	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
25	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,476.00</b>	<b>3,855.40</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>360.54</b>
<b>Total Parts (\$\$)</b>	<b>10,476.00</b>	<b>3,494.86</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	-
3	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	-
4	TO SPRAY RUST PROOFING	New	100.00	50.00
5	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
6	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,280.00	700.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			3,440.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >