Surveyor Rasu | REF: ABMUAXA) | 75320

ASSIGNMENT

From: | Date: 10/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 8480K

at Workshop m/s Kah Motor

of 255 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Jack

(Policy Condition) 2pm owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 114K

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DG'

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SLH 8480K | Yr Regn: 2016 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Odyssey 2.4EX | c.c 2356

Colour Brown | A/C: Insured / Std / NI / NA

Sp.Reading 017053 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRC18904C206977

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	01/12/18	D.O.I.	10/12/18

Survey held at Kah Motor

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)