

(INSUR)

INS. CASE OWNER:

CC 4 /AIG1802

LKK:

IDAC:

Surveyor:

MARINAS

DOE:

ASSIGNMENT

12/12/18

Date / Time:

5/12/18

Registered in Merimen:

5/12/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SVD 1409J

Name of Insured:

THAM SHAN WONG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

24/12/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ANILAKSHI 30yrs

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

48986705459

Policy No.:

100469079-02

Make / Model:

Toyota

Place of Accident:

489 INSON ON TRKS 5th floor KTC

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FDR 27/12/18

INSRS:
WSP:
Tel:
Liability:
RMKS:AS
phovanINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

11/12/18
WATER

29/12/18

PARKING - X

SVD 1409J

File pass to shu pei to submit WP

STAGE

DATE / PIC

Non-Reporting hr (1st)

Non-Reporting hr (2nd)

Non-Reporting hr (Final)

Notification hr (if non-pickup)

Call OI

After call hr to OI

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA :

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

LIS

SS 3,096.97

(4 days) Reduction:

46 %

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass, Lia :

Repair Cost:

SS

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(\$ x days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
20/1/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

WP
\$ 250

ASSIGNMENT

From:
 Date: 13.12.2018
 Estimated Cost:
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: FBK 2125D
 at Workshop m/s: A.B. Phoon
 of: Blk 3007 Ubi Rd 1 #01-436
 Insured: 52111909J
 Policy No:
 Claims No:
 Sum Insured:
 Excess:
 (Client's Record)
 Make of Veh: Mr. Kue

(Policy Condition) 1030um
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 7500
 IDAC Accident Rpt: Consistent? : Yes or No
 C/A / PR Seen: Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 2694C
 Date: Person Contacted: Vehicle: IN / OUT

Veh No: FBK 2125D Yr Regn: S-15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: P. 9.0 IME C.C. 148
 Colour: Red A/C Insured / Std / NI / NA
 Sp Reading: 23175 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: PFVAF 365CF100 0157
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 120/70-12 R: 4.80 - 12
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Puro
 Front: 6 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 24.11.18 D.O.I: 13/12/18
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rear & O/S Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 3710
 6 yrs 6 mth.

C4S \$ 3096.97 / Red \$ 2,664.34 / 46%

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + R\$ \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18021925/eb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 05-12-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 1909J	Veh. Inspected	FBK 2125D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/12/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/11/2018	Inspection Date	
Survey held at	A.S. PHOON PTE LTD BLK 36 TOH GUAN ROAD EAST #01-35 SINGAPORE 608580		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



潘發展私人有限公司

A. S. PHOON PTE LTD

cas no one else

ATTN: KGE

Head Off : 399, Changi Road S'pore 419846 Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701 Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBK2125D PGO IME150 3 WHEELER REPAIR ESTIMATE 07/12/2018

ITEM	DESCRIPTION	AMOUNT SGD
1	REAR WHEEL ASSY	See \$320.00 X
2	REAR WHEEL AXLE & BUSHING	See \$448.00 X
3	REAR FENDER RH	See \$255.00 ✓
4	STAY REAR FENDER	See \$45.00 ✓
5	FRONT FENDER	See \$165.00 ✓
6	FRONT FORK LH	See \$492.08 ✓
7	FRONT FORK RH	See \$492.08 ✓
8	STEM STEERING	See \$245.00 ✓
9	CONE BEARING SET	See \$95.00 ✓
10	FRONT WHEEL	See \$280.00 X
11	FRONT WHEEL AXLE	See \$55.00 ✓
12	FRONT LOWER FAIRING RH	See \$95.00 ✓
13	BACK SHIELD	See \$209.00 ✓
14	LOWER SIDE PANEL RH	See \$85.00 ✓
15	HANDLEBAR	See \$294.00 ✓
16	WINDSHIELD	See \$300.00 X
17	BRAKE LEVER	See \$25.00 ✓
18	BALANCER	See \$26.15 ✓
19	HANDLE GRIP	See \$50.00 ✓
20	SIDE MIRROR	See \$35.00 ✓
21	TRANSPORTATION TP/ IDAC/ W-SHOP @\$100	\$200.00 100
22	WORKMANSHIP (REMOVE ,REPLACE & REPAIR DAMAGED AREAR)	\$350.00 300
23	TRANSPORTATION 2-WAY TO REPAIR CHASSIS @\$100	See \$200.00 X
24	BODY CHASSIS REPAIR	See \$450.00 X
25	SPRAY PAINTING (F-FENDER /REAR RENDER & CHASSIS)	\$300.00 ✓
26	REAR TOP BOX	See \$250.00 X
TOTAL		\$5,761.31

Auto Consultants hence notify
Reparior of the following:
• To remove before spray painting
• To ensure damaged part(s) being removed
• To ensure proper use of paint to avoid rust
• To ensure proper use of "Internal Protection" paint
• To ensure proper use of "Internal Protection" paint
• To ensure proper use of "Internal Protection" paint
• To ensure proper use of "Internal Protection" paint

Approved by Repaired:

Signature

Date

Not Approved
H/S
H/S
Stephens
13/12/18
P/P & 3096.97
P-2663.31
107
2396.97



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBK2125D PGO IME150 3 WHEELER REPAIR ESTIMATE 07/12/2018

ITEM	DESCRIPTION	AMOUNT SGD
1	REAR WHEEL ASSY	Scr \$320.00 X
2	REAR WHEEL AXLE & BUSHING	\$448.00 ?
3	REAR FENDER RH	Scr \$255.00 ✓
4	STAY REAR FENDER	Scr \$45.00 ✓
5	FRONT FENDER	Scr \$165.00 ✓
6	FRONT FORK LH	\$492.08 ?
7	FRONT FORK RH	\$492.08 ?
8	STEM STEERING	\$245.00 ?
9	CONE BEARING SET	\$95.00 ?
10	FRONT WHEEL	11 \$280.00 X
11	FRONT WHEEL AXLE	Scr \$55.00 ✓
12	FRONT LOWER FAIRING RH	Scr \$95.00 ✓
13	BACK SHIELD	\$209.00 ?
14	LOWER SIDE PANEL RH	Scr \$85.00 ✓
15	HANDLEBAR	\$294.00 ?
16	WINDSHIELD	102 Scr \$300.00 X
17	BRAKE LEVER	Scr \$25.00 ✓
18	BALANCER	Scr \$26.15 ✓
19	HANDLE GRIP	Scr \$50.00 ✓
20	SIDE MIRROR	Scr \$35.00 ✓
21	TRANSPORTATION TP/ IDAC/ W-SHOP @\$100	\$200.00 100
22	WORKMANSHIP (REMOVE ,REPLACE & REPAIR DAMAGED AREA)	\$350.00 300
23	TRANSPORTATION 2-WAY TO REPAIR CHASSIS @\$100	\$200.00 ?
24	BODY CHASSIS REPAIR	\$450.00 ?
25	SPRAY PAINTING (F-FENDER /REAR RENDER & CHASSIS)	\$300.00 ?
26	REAR TOP BOX	Scr \$250.00 X
TOTAL		\$5,761.31

Auto Consultants hence notify
the Repairer of the following:
• To survey before/after spray painting
• To replace damaged parts along the way
• To replace parts subject to confirmation
• To add parts survey is on a "Without Prejudice" basis
• To accept modifications to a claim
• Supplementary Worked items not included and
to design to meet approval from Insurance Company

Approved by Repairer

Date: _____

Not Accepted
L/s S
Hdn
Theophanes, 13/12/18

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2694C

Vehicle Details

Vehicle No.: FBK2125D

Vehicle to be Exported: No

Intended Deregistration Date: 13 Dec 2018

Vehicle Make: P.G.O.

Vehicle Model: I ME 150 WEL BIKE 3-WHEELER

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: C5H15979

Chassis No.: RFVBF3C5CF1000157

Maximum Power Output: -

Open Market Value: \$3,311.00

Original Registration Date: 07 May 2015

First Registration Date: 07 May 2015

Transfer Count: 1

Actual ARF Paid: \$497.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 06 May 2025

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$5,800.00

COE Rebate Amount: \$3,710.00

Total Rebate Amount: \$3,710.00

The information contained herein is correct as at 13 Dec 2018

OK

- Pre repair inspection request - FBK2125D VS SLD1909J (OI) DOA ON 24/11/2018

From: Aslan, Syazairina
To: admin-a@ikauto.com, assignments@ikauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Manessa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithooasingh, Aashweenjeetkaur, Hor, Yinnul, Chan, Yoke Shi
Sent: Wednesday, 5 December, 2018 10:26:42 AM
Attachments:  kmp83324f

Hi,

Please refer to the enclosed request from TAN CHIN HOE & CO.

Claim no : 4898863054SG003
Case Owner : BERNARD JT QIAS LER

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Syazairina Aslan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

-----Original Message-----

From: sheena@tanchinhoe.com.sg [mailto:sheena@tanchinhoe.com.sg]
Sent: Wednesday, December 05, 2018 12:00 AM
To: Chan, Yoke Shi
Cc: 'Lee Kee'
Subject: RE: [Fwd] - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLD1909J AND FBK2125D ON 24/11/2018] Our Ref: RT/460/2018/sh

Dear Yoke Shi

1. Our client's workshop agrees to Mr Marcus Chia from LEE Auto Consultants Pte Ltd to carry out the survey but reserve their position as whether to agree to Mr Marcus Chia being the SCE at the appropriate time.

Sheena Ng, Paralegal
TAN CHIN HOE & CO
24 Raffles Place
#24-01 Clifford Centre
Singapore 048621
Tel: 65382687
Fax: 65380287
Email: sheena@tanchinhoe.com.sg

This email is subject to legal privilege. If you are not the intended recipient, please delete this email and all its attachments from your computer immediately.

INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLD1909J AND FBK2125D ON 24/11/2018]

----- Original Message -----

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLD1909J AND FBK2125D ON 24/11/2018
From: "Chan, Yoke Shi" <yokeshi.chan@aig.com>
Date: Tue, December 4, 2018 11:13 am
To: "Tan Chin Hoe & Co" <info@tanchinhoe.com.sg>
Cc: "Fong, Andy-SY" <Andy-SY.Fong@aig.com>
"Chin, Lee-Ying" <Lee-Ying.Chin@aig.com>
"Abu Kassim, Noor Manessa" <NoorManessa.AbuKassim@aig.com>
"Md Ishak, Mohd Imran" <Imran.Ishak@aig.com>
"Lim, Sheng Yang" <ShengYang.Lim@aig.com>
"Mithooasingh, Aashweenjeetkaur" <Aashweenjeetkaur.Mithooasingh@aig.com>
"Aslan, Syazairina" <Syazairina.Aslan@aig.com>
"Hor, Yinnul" <Yinnul.Hor@aig.com>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息，如需阅读此信息，请开启附件。 [Click here https://securemail2.aig.com/formpostdir/securereader?i=dww_0M3y4WvIAE3Dkx1J7l8fhnJmRaj1abrandee851c96a](https://securemail2.aig.com/formpostdir/securereader?i=dww_0M3y4WvIAE3Dkx1J7l8fhnJmRaj1abrandee851c96a)
by 2018-12-11 11:13 +08 to read your message. After that, open the attachment.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is assumed by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: yokeshi.chan@aig.com
To: info@tanchinhoe.com.sg
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorManessa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithooasingh@aig.com, Syazairina.Aslan@aig.com, Yinnul.Hor@aig.com
Subject: agencrypt - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLD1909J AND FBK2125D ON 24/11/2018
Date: Tue, 4 Dec 2018 03:13:31 +0000
Without Prejudice

Your Reference : RT/460/2018/sh
Our Reference : 4898863054SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services

05/12/2018 @ 11:58am
Mr. Kee veh in
estimate not yet done, will call to arrange after done
check liability

Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HaaXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOI, Claims Operations – Auto

yokeshi.chan@aig.com <http://www.aig.com>

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2018 Edit Reg		05 Dec 2018 00:00 Edit Adj Rpt	S\$3,096.98 Edit Estimates	S\$3,096.98 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: THAM SHUEN LOONG , ID: S7606880A									
Main Claimant: CHIA YAM MENG , ID: S0492694C									
Vehicle Reg. No.: FBK2125D		Date of Loss: 24/11/2018 10:00 - :59 [42 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4898863054SG		Policy/Cover Note No.: 2100469679 (Comprehensive)							
Vehicle Reg. No. (Insured): SLD1909J		Policy No. (Claimant): 5071523571-03							
		Excess:							
Repairer: A.S. Phoon Pte Ltd (Ubi) Bk 3007 Ubi Road 1, #01-436, Ubi - Tel: 6744 0771									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/12/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBK2125D (4898863054SG)**
[SLD1909J]

TP
CHIA YAM MENG
Nov 24 2018 10:00AM
[THAM SHUEN LOONG]
A.S. Phoon Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/18 16:42	EMAIL FROM AIG DD 05122018		Load PDF	
2	05/12/18 16:42	NOTICE & GIA REPORT		Load PDF	
3	14/12/18 12:28	TP ESTIMATE- MARKED		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	06/12/18 10:04	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021925/UKB3Q2

Date: 08/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100469679
 Claimant Vehicle No: FBK2125D Insured Vehicle No: SLD1909J
 Date of Loss: 24/11/2018 Nature of Claim: TP Claim No: 4898863054SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBK2125D
 Make & Model: PGO I ME, 148cc S WEL Engine No: C5H15979
 Reg. Date: 07/05/2015 (Man. Year: 2015) Chassis No: RFVBF3C5CF1000157
 Colour: Red Odometer: 23175 km
 Engine Capacity: 148 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70-12 Rear Tyre Size: 4.80-12
 Front Left Side: Duro 6 mm Rear Left Side: Duro 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,261.31	2,396.98	1,864.33	43.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	700.00	800.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,761.31	3,096.98	2,664.33	46.25
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 05/12/2018
 Date Inspected: 13/12/2018 Inspected At: A.S. Phoon Pte Ltd (Ubi)
 Blk 3007 Ubi Road 1, #01-436
 Singapore
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL ASSY	Serviceable	320.00 F	*- FL
2	1		*REAR WHEEL AXLE & BUSHING	Serviceable	448.00 F	*- FL
3	1		*REAR FENDER RH	Bent	255.00 F	*255.00 FL
4	1		*STAY REAR FENDER	Bent	45.00 F	*45.00 FL
5	1		*FRONT FENDER	Cut	165.00 F	*165.00 FL
6	1		*FRONT FORK LH	Bent / Twisted	492.08 F	*492.08 FL
7	1		*FRONT FORK RH	Bent / Twisted	492.08 F	*492.08 FL
8	1		*STEM STEERING	Bent	245.00 F	*245.00 FL
9	1		*SET CONE BEARING	Necessary	95.00 F	*95.00 FL
10	1		*FRONT WHEEL	Not Necessary	280.00 F	*- FL
11	1		*FRONT WHEEL AXLE	Scratched	55.00 F	*55.00 FL
12	1		*FRONT LOWER FAIRING RH	Cut	95.00 F	*95.00 FL
13	1		*BACK SHIELD	Cut	209.00 F	*209.00 FL
14	1		*LOWER SIDE PANEL RH	Cut	85.00 F	*85.00 FL
15	1		*HANDLEBAR	Bent	294.00 F	*294.00 FL
16	1		*WINDSHIELD	Serviceable	300.00 F	*- FL
17	1		*BRAKE LEVER	Bent	25.00 F	*25.00 FL
18	1		*BALANCER	Scratched	26.15 F	*26.15 FL
19	1		*HANDLE GRIP	Cut	50.00 F	*50.00 FL
20	1		*SIDE MIRROR	Cut	35.00 F	*35.00 FL
21	1		*REAR TOP BOX	Serviceable	250.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,261.31	2,663.31
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	266.33
Total Parts (\$\$)	4,261.31	2,396.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORTATION TP/IDAC /W-SHOP	New	200.00	100.00
2	WORKMANSHIP (REMOE,REPLACE & REPAIR DAMAGED AREAR)	New	350.00	300.00
3	TRANSPORTATION 2-WAY TO REPAIR CHASSIS	New	200.00	0.00
4	BODY CHASSIS REPAIR	New	450.00	0.00
5	SPRAY PAINTING (F-FENDER/REAR FENDER & CHASSIS)	New	300.00	300.00
Gross Labour Cost (\$\$)			1,500.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >