

REF: CS5 / 0718021931 / J dssz

Surveyor:

Melinda

ASSIGNMENT (Office)

From (Person): Edine Cheong of CL Date/Time: 05/22/2018 3:17pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR U817X Insured: SKJ 6545J

at Workshop m/s Twncar Automotiv Tel: 68420051

of 2 Kaki Bukit Ave 2 # 01-17

Policy No: DMPCSN3045981801 Claim No: SNM18D0557102

Sum Insured: Excess:

Make of Veh: D.O.A. 28/12/2018

(Client's Record) 06.12.2018 @ morning

CA / REV / REP. / REV 24 HRS wpi

Date/Time: 05/22/2018 4pm Person Contacted: Hui Xin Vehicle: IN / LOFT

Date/Time	Action/Instruction (X) Estimate
	SJR U817X - NA / AT(18021465) / 24 DIA: 28/12/2018
	SKJ 6545J - X
	Dismantle: 7/12/2018.

PRS
Surat Hwee Jie
Mufimen

REF: CTL

ASSIGNMENT

From: _____ Date: 06/22/18
 Estimated Cost: _____
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJR 4817X
 at Workshop m/s: TwnCar
 of: 2 Kaki Bukit Ave 2 #01-17
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition) *Morning*
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S

Veh No: SJR 4817 X Yr Regn: 25 Jun 2009
 Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda City C.C. 1497
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 127547 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRH6M26509P020300
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / STD A/Rim or _____
 Tyre Size: F: 185/60 R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 28/11/18 D.O.I. 6/12/18
 Survey held at N-51
 Des. of Damages: Fr / Rear O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$3,000-\$4,000 2 days <i>[Signature]</i> 11/12/2018

Date/Time, File Pass to? Preli. Report Days Of Repair: 4
 Final Report Resurvey No. of Trip: 1
 Date/Time, File Return to? 2)
 Report Format: PRS
 Lump Sum / I.B.I. (\$) _____
 Add Fee: Site Insp (\$) S+RS \$
 Interview (\$) Photos
 Tech. Invs (\$) Others
 Weekend (\$)
 TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2018		05 Dec 2018 15:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				View All					
Insured: TAN KIM HUA , ID: S70283983				Compose Case Mail					
Main Claimant: LI HAI									
Vehicle Reg. No.:	SJR4817X	Date of Loss:	28/11/2018 12:00 - :59						
Claim Type:	TP / SNM18D05571C02	Policy/Cover Note No.:	DMPCSN3045981801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKJ6545Y	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17, 417921 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/12/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED				View All					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2018 14:58
Date Of Accident	28/11/2018 12:20
Exact Location Of Accident	42 BOON TECK RD TWDS JLN RAMA RAMA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR4817X
Insured/Policyholder	
Name Of Registered Owner	LI HAI
NRIC No	S9171608I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96455350
Alternative Phone No	OFFICE-96455350

Vehicle Particulars

Manufacturer	HONDA
Model	CITY 1.5L I-VTEC AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800003940
Cover Note Number	

Driver

Name of Driver	LI HAI
NRIC No	S9171608I
Date Of Birth	06/01/1991
Occupation	INDOOR
Date Of Driving Pass	03/12/2011
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96455350
Fax Number	
Contact Number	OFFICE-96455350
Email Address	NOEMAIL

Address	30 AH HOOD ROAD #05-02
Postcode	329976
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ6545Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was TRAVELLING ALONG BOUN TECK ROAD TOWARDS SUN SAM RONG DIRECTION. IT IS A DOUBLE LANE, DOUBLE CARRIAGE WAY.

WHILE DRIVING FORWARD, AS APPROXIMATING 42 BOUN TECK ROAD I SAW A VEHICLE STOPPED IN THE OPPOSITE DIRECTION. AS IT WAS STATIONARY I PROCEEDED ON TO PROCEED AHEAD. WHEN SUDDENLY THE VEHICLE START REVERSING, I IMMEDIATELY STOPPED MY VEHICLE. UNFORTUNATELY AS THE VEHICLE (SK3 6545 Y) MAKING A U-TURN INTO 42 BOUN TECK ROAD THE LEFT FRONT PORTION OF THE VEHICLE HIT INTO THE FRONT RIGHT PORTION OF MY VEHICLE, EVEN THOUGH I HURDLED TO WAEN THE DRIVE.

ALIGHTED FROM MY VEHICLE AND REALIZED IT WAS A VEHICLE WITH CAROLATA (SK3 6545 Y) THAT COLLIDED TO THE FRONT RIGHT PORTION OF MY VEHICLE WHEN I WAS IN A STATIONARY POSITION.

VEHICLE A - STR 4517 X
 VEHICLE B - SK3 6545 Y.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Person's Signature
 Name:
 NRIC/PIN No:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1608I
Vehicle Details	
Vehicle No.:	SJR4817X
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5L I-VTEC AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	L15A71801570
Chassis No.:	MRHGM26509P020300
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,873.00
Original Registration Date:	25 Jun 2009
First Registration Date:	25 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$18,873.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2019
PARF Rebate Amount:	\$9,436.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$709.00
Total Rebate Amount:	\$10,145.00

The information contained herein is correct as at 06 Dec 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2018		05 Dec 2018 15:17 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN KIM HUA, ID: S7028398J		
Main Claimant:	LI HAI		
Vehicle Reg. No.:	SJR4817X	Date of Loss:	28/11/2018 12:00 - :59 [113 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05571C02	Policy/Cover Note No.:	DMPCSN3045981801 (Comprehensive)
Vehicle Reg. No. (Insured):	SKJ6545Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17, 417921 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 14/12/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SJR4817X (SNM18D05571C02)**
[SKJ6545Y]
TP
LI HAI
Nov 28 2018 12:00PM
[TAN KIM HUA]
Twincar Automotive Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

[View](#) |
 [View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/11/18 15:47	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/11/18 14:12	Third Party - SJR 4817X [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	28/11/18 15:46	Third Party - SJR 4817X [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	28/11/18 15:46	Third Party - SJR 4817X Driver's Nric [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	28/11/18 15:47	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	28/11/18 15:47	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	28/11/18 15:47	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	28/11/18 15:47	CHASSIS NUMBER [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
2	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
3	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
4	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
5	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
6	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
7	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
8	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
9	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
10	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
11	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
12	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
13	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
14	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
15	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
16	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
17	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
18	06/12/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
19	12/12/18 12:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
20	12/12/18 12:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
21	12/12/18 12:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
22	12/12/18 12:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
23	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	12/12/18 12:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	12/12/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	12/12/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	12/12/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	12/12/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	12/12/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	12/12/18 14:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
71	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
72	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
73	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
74	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
75	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
76	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
77	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
78	12/12/18 14:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/11/18 14:42	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	28/11/18 14:43	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	Load TIF	
3	28/11/18 14:43	DRIVER'S NRIC + DRIVING LICENCE [Linked Accident Report Documents]	Load TIF	

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/12/18 15:16	PRS	Load PDF	
2	05/12/18 15:16	OI GIA	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/11/18 15:47	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/11/18 14:12	Third Party - SJR 4817X	Load JPG	<input checked="" type="checkbox"/>
2	28/11/18 15:46	Third Party - SJR 4817X	Load JPG	<input checked="" type="checkbox"/>
3	28/11/18 15:46	Third Party - SJR 4817X Driver's Nric	Load JPG	<input checked="" type="checkbox"/>
4	28/11/18 15:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	28/11/18 15:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	28/11/18 15:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	28/11/18 15:47	CHASSIS NUMBER	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	28/11/18 14:42	Sketch Plan	Load TIF	
2	28/11/18 14:43	CERTIFICATE OF INSURANCE	Load TIF	
3	28/11/18 14:43	DRIVER'S NRIC + DRIVING LICENCE	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18021931/JCBS2

Date: 18/12/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3045981801

Claimant Vehicle No: SJR4817X Insured Vehicle No: SKJ6545Y

Date of Loss: 28/11/2018 Nature of Claim: TP Claim No: SNM18D05571C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR4817X**

Make & Model: HONDA CITY, 1.5 (A) Engine No: L15A71801570

Reg. Date: 25/06/2009 (Man. Year: 2008) Chassis No: MRHGM26509P020300

Colour: Black Odometer: 127547 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/12/2018

Date Inspected: 06/12/2018 Inspected At: Twincar Automotive Pte Ltd (HQ)
2 KAKI BUKIT AVEUNE 2 #01-17
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Dec 2018)

Parts: 143 HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR4817X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >