

22/03/2002

ASS. REC. BY:

REF: CS / ICS / 8071933 / Kthoz

Special Instruction:

SURVIVAL:

ASSIGNMENT (Office)From (Person): Meimien Desmond Lee of ICS Date/Time: 27/12/2018 4.16pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGD 9800U Insured: SLR 3786Jat Workshop m/s Motor Image Tel: \_\_\_\_\_of 19 Loring 8 Tax PyschPolicy No: MPC18A00209601 Claim No: DMPCL8000430H / DL

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19.11.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

10.12.2018 @ after 1030am

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 05.12.2018 3.43pm Person Contacted: Daniel Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SGD 9800U - X</u>
	<u>SLR 3786J - X</u>
	<u>Part by Par + \$1824.24, 2 days.</u>
	<u>(Red: 3026.56, 62%)</u>

REF: JCS

## ASSIGNMENT

From:

Date: 10/12/2018

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGD 98004

at Workshop m/s

Motor Image

of

19 lorong 8 toa payoh

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

After 10:30am

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2-3 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>up</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SGD 98004 Yr Regn: 12 15

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru XV <sup>(A)</sup>

C.C.

1600

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading:

40318

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JF1GP3KC SPGL 58488

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

19/11/18

D.O.I.

10/12/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/12 File pass to Catherine

RECEIVED 2018

Date/Time, File Pass to?

11/12 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / ☒ P.I. (\$

TP

1824.24

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

240

10

260

## Nivitha (LKK Auto)

---

**From:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Sent:** Friday, 30 November 2018 8:51 AM  
**To:** assignments  
**Subject:** FW: SGD9800U - 3RD PARTY CLAIM - ( TP ) - // Our ref no: DMPC1800430H/DL // SLR3786J - ECICS INSURED ) - LIABILITY STATUS  
**Attachments:** SGD9800U ESTIMATE.PDF; SGD9800U GIA REPORT.PDF  
**Importance:** High

*call back on mondy.*

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Daniel Jude <danieljude@motorimage.net>  
**Sent:** Friday, 30 November 2018 8:49 AM  
**To:** motorsurvey <motorsurvey@ecics.com.sg>; ECICS Claims <claims@ecics.com.sg>; SUR <sur@lkkauto.com>  
**Cc:** TPY Insurance Team <tpyinsteam@tanchong.org>; Mohamed Isman <isman@motorimage.net>  
**Subject:** RE: SGD9800U - 3RD PARTY CLAIM - ( TP ) - // Our ref no: DMPC1800430H/DL // SLR3786J - ECICS INSURED ) - LIABILITY STATUS  
**Importance:** High

Hi Claims Team,

Kindly revert on liability status.

Has your insured reported yet?

Thank You.

Best Regards

*Daniel A Jude*

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: [danieljude@motorimage.net](mailto:danieljude@motorimage.net)

Website: [www.tanchong.com](http://www.tanchong.com) : [www.motorimage.net](http://www.motorimage.net)



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

---

**From:** motorsurvey [<mailto:motorsurvey@ecics.com.sg>]

**Sent:** Tuesday, November 27, 2018 4:16 PM

**To:** Daniel Jude <[danieljude@motorimage.net](mailto:danieljude@motorimage.net)>; motorsurvey <[motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg)>; ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Cc:** TPY Insurance Team <[tpyinsteam@tanchong.org](mailto:tpyinsteam@tanchong.org)>; Mohamed Isman <[isman@motorimage.net](mailto:isman@motorimage.net)>

**Subject:** RE: SGD9800U - 3RD PARTY CLAIM - ( TP ) - // Our ref no: DMPC1800430H/DL // SLR3786J - ECICS INSURED ) - LIABILITY STATUS

Dear LKK

Please assist with PRS.

Do contact Daniel for details of inspection.

Best regards,  
Desmond Lee  
Claims Division  
DID: +65 6303 0167  
FAX: +65 6338 9267

ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Center  
Singapore 408600

---

**From:** Daniel Jude [<mailto:danieljude@motorimage.net>]

**Sent:** Tuesday, 27 November, 2018 4:13 PM

**To:** motorsurvey; ECICS Claims; Survey

**Cc:** TPY Insurance Team; Mohamed Isman

**Subject:** RE: SGD9800U - 3RD PARTY CLAIM - ( TP ) - // Our ref no: DMPC1800430H/DL // SLR3786J - ECICS INSURED ) - LIABILITY STATUS

Hi Claims Team,

We choose the following:

1. LKK

Kindly revert to us on the liability status.

Thank You.

Best Regards

*Daniel A Jude*

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: [danieljude@motorimage.net](mailto:danieljude@motorimage.net)

Website: [www.tanchong.com](http://www.tanchong.com) : [www.motorimage.net](http://www.motorimage.net)



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

---

**From:** motorsurvey [<mailto:motorsurvey@ecics.com.sg>]

**Sent:** Tuesday, November 27, 2018 4:10 PM

**To:** Daniel Jude <[danieljude@motorimage.net](mailto:danieljude@motorimage.net)>; ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>; Survey <[survey@jpknights.com](mailto:survey@jpknights.com)>

**Cc:** TPY Insurance Team <[tpyinteam@tanchong.org](mailto:tpyinteam@tanchong.org)>; Mohamed Isman <[isman@motorimage.net](mailto:isman@motorimage.net)>

**Subject:** RE: SGD9800U - 3RD PARTY CLAIM - ( TP ) - // Our ref no: DMPC1800430H/DL // SLR3786J - ECICS INSURED ) - LIABILITY STATUS

Without Prejudice

Dear Daniel

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards,  
Desmond Lee  
Claims Division  
DID: +65 6303 0167  
FAX: +65 6338 9267

ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Center  
Singapore 408600

---

**From:** Daniel Jude [<mailto:danieljude@motorimage.net>]  
**Sent:** Tuesday, 27 November, 2018 3:25 PM  
**To:** ECICS Claims  
**Cc:** TPY Insurance Team; Mohamed Isman  
**Subject:** SGD9800U - 3RD PARTY CLAIM - ( TP ) - ( SLR3786J ) - ( ECICS INSURED ) - LIABILITY STATUS  
**Importance:** High

Hi Claims Team,


Kindly advise liability status of the above mentioned

Attached is the GIA report and Estimate

Thank You.


Best Regards  
*Daniel A Jude*  
Service Executive  
Motor Image Enterprises Pte Ltd  
19 Lorong 8 Toa Payoh Singapore 319255  
HP: 8611 3195  
Email: [danieljude@motorimage.net](mailto:danieljude@motorimage.net)  
Website: [www.tanchong.com](http://www.tanchong.com) : [www.motorimage.net](http://www.motorimage.net)

**LESS SLIP.  
MORE GRIP.**  
SYMMETRICAL AWD



**SUBARU**  
TECHNOLOGY

**LEARN MORE**



**SUBARU**



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/11/2018 17:20
Date Of Accident	19/11/2018 18:30
Exact Location Of Accident	KPE TOWARDS TPE AFT PIE EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGD9800U
Insured/Policyholder	
Name Of Registered Owner	EE ZHENG, BRENDAN ( YI ZHENG, BRENDAN )
NRIC No	S8126276D
Email Address	BRENDAN.EE@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-94366656
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	SUBARU
Model	XV-1.6 I-S AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL / LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100443951-02
Cover Note Number	
Driver	
Name of Driver	EE ZHENG, BRENDAN ( YI ZHENG, BRENDAN )
NRIC No	S8126276D
Date Of Birth	23/08/1981
Occupation	INDOOR
Date Of Driving Pass	28/09/2001
Driving Experience	17 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94366656
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	BRENDAN.EE@OUTLOOK.COM



Address	APT BLK 615 BEDOK RESERVOIR ROAD #09-1242
Postcode	470615
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO THE ATTACHED DOCUMENTS

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR3786J
Vehicle Make/Model/Colour	OPEL ASTRA
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	TUEA BOON PIN
NRIC/Passport Number	S9025714E
Contact Number	91295404
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

at about 6.30pm

I Was driving along KPE towards HPE, somewhere after PPE exit, it was peak period and traffic was slow. Suddenly a car knock into me from behind.

I was on right most lane when the car knock into me. I was at a complete stop for at least 10 seconds as the car in front of me has brake already.

SGD 9800U = VEH A

SLR 3786J = VEH B

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 20 Nov 18  
11.54hrs  
SIAMC Sketch Plan Form, V3

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 20 Nov 18  
11.54hrs

Reporting Centre Personnel's Signature  
Name: DANIEL A JUDE  
NRIC/FIN No.: S9001518D

## Accident Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:


20 Nov 18  
1154 Hrs

GIA/ACC SketchPlanForm\_V3

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

20 Nov 18  
1154 Hrs



  
Reporting Centre Personnel's Signature  
Name: DANIEL A JUDE  
NRIC/FIN No.: S9001518D

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/1047/2018  
DATE : 23-NOV-2018

ECICS LIMITED  
10 EUNOS ROAD 8  
#09-04A SINGAPORE POST CENTER  
S(408600)  
TEL : 6337 4779  
FAX : 6338 9267

OWNER'S NAME : EE ZHENG, BRENDAN (YI ZHENG, BRENDAN) \*\*  
ADDRESS : BLK 618B PUNGGOL DRIVE #16-713  
S(822618)  
TELEPHONE NO : 94366656

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100443951-02  
VEHICLE NO : SGD9800U  
MODEL CODE : GP3DKDC  
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT  
ENGINE NO : FB16Y056087  
CHASSIS NO : JF1GP3KC5FG158498  
MILEAGE : 1 KM  
DATE IN : 23/11/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : DANIEL A JUDE\*\*  
ACCIDENT DATE : 19/11/2018

Print Date : 23/11/2018  
Print Time : 13:43:30

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGD9800U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SLR3786J - ECICS INSURED		
2	ZZ/001	TO CONDUCT TP CLAIM ECICS LOCATION:KPE TOWARDS TPE DATE:19/11/2018 TIME:1830HRS		
3	ZZ/002	REPAIR/REPLACE RR BUMPER AND PANEL	1680.00	5201
4	ZZ/003	RESPRAY RR BUMPER AND PANEL	1260.00	4201
5	ZZ/004	FAULT DIAGNOSTIC AND RESET SYSTEM	280.00	7 nm
6	ZZ/005	TO CONDUCT LIGHTING TEST ON REAR	50.00	301
7	ZZ/006	TO SUPPLY AND INSTALL REVERSE SENSOR - 2EYES	300.00	X
8	ZZ/007	SUNDRIES	100.00	201
TOTAL LABOUR CHARGES			3670.00	

MOTORIMAGE ENTERPRISES PTE. LTD.  
 19 LORONG 8, TOA PAYOH  
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGD9800U

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
1	BUMPER FACE R XUV	57704FJ041	CM 594.00	✓	
2	BRKT RRH BUMP CORN	57707FJ080	28.80	7 R	
3	BRKT RLH BUMP CORN	57707FJ090	28.80	7 R	
4	BRKT RRH BUMP	57707FJ160	Sn 14.40	X Sn	
5	BRKT RLH BUMP	57707FJ170	Dis 14.40	✓	
6	BRKT BUMP R LWR	57707FJ201	28.80	7 R	
7	BEAM COMPL R EU	57711FJ0239P	187.20	7 R	
8	COVER-REAR BUMPER	57731FG010B7	Dis 14.40	✓	
9	REFLEX AY RH	84281FG000	Sn 21.60	X	
10	REFLEX ASSY LH	84281FG010	Sn 21.60	X	
11	LENS & BODY-FOG LIGHT,REAR (SUPP)	84913FG420	Sn 102.00	X	
12	CARGO STEP PNL RESIN (SUBARU WORD) XV ONLY	E775EFJ010	Sn 420.00	✓	
SUB TOTAL			1476.00	0.00	0.00
LESS DISCOUNT ( NETT-20 %)			295.20	0.00	0.00
GRAND TOTAL			1180.80	0.00	0.00
OVERALL TOTAL			1180.80		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGD9800U

TOTAL LABOUR CHARGES	3670.00
TOTAL SPARE PARTS CHARGES	1180.80
<hr/>	
GRAND TOTAL	4850.80 *
<hr/>	

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not Attached*  
*Running B4 paint*  
*2-3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Kt

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/1047/2018  
DATE : 23-NOV-2018

ECICS LIMITED  
10 EUNOS ROAD 8  
#09-04A SINGAPORE POST CENTER  
S(408600)  
TEL : 6337 4779  
FAX : 6338 9267

OWNER'S NAME : EE ZHENG, BRENDAN (YI ZHENG, BRENDAN) \*\*  
ADDRESS : BLK 618B PUNGGOL DRIVE #16-713  
S(822618)  
TELEPHONE NO : 94366656

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2100443951-02  
VEHICLE NO : SGD9800U  
MODEL CODE : GP3DKDC  
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT  
ENGINE NO : FB16Y056087  
CHASSIS NO : JF1GP3KC5FG158498  
MILEAGE : 40320 KM  
DATE IN : 23/11/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : DANIEL A JUDE\*\*  
ACCIDENT DATE : 19/11/2018

Print Date : 20/02/2019  
Print Time : 16:23:06



MYTORIMAGE ENTERPRISES PTE. LTD.  
17 LORONG 8, TOA PAYOH  
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGD9800U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SLR3786J - ECICS INSURED		
2	ZZ/001	TO CONDUCT TP CLAIM ECICS LOCATION:KPE TOWARDS TPE DATE:19/11/2018 TIME:1830HRS		
3	ZZ/002	REPAIR/REPLACE RR BUMPER AND PANEL	1680.00	520.00
4	ZZ/003	RESPRAY RR BUMPER AND PANEL	1260.00	420.00
5	ZZ/004	FAULT DIAGNOSTIC AND RESET SYSTEM	280.00	.00
6	ZZ/005	TO CONDUCT LIGHTING TEST ON REAR	50.00	30.00
7	ZZ/006	TO SUPPLY AND INSTALL REVERSE SENSOR - 2EYES	300.00	.00
8	ZZ/007	SUNDRIES	100.00	20.00
TOTAL LABOUR CHARGES			3670.00	990.00

MOTORIMAGE ENTERPRISES PTE. LTD.  
10 LORONG 8, TOA PAYOH  
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGD9800U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
1 BUMPER FACE R XUV	57704FJ041	594.00			OK
2 BRKT RRH BUMP CORN	<i>R</i> 57707FJ080	28.80			X
3 BRKT RLH BUMP CORN	<i>R</i> 57707FJ090	28.80			X
4 BRKT RRH BUMP	<i>Sn</i> 57707FJ160	14.40			X
5 BRKT RLH BUMP	57707FJ170	14.40			OK
6 BRKT BUMP R LWR	<i>R</i> 57707FJ201	28.80			X
7 BEAM COMPL R EU	<i>R</i> 57711FJ0239P	187.20			X
8 COVER-REAR BUMPER	57731FG010B7	14.40			OK
9 REFLEX AY RH	<i>Sn</i> 84281FG000	21.60			X
10 RELFLEX ASSY LH	<i>Sn</i> 84281FG010	21.60			X
11 LENS & BODY-FOG LIGHT, REAR (SUPP)	<i>Sn</i> 84913FG420	102.00			X
12 CARGO STEP PNL RESIN (SUBARU WORD) XV ONLY	E775EFJ010	420.00			OK
SUB TOTAL		1042.80	0.00	0.00	0.00
LESS DISCOUNT ( NETT-20 %)		208.56	0.00	0.00	0.00
GRAND TOTAL		834.24	0.00	0.00	0.00
OVERALL TOTAL		834.24			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
17 LORONG 8, TOA PAYOH  
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGD9800U

NETT ITEM 1042.80  
LESS 20 % -208.56  
NETT AMOUNT 834.24

LIST ITEM 0.00  
LESS 50 % 0.00  
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 0.00

S/LIST ITEM 0.00  
LESS 30 % 0.00  
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 990.00  
TOTAL SPARE PARTS CHARGES 834.24

TOTAL CHARGES 1824.24  
ADD 7 % GST 127.70

GRAND TOTAL 1951.94

✓ ok















## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	28 Feb 2019 10:38 <a href="#">Edit Reg</a>		27 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,824.24</b> <a href="#">Edit Estimates</a>	<b>S\$1,824.24</b> <a href="#">View Rpt</a>	
						<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>		
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM				
Main Claimant: <b>EE ZHENG, BRENDAN (YI ZHENG, BRENDAN)</b> , ID: S8126276D				
Vehicle Reg. No.: <b>SGD9800U</b>		Date of Loss: 19/11/2018 18:00 - :59 [35 Months From LTA Reg Date (Man Yr)]		
Claim Type: <b>TP / DMPC1800430H/DL</b>		Policy/Cover Note No.: MPC18A00209601		
Vehicle Reg. No. (Insured): <b>SLR3786J</b>		Policy No. (Claimant):		
		Excess:		
Repairer: <b>Motor Image Enterprises Pte Ltd (Toa Payoh)</b> 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101				
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Desmond Lee</b> - 6303 0167]				
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 20/12/2018]</b>				
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.				
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>
				<b>Handler</b>
				<b>Assigned By</b>
				<b>Completed On</b>
				<b>Created On</b>
				<b>Done?</b>
No results.				

## Claim Documents

**\*SGD9800U (DMPC1800430H/DL)**  
**[SLR3786J]**  
**TP**  
**EE ZHENG, BRENDAN (YI ZHENG, BRENDAN)**  
**Nov 19 2018 6:00PM**  
**[-]**  
**Motor Image Enterprises Pte Ltd**

Upload Documents   Upload Photos   Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/02/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/02/19 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
14	25/02/19 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18021933/KTBE2

Date: 28/02/2019

## REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC18A00209601  
 Claimant Vehicle No: SGD9800U Insured Vehicle No: SLR3786J  
 Date of Loss: 19/11/2018 Nature of Claim: TP Claim No: DMPC1800430H/DL

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGD9800U  
 Make & Model: SUBARU XV, 1.6 I-S AWD CVT (A) Engine No: FB16Y056087  
 Reg. Date: 19/12/2015 (Man. Year: 2015) Chassis No: JF1GP3KC5FG158498  
 Colour: Metallic Pearl White Odometer: 40318 km  
 Engine Capacity: 1600 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17  
 Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 5 mm  
 Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,280.80	854.24	426.56	33.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	970.00	2,600.00	72.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,850.80</b>	<b>1,824.24</b>	<b>3,026.56</b>	<b>62.39</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>339.56</b>	<b>127.70</b>	<b>211.86</b>	<b>62.39</b>
<b>Nett Amount (S\$)</b>	<b>5,190.36</b>	<b>1,951.94</b>	<b>3,238.42</b>	<b>62.39</b>

## INSPECTION

Date of Assignment: 27/11/2018  
 Date Inspected: 10/12/2018 Inspected At: Motor Image Enterprises Pte Ltd (Toa Payoh)  
 19 Lorong 8 Toa Payoh  
 Singapore 319255

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2019)
<b>Parts:</b>	144	SUBARU XV 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGD9800U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
2	1		*BUMPER FACE R XUV	Cracked	594.00 FN	*594.00 FN
3	1		*BRKT RRH BUMP CORN	Repair	28.80 FN	*- FN
4	1		*BRKT RLH BUMP CORN	Repair	28.80 FN	*- FN
5	1		*BRKT RRH BUMP	Serviceable	14.40 FN	*- FN
6	1		*BRKT RLH BUMP	Distorted	14.40 FN	*14.40 FN
7	1		*BRKT BUMP R LWR	Repair	28.80 FN	*- FN
8	1		*BEAM COMPL R EU	Repair	187.20 FN	*- FN
9	1		*COVER - REAR BUMPER	Missing	14.40 FN	*14.40 FN
10	1		*REFLEX AY RH	Serviceable	21.60 FN	*- FN
11	1		*RELFLX ASSY LH	Serviceable	21.60 FN	*- FN
12	1		*LENS & BODY - FOG LIGHT, REAR	Serviceable	102.00 FN	*- FN
13	1		*CARGO STEP PNL RESIN (SUBARU WORD) XV ONLY	Necessary	420.00 FN	*420.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>1,576.00</b>	<b>1,062.80</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (S\$)</b>	<b>295.20</b>	<b>208.56</b>
<b>Total Parts (S\$)</b>	<b>1,280.80</b>	<b>854.24</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR / REPLACE RR BUMPER AND PANEL	New	1,680.00	520.00
2	RESPRAY RR BUMPER AND PANEL	New	1,260.00	420.00
3	FAULT DIAGNOSTIC AND RESET SYSTEM	New	280.00	0.00
4	TO CONDUCT LIGHTING TEST ON REAR	New	50.00	30.00
5	TO SUPPLY AND INSTALL REVERSE SENSOR - 2EYES	New	300.00	0.00
Gross Labour Cost (\$\$)			<b>3,570.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >