

REF:

CC3/ML18021978 / Agber

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No. 2100503928-01

Claims No. 542551417759

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

881K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLM1186E, Yr Regn: 2017 / March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan. c.c 999

Colour:

White.

A/C: Insured / Std / NI / NA

Sp. Reading:

53657.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU2228V9H1039416.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16.

R:

205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

06/12/18-

Survey held at

Premium.

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD A16,

SLM 1186E - CC3/ML18021978/Agber

OD: 23052018

12/12/18 @ 11.34am Informed by James Tan, the owner would like to close off OD claim as TP had given them liability issued. They will continue on TP claim.

12/12/18 Submit Prelim. report.

RECEIVED 13 DEC 2018

Date/Time, File Pass to?



Prelim. Report

12/12/18 Informed



Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

\$ + RS \$

Photos

Others

TOTAL

200

10

210

Shiau Chan (LKKAuto)

From: Claims <claims@premiumauto.com.sg>
Sent: Wednesday, 12 December 2018 11:34 AM
To: Shiau Chan (LKKAuto)
Cc: Claims
Subject: RE: SLM1186E OD / 5425514177SG

Dear Shiau Chan,

My client will like to close off OD Claim as TP had given us liability already.
We will continue on TP Claim.

Best Regards,
James Tan
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 12 December, 2018 10:56 AM
To: Claims <claims@premiumauto.com.sg>
Subject: RE: SLM1186E OD / 5425514177SG

Dear Sir/Madam,

Any updates? As insurance officer is chasing.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7637E
Vehicle Details	
Vehicle No.:	SLM1186E
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED & NAV)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CHZ176582
Chassis No.:	WAUZZZ8V9H1039416
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$25,406.00
Original Registration Date:	21 Mar 2017
First Registration Date:	21 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$17,569.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2027
PARF Rebate Amount:	\$13,176.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$42,010.00
Total Rebate Amount:	\$55,186.00

The information contained herein is correct as at 12 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2018 15:54
Date Of Accident	01/11/2018 15:00
Exact Location Of Accident	33D BENOI RD PIONEER LOT S(627788)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM1186E
Insured/Policyholder	
Name Of Registered Owner	LAW LIWEI
NRIC No	S8677637E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98633140
Alternative Phone No	OFFICE-98633140

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI S-TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100503929-01
Cover Note Number	

Driver

Name of Driver	LO WING KWONG
NRIC No	S8022626H
Date Of Birth	01/08/1980
Occupation	INDOOR
Date Of Driving Pass	24/12/2004
Driving Experience	13 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98633140
Fax Number	
Contact Number	
EMail Address	BLAZER_QQ@HOTMAIL.COM

Address	111 COMPASSVALE BOW #07-02
Postcode	544998
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

CAR IS IN PARKING STATUS. LORRY REVERSED AND SCRATCHED THE FRONT OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH7913D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KOTTAIYAN SHETTIAPPAN PARAMASIUAM
NRIC/Passport Number	S6964946G
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

CAR IS IN PARKING STATUS.
LORRY ~~RESEV~~ REVERSED AND SCATLH THE
FRONT OF MY CAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Accident Photo



Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1294/2018/GW
Date : 14-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no:GBH 7913 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Law Li Wei
Address : 111 Compassvale Bow
: #07-02
Singapore 544998
Telephone : 98633140
Type of Claim : Own Damage Claim
Policy No. : 2100503929-01
Vehicle No : **SLM 1186 E**
Model Code : A3 Sedan 1.0 TFSI
Model / Year : Mar-17
Engine No : CHZ 176582
Chassis No : WAUZZZ8V9H1039416
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Nov-18
Place of Accident : 33 D Benoi Rd Pioneer Lot S(627788)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 1186 E

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle front bumper, rhs front fender, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	2,400.00 1250.
3	To respray front bumper, bonnet, hinges and rhs front fender. ✓ X	\$ 2,400.00 1100.
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 5,352.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 1186 E

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>
1	FRONT BUMPER <i>Repair</i>	\$	1,739.00 *
2	FRONT BUMPER FIXING PARTS	\$	161.00 *
3	FRONT BUMPER GUIDE SECTION-LH/RH <i>2</i>	2 \$	66.00 *
5	FRONT BUMPER CLOSING ELEMENT-LH/RH <i>2</i>	2 \$	508.00 *
6	RADIATOR GRILLE <i>new</i>	\$	1,239.00 *
7	RADIATOR GRILLE CLOSING ELEMENT <i>new</i>	\$	167.00 *
8	FRONT BUMPER END PLATE <i>3</i>	\$	105.00 *
9	STICKER FOR AIR CONDITIONER <i>new</i>	\$	12.00 *
10	FRONT FENDER-RH <i>new</i>	\$	746.00 *
11	FRONT FENDER BRACKET-RH <i>3 new</i>	\$	34.00 *
12	FRONT FENDER BRACE-RH	\$	84.00 *
13	BONNET <i>Dented</i>	\$	2,755.00 ✓
14	BONNET ATTACHMENT PARTS <i>?</i>	\$	141.00 ?
15	BONNET LID HINGE-LH/RH <i>new</i>	\$	106.00 *
16	BONNET STOP BUFFER <i>2</i>	2 \$	9.00 *
17	BONNET GAS FILLED STRUT <i>new</i>	\$	105.00 *
18	BONNET CATCH HOOK	\$	78.00 *
19	BONNET STRIKER-LH/RH <i>2</i>	2 \$	192.00 *
20	BONNET EDGE PROTECTION <i>new</i>	\$	24.00 ✓
SUB- TOTAL SPARE PARTS CHARGES		\$	8,271.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 1186 E

S/N	Parts Description		Damaged Par S/Nett
21	BONNET CATCH HOOK		\$ 55.00 ⁺
22	BONNET LID LOCK WITH MICRO	2	\$ 353.00 ⁺
23	BONNET BOWDEN CABLE-CENTER		\$ 50.00 ⁺
24	BONNET SOUND ABSORBER		\$ 192.00 ⁺
25	PLENUM CHAMBER COVER		\$ 156.00 ⁺
26	FRONT WIPER COWL TRIM		\$ 14.00 ⁺
27	LED HEADLIGHT-RH		\$ 4,888.00 ✓
28	FRONT NO. PLATE	S/N	\$ 25.00 ⁺
29	SUNDRIES		\$ 500.00 [?]
TOTAL SPARE PARTS CHARGES			\$ 14,504.00
TOTAL LABOUR CHARGES			\$ 5,352.00
GRAND TOTAL			\$ 19,856.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling.
Surveyed Date : 06/12/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repair, 04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Nov 2018		06 Dec 2018 15:04 Edit Adj Rpt	S\$10,569.00 Edit Estimates	S\$10,569.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LAW LIWEI , ID: S8677637E									
Vehicle Reg. No.: SLM1186E		Date of Loss: 01/11/2018 15:00 - :59 [19 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 5425514177SG		Policy/Cover Note No.: 2100503929-01 (Comprehensive)							
Excess:									
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/12/2018]									
Driver/Custodian: LO WING KWONG (38 / Male), NRIC: S8022626H, Tel: +6598633140									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM1186E (5425514177SG)
OD
Nov 1 2018 3:00PM
[LAW LIWEI]
Premium Automobiles Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser	
Video						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	13/11/18 16:37	Video - Accident [Linked Accident Report Documents]		Load MP4			
2	13/11/18 16:38	Video - Accident [Linked Accident Report Documents]		Load MP4			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
2	12/12/18 14:46	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
3	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
4	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
5	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
6	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
7	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
8	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
9	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
10	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
11	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
12	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
13	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
14	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
15	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
16	12/12/18 14:46	General View		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	12/12/18 17:31	Singapore Accident Statement		Load PDF			
2	12/12/18 17:31	ESTIMATE		Load PDF			

Linked Accident Report Documents

					View	View in Browser	
Video						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	13/11/18 16:37	Video - Accident		Load MP4			
2	13/11/18 16:38	Video - Accident		Load MP4			
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	13/11/18 16:42	Accident Statement		Load HTM			
Photos/Images						3 per page	<input checked="" type="checkbox"/>

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	13/11/18 16:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	13/11/18 16:07	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 16:07	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18021978/AQBE2

Date: 13/12/2018

REFERENCE

Insured/Claimant: LAW LIWEI Policy No: 2100503929-01
Date of Loss: 01/11/2018 Nature of Claim: OD Claim No: 5425514177SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM1186E**
Make & Model: AUDI A3, 999cc TFSI S-TRONIC (A) Engine No: CHZ176582
Reg. Date: 21/03/2017 (Man. Year: 2016) Chassis No: WAUZZZ8V9H1039416
Colour: White Odometer: 53657 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$88,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Sumitomo 6 mm Rear Left Side: Sumitomo 6 mm
Front Right Side: Sumitomo 6 mm Rear Right Side: Sumitomo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,504.00	7,667.00	6,837.00	47.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,352.00	2,902.00	2,450.00	45.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,856.00	10,569.00	9,287.00	46.77
+ GST 7.00/7.00% (S\$)	1,389.92	739.83	650.09	46.77
Nett Amount (S\$)	21,245.92	11,308.83	9,937.09	46.77

INSPECTION

Date of Assignment: 06/12/2018
Date Inspected: 06/12/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

ACCORDING TO THE REPAIRER, THE OWNER WOULD LIKE TO CLOSE OFF THE OD CLAIM AND THEY WILL CONTINUE ON TP CLAIM.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$641.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,739.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	161.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH/RH	Not Necessary	66.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT - LH/RH	Not Necessary	508.00 FS	*- FS
5	1		*RADIATOR GRILLE	Not Necessary	1,239.00 FS	*- FS
6	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	167.00 FS	*- FS
7	1		*FRONT BUMPER END PLATE	Not Necessary	105.00 FS	*- FS
8	1		*STICKER FOR AIR CONDITIONER	Not Necessary	12.00 FS	*- FS
9	1		*FRONT FENDER - RH	Not Necessary	746.00 FS	*- FS
10	1		*FRONT FENDER BRACKET - RH	Not Necessary	34.00 FS	*- FS
11	1		*FRONT FENDER BRACE - RH	Not Necessary	84.00 FS	*- FS
12	1		*BONNET	Dented	2,755.00 FS	*2,755.00 FS
13	1		*BONNET ATTACHMENT PARTS	* Check	141.00 FS	*- FS
14	1		*BONNET LID HINGE - LH/RH	Not Necessary	106.00 FS	*- FS
15	2		*BONNET STOP BUFFER	Not Necessary	9.00 FS	*- FS
16	1		*BONNET GAS FILLED STRUT	Not Necessary	105.00 FS	*- FS
17	1		*BONNET CATCH HOOK	Not Necessary	78.00 FS	*- FS
18	2		*BONNET STRIKER - LH/RH	Not Necessary	192.00 FS	*- FS
19	1		*BONNET EDGE PROTECTION	Necessary	24.00 FS	*24.00 FS
20	1		*BONNET CATCH HOOK	Not Necessary	55.00 FS	*- FS
21	2		*BONNET LID LOCK WITH MICRO	Not Necessary	353.00 FS	*- FS
22	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	50.00 FS	*- FS
23	1		*BONNET SOUND ABSORBER	Not Necessary	192.00 FS	*- FS
24	1		*PLENUM CHAMBER COVER	Not Necessary	156.00 FS	*- FS
25	1		*FRONT WIPER COWL TRIM	Not Necessary	14.00 FS	*- FS
26	1		*LED HEADLIGHT - RH	Cut	4,888.00 FS	*4,888.00 FS
27	1		*FRONT NO. PLATE	Not Necessary	25.00 FS	*- FS
28	1		*SUNDRIES	* Check	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **14,504.00** **7,667.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,250.00
3	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER	New	2,400.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,352.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >