

ASS. REC. BY:

REF: CS3 /ms118021989 /Gcb21 Special Instruction:

Surveyor
murimen

ASSIGNMENT (Office)

From (Person);

Irene Tan

of

MSLH

Date/Time: 06-12-2018 1:42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JSM 8413

Insured:

Ym 840267

at Workshop m/s

Xin Yun Auto

Tel:

9839 1555

of

8 Kaki Bukit Ave 4 #05-23

Policy No:

A29 078841M5C

Claim No:

573633

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/10/2018

CA / REV / REP. / REV 24 HRS' WP

H.O.D. Endorsement:

Date/Time:

06122018

223 pm

Person Contacted:

Yi Xin

Vehicle ^{RA} IN/OUT

Date/Time	Action/Instruction (X) Estimate.
	JSM 8913 - x
	Ym 8402G - x

Surveyor

MS
XHL

REF: MSG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Xin Yun Auto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: ~~\$7700~~ \$3600
 IDAC Accident Rpt.: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: ISM8913 Yr Regn: 2d8
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha 135LC c.c. 134
 Colour: red A/C: Insured / Std / NI / NA
 Sp. Reading: 17886 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: PMYU60810J0000823
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 80/90-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Vel Rubber

Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 06-12-18
 Survey held at w/s LPKSPM
 Des. of Damages: Frt / Rear / O/S / W/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$2000 - \$3000</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format : PRS

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation: _____

_____ S + RS. _____ SI

Photos

Others

TOTAL

120
10
130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2018		06 Dec 2018 13:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	RAKKI TECH PTE LTD, Co. Reg. No.: 200511694R, Email: RAKKI@SINGNET.COM.SG			[Created by insurer]
Main Claimant:	HOH KOCK KHIONG, ID: F7482507U			
Vehicle Reg. No.:	JSM8913	Date of Loss:	09/10/2018 19:00 - :59 [21 Months and 8 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 573633	Policy/Cover Note No.:	A29078841MKC (TP, Fire & Theft) Coverage: 11/04/2018 - 10/04/2019	
Vehicle Reg. No. (Insured):	YM8402G	Policy No. (Claimant):		
		Excess:		
Repairer:	Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/12/2018]			
Driver/Custodian (Insured):	PERIYASAMY KATHIRESAN (38 / Male), NRIC: G7188710W, Tel: +6598101934			
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY DISPUTE Please appoint LKK AUTO CONSULTANCT PTE LTD to conduct the survey . Kindly contact YI XIN 9839 1555 or FABIAN 9839 1666 to arrange for survey .			

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?



**SINGAPORE
POLICE FORCE**



T/20181022/2080

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20181022/2080

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/10/2018 14:25	Vide Report No.: J/20181009/0201	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: HOH KOCK KHIONG			Address: 81 JALAN ABU BAKAR 81000 KULAI JOHOR	
ID Type / ID No.: FIN NO / F7482507U			Contact No.: Home/Office: 0127666628 Mobile: 97761909	
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 47	Date of Birth: 24/11/1970	Type of Informant: Rider	
Race: Chinese			Language: Chinese	Institution / School Name:
Occupation: Welder			Driving Licence Information: Class: 2B,3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 09/10/2018 19:45	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 PIONEER ROAD GUL WAY PIONEER ROAD JUNCTION GUL WAY Lamp Post Number: 144				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision:			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JSM8913	Motorcycle					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181022/2080

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20181022/2080

CONTINUATION OF REPORT

Rider			
Name	HOH KOCK KHIONG	ID No.	F7482507U
Related Vehicle	JSM8913 (Motorcycle)	Contact No.	0127666628
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	09/10/2018	Date Discharge	15/10/2018
No. of Days granted Medical Leave	25	Degree of Injury	NIL

Brief Details.

ON THE 09/10/2018 AT AROUND 1945HRS ALONG PIONEER ROAD JUNCTION GUL WAY

THE TRAFFIC FLOW WAS MODERATE AND THE ROAD SURFACE WAS DRY. I WAS RIDING ALONG PIONEER ROAD. WHEN I HAD AN ACCIDENT. I STOPPED AT THE JUNCTION AS THE TRAFFIC LIGHT WAS RED, WHEN I SAW THE TRAFFIC LIGHT TURN GREEN AND THE NEXT MOMENT I DO NOT REMEMBER ANYTHING. THE NEXT TIME I OPEN MY EYE, I WAS IN THE HOSPITAL.

THAT'S ALL



**SINGAPORE
POLICE FORCE**



T/20181022/2080

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20181022/2080

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
KEE CHUAN JIA MARCUS

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt IRMAN BIN MOHAMAD SAID
Contact No.: 65476145

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
22/10/2018 14:25

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature: 

Notis Penting : Kami tidak butiran-butiran polisi

NEWDEGATE PS



...CLAIM SUBFOLDER...(Pending for Survey Report)




























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2018		06 Dec 2018 13:42 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: RAKKI TECH PTE LTD , Co. Reg. No.: 200511694R, Email: RAKKI@SINGNET.COM.SG									
Main Claimant: HOH KOCK KHIONG , ID: F7482507U									
Vehicle Reg. No.: JSM8913		Date of Loss:	09/10/2018 19:00 - :59 [9 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / 573633		Policy/Cover Note No.:	A29078841MKC (TP, Fire & Theft) Coverage: 11/04/2018 - 10/04/2019						
Vehicle Reg. No. (Insured): YM8402G		Policy No. (Claimant):							
		Excess:							
Repairer: Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 07/12/2018]									
Driver/Custodian (Insured): PERIYASAMY KATHIRESAN (38 / Male), NRIC: G7188710W, Tel: +6598101934									
Adj Asg. Remarks: SJE : DISAGREED / LIABILITY DISPUTE Please appoint LKK AUTO CONSULTANCT PTE LTD to conduct the survey . Kindly contact YI XIN 9839 1555 or FABIAN 9839 1666 to arrange for survey .									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JSM8913 (573633)
[YM8402G]
TP
HOH KOCK KHIONG
Oct 9 2018 7:00PM
[RAKKI TECH PTE LTD]
Xin Yun Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/12/18 08:38	Accident Statement From: SC - Reg. No: YM8402G, Claimant: RAKKI TECH PTE LTD		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
2	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
3	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
4	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
5	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
6	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
7	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
8	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
9	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
10	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
11	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
12	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
13	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
14	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
15	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
16	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
17	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
18	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
19	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
20	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
21	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
22	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
23	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
24	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
25	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
26	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
27	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
28	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
29	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
30	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
31	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
32	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>
33	07/12/18 18:59	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
54	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
55	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
57	07/12/18 18:59	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/12/18 08:41	TPD JSM8913 - POLICE REPORT	 Load PDF	
2	06/12/18 08:41	TPD JSM8913 - PRI	 Load PDF	
3	06/12/18 13:33	Reply email from TP Lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18021989/GCBE2

Date: 14/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29078841MKC

Claimant Vehicle
No : JSM8913

Insured Vehicle No : YM8402G

Date of Loss: 09/10/2018

Nature of Claim: TP

Claim No: 573633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JSM8913

Make & Model: YAMAHA 135LC, 135cc ES

Engine No: G3G5E000553

Reg. Date: 01/01/2018 (Man. Year: 2018)

Chassis No: PMYUG0810J0000833

Colour: Red

Odometer: 17886 km

Engine Capacity: 134 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-17

Rear Tyre Size: 80/90-17

Front Left Side: Vee Rubber 5 mm

Rear Left Side: Vee Rubber 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/12/2018

Date Inspected: 06/12/2018 Inspected At:

Xin Yun Auto Pte Ltd (HQ)
BLK 8 KAKI BUKIT AVE 4 #05-23
PREMIER @KAKI BUKIT
Singapore 415675

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Dec 2018)

Parts: N/A YAMAHA 135LC 135cc ES (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JSM8913)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >