

22/03/2002

ASS. REC. BY:

REF: C9/17/18022019 / Asb2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Syazwinda

of

ACU

Date/Time: 07/12/2018 11:31am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGA 2115B

Insured:

SLP 4892P

at Workshop m/s

Eunos Motor

Tel:

6747 2033

of

Blk 1 Kaki Bukit Ave 6 #01-64

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

10-12-2018

H.O.D. Endorsement:

Date/Time: 04/12/2018 11:37am

Person Contacted:

Ms. Ng

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGA 2115B - x

SLP 4892P - x

24/12/18

Confirmed L/S \$ 2,550/- @ 4 days with Adrian.
(\$ 3,560.64 Rd - 58%.)

REF: AIG

ASSIGNMENT

From: Date: 10/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGA 2115B

at Workshop m/s: Eunos Motor

of Blk 1 kaki Blk Ave 6 #01-64

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: MS Ng @ 6747 2033

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGA 2115B. Yr Regm: 2015 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 81779 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 211103930

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16-

R: 215/60R16-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken-

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 10/12/18-

Survey held at Eunos Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

RECEIVED 24 DEC 2018

Date/Time. File Pass to?

24/12/18

1) Typist

Date/Time. File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 2,550/- H/s

250

20

270

- Pre repair inspection request - SGA2115B VS SLP4892P (OI) DOA: 05/12/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinrul, Chan, Yoke Shi, Kaur, Baljit
Sent: Friday, 7 December, 2018 11:31:14 AM
Attachments: Eunus Motor - Pre-Repair Notice (AIG)(SGA2115B).pdf

Hi,

Please refer to the enclosed request from **CrossBorders LLC**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Hui Ting [mailto:huiting@crossbordersllc.com]
Sent: Friday, December 07, 2018 11:14 AM
To: Azlan, Syazairdina; Corene
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLP4892P AND SGA2115B ON 05/12/2018

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Syaza

1. We refer to your email dated 7 December 2018.
2. We are instructed that our client has confirmed Adrian Ling from LKK Auto Consultants Pte Ltd as a single joint expert.
3. Please be informed that the said vehicle can be inspected at:

Venue: Eunus Motor Service
Address: Blk C, 1 Kaki Bukit Ave 6
#01-064 Autobay @ Kaki Bukit
Singapore 417883
Contact: Ms Ng (6747 2033)

4. Please liaise with the above workshop.

Thank You.

Regards
Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

NOTICE OF OFFICE CLOSURE

Please be informed that our office will be closed for the dates specified below. During the period of closure stated below, we will not be able to accept service of Court documents nor be able to receive/attend to any incoming correspondence.

Closed From	To
24 December 2018, 9.00AM	24 December 2018, 6.00PM
31 December 2018, 9.00AM	31 December 2018, 6.00PM
04 February 2019, 9.00AM	08 February 2019, 6.00PM

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: Azlan, Syazairdina <Syazairdina.Azlan@aig.com>
Sent: Friday, 7 December 2018 8:59 AM
To: Hui Ting <huiting@crossbordersllc.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLP4892P AND SGA2115B ON 05/12/2018



Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina Azlan@aig.com

To: huijing@crossbordersilc.com

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, NoorMarisa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Yinrul.Hor@aig.com, yokeshi.chan@aig.com, Bai

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLP4892P AND SGA2115B ON 05/12/2018

Date: Fri, 7 Dec 2018 00:59:14 +0000

Without Prejudice

Your Reference : AJ.tk.ES (SGA2115B)

Our Reference : SLP4892P

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: AIG SGP, Claims-Survey
Sent: Thursday, December 06, 2018 4:06 PM
To: Azlan, Syazairdina
Subject: FW: Our client's vehicle no. SGA2115B (ES); Your insured's vehicle no. SLP4892P - PRI

From: Hui Ting [mailto:huiting@crossbordersllc.com]
Sent: Thursday, December 06, 2018 3:59 PM
To: AIG SGP, Claims-Survey
Cc: Corene
Subject: Our client's vehicle no. SGA2115B (ES); Your Insured's vehicle no. SLP4892P - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. Please find attached our PRI notice dated 06 December 2018 for your kind attention.
2. Please reply email to corene@crossbordersllc.com & huiting@crossbordersllc.com

Thank You.

Regards
Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

NOTICE OF OFFICE CLOSURE

Please be informed that our office will be closed for the dates specified below. During the period of closure stated below, we will not be able to accept service of Court documents nor be able to receive/attend to any incoming correspondence.

Closed From	To
24 December 2018, 9.00AM	24 December 2018, 6.00PM
31 December 2018, 9.00AM	31 December 2018, 6.00PM
04 February 2019, 9.00AM	08 February 2019, 6.00PM

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.lk.ES (SGA2115B)
Your Ref: SLP4892P

06 December 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

BY FAX: 6415 3727 & EMAIL

URGENT

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: LIN JIN HUAN
TRAFFIC ACCIDENT ON 05 DECEMBER 2018 AT 09:20 HRS ALONG PIE (CHANGI)
BEFORE EXIT TO CTE (SLE) INVOLVING VEHICLES NO. SGA2115B & SLP4892P

We are instructed by Lin Jin Huan to notify you of a road accident on 05 December 2018 at about 09:20 hrs along PIE (Changi) Before Exit to CTE (SLE) involving our client's vehicle registration number SGA2115B and vehicle registration number SLP4892P driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Eunox Motor Service
Address: Blk C, 1 Kaki Bukit Ave 6
#01-064 Autobay @ Kaki Bukit
Singapore 417883
Contact: Ms Ng (6747 2033)

Please liaise with the above workshop directly.

Yours faithfully

Crossborders LLC
Crossborders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com
encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

MPA216157883 / Progressive Car Care Pte Ltd - HQ
 ENTRY DATE & TIME: 06/12/2018 15:17
 SUBMITTED BY: Soo Leong Keat

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2018 15:17
Date Of Accident	05/12/2018 09:20
Exact Location Of Accident	PIE (CHANGI) BEFORE EXIT TO CTE (SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGA2115B
Insured/Policyholder	
Name Of Registered Owner	LIN JIN HUAN
NRIC No	S8535416G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81688040
Alternative Phone No	OFFICE-81688040

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA409952/1
Cover Note Number	

Driver

Name of Driver	ZHENG JING SHENG
NRIC No	S8333315D
Date Of Birth	01/10/1983
Occupation	INDOOR
Date Of Driving Pass	31/05/2002
Driving Experience	16 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98472283
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 633B SENJA ROAD #10-149
Postcode	672633
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

STATEMENT RECORDED BY SOO - PROGRESSIVE CAR CARE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP4892P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to terminate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the officers of the SIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurer, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if needed.
8. Consent under the Personal Data Protection Act (PDPA):

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to its insurer(s) who have insured vehicles involved in the accident and/or insurer(s) who have insured vehicles involved in the accident shall be collectively referred to as the "insurers", the insurer's lawyers/law firms, the statutory bodies of the insurers and any relevant government agency/authority such as the police, for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out or their dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the handling of correspondence, statements, invoices, reports or notices by me, which shall include verification of certain personal data about me to being about delivery of the same as well as the external cover of envelopes/mailed packages) and/or;
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicles involved in the accident and the insurer's lawyers/law firms, may/are permitted to collect, use, disclose and/or process the Personal Information for one or more of the above Purposes and;
- (c) my Personal Information may/also be disclosed by any of the insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be based outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of trend detection, investigation and intelligence in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in settling, investigating, monitoring or managing claims, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature:
Name:
NIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

		Vehicle A - SGA 2115 B B - SP4892P
		Legend

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no: 7/2018/206/2073

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days time limit for the claim against your policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181206/2073

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

1 of 3

Report No. T/20181206/2073

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/12/2018 13:00		Vide Report No.:		Station Diary No.: 72	
Informant's Particulars					
Name of Informant: TAY JINGSHENG			Address: APT BLK 633B SENJA ROAD #10-149 SINGAPORE 672633		
ID Type / ID No.: NRIC NO / S8333315D			Contact No.: Home/Office: Mobile: 98472283		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 35	Date of Birth: 01/10/1983	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Real estate agent			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 05/12/2018 09:20	Type of Location: EXPRESSWAY
Location: Along Road 1 Traveling Toward Road 2 PAN ISLAND EXPRESSWAY ALONG PAN-ISLAND EXPRESSWAY (PIE) HEADING TOWARDS CHANGI AIRPORT, JUST BEFORE UPP SERANGOON ROAD / CTE EXIT				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGA2115B	Car	HONDA	VEZEL 1.5X A	White	Slightly Damaged	0
SLP4892P	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	White	Slightly Damaged	0

POLICE REPORT Pg. 1

**SINGAPORE
POLICE FORCE**

T/20181206/2073

2 of 3

Police Station Of Origin:

Geylang N.P.C

132 Paya Lebar Road SINGAPORE 409014

Tel No: 1800-8486999

Report No. T/20181206/2073

CONTINUATION OF REPORT

Brief Details.

On the 5th of December 2018 at about 0920hrs, I was driving my vehicle bearing registration plate number SGA2115B along Pan-Island Expressway (PIE) heading towards Changi Airport direction. While I was driving on the 4th lane of the 5-lane expressway, just before Upper Serangoon Road / Central Expressway (CTE) exit, all of a sudden, another vehicle bearing registration plate SLP4892P, which was from the 5th lane of the 5-lane expressway, cut into my lane and hit onto the front left portion of my vehicle. The driver however didn't stopped his vehicle but he continued driving along the road. The driver then made another lane change onto the 3rd lane and headed towards Changi Airport direction, while I made my way towards Upper Serangoon Road direction.

I wish to state that there is in-car camera installed in my vehicle and that it captured the incident. I also wish to state that the damages on the front left portion, near to the front left tyre area, were scratches and paint job cracks. I also wish to state that I could not recall if the other vehicle had any passengers in it. After the collision and after driving for a distance, I felt some pain on the upper left portion of my back, however, I have yet to see a doctor with regards to the pain.

POLICE REPORT

SINGAPORE
POLICE FORCE

T/20181206/2073

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

3 of 3

Report No: T/20181206/2073

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G/ Sgt 3 MUHAMMAD ARIF BIN HAIRUDIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 05/12/2018 13:00
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt IRMAN BIN MOHAMAD SAID Contact No: 65476145	Classification Of Case:
Authentication Stamp NP186	

EUNOS MOTOR SERVICE

BLK 1 KAKI BUKIT AVE 6
#01-064 SINGAPORE 417883

TEL: 6747 2033, 6748 0107

FAX: 6741 5197

Mr. Adrian

TPAIG Shirley

SGA 2115B Honda Vezel

	Date	No.
Fit. Bumper to	927.80	880.
Fit Lower Bumper HEM	459.80	X.
Fit Bumper Retainer LH NEW	20.60	/
Fit. Fender LH Big	558.70	X.
" " protecto - LH UT	153.00	✓
Head Lamp Assy. LH could	1784.50	✓
Fit. Grille Assy. NEW	630.20	X.
" Bumper Retainer LH - Big HEM	35.00	X.
" " Fog Lamp LH could	327.70	✓
" " Lamp Cover LH HEM	45.00	X.
" " Reinforcement HEM	321.00	X.
	5263.30	
	less 20%.	1052.66
	4210.64	
To spray painting affected parts	900.00	400.
To knock, straighten all necessary parts in cleaning & repairing of all damaged part	1000.00	300
	6110.64	
Jump Sum: \$ 4888 / xx		
list: 3165.80	Labour: 700	
less 20%: 2532.64	total: 3232.64	
	h/s: 2550	
	0A Days.	

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)





































PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2018 Edit Reg		07 Dec 2018 00:00 Edit Adj Rpt	S\$2,550.00 Edit Estimates	S\$2,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd, Co. Reg. No.: NA								
Main Claimant:	LIN JIN HUAN								
Vehicle Reg. No.:	SGA2115B	Date of Loss:	05/12/2018 09:00 - :59 [37 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0610071955SG	Policy/Cover Note No.:	0999994772 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLP4892P	Policy No. (Claimant):							
		Excess:							
Repairer:	Eunos Motor Service (HQ) 1 Kaki Bukit Ave 6, #01-64 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 2033								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/12/2018]								
Claimant's Solicitor:	CROSSBORDERS LLC - Tel: 64381323								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (10/12/2018): No OI GIA Report AIG_SG (10/12/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGA2115B (0610071955SG)**
[SLP4892P]
TP
LIN JIN HUAN
Dec 5 2018 9:00AM
[LCRF Pte Ltd]
Eunos Motor Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
2	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
3	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
4	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
5	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
6	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
7	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
8	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
9	24/12/18 10:55	General View														Load JPG	<input checked="" type="checkbox"/>			
10	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
11	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
12	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
13	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
14	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
15	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
16	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
17	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
18	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
19	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
20	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
21	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
22	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
23	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
24	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
25	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
26	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
27	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
28	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
29	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
30	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
31	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
32	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
33	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
34	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
35	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
36	24/12/18 10:55	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/12/18 10:49	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18022019/ASBE2

Date: 26/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994772

Claimant Vehicle No : SGA2115B

Insured Vehicle No : SLP4892P

Date of Loss: 05/12/2018

Nature of Claim:

TP

Claim No: 0610071955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGA2115B

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: L15B4023933

Reg. Date: 27/10/2015 (Man. Year: 2015)

Chassis No: RU11103930

Colour: White

Odometer: 81779 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,210.64	2,532.64	1,678.00	39.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	700.00	1,200.00	63.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,110.64	3,232.64	2,878.00	47.10
Approved Total (Overridden) (S\$)		2,550.00		
Nett Amount (S\$)	6,110.64	2,550.00	3,560.64	58.27

INSPECTION

Date of Assignment: 07/12/2018

Date Inspected: 10/12/2018 Inspected At:

Eunos Motor Service (HQ)

1 Kaki Bukit Ave 6, #01-64 AutoBay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Torn	927.80 FL	*880.00 FL
2	1		*FRT LOWER BUMPER	Not Necessary	459.80 FL	*- FL
3	1		*FRT BUMPER RETAINER LH	Necessary	20.60 FL	*20.60 FL
4	1		*FRT FENDER LH	Repair	558.70 FL	*- FL
5	1		*FRT FENDER PROTECTOR LH	Cut	153.00 FL	*153.00 FL
6	1		*HEAD LAMP ASSY LH	Cracked	1,784.50 FL	*1,784.50 FL
7	1		*FRT GRILLE ASSY	Not Necessary	630.20 FL	*- FL
8	1		*FRT BUMPER RETAINER LH-BIG	Not Necessary	35.00 FL	*- FL
9	1		*FRT BUMPER FOG LAMP LH	Cracked	327.70 FL	*327.70 FL
10	1		*FRT BUMPER LAMP COVER LH	Not Necessary	45.00 FL	*- FL
11	1		*FRT BUMPER REINFORCEMENT	Not Necessary	321.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,263.30	3,165.80
- List Item Discount on L Items 20.00/20.00% (S\$)	1,052.66	633.16

Total Parts (S\$)	4,210.64	2,532.64
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SPRAY PAINTING AFFECTED PARTS	New	900.00	400.00
2	TO KNOCK,STRAIGHTEN ALL NECESSARY PARTS INCLUDING & REPLACING OF ALL DAMAGED PART	New	1,000.00	300.00
Gross Labour Cost (\$\$)			1,900.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >