

ASS. REC. BY:

REF:

CS / ALH 18027022 / Ktber

Special Instruction:

Surveyor:

Kernuth

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALH

Date/Time: 07/12/01 8:51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 7770A

Insured:

at Workshop m/s

Motor Image

Tel:

of

19 Lorong 8 Tou Pongoh

Policy No:

2100425495

Claim No:

714107078489

Sum Insured:

Excess:

TAA \$30007

Make of Veh:

D.O.A.

06-11-2016

(Client's Record)

CA / KEY / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

07/12/01 9:30am

Person Contacted:

Daniel

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJD 7770A - X
10/12 @ 3:30pm	Revert via merimen
10/12 @	Revert via merimen
11/12 @ 1:15:41pm	authorise repair by Chiang Loi SKI
17/12 @ 4:34pm	inform Daniel authorise repair excess \$30007-

REF: **NU**

ASSIGNMENT

From: Date: **09/12/2018**

Estimated Cost:

00 / TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: **SJD 7770A**at Workshop with **Motor Image**of **19 Lorong 8 Toa Payoh.**

Insured:

Policy No:

Claims No:

Sum Insured: Excess: **70A**

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **882K**

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **04** days Res.: Yes or NoLump Sum: **1.81** % 3 Val: Yes or NoCA / **REV** REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: **SJD 7770A** Yr Regn: **08 15**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Suban Outback** **Wagon** **2498**Colour: **M. # P. White** A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No: **JF2BS9KC 2FG 011006**Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/60R18**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: **9** mmL/Bal: **9** mmD.O.A: **5/12/18**

Survey held at

Rear

R/Bal: **9** mmL/Bal: **9** mmD.O.A: **7/12/18**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

ols frt & ulc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/12 Repairs to Car, Parking Plot**Part by Part \$12248.29. (Red: 3495.96, 22%)**

Date/Time, File Pass to?

11/11 Typist

Date/Time, File Return to?

3

☐ : Prel. Report☒ : Final ReportDays Of Repair: **11**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

1. S + RS \$

2. Photos

3. Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$Report Format: **OD**Lump Sum / I.B.I: (\$ **12,248.29**)**200****11****211**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 10 Dec 2018

Preliminary Advice

Vehicle No	: SJD7770A	Accident Date	: 05/12/2018
Make	: SUBARU OUTBACK	Policy No.	: 2100425995
Assignment Date	: 07/12/2018	Excess	: S\$0.00
Date of Inspection	: 07/12/2018	Est. Duration of Repair	: 6.00
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and undercarriage parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,169.08
Revised Amount	:S\$	8,869.52
Check Items (Estimated)	:S\$	2,746.08
Total	:S\$	11,615.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	67,338.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,662.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 17 December 2018 4:34 PM
To: 'Daniel Jude'
Cc: 'TPY Insurance Team'; SUR
Subject: RE: SJD7770A - OD CLAIM - AIG INSURED - ARRANGE SURVEY - 07/12/2018 - 1100HRS - authorization

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJD 7770A (Excess \$3000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Monday, 17 December 2018 2:59 PM
To: 'Daniel Jude' <danieljude@motorimage.net>; AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Cc: TPY Insurance Team <tpyinsteam@tanchong.org>
Subject: RE: SJD7770A - OD CLAIM - AIG INSURED - ARRANGE SURVEY - 07/12/2018 - 1100HRS

Dear Daniel,

Already updated AIG on the documents, awaiting for approval

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Daniel Jude <danieljude@motorimage.net>
Sent: Monday, 17 December 2018 2:48 PM

View Received Message

This mail is associated with :

***SJD7770A (7141070784SG)**

OD

Dec 5 2018 5:00PM

[HOO WEE HOON]

Motor Image Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 17/12/2018 15:41 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8870.00) - SJD7770A - Claim Handler: Loo, Tong Shing

Approved:8870.00;RE-INSPECTION Require for hidden parts and supplementary item.

DOCUMENTS SUMMARY

There are no documents.

- SJD7770A - OD CLAIM - AIG INSURED - ARRANGE SURVEY - 07/12/2018 - 1100HRS

From: Chin, Lee-Ying
To: assignments.admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: Friday, 7 December, 2018 8:51:27 AM

Attachments:  SJD7770A ESTIMATE.PDF  0701_003.jpg  0701_004.jpg  0701_005.jpg  SJD7770A GIA REPORT.PDF  0718_001.jpg

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Daniel Jude [mailto:danieljude@motorimage.net]

Sent: Thursday, December 06, 2018 4:57 PM

To: AIG SGP, Claims-Survey; Chin, Lee-Ying

Cc: TPY Insurance Team; Mohamed Isman

Subject: SJD7770A - OD CLAIM - AIG INSURED - ARRANGE SURVEY - 07/12/2018 - 1100HRS

Hi Claims Team,

Kindly assist to arrange survey for the above mentioned

07/12/2018 - 1100hrs

Thank You.

Best Regards

Daniel A Jude

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part

of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SJD7770A (7141070784SG)**

OD

Dec 5 2018 5:00PM

[HOO WEE HOON]

Motor Image Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 02/07/2019 13:59 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SJD7770A - Claim Handler: Loo, Tong Shing

Maintained:LAMP - ASSEMBLY HEAD RIGHT - Damage photos? Upload PARF and MV.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SJD7770A (7141070784SG)**

OD

Dec 5 2018 5:00PM

[HOO WEE HOON]

Motor Image Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_5G), sent on 03/06/2019 13:20 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SJD7770A - Claim Handler: Loo, Tong Shing

Maintained:Kindly provide market value document at the time of accident. How to get market value \$82K??

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAUTO)

From: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>
Sent: Thursday, 5 December 2019 11:55 AM
To: Denise Tay (LKKAUTO)
Cc: Fong, Andy-SY; Koh, Victor-CK
Subject: RE: MANDATE APPROVAL

Hi Denise,

Kindly check in Merimen for mandate approval.

SJD7770A engine cradle frame was double charged by Motorimage, please remove one of them and inform repairer to bill only the correct part according and re-seek mandate.

Best Regards,

LIM KOK CHONG
AIG
Motor Surveyor
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1933 | Mobile +(65) 8876 5437
kok-chong.lim@aig.com | www.aig.sg



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. Click here to find out more.

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, December 04, 2019 5:56 PM
To: Lim, Kok-Chong
Subject: [EXTERNAL] MANDATE APPROVAL

This message is from an external sender; be cautious with links and attachments.

Dear Kok Chong,

Please help on the mandate

SMJ8120C
OD / 8633822092SG

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5695F
Vehicle Details	
Vehicle No.:	SJD7770A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2018
Vehicle Make:	SUBARU
Vehicle Model:	OUTBACK 2.5I-S CVT AWD SR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	FB251781368
Chassis No.:	JF2B59KC2FG011006
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$20,378.00
Original Registration Date:	21 Aug 2015
First Registration Date:	21 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$20,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2025
PARF Rebate Amount:	\$15,397.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$77,600.00
COE Rebate Amount:	\$51,941.00
Total Rebate Amount:	\$67,338.00

The information contained herein is correct as at 10 Dec 2018

OK

D.O.A. 5/12/2018

40,473.

$\$10,693 / \text{yr}$
 $\times 10.700 / \text{yr} = \$112,000$
 $\times 80.5 \text{ mths} = \$9,100$
 $\$101,900$

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2018 Honda Odyssey Hybrid 2.0A Absolute.

Low Mileage, Well kept,
Cheapest Honda Odyssey Hybrid
In The Market.
Direct Owner. See it!

PRIME MOTOR & LEASING
[CHONG YONG CREDIT ENTERPRISES PTE LTD GROUP (P) COMPANY]
With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

SUBARU OUTBACK

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	SUBARU OUTBACK	Any	Any	Any	Any	Any	Any	Available
	Subaru Outback 2.5i-S Sunroof	\$69,800	\$10,220 /yr	22-Sep-2015	2,498 cc	70,000 km	SUV	Available
Pearl White Unit! 1st Owner Car. Vehicle Fully Maintain By Agent "Motor Image" With Warranty Coverage Valid Till 21 Sep 2020 Purchase Comes With Premium Grooming And New Paint Coat. Bank And In House Financing Scheme Supported. Viewing Available Daily By Appt... Sincere Motoring Pte Ltd Posted: 04-Dec-2019 Tags: 2015 Subaru Outback, 2015 subaru outback, Subaru Outback, subaru outback, Subaru, Outback, outback, Used Subaru								
	Subaru Outback 2.5i-S	\$82,000	\$11,110 /yr	28-Apr-2016	2,498 cc	43,050 km	SUV	Available
Still Under Warranty. Very Spacious. Low Mileage. Posted: 25-Oct-2019 Tags: 2016 Subaru Outback, 2016 subaru outback, Subaru Outback, subaru outback, Subaru, Outback, outback, Used Subaru								

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used SUBARU OUTBACK, SUBARU OUTBACK Singapore, used SUBARU OUTBACK Singapore, used SUBARU OUTBACK, used vehicles Singapore or even buy used SUBARU OUTBACK Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2018 09:50
Date Of Accident	05/12/2018 17:50
Exact Location Of Accident	TAMPINES LINK TOWARDS PASIR RIS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD7770A
Insured/Policyholder	
Name Of Registered Owner	HOO WEE HOON
NRIC No	S6975695F
Email Address	WH_HOO@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96752818
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	OUTBACK 2.5I-S AWD CVT
Exact Purpose for which vehicle was being used at time of accident	PERSONAL / LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	IVAN HOO TIAN YEE
NRIC No	S9934240D
Date Of Birth	28/10/1999
Occupation	INDOOR
Date Of Driving Pass	12/06/2018
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97342039
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	9 PASIR RIS DRIVE 4 #10-15
Postcode	519462
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


PLEASE REFER TO THE ATTACHED DOCUMENTS

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 5TH DEC 18, MY SON IVAN HOO TIAN YEE (S9934240D) WAS DRIVING BACK FROM CAMP.

AT APPROXIMATELY 5:50 PM, HE SWAYED AND HIT A CURB ALONG TAMPINES LINK, NEAR GOLDEN PAGODA BUDDHIST TEMPLE. ROAD CONDITION WAS WET (AFTER RAIN) THEN.

A CALL WAS MADE TO A&A AND TOW TRUCK ARRANGED TO TOW THE CAR TO MOTOR IMAGE SUBARU TOA PAYOH BRANCH FOR REPAIR AND ARRIVED AROUND 7:30 PM.

VEH A: SJD 7770A

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 06 DEC 18
10.00 AM.

GRAAACC SketchPlanForm_V9

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: DANIEL JUDE
NRIC/FIN No: S9001518D

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 06 DEC 18 10:00 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: DANIEL JUDE

MUC/IN No.: S9001518D

SUBARU AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : HOO WEE HOON
Period of Insurance : 21 Aug 2018 To 20 Aug 2019
Engine No. : FB251781368
Chassis No. : JF2BS9KC2FG011006

Vehicle No. : SJD7770A
Policy No. : 2100425995-03
Endorsement No. :
Issued Date : 03 Jul 2018

ABOUT THE COVER

Make/Model : SUBARU OUTBACK 2.5 I-S
Engine Capacity/Tonnage : 2,498.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2015
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDE") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$0 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

HOO WEE HOON

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Motor Image Enterprises Pte Ltd Add: 19 Loring @ Toa Payoh Singapore 319255 64170100

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles/Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0500619202

TAN CHONG CREDIT SUBARU-JAT
 911 BUKIT TIMAH ROAD
 SINGAPORE 599622

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

ESP000

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/1077/2018
DATE : 06-DEC-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : HOO WEE HOON
ADDRESS : 9 PASIR RIS DRIVE 4
#10-15
S(519462)
TELEPHONE NO : 96752818

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1
VEHICLE NO : SJD7770A
MODEL CODE : BS9AKLC
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT
ENGINE NO : FB251781368
CHASSIS NO : JF2BS9KC2FG011006
MILEAGE : 1 KM
DATE IN : 06/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 05/12/2018

Print Date : 06/12/2018
Print Time : 16:50:01

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJD7770A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	OD/CLAIM	CONDUCT BOOTWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AT LOCATION: TAMPINES LINK TOWARD PASIR RIS DATE: 05/12/2018 TIME: 1750HRS		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT RH FENDER AND PANEL	1000.00	500 ✓
4	ZZ/003	RESPRAY FRT BUMPER, FRT RH FENDER AND PANEL	800.00	400 ✓
5	ZZ/004	TRANSFER / BALANCE / TYRE	28.00	✓ ✓
6	ZZ/005	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	684.00	✓ ✓
7	ZZ/006	FLUSHING / BLEEDING STEERING SYSTEM	114.00	✓ ✓
8	ZZ/007	4 WHEEL ALIGNMENT	171.00	✓ ✓
9	ZZ/008	MECHANICAL REPAIRS ON STEERING PUMP	171.00	? X
10	ZZ/009	FAULT DIAGNOSTIC AND RESET SYSTEM	235.00	? ✓
11	ZZ/011	TO CONDUCT PROTECTANT COATING	250.00	200 ✓
12	ZZ/012	TO CONDUCT ANTI-RUST COATING	290.00	✓ ✓
13	ZZ/013	REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING	125.00	? X
14	ZZ/014	SUNDRIES	100.00	40 ✓
15	ZZ/10	TO CONDUCT FRONT LIGHTING TEST	28.00	✓ ✓
TOTAL LABOUR CHARGES			3996.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJD7770A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	ARM ASSY F RH	20202AL000			B ₁ 306.00	✓
2	STRUT COMPL F RH	20310AL040			R ₁ 396.00	✓
3	MOUNT STRUT F	20320AL000			T ₁ 86.40	✓
4	COIL SPRING F	20330AL050			S ₂ 93.60	7 X
5	STABILIZER F	20401AL000			D ₁ 144.00	✓
6	STABILIZER LK RH	20420AL000			R ₁ 36.00	✓
7	SEN SUB AY FT	27540AL000			Short 140.40	✓
8	RIM WHEEL AL 18 C63	28111AL030			Ref 3400.00	✓ ✓ <i>1pc 1370</i>
9	HOUSING F RH	28313AL000			R ₁ 194.40	✓
10	DRV SFT ASSY F 9222	28321AL010			R ₁ 799.20	✓
11	HUB UNIT CPL STI RH/LH	28373VA000			R ₁ 270.00	✓
12	GR BOX ASSY P/S RHD	34110AL020			B ₁ 2160.00	✓
13	COLUMN ASSY	34500AL050			SVC X B ₁ 1224.00	? ✓
14	CRADLE FRM CP ORK	50527AL030			SVC X D ₁ 1080.00	7 ✓
15	FRAME SD UPR OUT RH 51610B+51625B+51233H+51462PA/B	51609AL0209P			S ₁ 187.20	7 X
16	FRAME SD FF CP RH	51620AL0209P			S ₂ 532.80	? X
17	ENGINE UNDER COVER	56410AL050			E ₁ 162.00	X X
18	FENDER F RH	57120AL0609P			R ₁ 270.00	✓
19	FRONT BUMPER ASSY	57702AL110			M ₁ 594.00	✓
20	BRKT CORNER F PHIRH	57707AL060			C ₁ 32.40	✓
21	BRKT SD F RH	57707AL081			D ₁ 18.00	? ✓
22	BEAM COMPL F EU	57711AL0119P			R 342.40	X
23	MUD GUARD ASSY F RH	59110AL060			C ₁ 108.00	✓
24	FOG LAMP ASSY RH	84501A3060			S ₁ 272.00	X
25	GARNISH AY SD SL RH <i>raiser panel garnish</i>	91112AL460			Ref 226.80	2 ✓

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26 GARNISH AY R QTR RH	91112AL480			28.80	<i>sn</i> ? X
SUB TOTAL		0.00	0.00	0.00	13104.40
LESS DISCOUNT (S/LIST-30 %)		0.00	0.00	0.00	3931.32
GRAND TOTAL		0.00	0.00	0.00	9173.08
OVERALL TOTAL		9173.08			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJD7770A

TOTAL LABOUR CHARGES	3996.00
TOTAL SPARE PARTS CHARGES	9173.08
GRAND TOTAL	13169.08 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

16700 25

Not Notified
1-B.1
Resurvey B4 paint
disk & ulc
120

Fax: 62564315

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SJD 7770 A

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1	<u>Remove and replace mounting and reset</u>	<u>\$ 200.00 / 18k</u>
2	_____	_____
3	_____	_____
4	_____	_____
5	_____	_____
6	_____	_____
7	_____	_____
8	_____	_____
9	_____	_____
10	_____	_____
11	_____	_____
12	_____	_____



Motor Image Enterprises Pte Ltd
19 Lorong 8 Ton Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SJD 7770 A

Surveyor: _____

DESCRIPTION	PART NO	AMOUNT
1 FRAMC COMPLETE - CRADLE	50527AL030 ✓ B1 ✓	\$1,080.00 ✓
2 CLAMP - STABILIZER BUSHING	20416AL000 ✓ B1 ✓	\$1,470.00 ✓
3 BUSHING - STABILIZER	20414AL000 ✓ B1 ✓	\$1,440.00 ✓
4 CUSHION RUBBER - CENTER X2	H1022AL050 ✓ B1 ✓	\$126.00 ✓
5 CUSHION RUBBER - ENGINE 4 >	H1022AL010 ✓ B1 ✓	\$288.00 ✓
6 CUSHION RUBBER - TRANSMISSION	H1022AL040 ✓ B1 ✓	\$90.00 ✓
7 Tyre RH Front B1 90/70		\$580.00 ✓
8		
9		
10 LAMP - ASSEMBLY HEAD RIGHT	84002AL000 ✓ B1 ✓	\$1,870.00 ✓
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		

kennethkong@lkk auto

96916663.


IMPREZA
www.motorimage.net

MotorImage

MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R000968
 Name 2: HOO WEE HOON
 Company: KUGAN
 License: SJD7770A
 Year: 15
 Technician: 9 PASIR RIS DRIVE 4
 Odometer: 40473
 Date: 31.12.18 11:13

Subaru : Legacy/Outback : 2015-17 (BN/BS) : Outback : with 200mm Ground Clearance
4-Wheel Total Alignment



All diagnosis code

TEL:

FAX:

Employee in charge:

E-mail:

Date and time: 2/1/2019 10:23:41 AM

Vehicle: Legacy / Liberty / Outback

VIN: JF2BS9KC2FG011006

Model: 15MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04406	579400	Current		
Past	C1231	Rear Right ABS Sensor Circuit	04373	500	Original		**

<Body Control : 3 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04406	579400	Current		
Past	B1011	Battery Control Power Supply	00000	0	ommo		
Past	B1012	Battery Backup Power Supply	00000	0	ommo		
Past	B1014	ACC power	00000	0	ommo		

<Airbag : 0 piece>

<Power Steering : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04406	579400	Current		
Past	U0131	Lost Communication With Power Steering Control Module	01078	56200	ommo		
Past	U0128	Lost Communication With Park Brake Control Module	01078	56300	ommo		
Past	U0122	Lost Communication With Vehicle Dynamics Control Module	01078	56300	ommo		
Past	U0101	Lost Communication With TCM	01078	56300	ommo		
Past	U0100	Lost Communication With ECM/PCM "A"	01078	56200	ommo		

<Power Rear Gate : 0 piece>

<Headlight / Foglight : 2 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04406	579400	Current		
Past	U0122	Lost Communication With Vehicle Dynamics Control Module	01078	56600	ommo		**
Past	U1140	Lost Communication With Body Control Module BODY-CAN	01078	56600	ommo		

<Infotainment : 0 piece>

All diagnosis code

TEL:

FAX:

Employee in charge:

E-mail:

Date and time: 2/1/2019 10:26:23 AM

Vehicle:

Legacy / Liberty / Outback

VIN: JF2BS9KC2FG011006

Model:

15MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count (count)	Time (msec)	Group		
			04407	10500	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/1077/2018
DATE : 06-DEC-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : BOO WEE HOON
ADDRESS : 9 PASIR RIS DRIVE 4
#10-15
S(519462)
TELEPHONE NO : 96752818

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100425995-03
VEHICLE NO : SJD777QA
MODEL CODE : BS9AKLC
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT
ENGINE NO : FB251781368
CHASSIS NO : JF2BS9KC2FG011006
MILEAGE : 40473 KM
DATE IN : 06/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 3000.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 05/12/2018

Print Date : 22/02/2019
Print Time : 11:39:57

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJD7770A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	OD/CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AT LOCATION: TAMPINES LINK TOWARD PASIR RIS DATE: 05/12/2018 TIME: 1750HRS		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT RH FENDER AND PANEL	1000.00	500.00
4	ZZ/003	RESPRAY FRT BUMPER, FRT RH FENDER AND PANEL	800.00	400.00
5	ZZ/004	TRANSFER / BALANCE / TYRE	28.00	28.00
6	ZZ/005	DISMANTLE & REFLX UNDERCARRIAGE TO FACILITATE REPAIRS	684.00	684.00
7	ZZ/006	FLUSHING / BLEEDING STEERING SYSTEM	114.00	114.00
8	ZZ/007	4 WHEEL ALIGNMENT	171.00	171.00
9	ZZ/008	MECHANICAL REPAIRS ON STEERING PUMP	171.00	.00
10	ZZ/009	FAULT DIAGNOSTIC AND RESET SYSTEM	235.00	235.00
11	ZZ/011	TO CONDUCT PROTECTANT COATING	250.00	200.00
12	ZZ/012	TO CONDUCT ANTI-RUST COATING	290.00	290.00
13	ZZ/013	REMOVE/REFLX FRT HEADLAMP WASHER AND PIPING	125.00	.00
14	ZZ/014	SUNRISES	100.00	40.00
15	ZZ/015	REMOVE AND REPLACE MOUNTING AND RESET (SUPP)	200.00	200.00
16	ZZ/10	TO CONDUCT FRONT LIGHTING TEST	28.00	28.00
TOTAL LABOUR CHARGES			4196.00	2890.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJD7770A

DAMAGED PARTS & PRICES					
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1 ARM ASSY F RH	20202AL000			306.00	OK
2 STRUT COMPL F RH	20310AL040			396.00	OK
3 MOUNT STRUT F	20320AL000			86.40	OK
4 COIL SPRING F	20330AL050			93.60	X
5 STABILIZER F	20401AL000			144.00	OK
6 HUB BUSH STAB D20	20414AL000			(A) 14.40	OK
7 CLAMP STAB F	20416AL000			(A) 4.70	OK
8 STABILIZER LK RH	20420AL000			36.00	OK
9 SEN SUB AY FT	27540AL000			140.40	OK
10 RIM WHEEL AL 18 C63	28111AL030			3400.00	OK
11 HOUSING F RH	28313AL000			194.40	OK
12 DRV SFT ASSY F 9222	28321AL010			799.20	OK
13 HUB UNIT CPL STI RH/LH	28373VA000			270.00	OK
14 GR BOX ASSY P/S RED	34110AL020			2160.00	OK
15 COLUMN ASSY	34500AL050			1224.00	X
16 CUSHION HUB MAIN	41022AL010			(A) 288.00	OK
17 CUSHION HUB R CPC	41022AL040			(A) 90.00	OK
18 CUSHION HUB F ARN	41022AL050			(A) 126.00	OK
19 CRADLE FRM CP ORK	50527AL030			(A) 1080.00	OK
20 FRAME SD UPR OUT RH 51610B+51625B+51233H+51462PA/B 51609AL0209P				187.20	X
21 FRAME SD FF CP RH	51620AL0209P			532.80	X
22 ENGINE UNDER COVER	56410AL050			162.00	X
23 FENDER F RH	57120AL0609P			270.00	OK
24 FRONT BUMPER ASSY	57702AL110			594.00	OK
25 BRKT CORNER F FRHR	57707AL060			32.40	OK

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJD7770A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 BRKT SD F RH	57707AL081				18.00 OK ✓
27 BEAM COMPL F EU	57711AL0119P				342.40 X
28 MID GUARD ASSY F RH	59110AL060				108.00 OK
29 LAMP ASSY HEAD RRS	84002AL000			(DA) 1870.00	OK
30 FOG LAMP ASSY RH	84501AJ060				272.00 X
31 GARNISH AY SD SL RH	91112AL460				226.80 OK
32 GARNISH AY R QTR RH	91112AL480				28.80 X
33 RH FRONT TYRE 225/60 R18 B/S ALENZA 001 (SUPP)	T001FRE			(DA) 500.00	OK
SUB TOTAL		0.00	0.00	500.00	12654.70
LESS DISCOUNT (S/LIST-30 X)		0.00	0.00	0.00	3796.41
GRAND TOTAL		0.00	0.00	500.00	8858.29
OVERALL TOTAL		9358.29			

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LOHONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJD7770A

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	500.00
S/LIST ITEM	12654.70
LESS 30 %	-3796.41
S/LIST AMOUNT	8858.29
TOTAL LABOUR CHARGES	2890.00
TOTAL SPARE PARTS CHARGES	9358.29
TOTAL CHARGES	12248.29
LESS EXCESS	3000.00
TOTAL	9248.29
ADD 7 % GST	647.38
GRAND TOTAL	9895.67

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BOOD REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/1077/2018
DATE : 06-DEC-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHEENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : BOO WEE BOON
ADDRESS : 9 PASIR RIS DRIVE 4
#10-15
S(519462)
TELEPHONE NO : 96752818

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1
VEHICLE NO : SJD777QA
MODEL CODE : BS9AKLC
MODEL/YEAR : OUTBACK 2.5I-S AND CVT
ENGINE NO : FB251781368
CHASSIS NO : JF2B99K2P0011006
MILEAGE : 1 KM
DATE IN : 06/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 05/12/2018

Print Date : 06/12/2018
Print Time : 16:50:01

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJD7770A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AIG LOCATION: TAMPINES LINK TOWARD PASIR RIS DATE: 05/12/2018 TIME: 1750HRS		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER, FRT RH FENDER AND PANEL	1000.00	500 ✓
4	ZZ/003	RESPRAY FRT BUMPER, FRT RH FENDER AND PANEL	800.00	400 ✓
5	ZZ/004	TRANSFER / BALANCE / TYRE	28.00	✓ ✓
6	ZZ/005	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	684.00	✓ ✓
7	ZZ/006	FLUSHING / BLEEDING STEERING SYSTEM	114.00	✓ ✓
8	ZZ/007	4 WHEEL ALIGNMENT	171.00	✓ ✓
9	ZZ/008	MECHANICAL REPAIRS ON STEERING PUMP	171.00	X
10	ZZ/009	FAULT DIAGNOSTIC AND RESET SYSTEM	235.00	2 ✓
11	ZZ/011	TO CONDUCT PROTECTANT COATING	250.00	200 ✓
12	ZZ/012	TO CONDUCT ANTI-RUST COATING	290.00	✓ ✓
13	ZZ/013	REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING	125.00	?
14	ZZ/014	SUNDRIES	100.00	40 ✓
15	ZZ/10	TO CONDUCT FRONT LIGHTING TEST	28.00	✓ ✓
TOTAL LABOUR CHARGES			3996.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJD7770A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
1 ARM ASSY F RH	20202AL000			Ry 306.00	✓ -
2 STRUT COMPL F RH	20310AL040			Ry 396.00	✓ -
3 MOUNT STRUT F	20320AL000			Ry 86.40	✓ -
4 COIL SPRING F	20330AL050			93.60	?
5 STABILIZER F	20401AL000			D12 144.00	✓ -
6 STABILIZER LK RH	20420AL000			Ry 36.00	✓ -
7 SEN SUB AY FT	27540AL000			Short 140.40	✓ -
8 RIM WHEEL AL 18 C63	28111AL030			Not 3400.00	✓ → 1 PC (\$1700)
9 HOUSING F RH	28313AL000			Ry 194.40	✓ -
10 DRV SFT ASSY F 9222	28321AL010			Ry 799.20	✓ -
11 HUB UNIT CPL STL RH/LH	28373VA000			Ry 270.00	✓ -
12 GR BOX ASSY P/S RED	34110AL020			R17m 2160.00	✓ -
13 COLUMN ASSY	34500AL050			1224.00	?
14 CRADLE PYM CP ORK	50527AL030			1080.00	?
15 FRAME SD UPR OUT RH 51610B+51625B+51233E+51462PA/B 51609AL0209P				187.20	?
16 FRAME SD FF CP RH	51620AL0209P			532.80	?
17 ENGINE UNDER COVER	56410AL050			R 162.00	X
18 FENDER F RH	57120AL0609P			Ry 270.00	✓ -
19 FRONT BUMPER ASSY	57702AL110			m3m 594.00	✓ -
20 BRKT CORNER F PHIRH	57707AL060			CM 32.40	✓ -
21 BRKT SD F RH	57707AL081			18.00	✓ ? -
22 BEAM COMPL F EU	57711AL0119P			R 342.40	X
23 MID GUARD ASSY F RH	59110AL060			CM 108.00	✓ -
24 FOG LAMP ASSY RH	84501AJ060			Sm 272.00	X
25 GARNISH AY SD SL RH	91112AL460			Roll over 226.80	✓ -

radio panel garnish

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJD7770A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	GARNISH AY R QTR RH	91112AL480				28.80 ?
SUB TOTAL			0.00	0.00	0.00	13104.40
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	3931.32
GRAND TOTAL			0.00	0.00	0.00	9173.08
OVERALL TOTAL			9173.08			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTOCIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJD7770A

TOTAL LABOUR CHARGES	3996.00
TOTAL SPARE PARTS CHARGES	9173.08
GRAND TOTAL	13169.08 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAIM	: 0.00
LIABILITY	: 0.00
REMARKS	:

+5
6 DAYS

Not Notified
1-B.1
Returning B4 paint

also & me

12/1

Fax: 62564315

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

**Motor Image Enterprises Pte Ltd**

19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535
25 Leng Kee Road Singapore 159097
Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137
Website: www.motorimage.net

**TAX INVOICE**

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L508903

**For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.**

DATE REC'D: 19-Dec-2018

SERVICE ADVISOR: HOOI

JOB No.: L493397

MILEAGE: 40473

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: OUTBACK 2.5I-S AWD CVT
ENGINE No.: FB251781368
CHASSIS No.: JF2BS9KC2FG011006
REGISTRATION No.: SJD7770A

ITEMS	CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	ODCLAI	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)	
2	REMARK	CONDUCT OD CLAIM AIG DATE:05/12/2018 TIME:1750HRS LOCATION:TAMPINES LINK	
3	INS01	FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
4	INS02	IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	
5	INS03	STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
6	INS04	SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
7	INS05	INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
8	INS06	THE OWNER IS REQUIRED.	
9	INS07	CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
10	INS08	NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
11	INS09	CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
12	REMARK	REPAIR/REPLACE FRT BUMPER,FRT RH ENDER AND PANEL	500.00
13	REMARK	RESPRAY FRT BUMPER,FRT RH FENDER AND PANEL	400.00
14	REMARK	TRANSFER/BALANCE/TYRE	28.00
15	REMARK	DISMENTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	684.00
16	REMARK	FLUSHING/BLEEDING STREERING SYSTEM	114.00
17	REMARK	4 WHEEL ALIGMENT	171.00
18	REMARK	FAULT DIAGNOSTIC AND RESET SYSTEM	235.00
19	REMARK	TO CONDUCT PROTECTANT COATING	200.00

Certified True Copy



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh Singapore 319255
 Service Centre Tel (65) 64170100/101 Fax (65) 62535535
 25 Leng Kee Road Singapore 159097
 Service Centre Tel (65) 64764776 Fax (65) 64791137
 Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER
Invoice No: L508903

For cash sales, payment will be
 endorsed on this invoice and no
 separate receipt will be issued.

DATE REC'D: 19-Dec-2018
SERVICE ADVISOR: HOOI
JOB No.: L493397
MILEAGE: 40473
ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
 #07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: OUTBACK 2.5I-S AWD CVT
ENGINE No.: FB251781368
CHASSIS No.: JF2BS9KC2FG011006
REGISTRATION No.: SJD7770A

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
20	REMARK TO CONDUCT ANTI RUST COATING	290.00
21	REMARK SUNDRIES	40.00
22	REMARK REMOVE AND REPLACE MOUNTING AND RESET	200.00
23	REMARK TO CONDUCT FRONT LIGHTING TEST	28.00
	TOTAL(LABOUR)	2,890.00
1	ARM ASSY F RH	214.20
	20202AL000(Qty : 1 @ 306.00 each(Discount 30.00%))	
2	STRUT COMPL F RH	277.20
	20310AL040(Qty : 1 @ 396.00 each(Discount 30.00%))	
3	MOUNT STRUT F	60.48
	20320AL000(Qty : 1 @ 86.40 each(Discount 30.00%))	
4	STABILIZER F	100.80
	20401AL000(Qty : 1 @ 144.00 each(Discount 30.00%))	
5	RUB BUSH STABI D20 *2	10.08
	20414AL000(Qty : 1 @ 14.40 each(Discount 30.00%))	
6	CLAMP STAB F	3.29
	20416AL000(Qty : 1 @ 4.70 each(Discount 30.00%))	
7	STABILIZER LK RH	25.20
	20420AL000(Qty : 1 @ 36.00 each(Discount 30.00%))	
8	SEN SUB AY FT	98.28
	27540AL000(Qty : 1 @ 140.40 each(Discount 30.00%))	
9	RIM WHEEL AL 18 C63 OBK	2,380.00
	28111AL030(Qty : 1 @ 3400.00 each(Discount 30.00%))	
10	HOUSING F RH	136.08
	28313AL000(Qty : 1 @ 194.40 each(Discount 30.00%))	
11	DRV SFT ASSY F 9222	559.44
	28321AL010(Qty : 1 @ 799.20 each(Discount 30.00%))	
12	HUB UNIT CPL STI RH/LH	189.00

Certified True Copy

**Motor Image Enterprises Pte Ltd**

19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net

**TAX INVOICE**

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER**Invoice No: L508903**

For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.

DATE REC'D: 19-Dec-2018**SERVICE ADVISOR: HOOI****JOB No.: L493397****MILEAGE: 40473****ID:**

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: OUTBACK 2.5I-S AWD CVT
ENGINE No.: FB251781368
CHASSIS No.: JF2B59KC2FG011006
REGISTRATION No.: SJD7770A

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
13	28373VA000(Qty : 1 @ 270.00 each(Discount 30.00%)) GR BOX ASSY P/S RHD	1,512.00
14	34110AL020(Qty : 1 @ 2160.00 each(Discount 30.00%)) CUSHION RUB MAIN *2	201.60
15	41022AL010(Qty : 1 @ 288.00 each(Discount 30.00%)) CUSHION RUB R CFC	63.00
16	41022AL040(Qty : 1 @ 90.00 each(Discount 30.00%)) CUSHION RUB F ARN	88.20
17	41022AL050(Qty : 1 @ 126.00 each(Discount 30.00%)) CRADLE FRM CP OBK	756.00
18	50527AL030(Qty : 1 @ 1080.00 each(Discount 30.00%)) FENDER F RH	189.00
19	57120AL0609P(Qty : 1 @ 270.00 each(Discount 30.00%)) FRONT BUMPER ASSY	415.80
20	57702AL110(Qty : 1 @ 594.00 each(Discount 30.00%)) BRKT CORNER F FHIRH	22.68
21	57707AL060(Qty : 1 @ 32.40 each(Discount 30.00%)) BRKT SD F RH	12.60
22	57707AL081(Qty : 1 @ 18.00 each(Discount 30.00%)) MUD GUARD ASSY F RH	75.60
23	59110AL060(Qty : 1 @ 108.00 each(Discount 30.00%)) LAMP ASSY HEAD RHS	1,309.00
24	84002AL000(Qty : 1 @ 1870.00 each(Discount 30.00%)) GARNISH AY SD SL RH	158.76
25	91112AL460(Qty : 1 @ 226.80 each(Discount 30.00%)) RH FRONT TYRE 225/60 R18 B/S ALENZA 001	500.00
	T001FRH(Qty : 1 @ 500.00 each)	
	TOTAL(SPARE PARTS)	9,358.29

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L508903

**For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.**

DATE REC'D: 19-Dec-2018

SERVICE ADVISOR: HOOI

JOB No.: L493397

MILEAGE: 40473

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: OUTBACK 2.5I-S AWD CVT
ENGINE No.: FB251781368
CHASSIS No.: JF2BS9KC2FG011006
REGISTRATION No.: SJD7770A

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
	less INSURANCE EXCESS	3,000.00

Subtotal	9,248.29
GST(7%)	647.38
TOTAL	\$9,895.67

DATE : 26-Dec-2019

CUSTOMER



MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice falling which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
T (65) 6417 0333 F (65) 6252 5655
W www.motorimage.net

Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured: HOO WEE HOON
Address of Insured: 9 PASIR RIS DRIVE 4 #10-15 S(519462)
Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP
Address of Repairs: NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225
Place of Accident: TAMPINES LINK TOWARD PASIR RIS
Date of Accident: 05/12/2018 Vehicle No: SJD7770A
Policy No: 2100425995-03 Claim No: _____

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of AIG ASIA PACIFIC INS P.L. settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.

I/We further agree to furnish the said insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:



Company's Chop & Signature

INSURED:

S6975695F

IC No. & Signature/Company's Chop

DANIEL JUDE

Name

HOO WEE HOON

Name

09/01/2019

Date

09/01/2019

Date

MotorImage

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018 15:01		07 Dec 2018 11:53 Edit Adj Rpt	S\$12,248.29 Edit Estimates	S\$12,248.29 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: HOO WEE HOON , ID: S6975695F, Tel: +6596752818									
Vehicle Reg. No.:	SJD7770A	Date of Loss:	05/12/2018 17:00 - :59 [39 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 71410707845G	Policy/Cover Note No.:	2100425995 (Comprehensive)						
		Excess:	S\$3,000.00						
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/12/2018]								
Driver/Custodian:	IVAN HOO TIAN YEE (19 / Male), NRIC: S9934240D, Tel: +6597342039 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (05/12/2019): Alert - Adj Mandate Approved (S\$12248.29) - SJD7770A - Claim Handler: Loo, Tong ... - AIG_SG (05/12/2019): Alert - Adj Mandate Maintained - SJD7770A - Claim Handler: Loo, Tong Shing - AIG_SG (02/07/2019): Alert - Adj Mandate Maintained - SJD7770A - Claim Handler: Loo, Tong Shing - AIG_SG (03/06/2019): Alert - Adj Mandate Maintained - SJD7770A - Claim Handler: Loo, Tong Shing - AIG_SG (17/12/2018): Alert - Adj Mandate Approved (S\$8870.00) - SJD7770A - Claim Handler: Loo, Tong S... - AIG_SG (17/12/2018): SJD7770A / OD / 05/12/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJD7770A (7141070784SG)
 OD
 Dec 5 2018 5:00PM
 [HOO WEE HOON]
 Motor Image Enterprises Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Assessment Reports										1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	10/12/18 15:08	Adjuster Immediate Advice								 Load HTM		☒	
Photos/Images										3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	10/12/18 14:57	General View								 Load JPG		☒	
2	10/12/18 14:57	General View								 Load JPG		☒	
3	10/12/18 14:57	General View								 Load JPG		☒	
4	10/12/18 14:57	General View								 Load JPG		☒	
5	10/12/18 14:57	General View								 Load JPG		☒	
6	10/12/18 14:57	General View								 Load JPG		☒	
7	10/12/18 14:57	General View								 Load JPG		☒	
8	10/12/18 14:57	General View								 Load JPG		☒	
9	10/12/18 14:57	General View								 Load JPG		☒	
10	10/12/18 14:57	General View								 Load JPG		☒	
11	10/12/18 14:57	General View								 Load JPG		☒	
12	10/12/18 14:57	General View								 Load JPG		☒	
13	10/12/18 14:57	General View								 Load JPG		☒	
14	10/12/18 14:57	General View								 Load JPG		☒	
15	10/12/18 14:57	General View								 Load JPG		☒	
16	10/12/18 14:57	General View								 Load JPG		☒	
17	10/12/18 14:57	General View								 Load JPG		☒	
18	10/12/18 14:57	General View								 Load JPG		☒	
19	10/12/18 14:57	General View								 Load JPG		☒	
20	10/12/18 14:57	General View								 Load JPG		☒	
21	10/12/18 14:57	General View								 Load JPG		☒	
22	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
23	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
24	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
25	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
26	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
27	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
28	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
29	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
30	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
31	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
32	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
33	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
34	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
35	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
36	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
37	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
38	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
39	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
40	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	
41	30/05/19 10:27	Reinspection Photo								 Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
42	30/05/19 10:27	Reinspection Photo	 Load JPG	☒
43	30/05/19 10:27	Reinspection Photo	 Load JPG	☒
44	03/12/19 14:46	Reinspection Photo	 Load JPG	☒
45	03/12/19 14:46	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/12/18 14:56	Driver's Driving License and NIRC	 Load PDF	
2	10/12/18 14:56	estimate	 Load PDF	
3	10/12/18 14:56	Singapore Accident Statement	 Load PDF	
4	10/12/18 14:56	Driver's Driving License and Army ID	 Load PDF	
5	17/12/18 08:35	UNDERTAKING LETTER	 Load PDF	
6	17/12/18 08:35	INTERVIEW FORM	 Load PDF	
7	30/05/19 10:03	ESTIMATE	 Load PDF	
8	30/05/19 10:03	SUPPLEMENTARY	 Load PDF	
9	05/12/19 14:30	LTA LOG CARD	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	03/09/19 23:07	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	06/12/18 10:35	Accident Photo	 Load JPG	☒
2	06/12/18 10:35	Accident Photo	 Load JPG	☒
3	06/12/18 10:35	Accident Photo	 Load JPG	☒
4	06/12/18 10:35	Accident Photo	 Load JPG	☒
5	06/12/18 10:35	Accident Photo	 Load JPG	☒
6	06/12/18 10:35	Accident Photo	 Load JPG	☒
7	06/12/18 10:35	Accident Photo	 Load JPG	☒
8	06/12/18 10:35	Accident Photo	 Load JPG	☒
9	06/12/18 10:35	Accident Photo	 Load JPG	☒
10	06/12/18 10:35	Accident Photo	 Load JPG	☒
11	06/12/18 10:36	Accident Photo	 Load JPG	☒
12	06/12/18 10:36	Accident Photo	 Load JPG	☒
13	06/12/18 10:36	Accident Photo	 Load JPG	☒
14	06/12/18 10:36	Accident Photo	 Load JPG	☒
15	06/12/18 10:36	Accident Photo	 Load JPG	☒
16	06/12/18 10:36	Accident Photo	 Load JPG	☒
17	06/12/18 10:36	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	06/12/18 10:40	Accident Sketch Plan	 Load JPG	☒
2	06/12/18 10:40	Accident Sketch Plan	 Load JPG	☒
3	06/12/18 10:41	OWNER LICENSE AND NRIC	 Load JPG	☒
4	06/12/18 10:41	DRIVER NRIC	 Load JPG	☒
5	06/12/18 10:41	DRIVER LICENSE	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG18022022/KTBE2

Date: 09/01/2020

REFERENCE

Insured/Claimant:	HOO WEE HOON	Policy No:	2100425995	
Date of Loss:	05/12/2018	Nature of Claim:	OD	Claim No: 7141070784SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD7770A		
Make & Model:	SUBARU OUTBACK, 2.5 I-S CVT AWD SR (A)	Engine No:	FB251781368
Reg. Date:	21/08/2015 (Man. Year: 2015)	Chassis No:	JF2BS9KC2FG011006
Colour:	Metallic Pearl White	Odometer:	0 km
Engine Capacity:	2498 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,204.25	9,398.29	2,805.96	22.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,096.00	2,850.00	1,246.00	30.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,300.25	12,248.29	4,051.96	24.86
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	13,300.25	9,248.29	4,051.96	30.47
+ GST 7.00/7.00% (S\$)	931.02	647.38	283.64	30.47
Nett Amount (S\$)	14,231.27	9,895.67	4,335.60	30.47

INSPECTION

Date of Assignment: 07/12/2018

Date Inspected: 07/12/2018 Inspected At:

Motor Image Enterprises Pte Ltd (Toa Payoh)
19 Lorong 8 Toa Payoh
Singapore 319255

Estimated Period of Repair: 11.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*40.00 FS
2	1		*ARM ASSY F RH	Bent	306.00 FL	*306.00 FL
3	1		*STRUT COMPL F RH	Bent	396.00 FL	*396.00 FL
4	1		*MOUNT STRUT F	Torn	86.40 FL	*86.40 FL
5	1		*COIL SPRING F	Serviceable	93.60 FL	*- FL
6	1		*STABILIZER F	Distorted	144.00 FL	*144.00 FL
7	1		*STABILIZER LK RH	Bent	36.00 FL	*36.00 FL
8	1		*RIM WHEEL AL 18 C63	Dented	3,400.00 FL	*3,400.00 FL
9	1		*HOUSING F RH	Bent	194.40 FL	*194.40 FL
10	1		*DRV SFT ASSY F 9222	Bent	799.20 FL	*799.20 FL
11	2		*HUB UNIT CPL STI RH / LH	Bent	270.00 FL	*270.00 FL
12	1		*GR BOX ASSY P/S RHD	Bent / Jammed	2,160.00 FL	*2,160.00 FL
13	1		*COLUMN ASSY	Serviceable	1,224.00 FL	*- FL
14	1		*CRADLE FRM CP OBK	Serviceable	1,080.00 FL	*- FL
15	1		*FRAME SD UPR OUT RH 51610B+51625B+51233H+51462PA/B	Serviceable	187.20 FL	*- FL
16	1		*FRAME SD FF CP RH	Serviceable	532.80 FL	*- FL
17	1		*ENGINE UNDER COVER	Serviceable	162.00 FL	*- FL
18	1		*FENDER F RH	Bent	270.00 FL	*270.00 FL
19	1		*FRONT BUMPER ASSY	Mtg Cracked	594.00 FL	*594.00 FL
20	1		*BRKT CORNER F FHIRH	Cracked	32.40 FL	*32.40 FL
21	1		*BRKT SD F RH	Distorted	18.00 FL	*18.00 FL
22	1		*BEAM COMPL F EU	Repair	342.40 FL	*- FL
23	1		*MUD GUARD ASSY F RH	Cracked	108.00 FL	*108.00 FL
24	1		*FOG LAMP ASSY RH	Serviceable	272.00 FL	*- FL
25	1		*GARNISH AY SD SL RH (ROCKER PANEL GARNISH)	Dented / Cut	226.80 FL	*226.80 FL
26	1		*GARNISH AY R QTR RH	Serviceable	28.80 FL	*- FL
27	1		*CLAMP - STABILIZER BUSHING	Distorted	4.70 FL	*4.70 FL
28	1		*BUSHING-STABILIZER	Distorted	14.40 FL	*14.40 FL
29	1		*CUSHION RUBBER - CENTER	Distorted	126.00 FL	*126.00 FL
30	2		*CUSHION RUBBER - ENGINE	Punctured	288.00 FL	*288.00 FL
31	1		*CUSHION RUBBER - TRANSMISSION	Punctured	90.00 FL	*90.00 FL
32	1		*LAMP - ASSEMBLY HEAD RIGHT	Mtg Cracked	1,870.00 FL	*1,870.00 FL
33	1		*TYRE RH FRONT	Punctured	500.00 FS	*500.00 FS
34	1		*SEN SUB AY FT	Shorted	140.40 FL	*140.40 FL
35	1		*FRAME COMPLETE - CRADLE	Bent	1,080.00 FL	*1,080.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,177.50 13,194.70

- List Item Discount on L Items 30.00/30.00% (\$\$) 4,973.25 3,796.41

Total Parts (\$\$) 12,204.25 9,398.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE FRT BUMPER, FRT RH FENDER AND PANEL	New	1,000.00	500.00
2	TRANSFER / BALANCE / TYRE	New	28.00	28.00
3	DISMENTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	New	684.00	684.00
4	FLUSHING / BLEEDING STEERING SYSTEM	New	114.00	114.00
5	4 WHEEL ALIGNMENT	New	171.00	171.00
6	MECHANICAL REPAIRS ON STEERING PUMP	New	171.00	0.00
7	FAULT DIAGNOSTIC AND RESET SYSTEM	New	235.00	235.00
8	TO CONDUCT PROTECTANT COATING	New	250.00	200.00
9	TO CONDUCT ANTI-RUST COATING	New	290.00	290.00
10	REMOVE / REFIX FRT HEADLAMP WASHER AND PIPING	New	125.00	0.00
11	TO CONDUCT FRONT LIGHTING TEST	New	28.00	28.00
12	REMOVE AND REPLACE MOUNTING AND RESET	New	200.00	200.00
13	RESPRAY FRT BUMPER, FRT RH FENDER AND PANEL	New	800.00	400.00
Gross Labour Cost (S\$)			4,096.00	2,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >