

22/03/2007

ASS. REC. BY:

REF: CS3/III18022068/ Jcd3<sup>sr</sup> Special Instruction:

Surveyor

Momen

Hwee Jie

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

07/12/18 @ 3.56pm.

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBE 8030K

Insured:

SHD 362SL

at Workshop m/s

GP Motoring

Tel:

90618091

of

282 Macpherson Rd

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

10/12/18

H.O.D. Endorsement:

Date/Time:

4.28pm @ 7/12/18

Person Contacted:

Mr. Ken

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBE 8030K-X

SHD 362SL - CS3/III18016089/71cbe2

Don: 2/9/2018

After repair: 13/12/2018 @ 5pm.

PRs

REF:

III

Hwee Jia

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop m/s 282 Macpherson Rd

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBE 8030K Yr Regn: 21 Sep 2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Sport 7135 C.C. 135

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 20395 T/Ratio: Insured / Std / NI / NA

Eng/No: -

C/No: SYP302782

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 9 Rim / STD A/Rim or

Tyre Size: F: 70/90-17

R: 80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: - mm L/Bal: - mm

D.O.A. 1/12/18 D.O.I. 10/12/18

Survey held at GP Motoring

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

\* Knock o/s, fall n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair range \$2600 - \$3500

18/12/2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Y 3 + RS \$

Photos

Taxes

TOTAL

Report Format: PRE.

Lump Sum / I.B.I. / \$

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Friday, 7 December 2018 3:56 PM  
**To:** Alfred Ng; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Manivel Priyadarshini  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBE8030K (Accident involving FBE8030K and SHD3625L on 01.12.2018)  
**Attachments:** shd3625L\_20181207114601.pdf

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : FBE8030K  
III INSURED VEHICLE NO. : SHD3625L  
DATE OF LOSS : 01.12.18

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Priya.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Alfred Ng [mailto:alfred\_ng@juseq.com.sg]  
**Sent:** 07 December, 2018 2:39 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** Fw: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBE8030K (Accident involving FBE8030K and SHD3625L on 01.12.2018)

Your ref: SHD3625L

Our ref: JEQ/180946/1218/GP/PI

Dear Sir,

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Delta V Consultant;
5. Prominent Appraisal Services Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;
8. S K Auto Consultants;
9. Oh Appraisal Services;
10. KAAS.

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

**GP Motoring Pte Ltd**

**282 Macpherson Road**

**Singapore 348607**

**Tel: 6746-4240 Mobile: 9061-8091.**

**Fax: 6746-4596**

**Person In charge : Mr. Ken Sim**

\* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11

With Regards

Alfred Ng  
Executive  
On behalf of Mr Michael Yap  
M/s JusEquity Law Corporation  
No. 171 Chin Swee Road  
#02-01/02/06 Singapore 169877  
Tel : 6536 9339  
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential

information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

----- Original Message -----

**From:** [claims@juseq.com.sg](mailto:claims@juseq.com.sg)

**To:** [alfred\\_ng@juseq.com.sg](mailto:alfred_ng@juseq.com.sg)

**Sent:** Friday, December 07, 2018 12:01 PM

**Subject:** FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBE8030K (Accident involving FBE8030K and SHD3625L on 01.12.2018)

---

**From:** Motor Claim - III [[mailto:motorclaim@iii.com.sg](mailto:mailto:motorclaim@iii.com.sg)]

**Sent:** Friday, December 7, 2018 11:56 AM

**To:** [claims@juseq.com.sg](mailto:claims@juseq.com.sg)

**Subject:** PRE-REPAIR INSPECTION FOR VEHICLE NO. FBE8030K (Accident involving FBE8030K and SHD3625L on 01.12.2018)

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached

you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



# JusEquity Law Corporation

**ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS**

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone (65) 6536 9338,

Email : [clalma@juseq.com.sg](mailto:clalma@juseq.com.sg)

Fax : (65) 6536 5368 (Litigation & Conveyancing)

website : [www.juseq.com.sg](http://www.juseq.com.sg)

Our Ref: JEQ/FBE8030K/GP/PI (zl)

Your Ref: SHD3625L

7 December 2018

**COMFORT TRANSPORTATION PTE LTD**

383 Sin Ming Drive

GAS Building

Singapore 575717

By Post Only

**INDIA INTERNATIONAL INSURANCE PTE LTD**

Singapore

By Fax: 6224 4174 Only

Dear Sir

**ACCIDENT INVOLVING FBE8030K & SHD3625L ON 01.12.2018**

We act for the owner of vehicle no. FBE8030K.

We hereby notify you of a road traffic accident on **1 December 2018** at about 2310 hrs, along Kramat Road involving our client's vehicle and vehicle registration no. **SHD3625L** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.



**CONFIDENTIALITY CAUTION**

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

MVA218157710 / VAC - Sin Ming  
ENTRY DATE & TIME: 06/12/2018 11:47  
SUBMITTED BY: James Ng Wing Kin

Your NCD will be affected due to late reporting  
Actual e-Filing Submission Date & Time: 07/12/2018 09:26

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 06/12/2018 11:47  
Date Of Accident 01/12/2018 23:10  
Exact Location Of Accident KRAMAT ROAD  
Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number FBE8030K  
Insured/Policyholder  
Name Of Registered Owner MOHAMMAD MAHFUDZ BIN KAYMI  
NRIC No S8204953C  
Email Address FUDZZY\_92@YAHOO.COM  
Mobile Phone No (LOCAL) +65-98365733  
Alternative Phone No OFFICE-98365733  
Vehicle Particulars  
Manufacturer YAMAHA  
Model T135  
Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category MOTORCYCLE  
Insurance Company  
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
Fleet Policy NO  
Policy Number 5105547336  
Cover Note Number

## Driver

Name of Driver MOHAMMAD MAHFUDZ BIN KAYMI  
NRIC No S8204953C  
Date Of Birth 08/02/1982  
Occupation INDOOR  
Date Of Driving Pass 03/03/2004  
Driving Experience 14 YEARS AND 8 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-98365733  
Fax Number  
Contact Number OFFICE-98365733  
Email Address FUDZZY\_92@YAHOO.COM

Address BLK 613 #12-483 WOODLANDS AVENUE 4  
 Postcode 730613  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name WOODLANDS EAST N.P.C  
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63, POSTCODE: 737890, COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of Intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER POLICE REPORT REMARK: REPORTED LATE DUE TO MEDICAL REASONS. (ATTENDED BY: JAMES NG)

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHD3625L  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category TAXI  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

## DETAILS OF INJURED PERSON 1

Name	MOHAMMAD MAHFUDZ BIN KAYMI
Approximate Age	36
Injuries Sustain	SWELLING ON FINGERS AND PALM, SUSPECTED HEAD INJURY, ABRASIONS ON RIGHT LEG AND LEFT HAND
Injured person in which vehicle?	FBE8030K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 613 #12-483 WOODLANDS AVENUE 4
Postcode	730813

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

06 DEC 2018

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: NG WING KIN JAMES  
NRIC/FIN No.: S7927881E



## Sketch Plan #2 Pg. 1

### SKETCH PLAN

REAL LEFT LOGIC OVEN

A. 1-15 802K

B. 1-15 802K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer  
Police  
Report

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time:

06 DEC 2018

Driver's Signature

(If driver is not the policyholder)

**Date & Time:**



Reporting Centro Personnel's Signature

Name: \_\_\_\_\_

NRG/FIN No.:

NG WING KIN JAMES

**S7927881E**

## Sketch Plan #3 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20181205/2162

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

1 of 3

Report No. T/20181205/2162

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/12/2018 21:34		Vide Report No.:		Station Diary No.: 240	
Name of Informant: MOHAMMAD MAHFUDZ BIN KAYMI					
ID Type / ID No.: NRIC NO / S8204953C		Address: APT BLK 613 WOODLANDS AVENUE 4 #12-483 SINGAPORE 730613			
Nationality: SINGAPORE CITIZEN		Contact No.: Home/Office: Mobile: 98365733			
Sex: Male		Age: 36		Date of Birth: 08/02/1982	
Race: Malay		Type of Informant: Rider		Language:	
Occupation: QA EXECUTIVE		Driving Licence Information: Class: 2B,2A,3		Institution / School Name: Date of Expiry:	

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/12/2018 23:10	Type of Location:
Location: Along Road 1 KRAMAT ROAD Below the ERP Gantry				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Opening car door against motorcyclist			Anyone conveyed by ambulance: Yes	

FBE8030K	Motorcycle	YAMAHA	T135	Black	Slightly Damaged	0
SHD3625L	Taxi				Slightly Damaged	2

FBE8030K	NTUC Income Insurance Co-Operative Limited	5105547338	15/11/2018	21/09/2019
----------	--	------------	------------	------------

## Sketch Plan #4 Pg. 1



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999



T/20181205/2162

2 of 3

Report No. T/20181205/2162

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	MOHAMMAD MAHFUDZ BIN KAYMI	ID No.	S8204953C
Related Vehicle	FBE8030K (Motorcycle)	Contact No.	98365733
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	01/12/2018	Date Discharge	02/12/2018
No. of Days granted Medical Leave	06	Degree of Injury	Slight

Brief Details.

On 01/12/2018 at about 11.10pm, I was riding motorcycle, FBE8030K along Kramat Road. Traffic was heavy.

There was a taxi, SHD3625L which had stopped in the middle of the lane due to traffic congestion. I then try to move pass the left side of the taxi as there was no room on the right side. While passing the taxi, the left rear passenger door suddenly opened and hit my right arm. Due to the impact, I fell down from my motorcycle.

I sustained injuries on my right arm and right leg. Ambulance was at scene and I was conveyed to Tan Tock Seng Hospital for treatment. I was given 6 days Outpatient Medical Leave as a result.

## Sketch Plan #5 Pg. 1

**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999



T/20181205/2162

3 of 3

Report No. T/20181205/2182

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sgt 3 ROGER ONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MA JUNXIANG

Contact No.: 65476251

Authentication Stamp

NP168

Singapore

Signature Of Informant:

Date/Time:

05/12/2018 21:34

Classification Of Case:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4953C
<b>Vehicle Details</b>	
Vehicle No.:	FBE8030K
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2018
Vehicle Make:	YAMAHA
Vehicle Model:	T135
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	5YP302782
Chassis No.:	5YP302782
Maximum Power Output:	-
Open Market Value:	\$1,800.00
Original Registration Date:	21 Sep 2010
First Registration Date:	21 Sep 2010
Transfer Count:	7
Actual ARF Paid:	\$270.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	20 Sep 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,502.00
COE Rebate Amount:	\$267.00
<b>Total Rebate Amount:</b>	<b>\$267.00</b>

The information contained herein is correct as at 10 Dec 2018

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Dec 2018 10:10 <a href="#">Edit Reg</a>		07 Dec 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	<b>MOHAMMAD MAHFUDZ BIN KAYMI</b> , ID: S8204953C		
Vehicle Reg. No.:	<b>FBE8030K</b>	Date of Loss:	01/12/2018 23:00 - :59 [98 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	<b>SHD3625L</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>GP MOTORING PTE LTD (HQ)</b> 282 Macpherson Road, 348607 Macpherson - Tel: 67464240		
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Priya</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 18/12/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.





































## Claim Documents

\*FBE8030K  
[SHD3625L]  
TP  
MOHAMMAD MAHFUDZ BIN KAYMI  
Dec 1 2018 11:00PM  
[-]  
GP MOTORING PTE LTD

Upload Documents   Upload Photos   Compose New Letter

View   View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/12/18 16:56	General View	 Load JPG	✓
2	10/12/18 16:56	General View	 Load JPG	✓
3	10/12/18 16:56	General View	 Load JPG	✓
4	10/12/18 16:56	General View	 Load JPG	✓
5	10/12/18 16:56	General View	 Load JPG	✓
6	10/12/18 16:56	General View	 Load JPG	✓
7	10/12/18 16:56	General View	 Load JPG	✓
8	10/12/18 16:56	General View	 Load JPG	✓
9	10/12/18 16:56	General View	 Load JPG	✓
10	10/12/18 16:56	General View	 Load JPG	✓
11	10/12/18 16:56	General View	 Load JPG	✓
12	10/12/18 16:56	General View	 Load JPG	✓
13	10/12/18 16:56	General View	 Load JPG	✓
14	10/12/18 16:56	General View	 Load JPG	✓
15	10/12/18 16:56	General View	 Load JPG	✓
16	10/12/18 16:56	General View	 Load JPG	✓
17	10/12/18 16:56	General View	 Load JPG	✓
18	10/12/18 16:56	General View	 Load JPG	✓
19	10/12/18 16:56	General View	 Load JPG	✓
20	10/12/18 16:56	General View	 Load JPG	✓
21	10/12/18 16:56	General View	 Load JPG	✓
22	10/12/18 16:56	General View	 Load JPG	✓
23	10/12/18 16:56	General View	 Load JPG	✓
24	10/12/18 16:56	General View	 Load JPG	✓
25	10/12/18 16:56	General View	 Load JPG	✓
26	10/12/18 16:56	General View	 Load JPG	✓
27	17/12/18 09:37	Photo After Spray	 Load JPG	✓
28	17/12/18 09:37	Photo After Spray	 Load JPG	✓
29	17/12/18 09:37	Photo After Spray	 Load JPG	✓
30	17/12/18 09:37	Photo After Spray	 Load JPG	✓
31	17/12/18 09:37	Photo After Spray	 Load JPG	✓
32	17/12/18 09:37	Photo After Spray	 Load JPG	✓
33	17/12/18 09:37	Photo After Spray	 Load JPG	✓
34	17/12/18 09:37	Photo After Spray	 Load JPG	✓
35	17/12/18 09:37	Photo After Spray	 Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	17/12/18 09:37	Photo After Spray	 Load JPG	✓
37	17/12/18 09:37	Photo After Spray	 Load JPG	✓
38	17/12/18 09:37	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/12/18 08:55	Singapore Accident Statement	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18022068/JCD3S2

Date: 24/12/2018

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : FBE8030K

Insured Vehicle No : SHD3625L

Date of Loss: 01/12/2018

Nature of Claim: TP Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBE8030K

Make &amp; Model: YAMAHA T135, 135cc

Engine No: 5YP302782

Reg. Date: 21/09/2010 (Man. Year: 2010)

Chassis No: 5YP302782

Colour: Red

Odometer: 20395 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size: 80/90-17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 07/12/2018

Date Inspected: 10/12/2018

Inspected At:

GP MOTORING PTE LTD (HQ)  
282 Macpherson Road  
Singapore 348607

Estimated Period of Repair: 0.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,600.00 - \$3,500.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 Dec 2018)	
<b>Parts:</b>	N/A	YAMAHA T135 135cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBE8030K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >