



Case Details

Case Reference Number : BUS/12/18/1004
 Type of Repair : Accident Repair
 Vehicle Registration Number : SG1180U

Company Type : SMRT Buses Ltd
 Estimation ID : EST-4842-ID
 Assigned By : Audrey Woo Yee Shin

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 04/12/2018 01:15 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	VE	6010013	LAMP,BLINKER:RH,FOR MB CITARO O530 BUS	1	68.61	68.61	0.00	68.61	Replace	1	68.61	Replace ▾
Total Spare Part Cost									68.61		Surveyor Total	68.61	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									68.61		Final Sur Total	68.61	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	795	
Total:		1,325.00	795.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	528	
Total:		616.00	528.00	


Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

Summary

Estimator Assesment(\$)

Surveyor Assesment(\$)

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	68.61	68.61
Total Labour Cost	1,325.00	795.00
Total Spray Painting	616.00	528.00
Other	0.00	0.00
Overall Total	2,009.61	1,391.61
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,391.61
Surveyor Approved Amount		1,391.61
No of Repair Days*	3	2
Remarks	-	resurvey after repair / lump sum
Surveyor Name		Rasul
Signature		 Save Clear
Survey Date	06/12/2018	