



Case Details

Case Reference Number : BUS/12/18/1008
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB8036E

Company Type : SMRT Buses Ltd
 Estimation ID : EST-4843-ID
 Assigned By : Bus Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 04/12/2018 11:42 PM
 Vehicle Age(In Months) : 37

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	Body	6010152	COVER,HEADLAMP:FRT,RH,FOR MAN A22 BUS	1	974.70	974.70	0.00	974.70	Replace	1	974.70	Replace ▾
One Time Key In	Main			STICKER SMRT	1	75.00	75.00	0.00	75.00	Replace	1	75.00	Replace ▾
Total Spare Part Cost									1,049.70		Surveyor Total	1,049.70	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									1,049.70		Final Sur Total	1,049.70	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	795	
Total:		1,060.00	795.00	


Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	528.00	446	
Total:		528.00	446.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,049.70	1,049.70
Total Labour Cost	1,060.00	795.00
Total Spray Painting	528.00	446.00
Other	0.00	0.00
Overall Total	2,637.70	2,290.70
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	2,290.70
Surveyor Approved Amount		2,290.70
No of Repair Days*	3	2
Remarks	-	resurvey after repair / lump sum
Surveyor Name		Rasul
Signature		 Save Clear
Survey Date	06/12/2018	