

ASS. REC. BY:

REF:

CS/AIG18022101/Gad3/1

Special Instructions:

Surveyor:

GUD@ing

ASSIGNMENT (Office)

Mennen

From (Person): Azlan Syazaidina

of

AIG

Date/Time: 10/12/12 @ 9am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 9532C

Insured:

GV 6228Y

at Workshop m/s

Seah Motor

Tel:

81610428 / 96775090 Samuel

of

Blk 2 Krunji Jero #01-06

Policy No:

2100455911

Claim No:

337638760386

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/12/2018.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:11am 10/11/12

Person Contacted:

Ah Hwee

Vehicle ☒ IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKQ 9532C-X
	GV 6228Y - CF/AIG18022101/36/aj
	Pending estimate from Repairer.

DON: 20/05/2008

PRS
Khl.

REF: AIG

3773H

ASSIGNMENT


(-2028)

30 Oct 2008

From: 10/12/18
Estimated Cost:
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: SKQ 9532C
at Workshop nbs: Seah Motor
Blk 2 Krungi loop # 01-06

Insured:
Policy No:
Claims No:
Sum Insured:
(Client's Record)
Make of Veh: Ah hwee @ 8161 0428

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Ball. or Market Value:
IDAC Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repair: 5 days Res: Yes or No
Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKQ 9532C
Type: M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Mer ce C200
Color: Green
Sp. Reading: 109400
A/C: Insured / Std / NI / NA
T/Radio: Insured / Std / NI / NA

Eng/No:
C/No: WPD 20404/2A 208575

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 225/45 R17
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front: R/Bal. 6 mm
L/Bal. 6 mm

D.O.A. 10-12-18

Survey held at: w/s 4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

09/11 Finalized \$ 4300 with Sammal. (Ref. 6333/592)

RECEIVED 13 JAN 2020

10/1/2020

Date/Time: File Pass 107

11/3/11 typrise

Date/Time: File Return 107

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee: 250 + 11

Transportation: 100 + 100 = 200

Photos: 100

Others: 100

TOTAL

Report Format: Mer TP
Lump Sum / I.B.C. (\$ 4300)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018 Edit Reg		10 Dec 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: 01 Computer System Pte Ltd									
Main Claimant: NG BAO LIN PAULYNE									
Vehicle Reg. No.: SKQ9532C		Date of Loss: 05/12/2018 17:00 - :59							
Claim Type: TP / 3376387603SG		Policy/Cover Note No.: 2100455911-02 (Comprehensive)							
Vehicle Reg. No. (Insured): GV6228Y		Policy No. (Claimant):							
		Excess:							
Repairer: Seah Motor Trading Co (Kranji) Blk 2 Kranji Loop #01-06, 739538 Kranji - Tel: 6365 0428									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/12/2018]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- AIG_SG (11/12/2018): NO OI GIA REPORT - AIG_SG (11/12/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- Pre repair inspection request - SKQ9532C VS GV6228Y (OI) DOA: 05/12/2018

From: Azlan, Syazairdina
To: admin-a@kkauto.com; assignments@kkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinnul; Chan, Yoke Shi
Sent: 10/12/2018 8:00:14 AM
Attachments: 20181207100645.pdf; 20181206164026.pdf

Hi,

Please refer to the enclosed request from **Vision Law LLC**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Prestina Moh (mailto:prestinamoh@visionlawllc.com)
Sent: Friday, December 07, 2018 6:11 PM
To: Azlan, Syazairdina; 'SUR'; 'assignments'
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinnul; Chan, Yoke Shi; Kaur, Baljit
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GV6228Y AND SKQ9532C ON 05/12/2018

WITHOUT PREJUDICE

Our ref: SKQ 9532 C

Dear Sir/Mdm

Please refer to our letter of even date which is self-explanatory.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

From: Azlan, Syazairdina (mailto:Syazairdina.Azlan@aig.com)
Sent: Friday, 7 December, 2018 9:04 AM
To: prestinamoh@visionlawllc.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinnul; Chan, Yoke Shi; Kaur, Baljit
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GV6228Y AND SKQ9532C ON 05/12/2018

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือข้อความที่ปลอดภัยและเข้ารหัสไว้เพื่อความเป็นส่วนตัว กรุณาเปิดไฟล์แนบก่อน

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-12-14 09:04 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. Please notify the sender if you have received this email in error or simply delete it.

Secured by Freeform Encryption, Copyright © 2004-2017 Freeform, Inc. All rights reserved.

Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (B13 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairina Azlan@sig.com
To: prestinamoh@visionlawllc.com
Cc: Andy-SY Fong@sig.com, Lee-Ying.Chin@sig.com, NoorMarissa.AbuKassim@sig.com, Imran.Ishak@sig.com, ShengYang Lim@sig.com, Aashweerjeetkaur.Mithoosingh@sig.com, Yennul.Hor@sig.com, yakeshi.chan@sig.com, Bai Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GV6228Y AND BKQ3532C ON 05/12/2018
Date: Fri, 7 Dec 2018 01:03:57 +0000
Without Prejudice

Your Reference : SKQ 9532 C (PM)
Our Reference : GV6228Y

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Indira Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Chan, Yoke Shi
Sent: Thursday, December 06, 2018 4:45 PM
To: Azlan, Syazairina
Subject: FW: PRE-REPAIR SURVEY

From: Prestina Moh (mailto:prestinamoh@visionlawllc.com)
Sent: Thursday, December 06, 2018 4:37 PM
To: Supramaniam, Darshene; Abu Kassim, Noor Marissa
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Marissa; Fan, Winnie-LW; Md Ishak, Mohd Imran
Subject: PRE-REPAIR SURVEY

WITHOUT PREJUDICE
Our ref: SKQ 9532 C

Dear Sir/Mdm

Please see attached our PRS request for your attention.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI DIO MUNIANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

✓ HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Liaison)
E-mail : yvonneim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SKQ 9532 C (PM)
Your Ref: GV 6228 Y

07 December 2018

BY EMAIL ONLY

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
[Attention : Motor Claim Department]

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SKQ 9532 C & GV 6228 Y ON 05 DECEMBER 2018
ALONG MCE TO ECP EXIT TUNNEL AT ABOUT 1740 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : M/s Seah Motor Trading Co.
Block 2 Kranji Loop
#01-06
Singapore 739538
Contact : Mr. Ah Hwee @ 8161 0428 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



DIANE ANG
(HEAD OFFICE)

cc: SKQ 9532 C – By fax: 63678421 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3773H
Vehicle Details	
Vehicle No.:	SKQ9532C
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 200 KOMPRESSOR
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	27195031126210
Chassis No.:	WDD2040412A208575
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$43,095.00
Original Registration Date:	30 Oct 2008
First Registration Date:	30 Oct 2008
Transfer Count:	3
Actual ARF Paid:	\$43,095.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$32,279.00
COE Rebate Amount:	\$31,897.00
Total Rebate Amount:	\$31,897.00

The information contained herein is correct as at 11 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2018 14:43
Date Of Accident	05/12/2018 17:40
Exact Location Of Accident	MCE TO ECP EXIT TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ9532C
Insured/Policyholder	
Name Of Registered Owner	NG BAO LIN PAULYNE (HUANG BAOLIN)
NRIC No	S8243773H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93697858
Alternative Phone No	OFFICE-98784363
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	C200
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	
	NO
If No, Please state action to be taken	
	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104778597
Cover Note Number	
Driver	
Name of Driver	HO ENWEI,EDWIN
NRIC No	S8124007H
Date Of Birth	04/08/1981
Occupation	INDOOR
Date Of Driving Pass	03/07/2008
Driving Experience	10 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98784363
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 468C FERNVALE LINK #24-555
Postcode	793468
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NG BAO LIN PAULYNE (HUANG BAOLIN) GENDER: : FEMALE
Passenger 2	NAME: : RAE HO GENDER: : FEMALE
Passenger 3	NAME: : MUAI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SIZE TOO BIG
Was there any audio recorded?	NO

Details of Witness 1

Name	CHUA YUNG HAN
Phone Number	93621386
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV6228Y
Vehicle Make/Model/Colour	NISSAN

Sketch Plan #2

SKETCH PLAN



A - SKQ9532C

B - GVEJ28Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident happened on MCR towards ECP exit tunnel at about 5:40pm. There was a Toyota Estima involved. It was ~~driving~~ ^{came} to a complete stop (200ft). Being the brake lights and applied the brake pedal in. There a long bang was heard ^{while a Nissan} ~~and a Nissan~~ crashing behind it. The driver saw the Estima car skidded together with me and the driver from the van.

All of us observed the damages and the pictures of the 2 cars involved. The driver of the Estima car is willing to be our witnesses at the point of accident.

DECLARATION

I/We declare that the information given is true and correct.

Declarant's Signature
Date & Time:

Driver's Signature
(If driver is not the declarant)
Date & Time:

Declarant's Signature
Name: G
MCR 28/14

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misstatement or withholding of material facts may affect insurance cover and/or invalidate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers at the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for permitting an archiving of this report which can be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the drafting of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insured(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and for my defence;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims/collectively the "Purposes".

- (b) My insurer and workshop involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may be collected by any of the Insurers and/or GIA to their third party service providers or agents (including if any agents located) who may be situated outside of Singapore for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to complete claims, for the purpose of fraud detection, investigation and/or regulatory compliance and all future claims.

(e) the Personal Information collected under this Form may be shared, exchanged

(f) I do not intend to lodge any other third party claim against any party involved in this accident and I am not seeking to sue, claim or sue any party involved in this accident and I am not seeking to sue, claim or sue any party involved in this accident.

(g) I am not seeking to sue, claim or sue any party involved in this accident.


Policyholder's Signature
Date & Time:


Insurer's Signature
(If driver is not the policyholder)
Date & Time:


Insurer's Signature
Date & Time:

SEAH MOTOR TRADING CO.

Page 1 / 2

BLK 2 KRANJI LOOP #01-06

SINGAPORE 739538

Tel No. : 63650428 Fax No. : 63678421

E-Mail : seahmotor@gmail.com

Buss. Reg. No. : 288020/00J

AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 SHENTON WAY #07-16 SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64193000 Fax No. : 64153723

Estimate : ES000268

Date : 05/12/2018

Vehicle Num. : SKQ9532C

Make/Model : MERC C200-2009

Chassis/Eng# : WDD2040412A208575

Accident Date : 05/12/2018

Claim No. :

Reference : Y18DEC/SKQ9532C/TP

Policy No. : 5104778597

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	2	LIST ITEMS :		
2.	1	TAILLAMP X NN		
3.	1	REAR BUMPER / Re	780.00	1,560.00
4.	1	REAR BUMPER CHROME / { ml	146.00	219.00
5.	1	REAR BUMPER CHROME RH / BT		125.00
6.	1	REAR BUMPER CHROME LH / BT		99.00
7.	1	REAR BUMPER REINFORCEMENT / BT		99.00
8.	2	REAR BUMPER CENTRE BRACKET X NN	615.9	670.00
9.	2	REAR BUMPER SIDE BRACKET X NN		99.00
10.	1	REAR BUMPER RETAINER / Re	78.00	156.00
11.	1	REAR BOOT / Re	39.00	78.00
12.	1	EMBLEM KOMPRESSOR / { ml	165.12	1,732.00
13.	1	EMBLEM STAR /	53	105.00
14.	2	EMBLEM C200 /		50.00
15.	1	REVERSE SENSOR / DM		74.00
16.	1	REAR BUMPER LOWER GARNISH X NN	155.00	310.00
17.	1	REAR INNER LOCK (BOOT) X		59.00
18.	1	END PANEL X Repair		290.00
19.	1	END PANEL TOP GARNISH X Re		1,440.00
20.	1	REAR BOOT CHROME X		115.00
21.	1	REAR BOOT HANDLE X		222.00
22.	1	REAR BOOT RUBBER X NN		54.00
		TOW COVER REAR X		189.00
				25.00
		List Total S\$:	9670	7,670.00
		10.00% Discount S\$:		767.00
			8703	6,903.00

4754.02

CONTINUE / ...

10%: 4278.62

SEAH MOTOR TRADING CO.

Page 2 / 2

BLK 2 KRANJI LOOP #01-06

SINGAPORE 739538

Tel No. : 63650428 Fax No. : 63678421

E-Mail : seahmotor@gmail.com

Buss. Reg. No. : 288020/00J

AIG ASIA PACIFIC INSURANCE PTE. LTD.

AIG BUILDING

78 SHENTON WAY #07-16 SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64193000 Fax No. : 64153723

Estimate : ES000268

Date : 05/12/2018

Vehicle Num. : SKQ9532C

Make/Model : MERC C200-2009

Chassis/Eng# : WDD2040412A208575

Accident Date : 05/12/2018

Claim No. :

Reference : Y18DEC/SKQ9532C/TP

Policy No. : 5104778597

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 SET	SPECIAL NETT ITEMS : REAR NUMBER PLATE W CASING		80.00
		Special Nett Total S\$:		80.00
		LABOUR :		
		TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL PARTS TO FACILITATE REPAIRS		100.00
		TO APPLY TUFT COAT TO THE DAMAGED PARTS		150.00
		TO CUT/WELD AND KNOCKOUT END PANEL / RELATED PANELS AND PARTS TO FACILITATE THE REPAIRS. TO ALIGN AND STARIGHTEN THE REAR DAMAGES AND PARTS		850.00
		TO PUTTY AND SPRAY PAINTING REPLACED AND WELDED PARTS		750.00
		Labour Total S\$:		1,850.00

SingDollars : Eight Thousand Eight Hundred Thirty-Three Only


for SEAH MOTOR TRADING CO. Samuel
96275090

E. & O.E.

Total S\$: 8,833.00

10633.00

5408.62

20% : 4300

5 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018 Edit Reg		10 Dec 2018 00:00 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: 01 Computer System Pte Ltd, Co. Reg. No.: -									
Main Claimant: NG BAO LIN PAULYNE									
Vehicle Reg. No.: SKQ9532C		Date of Loss: 05/12/2018 17:00 - :59 [121 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3376387603SG		Policy/Cover Note No.: 2100455911-02 (Comprehensive)							
Vehicle Reg. No. (Insured): GV6228Y		Policy No. (Claimant):							
		Excess:							
Repairer: Seah Motor Trading Co (Kranji) Bldg 2 Kranji Loop #01-06, 739538 Kranji - Tel: 6365 0428									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/12/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (11/12/2018): NO OI GIA REPORT - AIG_SG (11/12/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKQ9532C (3376387603SG)
[GV6228Y]
TP
NG BAO LIN PAULYNE
Dec 5 2018 5:45PM
[01 Computer System Pte Ltd]
Seah Motor Trading Co

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Photos/Images											3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print
1	30/09/19 14:47	General View									 Load JPG	☒
2	30/09/19 14:47	General View									 Load JPG	☒
3	30/09/19 14:47	General View									 Load JPG	☒
4	30/09/19 14:47	General View									 Load JPG	☒
5	30/09/19 14:47	General View									 Load JPG	☒
6	30/09/19 14:47	General View									 Load JPG	☒
7	30/09/19 14:47	General View									 Load JPG	☒
8	30/09/19 14:47	General View									 Load JPG	☒
9	30/09/19 14:47	General View									 Load JPG	☒
10	30/09/19 14:47	General View									 Load JPG	☒
11	30/09/19 14:47	General View									 Load JPG	☒
12	30/09/19 14:47	General View									 Load JPG	☒
13	30/09/19 14:47	General View									 Load JPG	☒
14	30/09/19 14:47	General View									 Load JPG	☒
15	30/09/19 14:47	General View									 Load JPG	☒
16	30/09/19 14:47	General View									 Load JPG	☒
17	30/09/19 14:47	General View									 Load JPG	☒
18	30/09/19 14:47	General View									 Load JPG	☒
19	30/09/19 14:47	General View									 Load JPG	☒
20	30/09/19 14:47	General View									 Load JPG	☒
21	30/09/19 14:47	General View									 Load JPG	☒
22	30/09/19 14:47	General View									 Load JPG	☒
23	30/09/19 14:47	General View									 Load JPG	☒
24	30/09/19 14:47	General View									 Load JPG	☒
25	30/09/19 14:47	General View									 Load JPG	☒
26	30/09/19 14:47	General View									 Load JPG	☒
27	30/09/19 14:47	General View									 Load JPG	☒
28	30/09/19 14:47	General View									 Load JPG	☒
29	30/09/19 14:47	General View									 Load JPG	☒
30	30/09/19 14:47	General View									 Load JPG	☒
31	30/09/19 14:47	General View									 Load JPG	☒
32	30/09/19 14:47	General View									 Load JPG	☒
33	30/09/19 14:47	General View									 Load JPG	☒
34	30/09/19 14:47	General View									 Load JPG	☒
35	30/09/19 14:47	General View									 Load JPG	☒
36	30/09/19 14:47	General View									 Load JPG	☒
37	30/09/19 14:47	General View									 Load JPG	☒
38	30/09/19 14:47	Odometer Reading									 Load JPG	☒
39	30/09/19 14:47	Chassis Number									 Load JPG	☒
40	30/09/19 14:48	Dismantled Parts									 Load JPG	☒
41	30/09/19 14:48	Dismantled Parts									 Load JPG	☒
42	30/09/19 14:48	Dismantled Parts									Load JPG	☒
43	30/09/19 14:48	Dismantled Parts									Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	30/09/19 14:48	Dismantled Parts		☒
45	30/09/19 14:48	Dismantled Parts		☒
46	30/09/19 14:48	Dismantled Parts		☒
47	30/09/19 14:48	Dismantled Parts		☒
48	30/09/19 14:48	Dismantled Parts		☒
49	30/09/19 14:48	Dismantled Parts		☒
50	30/09/19 14:48	Dismantled Parts		☒
51	30/09/19 14:48	Dismantled Parts		☒
52	30/09/19 14:48	Dismantled Parts		☒
53	30/09/19 14:48	Dismantled Parts		☒
54	30/09/19 14:48	Dismantled Parts		☒
55	30/09/19 14:48	Dismantled Parts		☒
56	30/09/19 14:48	Dismantled Parts		☒
57	30/09/19 14:48	Dismantled Parts		☒
58	30/09/19 14:48	Dismantled Parts		☒
59	30/09/19 14:48	Dismantled Parts		☒
60	30/09/19 14:48	Dismantled Parts		☒
61	30/09/19 14:48	Dismantled Parts		☒
62	30/09/19 14:48	Dismantled Parts		☒
63	30/09/19 14:48	Dismantled Parts		☒
64	30/09/19 14:48	Dismantled Parts		☒
65	30/09/19 14:48	Dismantled Parts		☒
66	30/09/19 14:48	Dismantled Parts		☒
67	30/09/19 14:48	Dismantled Parts		☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/12/18 14:56	OI GIA REPORT		☒
2	02/01/19 17:28	TP GIA		☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18022101/GQD3Q2

Date: 14/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100455911-02

Claimant

Vehicle No : SKQ9532C

Insured Vehicle No : GV6228Y

Date of Loss: 05/12/2018

Nature of Claim: TP

Claim No: 3376387603SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ9532C

Make & Model: MERCEDES-BENZ C200 KOMPRESSION, 1.8 (A) Engine No: 27195031126210

Reg. Date: 30/10/2008 (Man. Year: 2008)

Chassis No: WDD2040412A208575

Colour: Green

Odometer: 109400 km

Engine Capacity: 1796 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,783.00	4,278.62	4,504.38	51.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,130.00	720.00	38.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,633.00	5,408.62	5,224.38	49.13
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	10,633.00	4,300.00	6,333.00	59.56

INSPECTION

Date of Assignment: 10/12/2018

Date Inspected: 10/12/2018 Inspected At:

Seah Motor Trading Co (Kranji)
Blk 2 Kranji Loop #01-06
Singapore 739538

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMP	Not Necessary	1,560.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	2,119.00 FL	*1,460.00 FL
3	1		*CENTRE REAR BUMPER CHROME	Necessary	125.00 FL	*125.00 FL
4	1		*REAR BUMPER CHROME RH	Necessary	99.00 FL	*99.00 FL
5	1		*REAR BUMPER CHROME LH	Necessary	99.00 FL	*99.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	670.00 FL	*615.90 FL
7	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	99.00 FL	*- FL
8	2		*REAR BUMPER SIDE BRACKET	Not Necessary	156.00 FL	*- FL
9	2		*REAR BUMPER RETAINER	Deformed	78.00 FL	*78.00 FL
10	1		*REAR BOOT	Buckled	1,732.00 FL	*1,675.12 FL
11	1		*EMBLEM KOMPRESSOR	Necessary	105.00 FL	*53.00 FL
12	1		*EMBLEM STAR	Necessary	50.00 FL	*50.00 FL
13	1		*EMBLEM C200	Necessary	74.00 FL	*74.00 FL
14	2		*REVERSE SENSOR	Damaged	310.00 FL	*310.00 FL
15	1		*REAR BUMPER LOWER GARNISH	Not Necessary	59.00 FL	*- FL
16	1		*REAR INNER LOCK (BOOT)	Not Necessary	290.00 FL	*- FL
17	1		*END PANEL	Repair	1,440.00 FL	*- FL
18	1		*END PANEL TOP GARNISH	Deformed	115.00 FL	*115.00 FL
19	1		*REAR BOOT CHROME	Not Necessary	222.00 FL	*- FL
20	1		*REAR BOOT HANDLE	Not Necessary	54.00 FL	*- FL
21	1		*REAR BOOT RUBBER	Not Necessary	189.00 FL	*- FL
22	1		*TOW COVER REAR	Not Necessary	25.00 FL	*- FL
23	1		*SET REAR NUMBER PLATE W CASING	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,750.00	4,754.02
- List Item Discount on L Items 10.00/10.00% (\$\$)	967.00	475.40
Total Parts (\$\$)	8,783.00	4,278.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL PARTS TO FACILITATE REPAIRS	New	100.00	30.00
2	TO APPLY TUFF COAT TO THE DAMAGED PARTS	New	150.00	0.00
3	TO CUT/WELD AND KNOCKOUT END PANEL /RELATED PANELS AND PARTS TO FACILITATE THE REPAIRS .TO ALIGN AND STRAIGHTEN THE REAR DAMAGES AND PARTS	New	850.00	500.00
4	TO PUTTY AND SPRAY PAINTING REPLACED AND WELDED PARTS	New	750.00	600.00
Gross Labour Cost (S\$)			1,850.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >