

22/03/2002

ASS. REC. BY:

REF: CS3 / ASM18022103 / Jcb2

Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person):

Cynthia Loh

of

ASM

Date/Time: 10.12.2018 857am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

WNH 7978

Insured:

YP 6870K

at Workshop m/s

Asia Motorsport

Tel:

6745 2811

of

568 Geylang Rd

Policy No:

Claim No:

88M0147T

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24.11.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

10/12/2018 10:00am

Person Contacted:

mm100

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	WNH 7978 - X
	YP 6870K - RM / INC (170) 18914 / 24 DA: 31082017
	No GIA & log card.
	Range \$2,000/2 - \$3,000/2
	TECIMA bill 13/12/18

PRS
Hwee Jie


REF: AXA

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: WNH7978 Yr Regn: /
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Modenas Kriss C.C. _____
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 71015 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: _____
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / Rim / STD A/Rim or _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.



Tyre Size: F: 70/90 R17
R: 80/90 R17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PTIR SUMI /
TOYO / YOKO or _____

Bal. or Market Value: _____
IDAC Accident Rport: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. _____ D.O.I. 10/12/18 @1149Am
Survey held at Asia motorsports
Des. of Damages: Rear / Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____
Range \$2,800/2 - \$3,600/2
13/12/2018
T. Lim
13/12/18

Date/Time. File Pass to? : Preli. Report
 : Final Report
1) _____
Date/Time. File Return to? _____
2) _____
Report Format : PRS
Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 4
Resurvey No. of Trip: -
Survey Fee: _____
Transportation: _____
Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)
TOTAL 100



Service Request Details

Claim
S8M0147T

Reference
None 

Loss Date
November 24, 2018

Request Date
December 10, 2018

Due Date
December 17, 2018

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step
Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #
WNH7978

Make
TPVD MOTORCYCLE

Model

Service Address

...

Primary Contact/Insured

QUALITY TRANSPORT (S) PTE LTD
115 AIRPORT CARGO ROAD, #02-10 CARGO AGENTS BUILDING C, 819466, Singapore
65431071

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

- Messages
 - Invoices
 - History
 - Documents
 - Assessment
 - Metrics
 - Notes
-

New Message

Catherine Chong (LKK Auto)

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>
Sent: Friday, 7 December, 2018 11:53 AM
To: customer.service@axa.com.sg; SG AXA Insurance SM AXA SGP - Motor Survey
Subject: NOTICE OF ACCIDENT: ACCIDENT INVOLVING WNH 7978 & YP 6870 K ON 24 NOVEMBER 2018

Categories: Namrata

Your Ref:
Our Ref: WNH 7978

7 December 2018

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
AXA Tower
Singapore 068811

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

Attn: Claims
Department

Dear Sir/Mdm,

NOTICE OF ACCIDENT: ACCIDENT INVOLVING WNH 7978 & YP 6870 K ON 24 NOVEMBER 2018

We are instructed to notify you of a road traffic accident on **24 November 2018** at about **10.00 am** at **Loyang Avenue towards Changi Village** involving our client's vehicle registration number **WNH 7978** and vehicle registration number **YP 6870 K** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **11 December 2018 (Tuesday), 1200H**, we will be forwarding **our proposed list of 10 motor surveyors** for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports Solution Pte Ltd
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD		Ref: CS3/ASM18022103/Jcbe2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 02-01-2019	
ATTN : CYNTHIA LOH		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	YP 6870K	Veh. Inspected	WNH 7978
Policy No.		Coverage (\$)	0.00
Claim No.	S8M0147T	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	10/12/2018
2. Vehicle Particulars & Condition			
Make & Model	MODENAS KRISS	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	BLUE
Odometer	71015 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90 R17	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90 R17	PIRELLI	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information			
Accident Date	24/11/2018	Inspect Date / Time	10/12/2018 (11:49 AM)
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800-\$3,600			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/ASM18022103/Jcbe2

Inspected By

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.