

08/11/13 wef

ASS. REC. BY: *MORCUS*

REF:

MSIC/ C3/MSH18022117/ULD302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKF 69815*

at Workshop m/s *24.*

of *5JN 86924*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *57K.*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: *1* Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: *17A 45527*

Vehicle: *7728D* IN / OUT

Date / Time Action / Instruction *11/12/18*

31/5. bal. have 6.4 net 11473

11/12@2:04pm - Revert via email. base on estimate 13k.

3/1/19 4/5 @ 11,000 conf. with Aler. (Red: 34629.50, 76%)

RECEIVED 04 JAN 2019

Veh No: *SKF 69815* Yr Regn: *27/6/12*

Type: *M* Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA*

Make: *Toyota Camry* c.c. *1998*

Colour: *Grey* A/C: Insured / Std / NI / NA

Sp. Reading: *139991* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *M R 05313K510 4001401*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *Inorder* / Jammed / Leaked / Burnt or

Brake: *Inorder* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *215/60R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6* Rear *6*

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. *8/12/18* D.O.I. *10/12/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Lf. &

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

1) *411 TYPIST*

2) _____

Days Of Repair: *12*

Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: *250*

Transportation: _____

S + RS, SI _____

Photos _____

Others *10*

TOTAL

260

Report Format: *TP*

Lump Sum / I.B.I. (\$) *11,000*

sgcarmart.com

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Don't compromise,
start cleaning today.

FIND OUT MORE

camry

Price Range

Depreciation

2013

Vehicle Type

Submit

Advanced Search

Home » Used Cars » WM Car Pte Ltd » Toyota Camry 2.0A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

6769 7117 8720 5000 8720 8000

Toyota Camry 2.0A

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$65,800

Depreciation

\$11,450 /yr

View models with similar depreciation

Reg Date

11-Jul-2013

(4yrs 7mths COE left)

Manufactured

2013

Mileage

75,000 km (13.8k /yr)

Transmission

Auto

Engine Cap

1,998 cc

Road Tax

\$1,210 /yr

Power

109.0 kW (146 bhp)

View specs of the Toyota Camry (2012-2015)

Curb Weight

1,445 kg

Features

2.0L DOHC VVTi Engine, Automatic Transmissions, Super Fuel Efficiency Of 14Km/L, SRS Airbags, ABS, Auto Headlamps And Rain Sensors And Cruise Control.

Accessories

Keyless Entry/Start/Stop, Touch Screen Head Unit With Bluetooth Connectivity/Navl, 2x Electric Leather Seats, Rear AC, Reverse Cam/Sensors, Fog Lamps.

Description

Optional New 6 Months Road Tax! One Owner Only, Low Mileage Done, Most Popular Toyota Camry For Your Family And Daily Usage. Elegant Silver, Spacious Sedan, Low Maintenance Cost, Fuel Saving Yet Powerful Drive. Very Well Maintained Unit With No Repairs Needed. Test Drive To Believe. Trade In Welcome, High Loan Available. Don't Miss It! Call Now For Viewing.

COE

\$77,000

OMV

\$24,721

ARF

\$26,610

Dereg Value

\$53,920 as of today (change)

No. of Owners

1

Type of Veh

Luxury Sedan

Category

PARF Car, Premium Ad Car

Availability

Available

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 08-Dec-2018 | Last Updated on: 08-Dec-2018

Compare

Location Map

Seller Information

Company

WM Car Pte Ltd

» dealer's pricelist

» 38 vehs sold | 23 vehs available

Address

210 Turf Club Road Lot B65/B78

Search cars nearby this location

Location

Car Mall @ The Grandstand

Office No

64634936

Contact Person(s)

Sam

97829493

Ivan Choo

97629200

Peng Hee

91761283

Chris Ong

91375618

Useful Services

Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

https://www.sgcarmart.com/used_cars/info.php?ID=776555&DL=3091

10-Dec-18

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7728D

Vehicle Details

Vehicle No.: SKF6981S

Vehicle to be Exported: No

Intended Deregistration Date: 10 Dec 2018

Vehicle Make: TOYOTA

Vehicle Model: CAMRY 2.0 AUTO

Primary Colour: Silver

Manufacturing Year: 2012

Engine No.: 1AZE244848

Chassis No.: MR053BK5104001401

Maximum Power Output: 109.0 kW (146 bhp)

Open Market Value: \$23,475.00

Original Registration Date: 27 Jun 2012

First Registration Date: 27 Jun 2012

Transfer Count: 1

Actual ARF Paid: \$23,475.00 11737

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Jun 2022

PARF Rebate Amount: \$15,258.00

Intended COE Rebate Details

COE Expiry Date: 26 Jun 2022

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$85,400.00

COE Rebate Amount: \$30,269.00

Total Rebate Amount: \$45,527.00

The information contained herein is correct as at 10 Dec 2018

OK

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 11 December 2018 2:04 PM
To: Irene Tan; Hasrianah Binte Hassan
Cc: SUR; Accounts (LKKAUTO); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 8/12/2018, SKF 6981S (TP VEHICLE), SKF 6981S (OI VEHICLE)
Attachments: GIA REPORT SKF 6981S.pdf

Dear Hasrianah/Irene,

Please be informed that we had inspected the vehicle SKF 6981S at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 28 November 2018 3:31 PM
To: elaine_ngu@sg.msiga.com; irvani_amin@sg.msiga.com
Cc: KKLau <kklau@lkkauto.com>; Accounts (LKKAUTO) <account@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 27/11/2018, SLW 1253S (TP VEHICLE), SLU 130E (OI VEHICLE)

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 10:50
Date Of Accident	08/12/2018 11:30
Exact Location Of Accident	ALONG PIE TWDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF6981S
Insured/Policyholder	
Name Of Registered Owner	MR GOH BOON KAI
NRIC No	S8177728D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98586509
Alternative Phone No	OTHERS-91725540

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.0 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MU004298-R01
Cover Note Number	-

Driver

Name of Driver	MR GOH BOON KAI
NRIC No	S8177728D
Date Of Birth	28/01/1981
Occupation	INDOOR
Date Of Driving Pass	05/11/1999
Driving Experience	19 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98586509
Fax Number	
Contact Number	OTHERS-91725540
EEmail Address	NOEMAIL

Address	BLK 318 UBI AVE 1 #09-475
Postcode	400318
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN8692H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLL6383A
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJF1671G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SH6683Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	MR GOH BOON KAI
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SKF6981S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 28/10/18
12:39 AM

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Diagram of a 5-story building with elevators:

- A - SKF 6981S
- B - SJN 8692H
- C - LL 6333A
- D - SJF 1671G
- E - SH 6683Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time I was driving my vehicle A along the road towards the shop. In front of the vehicle C stop. A yellow suit. Out of sudden, vehicle B hit on my rear portion and cause my car to push forward and hit on vehicle C. There were 5 cars involved in an accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: 08/10/12
12 34 PM

the true in every respect.

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Hand

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

Not Attached
Main
2/5 \$11,000/
10/12/18
12dy.

VEHICLE NO:SKF 6981S

QTY	PARTICULAR		
1 PCS	BOOTLID	1092.10	But/Buc \$1,455.10 ✓
1 PCS	BOOTLID '2.0' EMBLEM	52.00	rec \$58.50 ✓
1 PCS	BOOTLID 'ARMY' EMBLEM	58.20	rec \$62.50 ✓
1 PCS	BOOTLID CHROME MOULDING		17 \$311.20 X
2 PCS	BOOTLID REFLECTORS @\$481.50	465.10 X 2 = 930.20	one \$963.00 ✓
1 PCS	BOOTLID INNER LOCK	378.20	Two/But \$399.50 ✓
1 PCS	BOOTLID WEATHERSTRIP	295.30	Two \$315.10 ✓
1 PCS	BOOTLID INNER TRIM		17 \$422.10 X
1 SET	BOOTLID INNER TRIM CLIPS		17 \$50.00 X
1 PCS	REAR BUMPER	589.60	Dis \$781.10 ✓
1 PCS	REAR BUMPER REINFORCEMENT	391.80	But \$415.50 ✓
2 PCS	REAR BUMPER SIDE RETAINERS @\$91.10		But \$182.20 ✓
2 PCS	REAR BUMPER PDC SENSORS @\$377.80	266 X 2 = 532.00	Shut \$755.60 2 pcs
1 SET	REAR BUMPER CLIPS		rec \$50.00 ✓
1 PCS	REAR BUMPER UNDER COVER		Two \$312.20 ✓
1 SET	REAR BUMPER UNDER COVER CLIPS		rec \$50.00 ✓
2 PCS	REAR BUMPER REFLECTORS @\$98.10		one \$196.20 ✓
1 PCS	REAR END PANEL		Body \$639.10 ✓
1 PCS	REAR END PANEL TOP GARNISH		Two \$415.20 ✓
2 PCS	TAILLAMPS @\$680.10	495.20 X 2 = 990.40	one \$1,360.20 ✓
2 PCS	TAILLAMP HOUSING PANELS @\$450.10	425.10	Alto \$900.20 1 pc
2 PCS	REAR FENDERS @\$1685.10	1019.30	Alto \$3,370.20 1 pc
2 PCS	REAR FENDER INNER TRIMS @\$390.50		17 \$781.20 X
1 SET	REAR FENDER INNER TRIM CLIPS		17 \$60.00 X
1 PCS	REAR FLOOR PANEL	1124.30	crumpled/buc \$1,480.50 ✓
1 PCS	REAR FLOOR PANEL TOOL SPONGE	488.50	Two \$665.10 ✓
1 PCS	REAR FLOOR PANEL TOP BOARD	645.10	warped/oe \$688.50 ✓
1 PCS	REAR WINDSCREEN MOULDING	98.80	rec \$211.10 ✓
1 PCS	REAR EXHAUST		rec \$1,021.50 X
1 PCS	REAR EXHAUST CHROME		rec \$85.00 X
1 PCS	REAR CHASSIS MEMBER N/S		rec \$699.10 X
1 PCS	REAR SPARE TYRE LOCK NUT		one \$142.30 ✓
1 PCS	FRONT BUMPER	625.10	17/oe \$788.10 ✓
1 PCS	FRONT BUMPER LOWER CENTRE GRILLE	184.20	rec/Two \$215.10 ✓
2 PCS	FRONT BUMPER SIDE RETAINER @\$105.10	78.15 X 2 = 156.30	But \$210.20 ✓
1 SET	FRONT BUMPER CLIPS		rec \$50.00 ✓
1 PCS	FRONT BUMPER SPONGE	188.20	one \$245.30 ✓
1 PCS	FRONT BUMPER REINFORCEMENT	385.60	17 \$619.10 ✓
2 PCS	FRONT BUMPER FOG LAMPS @\$450.50		17 \$901.00 X

257

2 PCS	FRONT BUMPER FOG LAMP GARNISHS @\$185.00	11	\$370.00	X
1 PCS	FRONT GRILLE 565-40	one	\$613.00	✓
1 PCS	FRONT GRILLE LOGO	ner	\$68.50	✓
2 PCS	HEAD 'HID' @\$2800.00 2597-20	1/5 one	\$5,600.00	PC
1 PCS	FRONT SUPPORT PANEL	R	\$899.10	X
1 PCS	AIR CON CONDENSER	11	\$1,485.10	X
1 PCS	RADIATOR	11	\$1,689.40	X
1 PCS	RADIATOR FAN ASSY	11	\$699.10	X
1 PCS	BONNET	R	\$1,450.10	X
1 PCS	BONNET INNER LOCK	25% 11	\$215.00	X
1 PCS	BONNET CHROME	11	\$288.20	X
2 PCS	FRONT FENDERS @\$922.10	11	\$1,844.20	X
			\$37,549.50	
	S.NETT ITEM			
1 PCS	REAR WINDSCREEN SEALANT	ner	\$50.00	40
1 SET	REAR FLOOR PANEL INSULATOR	ner	\$300.00	200
1 PCS	REAR LICENCE PLATE W/HOLDER	ner	\$50.00	X
1 PCS	REAR END PANEL SEALANT	ner	\$50.00	✓
1 BOT	RADIATOR COOLANT	11	\$50.00	X
	LABOUR CHRAGES:			
	TO CHECK WIRING		\$100.00	30
	TO DISMANTLE & REPLACING PDC SENSOR		\$100.00	50
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	120
	TO TRANSFER BOOTLID MECHANISM		\$120.00	60
	TO SPRAY RUST PROOFING		\$200.00	100
	TO REFILL AIR CON GAS	11	\$150.00	X
	TO DISMANTLE & REFIX REAR EXHAUST		\$100.00	60
	TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00	X
	TO DISMANTLE & REFIX PETROL TANK		\$100.00	60
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY		\$180.00	80
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$3,000.00	2000
	TO PUTTY & SPRAY PAINTING		\$3,000.00	1800
	TOTAL		\$45,629.50	

4650

I have read and understand the terms and conditions of the above quotation and agree to the work being carried out on the basis of the above quotation. I understand that the above quotation is based on the information provided and is subject to final approval from the Insurance Company.

Acknowledged by Repairer
 Signature: _____
 Date: _____

15/8/18
 1193895
 1658895
 13271

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Dec 2018		12 Dec 2018 13:24 Edit Adj Rpt	S\$11,000.00 Edit Estimates	S\$11,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: WAM BOON ANN , ID: S7504470D, Tel: +6590091809									
Main Claimant: MR GOH BOON KAI , ID: S8177728D									
Vehicle Reg. No.:	SKF6981S	Date of Loss:	08/12/2018 11:00 - :59 [77 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 578613	Policy/Cover Note No.:	A29090442TMP (Third Party Only) Coverage: 30/07/2018 - 29/07/2019						
Vehicle Reg. No. (Insured):	SJN8692H	Policy No. (Claimant):							
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/01/2019]									
Driver/Custodian (Insured):	WAM BOON ANN (43 / Male), NRIC: S7504470D, Tel: +6590091809								
Adj Asg. Remarks:	DIRECT SURVEY DONE BY LKK AUTO ON 11/12/2018								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKF6981S (578613)
[SJN8692H]
TP
MR GOH BOON KAI
Dec 8 2018 11:00AM
[WAM BOON ANN]
Fastech Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print					
1	12/12/18 13:21	Accident Statement From: SC - Reg. No: SJN8692H, Claimant: WAM BOON ANN		Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	04/01/19 15:19	Adjuster Immediate Advice		Load HTM						
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	04/01/19 15:13	General View		Load JPG	☒					
2	04/01/19 15:13	General View		Load JPG	☒					
3	04/01/19 15:13	General View		Load JPG	☒					
4	04/01/19 15:13	General View		Load JPG	☒					
5	04/01/19 15:13	General View		Load JPG	☒					
6	04/01/19 15:13	General View		Load JPG	☒					
7	04/01/19 15:13	General View		Load JPG	☒					
8	04/01/19 15:13	General View		Load JPG	☒					
9	04/01/19 15:13	General View		Load JPG	☒					
10	04/01/19 15:13	General View		Load JPG	☒					
11	04/01/19 15:13	General View		Load JPG	☒					
12	04/01/19 15:13	General View		Load JPG	☒					
13	04/01/19 15:13	General View		Load JPG	☒					
14	04/01/19 15:13	General View		Load JPG	☒					
15	04/01/19 15:13	General View		Load JPG	☒					
16	04/01/19 15:13	General View		Load JPG	☒					
17	04/01/19 15:13	General View		Load JPG	☒					
18	04/01/19 15:13	General View		Load JPG	☒					
19	04/01/19 15:13	General View		Load JPG	☒					
20	04/01/19 15:13	General View		Load JPG	☒					
21	04/01/19 15:13	General View		Load JPG	☒					
22	04/01/19 15:13	General View		Load JPG	☒					
23	04/01/19 15:13	General View		Load JPG	☒					
24	04/01/19 15:13	General View		Load JPG	☒					
25	04/01/19 15:13	General View		Load JPG	☒					
26	04/01/19 15:13	General View		Load JPG	☒					
27	04/01/19 15:13	General View		Load JPG	☒					
28	04/01/19 15:13	General View		Load JPG	☒					
29	04/01/19 15:13	General View		Load JPG	☒					
30	04/01/19 15:13	General View		Load JPG	☒					
31	04/01/19 15:13	General View		Load JPG	☒					
32	04/01/19 15:13	General View		Load JPG	☒					

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	04/01/19 15:13	General View	 Load JPG	☒
34	04/01/19 15:13	General View	 Load JPG	☒
35	04/01/19 15:13	General View	 Load JPG	☒
36	04/01/19 15:13	General View	 Load JPG	☒
37	04/01/19 15:13	General View	 Load JPG	☒
38	04/01/19 15:13	General View	 Load JPG	☒
39	04/01/19 15:13	General View	 Load JPG	☒
40	04/01/19 15:13	General View	 Load JPG	☒
41	04/01/19 15:13	General View	 Load JPG	☒
42	04/01/19 15:13	General View	 Load JPG	☒
43	04/01/19 15:13	General View	 Load JPG	☒
44	04/01/19 15:13	General View	 Load JPG	☒
45	04/01/19 15:13	General View	 Load JPG	☒
46	04/01/19 15:13	General View	 Load JPG	☒
47	04/01/19 15:13	General View	 Load JPG	☒
48	04/01/19 15:13	General View	 Load JPG	☒
49	04/01/19 15:13	General View	 Load JPG	☒
50	04/01/19 15:13	General View	 Load JPG	☒
51	04/01/19 15:13	General View	 Load JPG	☒
52	04/01/19 15:13	General View	 Load JPG	☒
53	04/01/19 15:13	General View	 Load JPG	☒
54	04/01/19 15:13	General View	 Load JPG	☒
55	04/01/19 15:13	General View	 Load JPG	☒
56	04/01/19 15:13	General View	 Load JPG	☒
57	04/01/19 15:13	General View	 Load JPG	☒
58	04/01/19 15:13	General View	 Load JPG	☒
59	04/01/19 15:13	General View	 Load JPG	☒
60	04/01/19 15:13	General View	 Load JPG	☒
61	04/01/19 15:13	General View	 Load JPG	☒
62	04/01/19 15:13	General View	 Load JPG	☒
63	04/01/19 15:13	General View	 Load JPG	☒
64	04/01/19 15:13	General View	 Load JPG	☒
65	04/01/19 15:13	General View	 Load JPG	☒
66	04/01/19 15:13	General View	 Load JPG	☒
67	04/01/19 15:13	General View	 Load JPG	☒
68	04/01/19 15:13	General View	 Load JPG	☒
69	04/01/19 15:13	General View	 Load JPG	☒
70	04/01/19 15:13	General View	 Load JPG	☒
71	04/01/19 15:13	General View	 Load JPG	☒
72	04/01/19 15:13	General View	 Load JPG	☒
73	04/01/19 15:13	General View	 Load JPG	☒
74	04/01/19 15:13	General View	 Load JPG	☒
75	04/01/19 15:13	General View	 Load JPG	☒
76	04/01/19 15:13	General View	 Load JPG	☒
77	04/01/19 15:13	General View	 Load JPG	☒
78	04/01/19 15:13	General View	 Load JPG	☒
79	04/01/19 15:13	General View	 Load JPG	☒
80	04/01/19 15:13	General View	 Load JPG	☒
81	04/01/19 15:13	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	04/01/19 15:13	General View	 Load JPG	☒
83	04/01/19 15:13	General View	 Load JPG	☒
84	04/01/19 15:13	General View	 Load JPG	☒
85	04/01/19 15:13	General View	 Load JPG	☒
86	04/01/19 15:13	General View	 Load JPG	☒
87	04/01/19 15:13	General View	 Load JPG	☒
88	04/01/19 15:13	General View	 Load JPG	☒
89	04/01/19 15:13	General View	 Load JPG	☒
90	04/01/19 15:13	General View	 Load JPG	☒
91	04/01/19 15:13	General View	 Load JPG	☒
92	04/01/19 15:13	General View	 Load JPG	☒
93	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
94	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
95	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
96	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
97	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
98	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
99	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
100	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
101	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
102	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
103	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
104	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
105	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
106	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
107	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
108	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
109	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
110	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
111	04/01/19 15:14	Reinspection Photo	 Load JPG	☒
112	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
113	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
114	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
115	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
116	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
117	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
118	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
119	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
120	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
121	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
122	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
123	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
124	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
125	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
126	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
127	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
128	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
129	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
130	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
131	04/01/19 15:15	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
132	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
133	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
134	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
135	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
136	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
137	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
138	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
139	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
140	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
141	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
142	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
143	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
144	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
145	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
146	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
147	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
148	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
149	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
150	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
151	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
152	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
153	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
154	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
155	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
156	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
157	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
158	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
159	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
160	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
161	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
162	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
163	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
164	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
165	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
166	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
167	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
168	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
169	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
170	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
171	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
172	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
173	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
174	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
175	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
176	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
177	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
178	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
179	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
180	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
181	04/01/19 15:15	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
182	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
183	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
184	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
185	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
186	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
187	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
188	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
189	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
190	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
191	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
192	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
193	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
194	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
195	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
196	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
197	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
198	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
199	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
200	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
201	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
202	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
203	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
204	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
205	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
206	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
207	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
208	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
209	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
210	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
211	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
212	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
213	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
214	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
215	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
216	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
217	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
218	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
219	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
220	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
221	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
222	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
223	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
224	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
225	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
226	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
227	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
228	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
229	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
230	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
231	04/01/19 15:15	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
232	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
233	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
234	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
235	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
236	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
237	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
238	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
239	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
240	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
241	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
242	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
243	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
244	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
245	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
246	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
247	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
248	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
249	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
250	04/01/19 15:15	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/12/18 13:21	TPD SKF6981S GIA REPORT From: SC - Reg. No: S3N8692H, Claimant: WAM BOON ANN	 Load PDF	
2	12/12/18 13:22	DIRECT SURVEY DONE BY LKK AUTO CONSULTANTS PTE LTD	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18022117/UTD3E2

Date: 07/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29090442TMP

Claimant Vehicle No : SKF6981S

Insured Vehicle No : SJN8692H

Date of Loss: 08/12/2018

Nature of Claim: TP

Claim No: 578613

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKF6981S

Make & Model: TOYOTA CAMRY, 2.0 (A)

Engine No: 1AZE244848

Reg. Date: 27/06/2012 (Man. Year: 2012)

Chassis No: MR053BK5104001401

Colour: Grey

Odometer: 139991 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,049.50	12,228.95	25,820.55	67.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	4,360.00	3,220.00	42.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,629.50	16,588.95	29,040.55	63.64
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	45,629.50	11,000.00	34,629.50	75.89
+ GST 7.00/7.00% (S\$)	3,194.07	770.00	2,424.07	75.89
Nett Amount (S\$)	48,823.57	11,770.00	37,053.57	75.89

INSPECTION

Date of Assignment: 12/12/2018

Date Inspected: 10/12/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2019)
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF6981S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	1,455.10 F	*1,092.10 FL
2	1		*BOOTLID 2.0; EMBLEM	Necessary	58.50 F	*52.00 FL
3	1		*BOOTLID CAMRY EMBLEM	Necessary	62.50 F	*58.20 FL
4	1		*BOOTLID CHROME MOULDING	Not Necessary	311.20 F	*- FL
5	2		*BOOTLID REFLECTORS	Cracked	963.00 F	*930.20 FL
6	1		*BOOTLID INNER LOCK	Twisted / Bent	399.50 F	*378.20 FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	315.10 F	*295.30 FL
8	1		*BOOTLID INNER TRIM	Not Necessary	422.10 F	*- FL
9	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
10	1		*REAR BUMPER	Distorted	781.10 F	*589.60 FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	415.50 F	*391.80 FL
12	2		*REAR BUMPER SIDE RETAINERS	Bent	182.20 F	*182.20 FL
13	2		*REAR BUMPER PDC SENSORS	Shorted	755.60 F	*532.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR BUMPER UNDER COVER	Torn	312.20 F	*312.20 FL
16	1		*SET REAR BUMPER UNDER COVER CLIPS	Necessary	50.00 F	*50.00 FL
17	2		*REAR BUMPER REFLECTORS	Cracked	196.20 F	*196.20 FL
18	1		*REAR END PANEL	Badly Dented	639.10 F	*639.10 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	415.20 F	*415.20 FL
20	2		*TAILLAMPS	Cracked	1,360.20 F	*990.40 FL
21	1		*TAILLAMP HOUSING PANELS	N/S Dented	900.20 F	*425.10 FL
22	1		*REAR FENDERS	N/S Badly Dented/O/S Repair	3,370.20 F	*1,019.30 FL
23	2		*REAR FENDER INNER TRIMS	Not Necessary	781.20 F	*- FL
24	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
25	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,480.50 F	*1,124.30 FL
26	1		*REAR FLOOR PANEL TOOL SPONGE	Torn	665.10 F	*488.50 FL
27	1		*REAR FLOOR PANEL TOP BOARD	Warped / Deformed	688.50 F	*645.10 FL
28	1		*REAR EXHAUST	Repair	1,021.50 F	*- FL
29	1		*REAR EXHAUST CHROME	Serviceable	85.00 F	*- FL
30	1		*REAR CHASSIS MEMBER N/S	Repair	699.10 F	*- FL
31	1		*REAR SPARE TYRE LOCK NUT	Cracked	142.30 F	*142.30 FL
32	1		*FRONT BUMPER	Dented / Deformed	788.10 F	*625.10 FL
33	1		*FRONT BUMPER LOWER CENTRE GRILLE	Deformed / Torn	215.10 F	*184.20 FL
34	2		*FRONT BUMPER SIDE RETAINER	Bent	210.20 F	*156.30 FL
35	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
36	1		*FRONT BUMPER SPONGE	Cracked	245.30 F	*188.20 FL
37	1		*FRONT BUMPER REINFORCEMENT	Dented	619.10 F	*385.60 FL
38	2		*FRONT BUMPER FOG LAMPS	Not Necessary	901.00 F	*- FL
39	2		*FRONT BUMPER FOG LAMP GARNISHS	Not Necessary	370.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
40	1	*FRONT GRILLE	Cracked	613.00 F	*565.40 FL
41	1	*FRONT GRILLE LOGO	Necessary	68.50 F	*68.50 FL
42	1	*HEAD HID	N/S Cracked	5,600.00 F	*2,597.20 FL
43	1	*FRONT SUPPORT PANEL	Repair	899.10 F	*- FL
44	1	*AIR CON CONDENSER	Not Necessary	1,485.10 F	*- FL
45	1	*RADIATOR	Not Necessary	1,689.40 F	*- FL
46	1	*RADIATOR FAN ASSY	Not Necessary	699.10 F	*- FL
47	1	*BONNET	Repair	1,450.10 F	*- FL
48	1	*BONNET INNER LOCK	Not Necessary	215.00 F	*- FL
49	1	*BONNET CHROME	Not Necessary	288.20 F	*- FL
50	2	*FRONT FENDERS	Not Necessary	1,844.20 F	*- FL
51	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
52	1	*SET REAR FLOOR PANEL INSULATOR	Necessary	300.00 FS	*200.00 FS
53	1	*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*- FS
54	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
55	1	*BOT RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS
56	1	*REAR WINDSCREEN MOULDING	Necessary	211.10 F	*98.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	38,049.50	16,208.60
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	3,979.65
Total Parts (S\$)	38,049.50	12,228.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	100.00	30.00
2	TO DISMANTLE & REPLACING PDC SENSOR	New	100.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER BOOTLID MECHANISM	New	120.00	60.00
5	TO SPRAY RUST PROOFING	New	200.00	100.00
6	TO REFILL AIR CON GAS	New	150.00	0.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
8	TTO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	TO DISMANTLE & REFIX PETROL TANK	New	100.00	60.00
10	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	New	180.00	80.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	3,000.00	2,000.00
12	TO PUTTY & SPRAY PAINTING	New	3,000.00	1,800.00
Gross Labour Cost (\$\$)			7,580.00	4,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >