

ASS. REC. BY:

REF:

CSS/ALG18022119/Jcd3^{S2}

Special Instruction:

Survivor: Three Joe
myman

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

10/12/18 @ 9:32am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLG 9140R

Insured:

SLQ 5273P

at Workshop m/s

T.W Lim Motor

Tel:

9740 9067

of

160 sin Ming Drive # 08-12

Policy No:

0999994807

Claim No:

876303577286

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/11/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:55am @ 10/12/18

Person Contacted:

Mr. Lim

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLG 9140R - X</u>
	<u>SLQ 5273P - X</u>
	<u>Dismantle: 11/12/2018</u>

PRS

REF:

AIG

Damage Hwa 2/2

ASSIGNMENT

From

Date: 10/12/18

Estimated Cost:

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 9140 R

at Workshop m/s

T.W Lim Motor

of 160 Sin Ming Drive #08-12

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Mr. Lim @ 9740 9067

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 9140 R

Yr Regn:

18 Oct 2016

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toyota

c.c. 2494

Colour:

Black

A/C: Insured / Std / NI / NA

Sp Reading:

39268

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053AK5004011488

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F: 215/55 R17

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO ☒ YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/11/18

D.O.I.

10/12/18

Survey held at

T.W Lim motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S, Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) S + RS. \$

) Photos

) Others

TOTAL

Report Format :

DAR.

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 10/12/2018 9:32:06 AM
Attachments:  tmp69C0.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 2009045722

237 Alexandra Road #04-11
The Alexclar, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oracelaw.sg

FACSIMILE TRANSMISSION

To	: AIG Asia Pacific Insurance Pte Ltd	Date	: 6 th December 2018
Attention	: Motor Claims	From	: Mr Stanley Bay / Miss Pauline Ong
Your Ref.	: Insurer of SLQ 5273P	Our Ref.	: SB/PO/Acc/2018-8874
Facsimile	: 6835-7416	No. of Pages	: 5 (including this page)

IMMEDIATE ATTENTION

Dear Sirs

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SLG 9140R & SLQ 5273P ALONG UPPER ALJUNIED ROAD ON 29-11-2018 @ 5.45 P.M.

We act for the owner of vehicle registration no. SLG 9140R.

We are instructed by our client to notify you of the above accident involving our client's said vehicle and your insured's vehicle registration no. SLQ 5273P driven at the material time. A copy of our client's motor accident report is enclosed herein.

As a result of the above accident, our client said vehicle was damaged. Before our client proceed to repair their damaged vehicle, please let us know within the next (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair his said vehicle without further reference to you.

Please note that this notification does not in any way prejudice our client's right nor shall it be deemed as a waiver of any of their rights, as such our client's rights are expressly reserved.

Yours faithfully



Mr Stanley Bay / Miss Pauline Ong
Enc

Details of Repairers

T.W. Lim Motors Works
160 Sin Ming Drive
#08-12 Sin Ming Autocity S(575722)
Tel No : 9740-9067 (hp) - Lim Tau Wing
Fax No. 6457-2371

MBH118155313 / Ajax Mers Pte Ltd - Bukit Merah
ENTRY DATE & TIME: 30/11/2018 17:16
SUBMITTED BY: Boay Loke

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/11/2018 17:16
Date Of Accident 29/11/2018 17:45
Exact Location Of Accident ALONG UPPER ALJUNIED ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLG9140R
Insured/Policyholder
Name Of Registered Owner LIM THIAM CHYE
NRIC No S0047851B
Email Address RAYMONDTCLIM@GMAIL.COM
Mobile Phone No (LOCAL) +65-96173812
Alternative Phone No OTHERS-96173812

Vehicle Particulars

Manufacturer TOYOTA
Model CAMRY 2.5 2494CC
Exact Purpose for which vehicle was being used at time of accident PRIVATE

Are you claiming under your own Insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AVIVA LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 10874191
Cover Note Number N.A

Driver

Name of Driver LIM THIAM CHYE
NRIC No S0047851B
Date Of Birth 31/01/1951
Occupation INDOOR
Date Of Driving Pass 22/06/1972
Driving Experience 46 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96173812
Fax Number
Contact Number OTHERS-96173812
Email Address RAYMONDTCLIM@GMAIL.COM

Address NIL
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1

NAME: : TOH CHO MOOI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I was driving my car along Upper Aljunied road. Suddenly vehicle SLQ5273P came from my right side and hit onto my car. Damages of my car rear door right side position. No injuries were involved.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLQ5273P
 Vehicle Make/Model/Colour HONDA VEZEL HYBRID 1.5 AUTO
 Details Of Properties NIL
 Vehicle Category PRIVATE CAR
 Name of Driver SONI KISHAN GOPAL
 NRIC/Passport Number S2714405E
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and in copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their insurers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.

VERIFIED BY: JALAN KAREK
REPORTING OFFICER

SIGNATURE

VERIFICATION

Policyholder's Signature/Name/Print Name: Driver's Signature/Name/Print Name: Workshop Name/Address:

DECLARATION

I hereby declare that the information provided in this form is true and correct to the best of my knowledge and belief, and I understand that any false or misleading information provided may result in the insurer(s) repudiating the policy liability and/or taking legal action against me. I also declare that I have read and understood the terms and conditions of the policy and the General Insurance Association of Singapore (GIA) Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties. By the lodgement of this report to the Insurers, I hereby consent to the archiving of this report at the centre and in copies of the report being made available aforesaid.

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their insurers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.

Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

I was driving my car along Upper Aljunied road. Suddenly vehicle SLQ5273P came from my right side and hit onto my car. Damages of my car rear door right side position. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
JOHNNY VOO CHEON YEE

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

30 November 2018 at 2:07 PM

Date/Time:

30 November 2018 at 2:07 PM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7851B
Vehicle Details	
Vehicle No.:	SLG9140R
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2ARU339269
Chassis No.:	MR053AK5004011488
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$29,296.00
Original Registration Date:	18 Oct 2016
First Registration Date:	18 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$33,015.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Oct 2026
PARF Rebate Amount:	\$24,761.00
Intended COE Rebate Details	
COE Expiry Date:	17 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,501.00
COE Rebate Amount:	\$43,580.00
Total Rebate Amount:	\$68,341.00

The information contained herein is correct as at 10 Dec 2018

OK

MOTOR CAR (RH)

Right Portion

Vehicle No: **SLG9140M**

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	DD	R	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	DD	-	1
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper	DD	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer RH	DD	✓	
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender	DD	R	
1229	993450	Rear RH Fender Inner Shield			
1136	990247	Sticker			
		Rear RH Wheel Rim.	DD	R	

[Signature]
12/12/2018

No of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Nov 2018 Edit Reg		10 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K		
Main Claimant:	LIM THIAM CHYE, ID: S0047851B		
Vehicle Reg. No.:	SLG9140R	Date of Loss:	29/11/2018 00:00 - :59 [25 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8763035772SG	Policy/Cover Note No.:	0999994807 (Comprehensive)
Vehicle Reg. No. (Insured):	SLQ5273P	Policy No. (Claimant):	
		Excess:	
Repairer:	T.w. Lim Motor (HQ) 160 Sin Ming Drive, #08-12, Sin Ming Auto City, 575722 Sin Ming - Tel: 97409067		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Grace-TA] Tianaigrace.Ng@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 19/12/2018]		
Insurer's Solicitor:	Oracle Law Corporation		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (11/12/2018): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG9140R (8763035772SG)**
[SLQ5273P]
TP
LIM THIAM CHYE
Nov 29 2018 12:00AM
[LCRF Pte Ltd]
T.w. Lim Motor

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page ☐	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	11/12/18 15:34	Accident Statement From: SC - Reg. No: SLQ5273P, Claimant: LCRF PTE LTD		Load HTM
Photos/Images			3 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	10/12/18 13:45	General View		Load JPG
2	10/12/18 13:45	General View		Load JPG
3	10/12/18 13:45	General View		Load JPG
4	10/12/18 13:45	General View		Load JPG
5	10/12/18 13:45	General View		Load JPG
6	10/12/18 13:45	General View		Load JPG
7	10/12/18 13:45	General View		Load JPG
8	10/12/18 13:45	General View		Load JPG
9	10/12/18 13:45	General View		Load JPG
10	10/12/18 13:45	General View		Load JPG
11	10/12/18 13:45	General View		Load JPG
12	10/12/18 13:45	General View		Load JPG
13	10/12/18 13:45	General View		Load JPG
14	10/12/18 13:45	General View		Load JPG
15	10/12/18 13:45	General View		Load JPG
16	10/12/18 13:45	General View		Load JPG
17	10/12/18 13:45	General View		Load JPG
18	10/12/18 13:45	General View		Load JPG
19	10/12/18 13:45	General View		Load JPG
20	10/12/18 13:45	General View		Load JPG
21	10/12/18 13:45	General View		Load JPG
22	10/12/18 13:45	General View		Load JPG
23	12/12/18 14:53	Photographs of Damaged Parts		Load JPG
24	12/12/18 14:53	Photographs of Damaged Parts		Load JPG
25	12/12/18 14:53	Photographs of Damaged Parts		Load JPG
26	12/12/18 14:53	Photographs of Damaged Parts		Load JPG
27	12/12/18 14:53	Photographs of Damaged Parts		Load JPG
28	12/12/18 14:53	Photographs of Damaged Parts		Load JPG
29	12/12/18 14:53	Photographs of Damaged Parts		Load JPG
30	12/12/18 14:53	Photographs of Damaged Parts		Load JPG
31	12/12/18 14:54	Photographs of Damaged Parts		Load JPG

Assessment Reports			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
32	12/12/18 14:54	Photographs of Damaged Parts		Load JPG ☒
33	12/12/18 14:54	Photographs of Damaged Parts		Load JPG ☒
34	12/12/18 14:54	Photographs of Damaged Parts		Load JPG ☒
35	12/12/18 14:54	Photographs of Damaged Parts		Load JPG ☒
36	12/12/18 14:54	Photographs of Damaged Parts		Load JPG ☒
37	12/12/18 14:54	Photographs of Damaged Parts		Load JPG ☒
38	12/12/18 14:54	Photographs of Damaged Parts		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022119/JCD3S2
Date: 18/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994807
Claimant Vehicle No : SLG9140R **Insured Vehicle No :** SLQ5273P
 Date of Loss: 29/11/2018 Nature of Claim: TP Claim No: 8763035772SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG9140R**
 Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: 2ARU339269
 Reg. Date: 18/10/2016 (Man. Year: 2016) Chassis No: MR053AK5004011488
 Colour: Black Odometer: 39268 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/12/2018
 Date Inspected: 10/12/2018 Inspected At: T.w. Lim Motor (HQ)
 160 Sin Ming Drive, #08-12, Sin Ming Auto City
 Singapore 575722
 Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*REAR RH DOOR	Dented	0.00 F	*- F
3	1		*REAR RH DOOR RUBBER	*Check	0.00 F	*- F
4	1		*REAR RH DOOR LOCK	*Check	0.00 F	*- F
5	1		*REAR BUMPER	Cut	0.00 F	*- F
6	1		*REAR BUMPER SIDE RETAINER RH	Distorted	0.00 F	*- F
7	1		*REAR RH FENDER	Repair	0.00 F	*- F
8	1		*REAR RH FENDER INNER SHIELD	*Check	0.00 F	*- F
9	1		*REAR RH WHEEL RIM	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >