

12/03/2012

ASS. REC. BY:

REF:

CS3/AIG18022126/Acd3⁵⁷

Special Instruction:

Survivor:
Munmen

Adrian

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of

AIG

Date/Time: 10/12/18 @ 10:25am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 6394Y

Insured:

SJH 429L

at Workshop m/s

TopMax Auto Body shop

Tel:

6744 2653

of

Blk 3007 Ubi Rd 1 # 01-410

Policy No:

1800094282

Claim No:

06063488688G

Sum Insured:

Excess:

Make of Veh:

D.O.A.

6/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:44am 10/12/18

Person Contacted:

Carmen

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SLP 6394Y - X
	SJH 429L - X
	Dismantle: 10/10/2018
	After repair: 13/12/2018

REF: ALG

PRS

ASSIGNMENT

From:

Date:

10/11/12

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No:

SLP6394Y

at Workshop n/s

Topmax Auto bodyshop

of Blk 3007, Ubi Rd 1 # 01-410

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 2K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP6394Y.

Yr Regn: 2017 / Jue.

Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make:

Toyota CHR.

C.C. 1297

Colour:

White

A/C: Insured / Std / Nil / NA

Sp. Reading

38315.

T/Radio: Insured / Std / Nil / NA

Eng/No:

G/No:

27X 102012927

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orModi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size:

F:

215/60R17.

R:

215/60R17.

BS: ☒ BUN ☐ EXNOVA ☐ GY ☐ FS ☐ LIZA ☐ MIC ☐ OHTSU ☐ PIR ☐ SUMI ☐

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

10/12/18.

Survey held at

Topmax.

Des. of Damages: Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ALG PRS.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

) \$ + RS, \$

) Photos

) Others

TOTAL

Report Format:

DAR

Lump Sum / I.B.I. (\$)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 10/12/2018 10:25:37 AM
Attachments:  ttmp6FC1.tif

Hi LKK,

Kindly assist to survey, vehicle will be in at 11am.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: pearlyn_goh@rssolomon.com [mailto:pearlyn_goh@rssolomon.com]
Sent: Friday, December 07, 2018 2:25 PM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit; pearlyn_goh@rssolomon.com
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJH429L AND SLP6394Y ON 06/12/2018

Dear Syaza

We refer to your email of even date.

We writed to inform that our client will be appointing his own Surveyors.

In this respect, please arrange your Surveyors to contact Ms. Carmen Chang of Topmax Auto Body Shop at tel no.6744 2653 for a pre-repair survey of our client's vehicle located at blk 3007 Ubi Road 1 #01-410 Singapore 408701.

Thank you and Best Regards

Wendy Jiang

Sent for and On behalf of

R. S. Solomon LLC

Advocates & Solicitors

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Our Ref. : RSS/1812-4494(TOP)PD
Your Ref. :

W: Pearlyn Goh/Wendy Jiang
E: pearlyn_goh@rssolomon.com /wendy_jiang@rssolomon.com

7 December 2018



R. S. SOLOMON LLC

Advocate & Solicitors | Commissioner for Oaths

By FAX: [6835 7416] & PDX: [8181]

AIG Asia Pacific Insurance Pte Ltd
No, 78 Shenton Way
#07-16 Lippo Centre
Singapore 079120
Attn: Motor Claims Dept

Dear Sirs,

PRE-REPAIR SURVEY

ACCIDENT INVOLVING SLP6394Y & SJH429L ON 6TH DECEMBER 2018 AT ABOUT 0140 HRS

We act for the owner ("our Client") of vehicle no. SLP6394Y.

2. We hereby notify you of a road traffic accident on 6th December 2018 at about 0140 hours along the slip road of Tampines Expressway to Loyang Road involving our Client's vehicle and vehicle registration no. SJH429L driven by your insured. A copy of our Client's Singapore Accident Statement is enclosed.

3. As a result of the accident, our Client's vehicle has been damaged. Before our Client proceeds to repair the damaged vehicle, please let us know within 2 working days upon receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our Client shall proceed to repair his vehicle without further reference to you.

Yours faithfully,

R. S. SOLOMON LLC
Advocates & Solicitors

Encl.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2018 16:33
Date Of Accident	06/12/2018 01:40
Exact Location Of Accident	ALONG SLIP ROAD OF TPE TO LOYANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP6394Y
Insured/Policyholder	
Name Of Registered Owner	CHUA CHIN LEONG
NRIC No	S7611584B
Email Address	DONCHUA28@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93834998
Alternative Phone No	OFFICE-93834998

Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR HYBRID-1.8 E G CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP305737
Cover Note Number	

Driver

Name of Driver	CHUA CHIN LEONG
NRIC No	S7611584B
Date Of Birth	24/04/1976
Occupation	INDOOR
Date Of Driving Pass	06/04/1995
Driving Experience	23 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93834998
Fax Number	
Contact Number	OFFICE-93834998
Email Address	DONCHUA28@GMAIL.COM


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 6 Dec
 Policyholder's Signature
 Date & Time: 4pm

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:


Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 6 Dec 4pm

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This morning around 0140 hrs 6 Dec while I was exiting out from TPE via Logan exit. I stopped at the give way line for the straight vehicles. The vehicle driven by Marcus Chung SJH429L ie S79298246 hit onto my rear at the vehicle while my vehicle stopping at the give way line.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 6 Dec 18
Policyholder's Signature
Date & Time: 4 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1584B
Vehicle Details	
Vehicle No.:	SLP6394Y
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	2ZR8035489
Chassis No.:	ZYX102012927
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$28,161.00
Original Registration Date:	13 Jun 2017
First Registration Date:	13 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$42,477.00
Total Rebate Amount:	\$46,227.00

The information contained herein is correct as at 19 Dec 2018

OK

- Who like cats?
- Fast food meals have fewer calories than restaurant di...
- Consolidated Info on MRT/LRT Maintenance & Breakdo...

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A



2.88%P.A Lowest Interest@Gv.
Cars Financing \$2000
Downpayment Monthly From
\$638
GV Credit Pte Ltd StarAd



Browse by Category

* Back (1 2 3) Next *

Sort by Date Posted

20 results/page

41 vehicles

Toyota C-HR

Advanced Search

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Toyota C-HR		Any	Any	2017	Any	Any	Any	All

**Toyota C-HR Hybrid 1.8A S**

\$90,800

\$10,330 /yr

05-Jul-2017

1,797 cc

5,000 km

SUV

Available

Fuel Type: Petrol-Electric

Almost New Toyota C-HR S Hybrid With Toyota C Sensing, Lane Departure, Pre-Collision Sensing, New Facelift Pearl White, 10% Down Payment 10 Years Repayment, In House Loan Or Balloon Scheme Available ...

Trust Motoring

Posted: 19-Dec-2018

Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S (OPC)**

\$85,900

\$9,240 /yr

29-Dec-2017

1,797 cc

21 km

SUV

Available

Fuel Type: Petrol-Electric

Newly Registered. Mileage Only 21Km Done. Comes With Warranty For 3 Years Or 100000 Km Whichever Comes First Commence On Date Of Purchase.

Posted: 19-Dec-2018

Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S**

\$89,800

\$9,860 /yr

26-Oct-2017

1,797 cc

8,000 km

SUV

Available

Fuel Type: Petrol-Electric

Super Low Km Done Of 8000km Under Warranty, 100% Acct Free Sta Welcome 10% Down Payment With Loan Interst At 1.98%Mthly From \$788. Cheaper Than Renting A Car So Hurry Do Call For Our Friendly Sales For ...

Posted: 19-Dec-2018

Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S**

\$88,000

\$9,720 /yr

06-Oct-2017

1,797 cc

-

SUV

Available

Fuel Type: Petrol-Electric

Sporty Red SUV, Almost Brand New Condition, One Owner Only, Low Fuel Consumption With Hybrid, Low Maintenance Cost, With Warranty, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages...

Prime Motor & Leasing

Posted: 18-Dec-2018

Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Lee Sheng Auto Pte Ltd - Spray Painting**

Lee Sheng Motor Works is a one-stop repair centre offering vehicle servicing, repairs, accident claims and spray painting.

More info about this shop

**Toyota C-HR Hybrid 1.8A S**

\$95,000

\$10,980 /yr

23-May-2017

1,797 cc

50,000 km

SUV

Available

Fuel Type: Petrol-Electric

Well Maintained CHR With Yearly Sealant Waxing Own By A Car Lover Looking To Exchange With A Honda Civic Latest Model As An Option.

Posted: 18-Dec-2018

Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S**

\$86,500

\$9,300 /yr

29-Dec-2017

1,797 cc

2,300 km

SUV

Available

Fuel Type: Petrol-Electric

Rarely Used, Lowest Mileage Of Only 2300 Kms. Huge Savings Compared To New Car, Accident Free, Car Kept Under Shade. In Pristine Condition. Cheapest Unit On The Market From Direct Seller.

Posted: 17-Dec-2018

Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

Compare

Tc
Fuel T
Limited

8A G

\$102,800

\$11,090 /yr

29-Dec-2017

1,797 cc

50 km

SUV

Available

Interest Rate Of 1.98%! No Gimmicks, Act Fast! LED Version, 5 Years Warranty For Car And Hybrid Battery, Hottest SUV



On The Market Right Now. Kindly Contact Us For More D...

Auto Zoom Enterprise Pte Ltd

Posted: 16-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A G

\$101,800

\$10,980 /yr

22-Dec-2017

1,797 cc

SUV

Available

Elegant Blue SUV, "G" Edition Model, Low Fuel Consumption With Hybrid, Almost Brand New Condition, With Warranty, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 16-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A S

\$89,800

\$9,680 /yr

26-Dec-2017

1,797 cc

SUV

Available

Fuel Type: Petrol-Electric

Sporty Blue SUV, Almost Brand New Condition, One Owner Only, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Low Mileage Done, With Warranty, Drive Away With Minimum Down Payment, Flexible In-...

Prime Motor & Leasing

Posted: 16-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A S (OPC)

\$80,000

\$8,830 /yr

28-Sep-2017

1,797 cc

13,780 km

SUV

Available

Fuel Type: Petrol-Electric

\$0 Drive Away! High Loan Available. Low Mileage OPC Unit. 1.8 Hybrid. Revised OPC (Use Full Day On Saturday) Eco Fuel Saving. Beautiful Paintwork. 160 Points Check Done. One Owner. Massive Saving From...

Inchcape Pre-Owned

Posted: 16-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD



Compare your car insurance quotations!

Save 25% on your car insurance, compare your quote from 10 insurers! Make your choice on zero excess and own workshop! Get your cheaper quote now!

Find out more!



Toyota C-HR Hybrid 1.8A G

\$89,800

\$10,340 /yr

26-Apr-2017

1,797 cc

12,000 km

SUV

Available

Fuel Type: Petrol-Electric

90% Loan Available! 1 Owner High Spec G Model In Sporty White With Lush Black Interior! Extremely Well Maintained By Meticulous Owner! The Hybrid Option Will Prove Popular Choice For You. Toyota's Saf...

Autotruster Traders Pte Ltd

Posted: 16-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD



Toyota C-HR 1.2A S-T Turbo

\$86,800

\$8,330 /yr

24-Aug-2017

1,196 cc

19,559 km

SUV

Available

Only \$8K Plus Depreciation, C-HR 1.2A Turbo! 1 Owner, Guaranteed Non Grab/Uber Car. Genuine Low Mileage Done 19559km With Proof! Totally Brand New. 100% Accident Free. In-House Loan To 90%. Call Now!

Lake View Credit Pte Ltd

Posted: 15-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD



Toyota C-HR Hybrid 1.8A Icon

\$81,800

\$9,100 /yr

05-May-2017

1,798 cc

33,000 km

SUV

Available

Fuel Type: Petrol-Electric

Almost Brand New Condition, "Icon" Model With High OMV \$35k. One Owner Only, Low Fuel Consumption With Hybrid, With Warranty, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down P...

Posted: 15-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD



Toyota C-HR Hybrid 1.8A G

\$91,800

\$10,280 /yr

27-Jun-2017

1,797 cc

13,000 km

SUV

Available

Fuel Type: Petrol-Electric

Don't Miss This Rare G Specification Slip Away, 1 Lady Owner, Her Loss And Your Gain, New Rims And Tyres, Low Mileage, Ceramic Coating, Not A PHV Car, Accident Free Condition, Service And Maintained B...

Car Buyers Automotive Pte Ltd

Posted: 13-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD



Toyota C-HR Hybrid 1.8A S

-

N.A

22-Aug-2017

1,797 cc

-

SUV

SOLD

Fuel Type: Petrol-Electric

Sporty Silver SUV, Almost Brand New Condition, One Owner Only, Low Fuel Consumption With Hybrid, Low Maintenance Cost, With Warranty, Drive Away With Minimum Down Payment, Flexible In-house Loan Packa...

Prime Motor & Leasing

Posted: 13-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A S

\$104,888

\$11,370 /yr

21-Dec-2017

1,797 cc

13,000 km

SUV

Available

Fuel Type: Petrol-Electric

5 Years Warranty Till 2022! Well Maintained With \$5k Spent On Accessories! Upgraded G-Model Leather Seats, Front/Rear Sensors, Pioneer S050 Audio Headunit. Comes With Nice 3 Digits Number Plate "583"....

Euro Pi

Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD

Compare

P



Toyota C-HR Hybrid 1.8A G \$96,800 \$10,710 /yr 29-Aug-2017 1,797 cc 25,000 km SUV Available

Fuel Type: Petrol-Electric
Full Bodykit! Very Good Fuel Consumption. Flexible Loan! Tire Pressure Indicator, D1 Spec Rs B8K, Simota Air Intake, Cusco Strut Bar And Undercarriage Bar, 4 x Magnetic Shades, Pioneer 5850 Head Unit,...

Posted: 07-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD



Toyota C-HR Hybrid 1.8A S - N.A 29-Dec-2017 1,797 cc - SUV SOLD

Fuel Type: Petrol-Electric
New Car Condition. Superb Low Fuel Consumption Which Gives 30km For A Litre. Stylish Cut. Precision Drive. Paid Extra For Daytime Running Light And Additional Taillight. Classy Red. Dual Lens Car Cam....

Prem Roy Motoring

Posted: 07-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

COMMITMENT



Toyota C-HR Hybrid 1.8A G \$96,000 \$10,910 /yr 01-Jun-2017 1,797 cc 27,000 km SUV Available

Fuel Type: Petrol-Electric
High Spec 'G' Model With Full Specs. 1 Owner, In Brand New Condition Inside Out! 100% Accident Free Guaranteed. 5 Years Warranty! Low Fuel Consumption With Hybrid, Low Maintenance Cost. Flexible Loan ...

360 VR Cars

Posted: 06-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD



Toyota C-HR Hybrid 1.8A S - N.A 21-Dec-2017 1,797 cc - SUV SOLD

Fuel Type: Petrol-Electric
Car Buyers Automotive Pte Ltd

Posted: 01-Dec-2018 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Makes Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2 3) Next »

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota C-HR, Toyota C-HR Singapore, used Toyota C-HR Singapore, used vehicles Singapore or even buy used Toyota C-HR Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement
©2004-2018 sgCarMart. All rights reserved.

Compare

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (C)
(4) Not Consistent (N/C)

Aug 2005

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower (Black)	DD	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DLS	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector	Reflector	✓	2
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	RR	✓	2
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	RR	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	RR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	RR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	RR	✓	
1167	993853	Rear RH Taillamp Garnish	RR	✓	
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH Tailgate	RR	✓	
1176	992899	Bootlid Lamp RH Tailgate	RR	✓	
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber Tailgate	CRU	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	3
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish outer	RR	✓	
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	BT	✓	2
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	HT	✓	
1198	994651	Tailgate Rubber	CRU	✓	
1199	994611	Tailgate Hinge Lock Cover	CRU	✓	
1200	994594	Tailgate Damper	RR	✓	

Tailgate Camera

Vehicle No:

SLP 6394Y

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	CRU	✓	
1203	994328	Spare Tyre Panel	RR	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

19/12/2008

Steve 18/12/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Dec 2018 Edit Reg		10 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	CHUNG HENG MUN, MARCUS, ID: S7929824G		
Main Claimant:	CHUA CHIN LEONG, ID: S7611584B		
Vehicle Reg. No.:	SLP6394Y	Date of Loss:	06/12/2018 01:00 - :59 [17 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0606348568SG	Policy/Cover Note No.:	1800094282 (Comprehensive)
Vehicle Reg. No. (Insured):	SJH429L	Policy No. (Claimant):	
		Excess:	
Repairer:	Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410, 408701 Ubi - Tel: 90622722		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/12/2018]		
Claimant's Solicitor:	R.S. SOLOMON LLC - Tel: 68177498		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (11/12/2018): Request for TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLP6394Y (0606348568SG)**
[SJH429L]
TP
CHUA CHIN LEONG
Dec 6 2018 1:00AM
[CHUNG HENG MUN, MARCUS]
Topmax Auto Body Shop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
View [View in Browser](#) ▼


Assessment Reports












































1 per page ▼ ☒


























No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/12/18 12:11	Accident Statement From: OD - Reg. No: SJH429L, Claimant: CHUNG HENG MUN, MARCUS	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	11/12/18 14:39	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	11/12/18 14:39	General View	 Load JPG	✓
33	11/12/18 14:39	General View	 Load JPG	✓
34	11/12/18 14:39	General View	 Load JPG	✓
35	11/12/18 14:39	General View	 Load JPG	✓
36	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
37	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
38	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
39	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
40	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
41	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
42	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
43	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
44	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
45	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
46	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
47	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
48	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
49	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
50	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
51	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
52	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
53	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
54	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
55	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
56	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
57	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
58	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
59	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
60	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
61	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
62	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
63	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
64	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
65	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
66	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
67	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
68	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
69	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
70	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
71	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
72	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
73	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
74	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
75	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
76	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
77	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
78	11/12/18 14:40	Photographs of Damaged Parts	 Load JPG	✓
79	11/12/18 14:40	Photographs of Damaged Parts	Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
80	11/12/18 14:40	Photographs of Damaged Parts		Load JPG ✓
81	11/12/18 14:40	Photographs of Damaged Parts		Load JPG ✓
82	11/12/18 14:40	Photographs of Damaged Parts		Load JPG ✓
83	11/12/18 14:40	Photographs of Damaged Parts		Load JPG ✓
84	11/12/18 14:40	Photographs of Damaged Parts		Load JPG ✓
85	11/12/18 14:40	Photographs of Damaged Parts		Load JPG ✓
86	24/12/18 14:03	Photo After Spray		Load JPG ✓
87	24/12/18 14:03	Photo After Spray		Load JPG ✓
88	24/12/18 14:03	Photo After Spray		Load JPG ✓
89	24/12/18 14:03	Photo After Spray		Load JPG ✓
90	24/12/18 14:03	Photo After Spray		Load JPG ✓
91	24/12/18 14:03	Photo After Spray		Load JPG ✓
92	24/12/18 14:03	Photo After Spray		Load JPG ✓
93	24/12/18 14:03	Photo After Spray		Load JPG ✓
94	24/12/18 14:03	Photo After Spray		Load JPG ✓
95	24/12/18 14:03	Photo After Spray		Load JPG ✓
96	24/12/18 14:03	Photo After Spray		Load JPG ✓
97	24/12/18 14:03	Photo After Spray		Load JPG ✓
98	24/12/18 14:03	Photo After Spray		Load JPG ✓
99	24/12/18 14:03	Photo After Spray		Load JPG ✓
100	24/12/18 14:03	Photo After Spray		Load JPG ✓
101	24/12/18 14:03	Photo After Spray		Load JPG ✓
102	24/12/18 14:03	Photo After Spray		Load JPG ✓
103	24/12/18 14:03	Photo After Spray		Load JPG ✓
104	24/12/18 14:03	Photo After Spray		Load JPG ✓

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022126/ACD3S2

Date: 27/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800094282
 Claimant Vehicle No: SLP6394Y Insured Vehicle No: SJH429L
 Date of Loss: 06/12/2018 Nature of Claim: TP Claim No: 0606348568SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP6394Y
 Make & Model: TOYOTA C-HR HYBRID, 1.8 E G CVT (A) Engine No: 2ZR8035489
 Reg. Date: 13/06/2017 (Man. Year: 2017) Chassis No: ZYX102012927
 Colour: White Odometer: 38315 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/12/2018
 Date Inspected: 10/12/2018 Inspected At: Topmax Auto Body Shop (HQ)
 Estimated Period of Repair: 6.0 days Blk 3007 Ubi Road 1 #01-410
 Singapore 408701

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER LOWER (BLACK)	Dented	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	2		*REAR BUMPER REFLECTOR GARNISH	Broken	0.00 F	*- F
7	2		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
8	1		*REVERSE SENSOR	Broken	0.00 F	*- F
9	1		*REAR END PANEL	Dented	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
11	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
12	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
13	1		*REAR RH TAILLAMP BRACKET	Broken	0.00 F	*- F
14	1		*TAILGATE LAMP LH	Broken	0.00 F	*- F
15	1		*TAILGATE LAMP RH	Broken	0.00 F	*- F
16	1		*TAILGATE RUBBER	Crushed	0.00 F	*- F
17	1		*TAILGATE	Dented	0.00 F	*- F
18	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
19	1		*TAILGATE GARNISH OUTER	Broken	0.00 F	*- F
20	2		*TAILGATE LAMP	Cut	0.00 F	*- F
21	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
22	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
23	1		*TAILGATE LOCK	Bent	0.00 F	*- F
24	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
25	1		*TAILGATE LOCK COVER	Cut	0.00 F	*- F
26	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
27	1		*TAILGATE CAMERA	*Check	0.00 F	*- F
28	1		*SPARE TYRE BOARD	Crushed	0.00 F	*- F
29	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
30	1		*REAR LH FENDER INNER SHIELD	*Check	0.00 F	*- F
31	1		*REAR RH FENDER INNER SHIELD	*Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >