

ASS. REC. BY:

REF: CS3/AIG18022127/Gcd3^{sr}

Special Instruction:

Surveyor: Guo Qiang

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 10/12/18 @ 10:35am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 6954C

Insured:

SKR 4596X

at Workshop m/s

Automorke Automotive

Tel:

94743434

of

8 koki Bkt Ave 4 # 05-01/02

Policy No:

2100402541

Claim No:

094402628986

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/11/18

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:56am @ 10/12/18

Person Contacted:

Mering

Vehicle: IN / LOUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLL 6954C - X</u>
	<u>SKR 4596X - X</u>
	<u>Disrupt: 13/12/2018</u>

WHS: 01
Bimpuir

PRS
Xarl.

REF: AIG

C4107W

ASSIGNMENT

(-2028)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: **Auto werke Auto**
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SLL6954C** Yr Regn: **22 Jan 2009**
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Toyota vellfire** c.c. **3456**
 Colour: **white** A/C: Insured / Std / NI / NA
 Sp. Reading: **255653** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **CHH 2080 15900**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD Rim or _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

<input checked="" type="radio"/>	
N/S	O/S

Tyre Size: F: **235/50 R18**
 R: **11**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **FALKEN**
 Front Rear
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. _____ D.O.I. **10-12-18**
 Survey held at **W/S** **12:45pm**
 Des. of Damages Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **8** days Res.: Yes or No
 Lum Sum: **20** % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	\$10K - \$12K

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____
 Report Format : **DAR**
 Lump Sum / I.B.I: (\$ _____)

Days Of Repair: **8**
 Resurvey No. of Trip: **1**
 Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)
 Survey Fee: _____
 Transportation: _____
 S + RS: \$ _____
 Photos: _____
 Others: _____
 TOTAL: _____

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 10/12/2018 10:35:45 AM
Attachments:  tmpD5A2.tif

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: SKR 4596X

Our Ref: AL.INS.2018.SLL6954C

5 December 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY FAX; 6835 7416

78, Shenton Way
AIG Building, #08-16
Singapore 079120

Dear Sirs,

**ACCIDENT INVOLVING SLL 6954C & SKR 4596X ALONG JUNCTION OF
BAYFRONT AVNUE AND CENTRAL BOLEVARD ON 30 NOVEMBER 2018 AT
ABOUT 1440 HOURS**

We act for the owner of vehicle no. SLL 6954C

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -

AUTOWERKE AUTOMOTIVE PTE LTD

8 Kaki Bukit Avenue 4
#05-01/02 Premier Building
Singapore 415875
Person In-Charge: Merina Chia
Mobile Number: 9474 3434

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jeremy Peh at 6438 3303 or email us at jeremypeh@alt.sg for future correspondences.

Yours faithfully



ALLISTER LIM

ALLISTER LIM & THRUMURGAN

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2018 13:29
Date Of Accident	30/11/2018 14:40
Exact Location Of Accident	BAYFRONT AVE X CENTRAL BLVD JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6954C
Insured/Policyholder	
Name Of Registered Owner	KINGEVER PTE. LTD.
Co Reg No	201504107W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88091708
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VELLFIRE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092168347-01
Cover Note Number	
Driver	
Name of Driver	CHEN YICHAO
Passport No/FIN	G1211729P
Date Of Birth	04/03/1991
Occupation	OUTDOOR
Date Of Driving Pass	26/07/2018
Driving Experience	0 YEAR AND 4 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98698777
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 668B JURONG WEST ST 64 #04-110
 Postcode 642668
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR4596X
 Vehicle Make/Model/Colour
 Details Of Properties VEH B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Handwritten Signature]


Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

BAYFRONT AVE & CENTRAL BLVD JUNCTION
 VEH A: SLL 6954C
 VEH B: SKR 4596X

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED DATE & TIME, I VEH A (SLL 6954C) WAS WAITING AT THE JUNCTION OF BAYFRONT AVE & CENTRAL BLVD FOR THE TRAFFIC LIGHT TO TURN GREEN & MOVE TOWARD JABS. AS THE TRAFFIC LIGHT TURN GREEN I MOVE OFF, JUST WHEN I MOVE OFF AT A VERY SLOW SPEED, AS I JUST PICK UP, VEH B (SKR 4596X) DID A RIGHT TURN ON THE OPP LANE INTO CENTRAL BLVD, AS VEH. B DIDNT TURN ON GREEN ARROW, VEH B HIT ONTO MY FRONT & DAMAGE MY VEH WHOLE FRONT PORTION MAKING MY VEH UNABLE TO START PLUS BADLY DAMAGE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4107W
Vehicle Details	
Vehicle No.:	SLL6954C
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 3.5Z G-EDITION A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	2GR0607763
Chassis No.:	GGH208015900
Maximum Power Output:	206.0 kW (276 bhp)
Open Market Value:	\$53,614.00
Original Registration Date:	22 Jan 2009
First Registration Date:	22 Jan 2009
Transfer Count:	2
Actual ARF Paid:	\$53,614.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2019
PARF Rebate Amount:	\$26,807.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,553.00
COE Rebate Amount:	\$2.00
Total Rebate Amount:	\$26,809.00

The information contained herein is correct as at 11 Dec 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2018 Edit Reg		10 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	WONG YONG MEI (HUANG RONGMEI) , ID: S7517439Z		
Main Claimant:	-		
Vehicle Reg. No.:	SLL6954C	Date of Loss:	30/11/2018 00:00 - :59 [118 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0944026289SG	Policy/Cover Note No.:	2100402541 (Comprehensive) Coverage: 10/02/2018 - 09/02/2019
Vehicle Reg. No. (Insured):	SKR4596X	Policy No. (Claimant):	
		Excess:	
Repairer:	Autowerke Automotive Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-01/02, Premier Building, 415875 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/12/2018]		
Claimant's Solicitor:	ALLISTER LIM & THRUMURGAN - Tel: 64222187		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (11/12/2018): Request for TP GIA report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLL6954C (0944026289SG)
[SKR4596X]**

TP

-

**Nov 30 2018 12:00AM
[WONG YONG MEI (HUANG RONGMEI)]
Autowerke Automotive Pte Ltd**

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/12/18 12:07	Accident Statement From:OD - Reg. No: SKR4596X, Claimant: WONG YONG MEI	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
2	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
3	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
11	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
12	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
13	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
14	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
15	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
16	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
17	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
18	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
19	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
20	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
21	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
22	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
23	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
24	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
25	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
26	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
27	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
28	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
29	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
30	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>
31	11/12/18 17:16	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	11/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	21/12/18 09:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022127/GCD3S2
Date: 26/12/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100402541
Claimant Vehicle No :	SLL6954C	Insured Vehicle No :	SKR4596X
Date of Loss:	30/11/2018	Nature of Claim:	TP
		Claim No:	0944026289SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL6954C	Engine No:	2GR0607763
Make & Model:	TOYOTA VELLFIRE, 3.5 Z G-EDITION A (A)	Chassis No:	GGH208015900
Reg. Date:	22/01/2009 (Man. Year: 2008)	Odometer:	255653 km
Colour:	White		
Engine Capacity:	3456 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	10/12/2018		
Date Inspected:	10/12/2018	Inspected At:	Autowerke Automotive Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-01/02, Premier Building Singapore 415875
Estimated Period of Repair:	8.0 days		

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Missing	0.00 F	*-F
2	1		*FRT NUMBER PLATE BASE	Missing	0.00 F	*-F
3	1		*FRT BUMPER	Missing	0.00 F	*-F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
5	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*-F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*-F
7	1		*FRT BUMPER SPONGE	Missing	0.00 F	*-F
8	1		*FRT BUMPER GRILLE (LOWER)	Missing	0.00 F	*-F
9	1		*FRT LH BUMPER FOG LAMP COVER	Missing	0.00 F	*-F
10	1		*FRT RH BUMPER FOG LAMP COVER	Missing	0.00 F	*-F
11	1		*FRT LH BUMPER FOG LAMP	Missing	0.00 F	*-F
12	1		*FRT RH BUMPER FOG LAMP	Missing	0.00 F	*-F
13	1		*FRT GRILLE	Missing	0.00 F	*-F
14	1		*FRT GRILLE EMBLEM	Missing	0.00 F	*-F
15	2		*FRT SUPPORT PANEL LH & RH	Bent	0.00 F	*-F
16	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Crushed	0.00 F	*-F
17	2		*HORN	Broken	0.00 F	*-F
18	1		*FRT BRACE PANEL	Bent	0.00 F	*-F
19	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*-F
20	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*-F
21	1		*BONNET	Dented	0.00 F	*-F
22	1		*BONNET LOCK	Bent	0.00 F	*-F
23	1		*BONNET LOCK SUPPORT PANEL	Bent	0.00 F	*-F
24	2		*BONNET HINGE	Bent	0.00 F	*-F
25	1		*AIR CON CONDENSER	Bent	0.00 F	*-F
26	1		*RADIATOR	Bent	0.00 F	*-F
27	1		*RADIATOR FAN ASSY	Broken	0.00 F	*-F
28	1		*AIR DUCT	Broken	0.00 F	*-F
29	1		*AIR CLEANER RESONATOR	Broken	0.00 F	*-F
30	2		*HEADLAMP GARNISH	Broken	0.00 F	*-F
31	2		*RADIATOR SIDE AIR DEFLECTOR	Missing	0.00 F	*-F
32	1		*FRONT LOWER PANEL	Bent	0.00 F	*-F
33	1		*RADIATOR LOWER SUPPORT BRACKET	Broken	0.00 F	*-F
34	1		*WIPER WASHER TANK	Crushed	0.00 F	*-F
35	1		*ENGINE UNDER COVER (REAR)	Broken	0.00 F	*-F
36	1		*ENGINE UNDER COVER (FRONT)	Broken	0.00 F	*-F
37	1		*ENGINE MOUNTING FRT	Torn	0.00 F	*-F
38	1		*FRT LH FENDER	Bent	0.00 F	*-F
39	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*-F
40	1		*FRT RH FENDER INNER SHIELD	Torn	0.00 F	*-F
41	1		*WIPER PANEL GARNISH	Crushed	0.00 F	*-F
42	1		*FRONT SUSPENSION CROSS MEMBER	Bent	0.00 F	*-F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >