

ASS. REC. BY:

REF: CS3 / msl18022162 / scb524

Special Instruction:

Surveyor: Amel He ASSIGNMENT (Office)From (Person): Irene Tan of MSH Date/Time: 10/12/2018 243pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: Scp 3409T Insured: YN 170261at Workshop m/s Platinum Werkz Tel: 88267413of 53 Ubi Rd 1 #01-25Policy No: 3290 40188 MKF Claim No: 578235

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 03-12-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

11.12.2018

H.O.D. Endorsement: _____

Date/Time: 10.12.2018 3:49pm Person Contacted: Dora Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>Scp 3409T - x</u>
	<u>YN 170261 - CCB / AXA 11011531 / Ugidkz</u> DPA: 14062011
	<u>Disassemble: 11/12/2018</u>
	<u>After repair: 17/12/2018</u>

RRS
Huei Jie
Mufimen

REF: MSLG

ASSIGNMENT

From: Date: 11-12-18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGP 3409 T
at Workshop m/s: Platinum Werkz
of: 53 Ubi Rd 1 #01-25

Insured

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est Repairs: 5 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGP 3409 T Yr Regn: 13 Dec 2006

Type: ☒ Car / ☒ ~~Car~~ / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish C.C. 1794

Colour: Blue A/C Insured / Std / NI / NA

Sp. Reading: 273896 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZNE100326032

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size: F: 215/45 R17

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 3/12/18 D.O.I. 11/12/18

Survey held at: Platinum Werkz

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$4,800 - \$5,500
5 days

[Signature]
17/12/2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Report Format: PRE

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + R5. \$

) Photos

) Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2018		10 Dec 2018 14:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TRACTORS SINGAPORE LTD, Co. Reg. No.: 196600025H								
Main Claimant:	MUHAMMAD ERMAN BIN JOHARI, ID: S1323229F								
Vehicle Reg. No.:	SGP3409T	Date of Loss:	03/12/2018 17:00 - :59 [143 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 578235	Policy/Cover Note No.:	B29040188MKF (Comprehensive) Coverage: 01/10/2017 - 30/09/2019						
Vehicle Reg. No. (Insured):	YN1702G	Policy No. (Claimant):							
		Excess:							
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/12/2018]								
Driver/Custodian (Insured):	TAN CHOON PENG (), NRIC: S6932208E, Tel: +6593394316								
Adj Asg. Remarks:	Liability 100%. SJE DISAGREE LKK. Contact person: Dorø 88261413								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2018 15:38
Date Of Accident	03/12/2018 17:20
Exact Location Of Accident	BRICKLAND RD TWDS CHOA CHU KANG AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGP3409T
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD ERMAN BIN JOHARI
NRIC No	S1323229F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97101176
Alternative Phone No	OFFICE-97101176

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1442652
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ERMAN BIN JOHARI
NRIC No	S1323229F
Date Of Birth	18/08/1958
Occupation	INDOOR
Date Of Driving Pass	15/08/1981
Driving Experience	37 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97101176
Fax Number	
Contact Number	OFFICE-97101176
Email Address	NOEMAIL

Address	BLK 203 CHOA CHU KANG AVE 1 #02-43
Postcode	680203
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 03/12/2018 AT AROUND 1720HRS, VEHICLE A (SGP3409T) WAS DRIVING AT THE SECOND LANE FROM BRICKLAND ROAD TOWARDS CHOA CHU KANG AVE 3. AFTER THAT, VEHICLE A FELT AN IMPACT FROM THE BACK OF THE CAR. VEHICLE A (SGP3409T) WENT DOWN AND NOTICE THE REAR SIDE WAS DAMAGED BY VEHICLE B (YN1702G).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN1702G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD ERMAN BIN JOHARI
------	---------------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGP3409T

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Along Brickland Road towards Choa Chu Kang Ave 3 2nd lane

Vehicle A: SGP3409T
Vehicle B: YN1702G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3rd December 2018 at around 17.20
Vehicle A (SGP3409T) was driving at the 2nd lane
from Brickland Road towards Choa Chu Kang Ave 3.
After that vehicle (A) feel an impact from the back
of the car. Vehicle A (SGP3409T) went down and
notice the rear side was damage by Vehicle B (YN1702G)

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

6/12/18 1.40pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, MUHAMMAD ERMAN BIN JOHARI, the owner of vehicle no. SEP 21097

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents **within 14(fourteen) days of occurrence or discovery of damage.**

My/Our Third Party claim is handle by my/our preferred workshop, _____

Signed and Acknowledge by:



NIC no. & signature of policyholder

Company stamp

06/12/2018

Date

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3229F
Vehicle Details	
Vehicle No.:	SGP3409T
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	1ZZ2694945
Chassis No.:	ZNE100326032
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,144.00
Original Registration Date:	13 Dec 2006
First Registration Date:	13 Dec 2006
Transfer Count:	1
Actual ARF Paid:	\$19,959.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$27,594.00
COE Rebate Amount:	\$16,571.00
Total Rebate Amount:	\$16,571.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Dec 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2018		10 Dec 2018 14:43 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TRACTORS SINGAPORE LTD, Co. Reg. No.: 196600025H			
Main Claimant:	MUHAMMAD ERMAN BIN JOHARI, ID: S1323229F			
Vehicle Reg. No.:	SGP3409T	Date of Loss:	03/12/2018 17:00 - :59 [143 Months and 20 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 578235	Policy/Cover Note No.:	B29040188MKF (Comprehensive) Coverage: 01/10/2017 - 30/09/2019	
Vehicle Reg. No. (Insured):	YN1702G	Policy No. (Claimant):		
		Excess:		
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 11/12/2018]			
Driver/Custodian (Insured):	TAN CHOON PENG (), NRIC: S6932208E, Tel: +6593394316			
Adj Asg. Remarks:	Liability 100%. SJE DISAGREE LKK. Contact person: Dora 88261413			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									































Claim Documents
















*SGP3409T (578235)
[YN1702G]
TP
MUHAMMAD ERMAN BIN JOHARI
Dec 3 2018 5:00PM
[TRACTORS SINGAPORE LTD]
Platinum Werkz Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/18 17:52	Accident Statement From: SC - Reg. No: YN1702G, Claimant: TRACTORS SINGAPORE LTD	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/12/18 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
21	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
23	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	12/12/18 09:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
33	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
34	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
35	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
36	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
37	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
38	17/12/18 10:32	Photo After Spray	 Load JPG	✓
39	17/12/18 10:32	Photo After Spray	 Load JPG	✓
40	17/12/18 10:32	Photo After Spray	 Load JPG	✓
41	17/12/18 10:32	Photo After Spray	 Load JPG	✓
42	17/12/18 10:32	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/18 17:52	PRI From:SC - Reg. No: YN1702G, Claimant: TRACTORS SINGAPORE LTD	 Load PDF	
2	07/12/18 17:52	TP SGP3409T E-REPORT From:SC - Reg. No: YN1702G, Claimant: TRACTORS SINGAPORE LTD	 Load PDF	
3	10/12/18 10:05	SJE DISAGREE LKK	 Load PDF	
4	10/12/18 10:29	workshop details	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022162/JCBS2

Date: 20/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29040188MKF

Claimant Vehicle No : SGP3409T

Insured Vehicle No : YN1702G

Date of Loss: 03/12/2018

Nature of Claim: TP

Claim No: 578235

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGP3409T

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2694945

Reg. Date: 13/12/2006 (Man. Year: 2006)

Chassis No: ZNE100326032

Colour: Blue

Odometer: 273896 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17

Rear Tyre Size:

215/45R17

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/12/2018

Date Inspected: 11/12/2018 Inspected At:

Platinum Werkz Pte Ltd (HQ)

53 Ubi Ave 1 01-25 Paya Ubi Industrial Park

Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,800.00 - \$5,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Dec 2018)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGP3409T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >