

ASS. REC. BY:

REF:

CS3/AIG18022175/ Jcd30

Special Instruction:

Surveyor:

Aue Jee

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

10/12/18 @ 4:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 3022D

Insured:

SKV 8168B

at Workshop m/s

Ace Autolution

Tel:

68441184 / 96572134

of

13 Kaki Bkt Rd 4 # 03-29

Policy No:

Claim No:

54350975228G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/11/18

CA / REV / REP. / REV 24 HRS

lup

11/12/18

H.O.D. Endorsement:

Date/Time:

4:39pm @ 10/12/18

Person Contacted:

Anna

Vehicle:

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLD 3022D - CC4/AXA 16018073/Aha3

Dua: 22/9/16

SKV 8168B - X

Dismantle: 12/12/2018

PRS  
Hwee Jie

REF: ALG

# ASSIGNMENT

From: Date: 11/12/18  
Estimated Cost:  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: STD 3022D  
at Workshop n/s: Ace Autolub  
of 13 Kaki Bkt Rd 4 #03-29 Biz  
Insured:  
Policy No:  
Claims No:  
Sum Insured: Excess:  
(Client's Record)  
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	①

Bal. or Market Value:  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 5 days Res.: Yes or No  
Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLD 3022D Yr Regn: 28 Feb 2011  
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: BMW 523i C.C. 2497  
Colour: Black A/C: Insured / Std / NI / NA  
Sp. Reading: 147594 T/Radio: Insured / Std / NI / NA  
Eng/No: -  
C/No: WBAFP32040C863934  
Gen. Cond: ☒ Good / Fair / Poor / Burnt  
Steering: ☒ In order / Jammed / Leaked / Burnt or  
Brake: ☒ In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 255 / 45 R19  
R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /  
TOYO / YOKO or

Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 29/11/18 D.O.I. 11/12/18  
Survey held at Ace Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) Date/Time, File Return to?  
2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : DAR.

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$


☐ : Weekend (\$

180

20

200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 10/12/2018 4:37:27 PM  
Attachments:  20181203095743441.pdf

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S

Our Ref : SLD 3022D (Jr)

Your Ref : To be advised

3 December 2018

AIG ASIA PACIFIC INSURANCE PTE LTD

BY EMAIL ONLY

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM  
CLAIMANT : MELVIN CHEONG HUI CAI  
ACCIDENT INVOLVING SLD 3022D & SKV 8168B ALONG SENGKANG EAST  
ROAD BEFORE SENGKANG EAST WAY ON 29 NOVEMBER 2018  
PRE-REPAIR SURVEY NOTICE

1. We act for Melvin Cheong Hui Cai, the owner of motor vehicle no. SLD 3022D which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SKV 8168B for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	Ace Autolution
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Ms. Anna (6844 1184)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

**MR ARULCHELVAN S**

cc: Client (By Email)

[Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4795B
Vehicle Details	
Vehicle No.:	SLD3022D
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	08687674N52B25AF
Chassis No.:	WBAFP32040C863934
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$41,236.00
Original Registration Date:	28 Feb 2011
First Registration Date:	28 Feb 2011
Transfer Count:	4
Actual ARF Paid:	\$41,236.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2021
PARF Rebate Amount:	\$24,741.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$58,890.00
COE Rebate Amount:	\$11,824.00
<b>Total Rebate Amount:</b>	<b>\$36,565.00</b>

The information contained herein is correct as at 11 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/12/2018 09:52
Date Of Accident	29/11/2018 20:45
Exact Location Of Accident	SENGKANG EAST ROAD (BEFORE SENGKANG EAST WAY)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD3022D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MELVIN CHEONG HUI CAI (MELVIN ZHUANG HUICAI)
NRIC No	S8104795B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83761611
Alternative Phone No	OTHERS-83761611

### Vehicle Particulars

Manufacturer	BMW
Model	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097430982 CLASSIC
Cover Note Number	

### Driver

Name of Driver	MELVIN CHEONG HUI CAI (MELVIN ZHUANG HUICAI)
NRIC No	S8104795B
Date Of Birth	20/02/1981
Occupation	INDOOR
Date Of Driving Pass	14/11/2016
Driving Experience	2 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83761611
Fax Number	
Contact Number	OTHERS-83761611
Email Address	NOEMAIL

Address	BLK 156 #08-249 MEI LING STREET
Postcode	140156
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV8168B
Vehicle Make/Model/Colour	VOLVO S60 T5 A/T ABS D/AIRBAG 2WD
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:


- 1 DEC 2018



SKETCH PLAN SENG KANG EAST RD BEFORE SENG KANG EAST WAY.

VEH "A" SLD 3022 D

VEH "B" SKY 8168 B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I was driving veh A along the stated venue. As I approach the traffic light, it was turning red. I slow down in lane 5, suddenly veh B hit onto the right side of my vehicle causing damages to my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

- 1 DEC 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Reporting Centre Personnel's Signature

Name: [varbb@singnet.com.sg](mailto:varbb@singnet.com.sg)

NRIC/FIN No.:

Condition (CND)

(1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
 (7) Deformed (8) Stuffed (9) Buckled (10) Broken (11) Necessary (12) Missing  
 (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (7)  
 (4) Not Consistent (NC)

Aug 2005

**MOTOR CAR (RH)****Right Portion**Vehicle No: **SLD 3022D**

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	DD	R	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender	DD	R	
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	DD	/	
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber		?	
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper	CUT	/	1
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RH	DIS	/
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender	DD	R	
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			
		Rear RH Rim	CUT	/	1

17/12/2018

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018 <a href="#">Edit Reg</a>		10 Dec 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [\[Created by adjuster\]](#)

Insured:	<b>YEO KIAN HWEE (YANG JIANHUI)</b> , ID: S7615540B		
Main Claimant:	<b>MELVIN CHEONG HUI CAI</b>		
Vehicle Reg. No.:	<b>SLD3022D</b>	Date of Loss:	29/11/2018 00:00 - :59 <b>[93 Months and 1 Days From LTA Reg Date (Man Yr)]</b>
Claim Type:	<b>TP / 5435097522SG</b>	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	<b>SKV8168B</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Ace Autolution (HQ)</b> 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... <b>[Final Rpt due 19/12/2018]</b>		
Claimant's Solicitor:	<b>CHIA S ARUL &amp; LLC</b> - Tel: 67334647		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)






































- AIG\_SG (11/12/2018): **Request To Upload TP GIA Report**

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLD3022D (5435097522SG)  
[SKV8168B]  
TP  
MELVIN CHEONG HUI CAI  
Nov 29 2018 12:00AM  
[YEO KIAN HWEE (YANG JIANHUI)]  
Ace Autolution

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
2	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
3	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
4	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
5	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
6	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
7	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
8	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
9	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
10	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
11	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
12	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
13	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
14	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
15	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
16	11/12/18 14:33	General View										Load JPG	<input checked="" type="checkbox"/>	
17	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
18	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
19	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
20	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
21	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
22	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
23	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
24	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
25	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
26	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
27	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
28	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
29	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
30	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
31	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
32	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
33	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
34	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
35	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
36	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	
37	17/12/18 09:36	Dismantled Parts										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/12/18 09:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/12/18 09:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/12/18 09:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/12/18 09:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/12/18 09:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/12/18 09:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/12/18 10:42	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022175/JCD3E2

Date: 31/12/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle  
No : SLD3022D

Insured Vehicle No : SKV8168B

Date of Loss: 29/11/2018

Nature of Claim: TP

Claim No: 5435097522SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLD3022D

Make &amp; Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)

Engine No: 08687674N52B25AF

Reg. Date: 28/02/2011 (Man. Year: 2011)

Chassis No: WBAFP32040C863934

Colour: Black

Odometer: 147594 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 255/45 R19

Rear Tyre Size: 255/45 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 10/12/2018

Date Inspected: 11/12/2018 Inspected At:

Ace Autolution (HQ)  
13 KAKI BUKIT ROAD 4, #03-29 Bartley  
Biz Centre  
Singapore 417807

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*FRT RH FENDER	Repair	0.00 F	*- F
3	1		*REAR RH DOOR	Dented	0.00 F	*- F
4	1		*REAR RH DOOR RUBBER	* Check	0.00 F	*- F
5	1		*REAR BUMPER	Cut	0.00 F	*- F
6	1		*REAR BUMPER SIDE RETAINER RH	Distorted	0.00 F	*- F
7	1		*REAR RH FENDER	Repair	0.00 F	*- F
8	1		*REAR RH RIM	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >