

Surveyor: Kalvin

REF: NS/INC 18022188 / K11bez

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

Insured: XD 1376D

Policy No. 5072281554-03 280618-270619

Claims No. WT/10 23016-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHD 4870M Yr Regn: 6 Mar, 2014

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 729024 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH18414ME4048622

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rrim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Master

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 7/12/18 D.O.I. 10/12/18

Survey held at C D G E (Loyang)

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

o/s Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 4870M - X
	XD 1376D - X
13/12/18	Check up \$3200 / 3 hrs. (Red: 2597, 44%)

RECEIVED 13 DEC 2018

Date/Time, File Pass to?

☐ Prel. Report

1) 13/12 Typist

☒ Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)

☐ Interview (\$ \_\_\_\_\_)

☐ Tech. Invs (\$ \_\_\_\_\_)

☐ Weekend (\$ \_\_\_\_\_)

Report Format: TP

Lump Sum / I.B.I. (\$) 3200

# TP Claims against NTUC Income: Follow-Through Survey

Date : 13/12/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1023016-002	COMFORT TRANSPORTATION PTE LTD	SHD 4870M	XD 1376D	7/12/2018	12:45	\$ 5,797.00
2	MT/1023382-002	COMFORT TRANSPORTATION PTE LTD	SHC 1114M	SJR 4632L	9/12/2018	14:05	\$ 2,402.32
3	MT/1023692-001	COMFORT TRANSPORTATION PTE LTD	SHC 7357P	SJU 416E	8/12/2018	6:40	\$ 1,940.16
4	MT/1023076-002	COMFORT TRANSPORTATION PTE LTD	SH 6683Y	SJF 1671G	8/12/2018	11:15	\$ 2,094.23
5	MT/1023696-001	COMFORT TRANSPORTATION PTE LTD	SHC 2729H	SLR 5667G	8/12/2018	20:50	\$ 2,752.46
6	MT/1023700-001	COMFORT TRANSPORTATION PTE LTD	SHD 4128Z	SKD 3208Y	5/12/2018	18:45	\$ 1,380.32
7	MT/1022942-002	COMFORT TRANSPORTATION PTE LTD	SHD 6822P	SHB 8780Z	6/12/2018	18:45	\$ 15,378.46
8	Duplicate Entry	COMFORT TRANSPORTATION PTE LTD	SHD 4128Z	SKD 3208Y	6/12/2018	19:45	\$ 1,380.32
9	MT/1023712-001	COMFORT TRANSPORTATION PTE LTD	SHC 3692Y	GBA 5648U	7/12/2018	15:30	\$ 4,503.68
10	MT/1023050-002	COMFORT TRANSPORTATION PTE LTD	SHA 7526D	SMA 5171Y	7/12/2018	18:35	\$ 5,179.84
11	MT/1023032-002	COMFORT TRANSPORTATION PTE LTD	SH 7276A	SJA 3473A	8/12/2018	3:20	\$ 2,419.06

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query


Policy No.  Date of Accident   
Vehicle No.(For Motor)  Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5072281554-03		BUILDMATE (S) PTE LTD	197801401G	GCV	Third Party	XD1376D	XD1376D	28/06/2018	27/06/2019

Team: ARC Repair TP(CLS0)1	<b>JOB CARD</b>	Sales Order: 3880353	JC NO.: 305248619
CUSTOMER	REGN NO.: SHD4870M	MILEAGE	
MS	MAKE: HYUNDAI	FUEL	
CUSTOMER NO. 7010045	MODEL I-40	E.....1/2.....F	
ADDRESS 383 SIN MING DRIVE	YR OF MANU 06.03.2014	DATE/TIME IN 07.12.2018 13:25	
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMEU048622	TARGET DATE	
65508755 (R) (P) (O)		COMPLETION DATE/TIME:	
COUNT CARD NO.			

Accident Date: 07.12.2018  
NATURE: 3P 07.12.18/B

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION
		

ISSUED & PASSED OUT BY: _____		CUSTOMER'S SIGNATURE _____	
SERVICE ADVISOR _____			
Assignment Slip	Exit Pass		
Vehicle No.: SHD4870M	FZ (NTUC)	SHD4870M	
Service Advisor _____	Signature/Date _____	Name of Service Advisor _____	Date _____
Returned to Service Reception upon collection		To be kept by Security Guard	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/12/2018 15:06
Date Of Accident	07/12/2018 12:45
Exact Location Of Accident	JLN EUNOS TOWARDS SIMS AVE AFTER JLN AWANG JUNCTIO
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4870M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	CHIA THAI HUAT
NRIC No	S1683154I
Date Of Birth	21/08/1965
Occupation	OUTDOOR
Date Of Driving Pass	21/09/1987
Driving Experience	31 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91011161
Fax Number	
Contact Number	
EMail Address	T.H.CHIA@LIVE.COM

Address	673B #04-609 EDGEFIELD PLAINS
Postcode	822673
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1376D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NO DAMAGE



## Sketch Plan Pg. 1

### SKETCH PLAN

7 = SHD 4870M

$$B = XD1376D$$

(SORRY)

Video Timing 12:43:25

# ARTICLE 30 IN AWWAKS

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SIMC AVE

Bus stop

CRP, BLE

7

5 4 3 2 1 0

JEN EUNO 2

Statement as per attached

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199702817R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Reporting Centre Personnel's Signature  
Name:



## Sketch Plan Pg. 2

Describe Circumstances of the Accident.

On 07/12/2018 at about 12:45hrs, I was driving along Jln Eunus towards Sims Ave direction.

Just after Jln Awang junction suddenly the lorry XD1376D encroached onto my lane and grazed onto my right wing mirror, front and rear door, rear right portion of my taxi.

01 male passenger on board my taxi. No injury reported at the point of accident.

## Declaration




I/We declare the foregoing particulars are true in every respect.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199903821R

Policyholder's Signature/Date &  
Time

Driver's Signature (If driver is not the policyholder)/Date  
& Time

Witnessed by Reporting  
Centre Personnel





Our Job Ref No : 305248619  
Date : 12.12.2018

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No : SHD 4870M

Date of Accident : 07.12.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC -- XD 1376D
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$0.00
  - (b) Labour Charges \$0.00
  - Total for Part-By-Part Repair Cost \$0.00
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$3,200.00  
Final Lumpsum Repair cost \$3,200.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and  
finalized amount

Signature : 

Name : FAUZY BIN MOKHTAR

Tel : 62148319

Fax : 65468156

Signature : 

Name : Calvin

Date : 13/12/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHD 4870M

DATE 7/12/2018 16:57

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Door (RH) <i>X Repair</i>			\$ 2,201.10	
	Front Door (RH) <i>Part</i>			\$ 2,256.40	
	Front Door Mirror Assy (RH) <i>Part</i>			\$ 670.00	
	<i>Rear Bumper X Repair (RH)</i>				
	<i>Front Windscreen Pillar X Repair</i>				
	SUB TOTAL			\$ 5,127.50	
	LESS 20%			\$ 1,025.50	
	DISCOUNTED TOTAL			\$ 4,102.00	
	Rear Door Advertisement Logo (RH) <i>AK</i>			\$ 100.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>AK</i>			\$ 80.00	Nett
	Front Door Coloured Comfort Logo (RH) <i>AK</i>			\$ 75.00	Nett
	Front Door Advertisement Logo (RH) <i>AK</i>			\$ 100.00	Nett
				\$ 355.00	
	Labour Charge				
	Panel Beating			\$ 100.00	
	Spray Painting Charge			\$ 30.00	
	Wiring Charge			\$ 50.00	
	Tuff Kote			\$ 160.00	
	Transfer of Door		\$ 80.00		
	TOTAL LABOUR			\$ 1340.00	
	ESTIMATE TOTAL			\$ 5797.00	
	<i>Kahri 10/12/18</i>				
	<i>10/12/18 11:30hr</i>				
	<i>3 hrs</i>				
	<i>4 hrs</i>				
	<i>After Repair plz</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify  
 Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged parts during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

6397




## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18022188/K1tbe2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 21-12-2018	
Code: INC4			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XD 1376D	Veh. Inspected	SHD 4870M
Policy No.	5072281554-03	Coverage (\$)	0.00
Claim No.	MT/1023016-002	Excess (\$)	0.00
Assign From		Assign Date	10/12/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHLB41UMEU048622	Colour	BLUE
Odometer	729024	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	07/12/2018	Inspection Date	10/12/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4870M**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR DOOR (RH)	TO REPAIR SEE LABOUR	2,201.10	-
1	FRONT DOOR (RH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR MIRROR ASSY (RH)	BROKEN	670.00	670.00
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT WINDSCREEN PILLAR (RH)(NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-1,025.50	-585.28
			4,102.00	2,341.12
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH)(SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
			355.00	355.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR (RH),REAR BUMPER AND FRONT WINDSCREEN PILLAR (RH).		700.00	400.00
	SPRAY PAINTING CHARGE.		1,000.00	800.00
	WIRING CHARGE.		30.00	20.00
	TUFF KOTE.		50.00	20.00
	TRANSFER OF DOOR.		160.00	50.00
			-	-
			-	-
			1,940.00	1,290.00
<b>GRAND TOTAL</b>			<b>6,397.00</b>	<b>3,986.12</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,200.00
--	--	--	----------

Report Ref No. NS/INC18022188/K1tbe2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.