

11/15/2018

ASS. REC. BY:

REF:

01/TPD18022211/P

Special Instruction

Supervisor

ASSIGNMENT (Office)

From (Person): Kameliah Kamis

of

SPF

Date/Time: 28/11/2018

Estimated Cost:

Bill to:

OD/TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YM5867T

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF06000010269

Claim No:

TP/1P/64157/2018

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

28/11/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	YM5867T-X

5501/8

⑦ YM 5867 T
Rohaizal (LKKAUTO)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Wednesday, 28 November 2018 2:36 PM
To: Rohaizal (LKKAUTO)
Cc: Bryan Ang (LKKAUTO); SPF-TP FAIT; Norashikin DAUD (SPF)
Subject: Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 13 vehicles below:

- a) Case IAFP-IB-20181028 - Mechanical Inspection of motorcycle FBJ6977L (TP/IP/60763/2018)
- b) Case IAFP-IB-20181028 - Mechanical Inspection of motor taxi SHA9324G (TP/IP/60763/2018)

On 27.10.2018 at about 8.27 am, motorcycle was travelling on the lane 1 of 2 lanes road where taxi ahead of him in-between 2 lanes suddenly made an illegal U-turn along Eng Neo Ave X Eng Neo Ave towards Dunearn Road. Motorcycle unable stop in time and collided onto the right side of taxi on the lane 1. Motorcyclists was pronounced dead at the scene.

Vehicle to be inspected: FBJ6977L – Rider (Deceased)

Vehicle to be inspected: SHA9324G – Accused

IO In-Charge: SIO Vilton

- c) Case IAFP-IB-20181113 - Mechanical Inspection of motorcycle JSJ 8870 (TP/IP/56239/2018)
- d) Case IAFP-IB-20181113 - Mechanical Inspection of motorcycle JPH 1866 (TP/IP/56239/2018)
- e) Case IAFP-IB-20181113 - Mechanical Inspection of motor Bus PC 1706 K (TP/IP/56239/2018)

On 2 October 2018 at 9.08 am, Motorcycle JSJ 8870 and Motorcycle JPH 1866 was travelling on the left lane of 4 lanes when both motorcycles side swiped onto each other causing rider of motorcycle JPH 1866 to be flung to lane 3. As a result the rider was run over by motor bus PC 1706 K travelling on lane 3. On 6 October 2018, the rider of motorcycle JPH 1866 succumbed to his injuries and was pronounced dead at TTSH.

Vehicles to be inspected: JPH 1866 (Deceased motorcycle)

Vehicles to be inspected: PC 1706K (Involved Party)

Vehicles to be inspected: JSJ 8870 (Involved Party)

IO In-Charge: SIO Yazid

- f) Case IAFP-IB-20181113 - Mechanical Inspection of Mini Bus CB 7364 H (TP/IP/59297/2018)

On 18 October 2018 at 5.22 pm, Mini Bus was entering slip road from Boon Lay way into Yuan Ching Road when the mini bus collided onto a female cyclist who was cycling on the driver's right to left. As a result of the accident the cyclist was pronounced dead in NUH the following day.

Vehicles to be inspected: Mini Bus CB 7364 H (Potential Defendant)

IO In-Charge: SIO Yazid

- g) Case IAFP-IB-20181122 - Mechanical Inspection of Motorcycle, FW8717X (TP/IP/58303/2018)
- h) Case IAFP-IB-20181122 - Mechanical Inspection of Motor car, SGK2283X (TP/IP/58303/2018)

On 12.10.2018 at about 2.59 pm, motorcycle was travelling along Ubi Ave 3 towards Kaki Bukit where at the signalised junction of Eunos Link, he was being hit by a motor car coming from his left side. Motorcyclists was pronounced dead in CGH on the next day.

Vehicle to be inspected: FW8717X – Rider (Deceased)

Vehicle to be inspected: SGK2283X – Accused

IO In-Charge: SIO Vilton

i) Case IAFP-IB-20181122 - Mechanical Inspection of Motor Car, SBJ7833R (TP/IP/63425/2018)

On 15.11.2018 at about 9.46 pm, the driver of motor car, SBJ7833R claimed that her brake did not respond when she stepped on the brake pedal. Thus, she could not brake in time and collided onto a pedestrian at a designated signalised pedestrian crossing; along Pasir Panjang Road.

Vehicle to be inspected: SBJ7833R – Accused

IO In-Charge: SIO Norashikin

j) Case IAFP-IB-20181122 - Mechanical Inspection of Mini Bus, PC5941X (TP/IP/64375/2018)

On 21 November 2018 at about 7.07 p.m., the Accused picked up 6 residents from Forestville Condo and he was proceeding to Woodlands MRT to alight them. While exiting from the said condo, the Accused made a right turn from the exit point of the condo. Halfway making the intended right turn, the frontal right portion of the Accused's mini bus collided into the right side of the Deceased while the Deceased was still walking ahead of the Accused's mini bus. Due to the collision, the Deceased sustained traumatic brain injury and he was pronounced dead on the same day at 7.26 p.m. by Paramedic Sergeant Ibnu.

Vehicle to be inspected: PC5941X – Driver (Accused)

IO In-Charge: SIO Kamaliah

k) Case IAFP-IB-20181122 - Mechanical Inspection of motorcycle FBG3870A (TP/IP/64127/2018)

l) Case IAFP-IB-20181122 - Mechanical Inspection of motor lorry YM5867T (TP/IP/64127/2018)

m) Case IAFP-IB-20181122 - Mechanical Inspection of motor lorry YN1397D (TP/IP/64127/2018)

On 20 November 2018 at about 11.28 a.m., the 1st Accused was travelling along AYE towards MCE on the centre of the 3 lanes expressway while the Deceased was riding in front within the same lane. As they were approaching the 5.5 km mark, the 1st Accused overtook the Deceased from his right however, his motor lorry veered back to the left and side-swipe against the Deceased's motorcycle. Deceased lost control of the motorcycle and fell to his left onto the left lane, under the 2nd Accused's motor lorry, in between the front and rear right tyres, and the rear right tyres of the 2nd Accused's motor lorry drove over the Deceased's helmet.

Vehicle to be inspected: FBG3870A – Rider (Deceased)

Vehicle to be inspected: YM5867T – Driver (Involved Party)

Vehicle to be inspected: YN1397D – Driver (Involved Party)

IO In-Charge: DOC Shahril

2. These request has been approved by my management.