

ASS. REC. BY:

REF:

CS/MSG1802248/USD322

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Merimer
Clarah Milah Yeo

of

MSIG

Date/Time: 11/12/18 @ 9:24am

Estimated Cost:

Bill to:

(OD) TP/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

SJT1805P

Insured:

at Workshop n/o:

WTS Automotive

Tel: 6844 9449/6844 9456

of

17 Kaki Bukit Rd 4 #01-58

Policy No:

A277649430MX

Claim No:

578401

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 29/11/2018

CA / REV

REF. / REV 24 HRS

Date/Time:

9:37am 11/12/18

Person Contacted:

Khor

H.O.D. Endorsement:

Vehicle:

(UN) UT

Date/Time

Action/Instruction

(✓) Estimate

11/12/18

SJT1805P- CA/AIG/0016812/51

DOI: 21/8/2010

@ 16:09 p.m. revised IA to Clara Milah Yeo via merimer.

11/12/18

@ 16:31 p.m. mandate request authorize repair to Clara Milah Yeo via merimer.

12/12/18

@ 12:02 p.m. mandate approval by Eng Huey Ni via merimer.

12/12/18

@ 16:54 p.m. revert authorize repair to Tram Chee Chuan 1 via email

(08/11/13) wef

ASS. REC. BY: MAV165

REF:

MS14/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MVTo Inspect Vehicle No: 571805Pat Workshop m/s W15

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 166

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / ☒ REV / REP. / 24 HRS70306

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time

Action / Instruction

27/10/1810 minRepier Ashy 45.18/12/18 carpenter 45 & 2150 with 10 min.18/12/18 Confirmed 45 & 2,150/- @ 4 days with Marv's
(\\$1,250/- Red - 37%)

RECEIVED 19 DEC 2018

Date/Time, File Pass to?

19/12/181) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

15010160

Report Format:

Lump Sum / I.B.I.: (\$ 2,150/- 45)Veh No: 571805PYr Regn: 28/9 09Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or CAMake: Toyota corolla Altis c.c1598Colour: GreyA/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 160340T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: MR0532EE106155294Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 195/65-15

R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /☒ TOYO / ☐ YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 29/11/18D.O.I. 11/12/18

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018 Sendback Est	10 Dec 2018 16:59 S\$3,400.00	11 Dec 2018 09:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	LIM HAN NANG , ID: S2007030G, Tel: +6591729790		
Vehicle Reg. No.:	SJT1805P	Date of Loss:	29/11/2018 00:00 - :59 [110 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 578401	Policy/Cover Note No.:	A27764943QMX (Comprehensive) Coverage: 28/09/2018 - 27/09/2019
		Excess:	S\$500.00
Repairer:	WTS Automotive Services Pte Ltd (HQ) 17 Kaki Bukit Road 4 #01-58/59/60/61/62, Bartley Biz Centre, 417809 Kaki Bukit - Tel: 6844 9449 / 6844 9456		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/12/2018]		
Driver/Custodian:	LIM HAN NANG (70) , NRIC: S2007030G, Tel: +6591729790		
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please check MV and revert. Thanks.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7030G

Vehicle Details

Vehicle No.: SJT1805P

Vehicle to be Exported: No

Intended Deregistration Date: 11 Dec 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: 3ZZ4932711

Chassis No.: MR053ZEE106155294

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$17,853.00

Original Registration Date: 28 Sep 2009

First Registration Date: 28 Sep 2009

Transfer Count: 0

Actual ARF Paid: \$17,853.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Sep 2019

PARF Rebate Amount: \$8,926.00

Intended COE Rebate Details

COE Expiry Date: 27 Sep 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$18,020.00

COE Rebate Amount: \$1,431.00

Total Rebate Amount: \$10,357.00

The information contained herein is correct as at 11 Dec 2018

OK

Das WeltAuto.
Used cars you can trust. Guaranteed.

Some rides are better than others.
Brace yourself for adrenaline pumping offers on certified,
pre-owned VW cars at the sgCarMart Carnival
@ Downtown East.



altis Price Range Depreciation 2009 Vehicle Type Submit Advanced Search

Home > Used Cars > D&L Auto Trading > Toyota Corolla Altis 1.6A

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



AResolve

Toyota Corolla Altis 1.6A

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$17,800	
Depreciation	\$11,020 /yr	?
	View models with similar depreciation	
Reg Date	02-Oct-2009	
	(9mths 20days COE left)	
Manufactured	2009	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,598 cc	
Road Tax	\$742 /yr	?
Power	80.0 kW (107 bhp)	
	View specs of the Toyota Corolla Altis (2008-2013)	
Curb Weight	1,195 kg	?
Features	Super Durable 16 Valves VVTi DOHC Engine, Fuel Efficient 14.5KM/L, 2XSRS Airbags, 4XABS Disc Brakes, Auto Climatic Aircon, Multi Function Steering.	
Accessories	Genuine Leather, New Sports Rims, New Tyres, Japan Factory Fitted Audio, Retractable Side Mirrors, Side Mirror Indicators, Reverse Sensors, Fog Lamps.	
Description	100% Guaranteed Accident-Free, Well Maintained, Wear And Tear Replaced, 90% Loan At 2.28%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewing.	
COE	\$18,020	?
OMV	\$17,853	?
ARF	\$17,853	?
Dereg Value	\$10,378 as of today (change)	?
No. of Owners	4	?
Type of Veh	Mid-Size Sedan	
Category	PAIF Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 09-Nov-2018 | Last Updated on: 20-Nov-2018
Tags: Toyota Corolla, toyota corolla, 2008 Toyota Corolla, 2009 toyota corolla, Toyota, Corolla, corolla, Used Toyota



Seller Information

Company	D&L Auto Trading
	» dealer's pricelist
	» 34 vehs sold 36 vehs available
Address	200 Jalan Sultan #04-20
	Search cars nearby this location
Location	Textile Centre
Office No	62960188
Contact Person(s)	Darren Low 96236322

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 19 December 2018 3:43 PM
To: 'Muham'mad Idram Bin Abdul Rahman'
Cc: roslee.puasa@pitstop.com.sg; SUR
Subject: RE: SJT 1805P OD (MSIG)

Hi Idram,

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muham'mad Idram Bin Abdul Rahman [mailto:muhammad.idram@pitstop.com.sg]
Sent: Wednesday, 19 December 2018 3:39 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: roslee.puasa@pitstop.com.sg; 'SUR' <sur@lkkauto.com>
Subject: RE: SJT 1805P OD (MSIG)

Hi Shirley,

I hereby confirm with the final figure.

Best Regards

Muhammad Idram

Service Advisor, Pitstop@Bartley







Woodlands Automotive Service Pte Ltd

17 Kaki Bukit Road 4 Bartley Biz Centre #01-58, Singapore 417809

Main Line : +65 6844 9449 Fax : +65 6844 9463

Direct Line : +65 6844 9457

www.woodlandstransport.com.sg 

Group of Companies:  Woodlands Transport  WTS travel  CASHBOX 

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 12 December 2018 4:54 PM
To: 'Muham'mad Idram Bin Abdul Rahman'
Cc: roslee.puasa@pitstop.com.sg; SUR
Subject: RE: SJT 1805P OD (MSIG)

Dear Idram,

As Spoken, instructed by our client, please proceed at repair cost not exceeding \$2,150.00 (inclusive supplementary) to repair the insured vehicle **SJT 1805P (Excess \$ 500/-)** on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Please contact our surveyor to conduct resurvey.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muham'mad Idram Bin Abdul Rahman [mailto:muhammad.idram@pitstop.com.sg]
Sent: Wednesday, 12 December 2018 4:07 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: roslee.puasa@pitstop.com.sg
Subject: RE: SJT 1805P OD (MSIG)

Dear Shirley,

I hereby agreed with the amount of \$2150 on lump sum before excess and gst.

Best Regards

Muhammad Idram


Service Advisor, Pitstop@Bartley


Woodlands Automotive Service Pte Ltd

17 Kaki Bukit Road 4 Bartley Biz Centre #01-58, Singapore 417809

Main Line : +65 6844 9449 Fax : +65 6844 9463

Direct Line : +65 6844 9457

www.woodlandstransport.com.sg 

Group of Companies:  Woodlands Transport  WTS travel  CASHBOX 

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Wednesday, 12 December, 2018 2:15 PM

To: muhammad.idram@pitstop.com.sg

Cc: roslee.puasa@pitstop.com.sg

Subject: SJT 1805P OD (MSIG)

Hi Idram,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 2,150.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



View Received Message

This mail is associated with :

SJT1805P (578401)

OD

Nov 29 2018 12:00AM

[LIM HAN NANG]

WTS Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/12/2018 15:02 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2150.00) - SJT1805P - Claim Handler: Clara Milah Yeo

Approved:2150,00:approved lump sum repair not exceeding \$2150 before excess \$500

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SJT1805P (578401)

OD

Nov 29 2018 12:00AM

[LIM HAN NANG]

WTS Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 12/12/2018 12:02 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2200.00) - SJT1805P - Claim Handler: Clara Milah Yeo

Approved:2200.00:approved lump sum repair not exceeding \$2200 before excess \$500

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 18 Dec 2018

Preliminary Advice

Vehicle No	: SJT1805P	Accident Date	: 29/11/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: A27764943QMX
Assignment Date	: 11/12/2018	Excess	: S\$500.00
Date of Inspection	: 11/12/2018	Est. Duration of Repair	: 4 days
Inspection At	: WTS Automotive Services Pte Ltd (HQ) 17 Kaki Bukit Road 4 #01-58/59/60/61/62, Bartley Biz Centre Singapore 417809		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,400.00
Revised Amount	:S\$	2,721.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,721.83

Lump Sum Repair	:S\$	2,150.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	10,357.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,643.00

Remarks

- (X) The vehicle is economical for repair. Repairer repair on lump sum basis.
- () The above survey was conducted on a 'without prejudice' basis.

Vehicle Registration Number of Driver's Own Vehicle (if applicable)

Insurance Company of Driver's Own Vehicle (if applicable)

General Information of the Accident

Type Of Accident Collision- Head to Side

Weather Conditions Clear

Road Surface Dry

Other Information

Was any body injured in the Accident? Yes

Was any other material or property damaged? Yes

Details of Police Action

Was the accident reported to the police? Yes

If Yes, Please state which Police Station

Police Station Name Changi N.p.c

Police Station Address ROAD: 9 SIMEI STREET 2 , POSTCODE: 529914 , COUNTRY: Singapore

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20120128/9009

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKA5311J

Vehicle Make/Model/Colour MINI

Details Of Properties

Name of Driver NG RUI FEN

NRIC/Passport Number S8720186D

Contact Number 90698671

Address

Postcode

Insurance Company Name

Nature Of Damage FRONT PORTION

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name KOH CHIN BOON

Approximate Age 36

Injuries Sustain NECK

Injured person in which vehicle? SH9237H

Were seat belts worn? Yes

Was injured conveyed to hospital by ambulance? No

Address BLK 167B PUNGGOL EAST
#13-403

Postcode 822167

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 11 Dec 2018

Preliminary Advice

Vehicle No	: SJT1805P	Accident Date	: 29/11/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: A27764943QMX
Assignment Date	: 11/12/2018	Excess	: S\$500.00
Date of Inspection	: 11/12/2018	Est. Duration of Repair	: 4 days
Inspection At	: WTS Automotive Services Pte Ltd (HQ) 17 Kaki Bukit Road 4 #01-58/59/60/61/62, Bartley Biz Centre Singapore 417809		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,400.00
Revised Amount	:S\$	2,745.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,745.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	10,357.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,643.00

Remarks

- (X) The vehicle is economical for repair. Repairer asking repair the vehicle on lump sum basis due to vehicle model year 2009.
- () The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIa Records Management Centre established by the General Insurance Association of Singapore (GIa) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/12/2018 11:36
Date Of Accident	29/11/2018 17:35
Exact Location Of Accident	TAMPINES STREET 31 TOWARDS AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT1805P
Insured/Policyholder	
Name Of Registered Owner	LIM HAN NANG
NRIC No	S2007030G
Email Address	ROSLEE.PUASA@PITSTOP.COM.SG
Mobile Phone No	(LOCAL) +65-98305991
Alternative Phone No	OFFICE-98305991

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA LATIS-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A27764943 QMX
Cover Note Number	

Driver

Name of Driver	LIM HAN NANG
NRIC No	S2007030G
Date Of Birth	13/10/1948
Occupation	INDOOR
Date Of Driving Pass	10/11/1968
Driving Experience	50 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98305991
Fax Number	
Contact Number	OFFICE-98305991
Email Address	ROSLEE.PUASA@PITSTOP.COM.SG

Address	BLK 485B TAMPINES AVE 9 #10-134
Postcode	1852
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 29/11/2018 @ 5.35pm while driving my car registration number SJT1805P along Tampines Street 31 towards Ave 2, I can't brake in time and hit another vehicle number SLZ2359Z. No major damaged to SLZ2359Z and nobody injure during this incident.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ2359Z
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONN CHANG DA
NRIC/Passport Number	S8426541A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

→ Tempus 81 31 towards Ave 2

A: SJT 1805P

B: SLZ 2359P

Lynn Han N

On 29/01/2018 ^{2:05-2:20 pm} while driving my car registration number
SOT 1805P along Tampere Street 31 towards Ave 2, I cut
brake in time and hit another vehicle number SLZ2359Z.
No major damage to SLZ2359Z and no body injured during
this incident. x Lillian May

I/We declare the foregoing particulars are true in every respect.

Driver's Signature Lin Han Wang
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

+ Lim Han Noy

Driver's Signature
(If driver is not the policyholder)
Date & Time:

x Lim Han Noy

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





MSIG

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel: +65 6827 7988, Fax: +65 6827 7800
 Co. Reg. No. 200417212G, SSI Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
 Individual Ownership

**MOTOR MAX
 Comprehensive**

Certificate No. A 27764943 QMX

Excess: SGD500

Windscreen Excess: SGD100

1. Index Mark and Registration Number of Vehicle
 SUT1805P

2. Name of Policyholder
 Lim Han Nang

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 28/09/2018

4. Date of Expiry of Insurance
 27/09/2019

5. Persons or Classes of Persons entitled to drive*

Lim Han Nang

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.


**PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG
 AUTHORISED WORKSHOP LISTED IN THE ATTACHED.**

This Certificate is not transferable to a new owner of the vehicle, if for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers


 for Chief Executive Officer





SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 11:43
Date Of Accident	29/11/2018 17:35
Exact Location Of Accident	ALONG TAMPINES ST 31 TOWARDS AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT1805P
Insured/Policyholder	
Name Of Registered Owner	LIM HAN NANG
NRIC No	S2007030G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91729790
Alternative Phone No	OFFICE-68449457

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	LIM HAN NANG
NRIC No	S2007030G
Date Of Birth	13/10/1948
Occupation	INDOOR
Date Of Driving Pass	03/11/1969
Driving Experience	49 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91729790
Fax Number	
Contact Number	OFFICE-68449457
Email Address	NOEMAIL

Address	BLK 485B TAMPINES AVENUE 9 #10-134
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	SLZ2359Z (PRIVATE CAR)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 29/11/2018 @ 17354HRS WHILE DRIVING MY CAR REGISTRATION NO: SGT1805P ALONG TAMPINES STREET 31 TOWARDS AVENUE 2, I CANT BRAKE ON TIME AND HIT ANOTHER VEHICLE NUMBER SLZ2359Z.NO MAJOR DAMAGED TO SLZ2359Z AND NO BODY INJURED DURING THIS INCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

+ Lim Han Nef
Policyholder's Signature
Date & Time:


x Lim Han Nef
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Accident Sketch Plan

SKETCH PLAN

→ Tampines St 31 towards Ave 2



A: SJT 1805P

B: SLZ 2359Z
x
Lim Han Nany

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/05/2018 ^{at 5:28 pm} while driving my car registration number
SJT 1805P along Tampines Street 31 towards Ave 2, I can't
brake in time and hit another vehicle number SLZ 2359Z.
No major damages to SLZ 2359Z and no body injured during
this incident x
Lim Han Nany

DECLARATION

I/We declare the foregoing particulars are true in every respect.

+ Lim Han Nany
Policyholder's Signature
Date & Time:

+ Lim Han Nany
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Identification Card



Driving License



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068933
Tel: +65 6927 2088, Fax: +65 6927 7900
Co. Reg. No. 2004122125, GST Reg. No. 20 04122125

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.K.1
Individual Ownership

MOTOR MAX
Comprehensive

Certificate No. A 27764545 GDR

Excess: S\$2500
Windscreen Excess: S\$2500

1. Index Mark and Registration Number of Vehicle
SJT14052

2. Name of Policyholder
Lin Han Neng

3. Effective Date of the Commencement of Insurance for the purpose of the Act
28/09/2018

4. Date of Expiry of Insurance
27/09/2019

5. Persons or Classes of Persons entitled to drive*

Lin Han Neng

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than examples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORIZED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurer


for Chief Executive Officer

**WTS Automotive Services
Pte Ltd**

**PITSTOP@Bartley
17 Kaki Bukit Road 4
Singapore 417806**

**Claim Reference: WTSSJT1805P
Assessment Number: WTS00041
Version: WTSAUTO1/1
Date Calculated: 10/12/2018 08:31**

**Full Report - V1
Registration: SJT1805P
Printed: 10/12/2018 16:32**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	ROSLEE BIN PUASA	Date of Incident:	29/11/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	WTSSJT1805P	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS
Model Sheet Number:	YCM 13
Registration:	SJT1805P
Registration Month:	September
Registration Year:	2009
VIN Number:	
Manufacture Month:	September
Manufacture Year:	2009
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 07/2009	AIR CONDITIONING
1.6 LTR 91 KW	TWO PACK STRT COLOUR
PREPARE OFF VEHICLE	

*Not Authorized
Helen Marcus
EXCESS \$500
11/12/18
Tel: 62863561
4 dr.*

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Severity of Impact:
Vehicle Status on
Inspection:
Date of Inspection:

Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

10/12/2018

WTS Auto Consultants hence notify
the Repaired of the following:
• To resurvey (bumpers) spray painting
• To resurvey (damaged parts) during resurvey
• Part (s) are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No legal modification(s) is allowed
• Supplementary (item(s)) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

WTS Automotive Services Pte Ltd

Claim Reference: WTSSJT1805P

Assessment Number: WTS00041



Version: WTSAUTO1/1

Date Calculated: 10/12/2018 08:31

Full Report - V1

Registration: SJT1805P

Printed: 10/12/2018 16:32



Addresses

Cost Summary

Total Labour	\$385.00
Total Paint/Material	\$89.00
Total Parts	\$2,651.00
Total of Additional Costs	\$275.00
Repair Cost Exc GST:	\$3,400.00
Overall Discount (0.0%):	- \$0.00
Excess:	-\$500.00
After Deduction -	
Grand Total Exc GST:	\$2,900.00
7 % GST:	\$203.00
Grand Total Inc GST:	\$3,103.00

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	3.0	15.00
B140	RENEW FRONT PANEL CPL	9.0	45.00
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	2.0	10.00
B010	R + R FRONT BUMPER	5.0	25.00
B020)	RENEW FRONT BUMPER (REMOVED)	9.0	45.00
NO NUMBER	R + R LEFT FRONT OUTER BUMPER BRACKET	1.0	5.00
NO NUMBER	R + R RIGHT FRONT OUTER BUMPER BRACKET	1.0	5.00
B040)	R + R LEFT HEADLAMP	1.0	5.00
B040)	R + R RIGHT HEADLAMP	1.0	5.00
M010)	R + R AIR CONDITIONING CONDENSER	3.0	15.00
002889	DRAIN/REFILL AIR CONDITIONING	7.0	35.00

LABOUR COST

Total Work Units	42.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.2HRS	\$210.00
Paint Labour	2.1 3.5HRS	155 \$175.00
Total Labour	7.3 7.7HRS	365 \$385.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description

- TWO PACK STRT COLOUR
- PREPARE OFF VEHICLE

WU Cost Price (\$)

WTS Automotive Services Pte Ltd

Claim Reference: WTSSJT1805P

Assessment Number: WTS00041

Version: WTSAUTO1/1

Date Calculated: 10/12/2018 08:31

Full Report - V1

Registration: SJT1805P

Printed: 10/12/2018 16:32

281	FRONT BUMPER SURFACE PAINT PLAST.	9.0	
340	BUMPER SUPPORT SURFACE PAINT	4.0 X	
410	GRILLE SURFACE PAINT PLAST.	3.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	22.0 18	
	Preparation Main Work Plastic	10.0	
	Preparation Comp. Work Metal	3.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	35.0 31	
	Total Paintwork Labour	3.1 3.5HRS	155
MATERIAL COST - PAINT			
	Surface-/Blend Paint		Cost Price
	Surface Paint Plastic		9.36 \$13.03
	Material-Const Main Work Plastic		\$38.37
	Material-Const Comp. Work Metal		\$28.60
	Total Excluding Pearlescent Uplift		\$9.00
	Pearlescent Uplift @ 0.0%		85.33 \$89.00
	Total Paint Material Cost		85.33 \$89.00

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
251	1	LWR RADIATOR GRILLE	53112 02190		0% Tom 80.00F ✓
281	1	FRONT BUMPER	52119 02850		0% PD/A 380.00F ✓
317	1	L/F BUMPER BRACKET	52116 02140		0% but 45.00F ✓
318	1	R/F BUMPER BRACKET	52115 02140		0% but 45.00F ✓
340	1	BUMPER SUPPORT	52021 02101		0% but 450.00F ✓
410	1	GRILLE	53100 02310		0% tail/cu 200.00F ✓
431	1	GRILLE BADGE	75301 02050		0% neu 60.00F ✓
1009	1	INNER FRT PANEL CPL	53201 02270	BUMPER REINFORCEMENT	0% PD 300.00F ✓
4465	1	CONDENSER CPL	88450 02350		0% but/lon 600.00F ✓
8780	1	LOWER ENGINE PROTECT	51451 02100		0% Tom 250.00F ✓
f: OEM Parts				Sub Total	\$2,410.00
g: Original				Mark Up From Cost (10 %)	\$241.00
h: Secondhand				Sundry Parts (Fixed)	\$0.00
p: Parallel				Total Parts	\$2,651.00
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
NUMBER PLATE + SPECIALIST	0%	but \$80.00 35
FRAME		
COOLANT SPECIALIST		11 \$85.00 X
AIR CON GAS SPECIALIST	0%	\$50.00 ✓
BUMPER CLIPS SPECIALIST		neu \$60.00 30
Total Extras		\$275.00

Final Calculation

Total Parts	\$2,651.00
Labour	
Total Panel/Mechanical	\$210.00 210
Total Paintwork	\$175.00 155

WTS Automotive Services Pte Ltd**Claim Reference: WTSSJT1805P****Assessment Number: WTS00041****Version: WTSAUTO1/1****Date Calculated: 10/12/2018 08:31****Full Report - V1****Registration: SJT1805P****Printed: 10/12/2018 16:32**

Total Labour		\$385.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$275.00	
Total of Additional Costs		\$275.00
Total Paint/Material Costs		\$89.00
Repair Costs Excludes GST		\$3,400.00
Deductions		
Deduction for Excess (Fixed)	-\$500.00	
Total Deductions		-\$500.00
Grand Total Excludes GST (After Deduction)		\$2,900.00
GST @ 7 %		\$203.00
Grand Total Includes GST (After Deduction)		\$3,103.00

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: WTSSJT1805P
Assessment Number: WTS00041
Version: LKKAUTOC/2
Date Calculated: 18/12/2018 01:42

Full Report - V1
Registration: SJT1805P
Printed: 18/12/2018 09:42

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	29/11/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	WTSSJT1805P	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS
Model Sheet Number:	YCM 13
Registration:	SJT1805P
Registration Month:	September
Registration Year:	2009
VIN Number:	
Manufacture Month:	September
Manufacture Year:	2009
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 07/2009	AIR CONDITIONING
1.6 LTR 91 KW	TWO PACK STRT COLOUR
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	10/12/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Cost Summary

Total Labour	\$365.00
Total Paint/Material	\$85.83
Total Parts	\$2,156.00
Total of Additional Costs	\$115.00
Repair Cost Exc GST:	\$2,721.83
Overall Discount (20%):	- \$544.37
Excess:	-\$500.00
After Deduction -	
Grand Total Exc GST:	\$1,677.46
7 % GST:	\$117.42
Grand Total Inc GST:	\$1,794.88

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	3.0	15.00
B140	RENEW FRONT PANEL CPL	9.0	45.00
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	2.0	10.00
B010	R + R FRONT BUMPER	5.0	25.00
B020	RENEW FRONT BUMPER (REMOVED)	9.0	45.00
NO NUMBER	R + R LEFT FRONT OUTER BUMPER BRACKET	1.0	5.00
NO NUMBER	R + R RIGHT FRONT OUTER BUMPER BRACKET	1.0	5.00
B040	R + R LEFT HEADLAMP	1.0	5.00
B040	R + R RIGHT HEADLAMP	1.0	5.00
M010	R + R AIR CONDITIONING CONDENSER	3.0	15.00
002889	DRAIN/REFILL AIR CONDITIONING	7.0	35.00

LABOUR COST

Total Work Units	42.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.2HRS	\$210.00
Paint Labour	3.1HRS	\$155.00
Total Labour	7.3HRS	\$365.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO PACK STRT COLOUR		
	- PREPARE OFF VEHICLE		
281	FRONT BUMPER SURFACE PAINT PLAST.	9.0	
410	GRILLE SURFACE PAINT PLAST.	3.0	

1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	18.0	
	Preparation Main Work Plastic	10.0	
	Preparation Comp. Work Metal	3.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	31.0	
	Total Paintwork Labour	3.1HRS	\$155.00
	MATERIAL COST - PAINT		Cost Price
	Surface-/Blend Paint		\$9.86
	Surface Paint Plastic		\$38.37
	Material-Const Main Work Plastic		\$28.60
	Material-Const Comp. Work Metal		\$9.00
	Total Excluding Pearlescent Uplift		\$85.83
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$85.83

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
4465	1	CONDENSER CPL	88450 02350		0% 600.00F
281	1	FRONT BUMPER	52119 02850		0% 380.00F
410	1	GRILLE	53100 02310		0% 200.00F
431	1	GRILLE BADGE	75301 02050		0% 60.00F
1009	1	INNER FRT PANEL CPL	53201 02270	BUMPER REINFORCEMENT	0% 300.00F
317	1	L/F BUMPER BRACKET	52116 02140		0% 45.00F
8780	1	LOWER ENGINE PROTECT	51451 02100		0% 250.00F
251	1	LWR RADIATOR GRILLE	53112 02190		0% 80.00F
318	1	R/F BUMPER BRACKET	52115 02140		0% 45.00F
f: OEM Parts			Sub Total		\$1,960.00
g: Original			Mark Up From Cost	(10 %)	\$196.00
h: Secondhand			Sundry Parts	(Fixed)	\$0.00
p: Parallel			Total Parts		\$2,156.00
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
NUMBER PLATE + SPECIALIST	0%	\$35.00
FRAME		
AIR CON GAS SPECIALIST		\$50.00
BUMPER CLIPS SPECIALIST	0%	\$30.00
Total Extras		\$115.00

Final Calculation

Total Parts	\$2,156.00
Labour	
Total Panel/Mechanical	\$210.00
Total Paintwork	\$155.00
Total Labour	\$365.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$115.00

Total of Additional Costs		\$115.00
Total Paint/Material Costs		\$85.83
Repair Costs Excludes GST		<u>\$2,721.83</u>
Deductions		
Deduction (20.00 %) Before GST	- \$544.37	
Deduction for Excess (Fixed)	-\$500.00	
Total Deductions		-\$1,044.37
Grand Total Excludes GST (After Deduction)		<u>\$1,677.46</u>
GST @ 7 %		\$117.42
Grand Total Includes GST (After Deduction)		<u>\$1,794.88</u>

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018 Sendback Est	10 Dec 2018 16:59 \$53,400.00	11 Dec 2018 09:24 Edit Adj Rpt	\$52,150.00 Edit Estimates	\$52,150.00 View Rpt		Pending for Survey Report Cancel Case





































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	LIM HAN NANG , ID: S2007030G, Tel: +6591729790								
Vehicle Reg. No.:	SJT1805P	Date of Loss:	29/11/2018 00:00 - :59 [110 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 578401	Policy/Cover Note No.:	A27764943QMX (Comprehensive) Coverage: 28/09/2018 - 27/09/2019						
		Excess:	S\$500.00						
Repairer:	WTS Automotive Services Pte Ltd (HQ) 17 Kaki Bukit Road 4 #01-58/59/60/61/62, Bartley Biz Centre, 417809 Kaki Bukit - Tel: 6844 9449 /6844 9456								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/01/2019]								
Driver/Custodian:	LIM HAN NANG (70), NRIC: S2007030G, Tel: +6591729790								
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please check MV and revert. Thanks.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (19/12/2018): Alert - Adj Mandate Approved (\$52150.00) - SJT1805P - Claim Handler: Clara Milah... MSIG_SG (12/12/2018): Alert - Adj Mandate Approved (\$52200.00) - SJT1805P - Claim Handler: Clara Milah... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















































Claim Documents

SJT1805P (578401)
 OD
 Nov 29 2018 12:00AM
 [LIM HAN NANG]
 WTS Automotive Services Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	WTS Automotive Services Pte Ltd (HQ)	Thumbnail	Print	
1	10/12/18 16:59	Repairer Estimates	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/12/18 16:09	Adjuster Immediate Advice	 Load HTM		
2	18/12/18 09:55	Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/12/18 18:03	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>	
2	11/12/18 18:03	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>	
3	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	WTS Automotive Services Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
34	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
59	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
60	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
61	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
62	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
63	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
64	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
65	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
66	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
67	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
68	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
69	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
70	11/12/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
71	17/12/18 21:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	17/12/18 21:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	17/12/18 21:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	17/12/18 21:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	17/12/18 21:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	17/12/18 21:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	17/12/18 21:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	17/12/18 21:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	WTS Automotive Services Pte Ltd (HQ)	Thumbnail	Print
1	10/12/18 16:52	Repair Estimates	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	WTS Automotive Services Pte Ltd (HQ)		Thumbnail	Print
1	10/12/18 18:26	COE/Parf		Load PDF	
2	10/12/18 18:26	TP SL22359Z GIA report		Load PDF	
3	10/12/18 18:26	OI GIA report		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/12/18 16:21	ESTIMATE MARKED.pdf		Load PDF	
2	18/12/18 09:45	SJT 1805P .AudatexMS.pdf		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18022248/USD3E2

Date: 20/12/2018

REFERENCE

Insured/Claimant:	LIM HAN NANG	Policy No:	A27764943QMX	Claim No:	578401
Date of Loss:	29/11/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT1805P		Engine No:	3ZZ4932711
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)		Chassis No:	MR053ZEE106155294
Reg. Date:	28/09/2009 (Man. Year: 2009)		Odometer:	160340 km
Colour:	Grey			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	S\$16,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,651.00	2,156.00	495.00	18.67
Miscellaneous Items	275.00	115.00	160.00	58.18
Paintwork Materials	89.00	85.83	3.17	3.56
Labour	210.00	210.00	0.00	0.00
Paintwork Labour	175.00	155.00	20.00	11.43
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,400.00	2,721.83	678.17	19.95
Approved Total (Overridden) (S\$)		2,150.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	2,900.00	1,650.00	1,250.00	43.10
+ GST 7.00/7.00% (S\$)	203.00	115.50	87.50	43.10
Nett Amount (S\$)	3,103.00	1,765.50	1,337.50	43.10

INSPECTION

Date of Assignment:	11/12/2018 Present Location:	WTS Automotive Services Pte Ltd (HQ)
Date Inspected:	11/12/2018 Inspected At:	WTS Automotive Services Pte Ltd (HQ)
		17 Kaki Bukit Road 4 #01-58/59/60/61/62,
		Bartley Biz Centre
		Singapore 417809

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT1805P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS (WCP)		2,410.00 F	*1,960.00 F
					Sub Total (S\$)	2,410.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	241.00
					Total Parts (S\$)	2,651.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Total Paint/Material	89.00	85.83
<u>Miscellaneous Items</u>				
2	1	SPECIALIST	275.00	115.00
Sub Total (S\$)			364.00	200.83

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paintwork	New	175.00	155.00
<u>Labour Items</u>				
2	Total Panel/Mechanical	New	210.00	210.00
Gross Labour Cost (S\$)			385.00	365.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

