

22/03/2002

ASS. REC. BY:

REF: CS3/SMO18022219/Ucd3k

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

Mejimen

From (Person) Han cheung Yong Bernard

SMO

Date/Time: 11/12/18 @ 9:35am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 2402K

Insured:

GBF 8453T

at Workshop m/s

Paul Hoe Batteries

Tel:

9623 5068

of

1 Kaki Bkt Ave G # 01-109

Policy No:

D18M7PCVE001093

Claim No:

CMTD1805A11

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

10:11am @ 11/12/18

Person Contacted:

paul

Vehicle IN/OUT

Date/Time	Action/Instruction (x) Estimate
	GBF 2402K - NA / INCI 18022020 / h4 Date: 8/12/18
	GBF 8453T - NA / INCI 18022020 / h4 Date: 6/12/18
	Dismantle: 12/12/2018

(08/11/13) wef
ASS. REC. BY: Marcus

REF: 5129/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GSE 2402K

at Workshop m/s Paul Lee

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 49

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 5388D

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GSE 2402K Yr Regn: 9 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (in)

Make: Toyota Make DX c.c. 2982

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 70461 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH 201 0175313

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 6/12/18 D.O.I. 11/12/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>6415. 9nd. Deptk.</u>
	<u>No copy LIA 31824</u>
	<u>net 17176</u>
	<u>11-12</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:	<u>100</u>
Transportation:	<u>60</u>
S + RS, SI	
Photos	
Others	<u>10</u>
TOTAL	<u>170</u>

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2018		11 Dec 2018 09:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	VALAR MATHI CONTRACTORS PTE LTD, Co. Reg. No.: 201602724H		
Main Claimant:	TREND STAR PTE LTD, Co. Reg. No.: 200305338D		
Vehicle Reg. No.:	GBE2402K	Date of Loss:	06/12/2018 14:00 - :59
Claim Type:	TP / CMTD1805411	Policy/Cover Note No.:	D18MTPCVE001093 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF8453T	Policy No. (Claimant):	
		Excess:	
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by HAN CHEUNG YONG BERNARD - 6322 4659]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/12/2018]		
Driver/Custodian (Insured):	SIVAGNANAM SIVAPRAKASAM (), NRIC: G2595818M, Tel: +6584055077		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

ONG & SHAN LLC

ADVOCATES & SOLICITORS
COMMISSIONERS FOR OATHS
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:

Lawyer : ongshanllc@gmail.com
Secretary :

Please send all correspondences to:

- 2 Kallang Avenue #08-19 Singapore 339407
Tel: 6444 7845 | Fax: 6444 5847
- 101 Upper Cross Street #06-15B Singapore 058357
Tel: 6536 7991 | Fax: 6536 7995
- 184 Toa Payoh Central #02-364 Singapore 310184
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.8316A.18.CM

Your Ref : Your insured vehicle GBF 8453T

11th December 2018

Valar Mathi Contractors Pte Ltd
c/o Sompo Insurance Pte Ltd
(Motor Claims Department)
80, Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

BY EMAIL

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA) ROAD TRAFFIC ACCIDENT INVOLVING GBE 2402K & GBF 8453T ON 06.12.2018 ALONG BEFORE JUNCTION OF INTERNATIONAL ROAD AND SOON LEE ROAD @ 1445HRS

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

- | | |
|-------------------------|--------------------------|
| 1. Patrick Ng Kong Beng | 2. Jayson Liaw Leong San |
| 3. Loi Boon Juan | 4. Ang Guea Kiang |
| 5. Matthew Ng Yong Chin | 6. Ong Poh Meng |
| 7. Tan Chin Suan | 8. Lee |
| 9. Phillip Foo | |

Name of workshop : M/s Paul Hoe Batteries & Motor Services
Address : 1 Kaki Bukit Ave 6 #01-109 Singapore 417883
Contact person : Mr. Paul
Telephone no : 9623-5068
Fax no : 6747-6918

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single Joint Expert".

We will accordingly inform you who the "Single Joint Expert" is to facilitate your conduct of a pre-repair survey.

If you object to our list of motor surveyors, we will accordingly inform the claimant to instruct his choice of motor surveyors to conduct the pre-repair survey.

Yours faithfully,

Ong & Shan LLC

cc. Paul Hoe Batteries & Motor Services (67476918)

For Surveyor

Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair inspection: /

ONG & SHAN LLC

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

THIS DOCUMENT IS FOR THE ADDRESSEE (S) ONLY & MAY CONTAIN CONFIDENTIAL INFORMATION &/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5388D
Vehicle Details	
Vehicle No.:	GBE2402K
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX VAN
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2548116
Chassis No.:	KDH2010175313
Maximum Power Output:	-
Open Market Value:	\$29,052.00
Original Registration Date:	30 Sep 2015
First Registration Date:	30 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$1,453.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,801.00
COE Rebate Amount:	\$31,824.00
Total Rebate Amount:	\$31,824.00

The information contained herein is correct as at 11 Dec 2018

OK



FREE **Car Search REWARDS MEMBERSHIPS**
 Get at least **10% DISCOUNT** on car services from repair, warranty & servicing, grooming to car accessories [Learn more](#)



Post an Advertisement
 Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5a



2.88%p.a Lowest Interest@GV
 Cars Financing \$2000
 Downpayment Monthly From \$488
 GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted 20 results/page

10 vehicles

hiace

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	hiace		Any	Any	2015	Any	Any	Any	Available
	Toyota	Hiace	\$56,800	\$8,470 /yr	24-Aug-2015	2,982 cc	-	Van	Available
	Fuel Type: Diesel AUTO Toyota Hiace 5 Door,New Paint Work, No Repair Needed, Well Maintained, Low Mileage Done, We Provide Flexible In House And Bank Loan Up To 100%, Welcome All Trade In, Please Call To Arrange For Vi... Car (S) Pte Ltd Posted: 10-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$48,888	\$7,770 /yr	27-Mar-2015	2,982 cc	83,000 km	Van	Available
	Fuel Type: Diesel Well Maintained, 1 Owner Panel Van. Agent Car And Serviced. Accident Free. With Prefixed Shelving In Van, Suitable For Aircon Service Man Or Other Storage Usage. Posted: 06-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace Commuter	\$70,800	\$11,050 /yr	07-May-2015	2,982 cc	-	Bus	Available
	Fuel Type: Diesel Nicely Done Up Toyota Hiace Commuter 13+1 Seater.We Spare No Effort To Transform This Vehicle To A Beauty.Only 1 Owner. We Provide Easy Approval In Hse Loan And Bank Loan.Call Us Now Before It's Gone. ABWIN Bus Pte Ltd Posted: 03-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$46,800	\$7,330 /yr	29-Apr-2015	2,982 cc	-	Van	Available
	Fuel Type: Diesel Superb Condition! Well Maintained By One Owner Only! Power And Comfort All In One! Beauty! Very Rare In The Market! Well Maintained By Previous Owner! Posted: 03-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Rear Compact Aircon Fan Blower Draws cool air from the front to the rear. Fits MPVs and Vans without aircon at the back. Compact size. More info about this product								
	Toyota	Hiace	\$48,800	\$7,290 /yr	21-Aug-2015	2,982 cc	-	Van	Available
	Fuel Type: Diesel Superb Condition! Well Maintained By One Owner Only! Power And Comfort All In One! Beauty! Very Rare In The Market! Well Maintained By Previous Owner! Posted: 03-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$47,800	\$7,270 /yr	08-Jul-2015	2,982 cc	-	Van	Available
	Fuel Type: Diesel Superb Condition! Well Maintained By One Owner Only! Power And Comfort All In One! Beauty! Very Rare In The Market! Well Maintained By Previous Owner! Posted: 30-Nov-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5388D
Vehicle Details	
Vehicle No.:	GBE2402K
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX VAN
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2548116
Chassis No.:	KDH2010175313
Maximum Power Output:	-
Open Market Value:	\$29,052.00
Original Registration Date:	30 Sep 2015
First Registration Date:	30 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$1,453.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,801.00
COE Rebate Amount:	\$31,811.00
Total Rebate Amount:	\$31,811.00

The information contained herein is correct as at 12 Dec 2018

OK

Das WeltAuto.
Used cars you can trust. Guaranteed.

Some rides are better than others.
Brace yourself for adrenaline pumping offers on certified, pre-owned VW cars at the sgCarMart Carnival @ Downtown East.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

New 10 Years Coe Renewal Toyota Estima 2.4A



2.88%P.A Lowest Interest@GV
Cars Financing \$5800
Downpayment Monthly From \$388
GV Credit Pte Ltd StarAd

HIN LUNG AUTO
HoBee Group
One Stop Car Hi
Finance, Insurance, Work
New and Used Cars

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted

10 vehicles

Toyota Hiace

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Typ
Search Selection	Toyota Hiace	Any	Any	2015	Any	Any	Any
	Toyota Hiace Fuel Type: Diesel AUTO Toyota Hiace 5 Door,New Paint Work, No Repair Needed, Well Maintained, Low Mileage Done, We Provide Flexible In House And Bank Lc To 100%, Welcome All Trade In, Please Call To Arrange For Vi... Car (5) Pte Ltd Posted: 10-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota	\$56,800	\$8,480 /yr	24-Aug-2015	2,982 cc	-	Van
	Toyota Hiace Fuel Type: Diesel Well Maintained, 1 Owner Panel Van. Agent Car And Serviced. Accident Free. With Prefixed Shelving In Van, Suitable For Aircon Service Man Or Storage Usage. Posted: 06-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota	\$48,888	\$7,770 /yr	27-Mar-2015	2,982 cc	83,000 km	Van
	Toyota Hiace Commuter Fuel Type: Diesel Nicely Done Up Toyota Hiace Commuter 13+1 Seater.We Spare No Effort To Transform This Vehicle To A Beauty.Only 1 Owner. We Provide Ea Approval In Hse Loan And Bank Loan.Call Us Now Before It's Gone. ABWIN Bus Pte Ltd Posted: 03-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota	\$70,800	\$11,060 /yr	07-May-2015	2,982 cc	-	Bus
	Toyota Hiace Fuel Type: Diesel Superb Condition! Well Maintained By One Owner Only! Power And Comfort All In One! Beauty! Very Rare In The Market! Well Maintained By P Owner! Posted: 03-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota	\$46,800	\$7,330 /yr	29-Apr-2015	2,982 cc	-	Van
	Bus and 'medi trips' from ComfortDelGro ComfortDelGro made a donation to three welfare organisations in the form of a refurbished nine-seater bus and free trips for seniors and their escorts. Read this article						
	Toyota Hiace Fuel Type: Diesel Superb Condition! Well Maintained By One Owner Only! Power And Comfort All In One! Beauty! Very Rare In The Market! Well Maintained By P Posted: 03-Dec-2018 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota	\$48,800	\$7,290 /yr	21-Aug-2015	2,982 cc	-	Van

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/12/2018 10:58
Date Of Accident	06/12/2018 14:45
Exact Location Of Accident	B4 JUNC OF INTERNATIONAL RD & SOON LEE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE2402K
Insured/Policyholder	
Name Of Registered Owner	TREND STAR PTE LTD
Co Reg No	200305388D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96650786

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084454674-02
Cover Note Number	-

Driver

Name of Driver	AMALAKESAN BALAMURUGAN
NRIC No	G5102508W
Date Of Birth	01/06/1982
Occupation	OUTDOOR
Date Of Driving Pass	14/06/2012
Driving Experience	6 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97758795
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	10 CARPMAEL RD ZHUJIAO CENTRE (TEKKA MARKET)
Postcode	429758
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4439999 - FAX NO: 62444376
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF8453T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKA952S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name AMALAKESAN BALAMURUGAN
Approximate Age
Injuries Sustain HEADACHE AND FELT PAIN ON SHOULDERS AND BACK
Injured person in which vehicle? GBE2402K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2018		11 Dec 2018 09:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	VALAR MATHI CONTRACTORS PTE LTD , Co. Reg. No.: 201602724H								
Main Claimant:	TREND STAR PTE LTD , Co. Reg. No.: 200305338D								
Vehicle Reg. No.:	GBE2402K	Date of Loss:	06/12/2018 14:00 - :59 [38 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1805411	Policy/Cover Note No.:	D18MTPCVE001093 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF8453T	Policy No. (Claimant):							
		Excess:							
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by HAN CHEUNG YONG BERNARD - 6322 4659]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2018]								
Driver/Custodian (Insured):	SIVAGNANAM SIVAPRAKASAM (), NRIC: G2595818M, Tel: +6584055077								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBE2402K (CMTD1805411)**
[GBF8453T]
TP
TREND STAR PTE LTD
Dec 6 2018 2:00PM
[VALAR MATHI CONTRACTORS PTE LTD]
Paul Hoe Batteries & Motor Services

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	11/12/18 09:34	Accident Statement From:SC - Reg. No: GBF8453T, Claimant: VALAR MATHI CONTRACTORS PTE LTD	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
2	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
3	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
4	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
5	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
6	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/12/18 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
35	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
36	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
37	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
38	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
39	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
40	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
41	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
42	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
43	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
44	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
45	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
46	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
47	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
48	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
49	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
50	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
51	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
52	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
53	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
54	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
55	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
56	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
57	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
58	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
59	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
60	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
61	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
62	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
63	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
64	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
65	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
66	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
67	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
68	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
69	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
70	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
71	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
72	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
73	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
74	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
75	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
76	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
77	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
78	14/12/18 13:37	General View		<input checked="" type="checkbox"/>
79	14/12/18 13:37	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
80	14/12/18 13:37	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
81	14/12/18 13:37	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
82	14/12/18 13:37	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
83	14/12/18 13:37	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
84	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
134	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
147	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
150	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
151	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
152	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
153	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
154	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
155	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
156	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
157	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
158	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
159	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
160	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
161	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
162	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
163	14/12/18 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/12/18 14:49	Third Party E-filed GIA report(M)	 Load PDF	
2	11/12/18 09:34	Pre-Repair Survey - OBJ	 Load PDF	
3	11/12/18 09:34	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18022249/UCD3E2
Date: 17/12/2018

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd.	Policy No: D18MTPCVE001093	
Claimant Vehicle No: GBE2402K	Insured Vehicle No: GBF8453T	
Date of Loss: 06/12/2018	Nature of Claim: TP	Claim No: CMTD1805411

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE2402K		
Make & Model:	TOYOTA HIACE, 2.0 (M)	Engine No:	1KD2548116
Reg. Date:	30/09/2015 (Man. Year: 2015)	Chassis No:	KDH2010175313
Colour:	Silver	Odometer:	70451 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/12/2018	
Date Inspected:	11/12/2018 Inspected At:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109 Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$11,000.00 - \$12,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Dec 2018)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE2402K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >