

22/03/2002

ASS. REC. BY:

REF:

CS3/HPC/18022251/Gsd322

Special Instruction:

Surveyor: Guo QiangASSIGNMENT (Office)From (Person): ong li li

of

HPCDate/Time: 10/12/18 @ 2:45pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFD 3663A

Insured:

YN 6966D

at Workshop m/s

King's Auto

Tel:

6457 8629

of

176 Sir Ming Drive # 02-10

Policy No:

Claim No:

18/18/18/VL00/021201

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS 1up

H.O.D. Endorsement:

Date/Time: 11:25am @ 11/12/18

Person Contacted:

Kui fangVehicle IN OUT

Date/Time

Action/Instruction ( x ) Estimate

SFD 3663A - xYN 6966D - x

Insurance

PRS  
Karl.

REF: LPC

28887 /

# ASSIGNMENT

From: Date: 11/12/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFD 3663A  
at Workshop n/s: King's Auto  
of 176 Sin Ming Drive #02-10

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFD3663A Yr Regn: 23 Aug 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Merce E250 C.C. 1796

Colour: A/C Insured / Std / NI / NA

Sp. Reading: 104307 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2120 472 A 632 086

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/358 R17

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A.

D.O.I.

Survey held at

w/s

11-12-18

Des. of Damages: 0 / Rear / O/S / N/S / U/C / Rooftop or

4:15pm

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

\$5000 - \$6000

Submit PRS report.

RECEIVED 14 DEC 2018

Date/Time, File Pass to?

14/12/18

1) Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + R5. \$

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Insp (\$



Weekend (\$

Report Format :

PRS

Lump Sum / I.B.I: (\$

450

450

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2888D

### Vehicle Details

Vehicle No.:	SFD3663A
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Brown
Manufacturing Year:	2012
Engine No.:	27186030483504
Chassis No.:	WDD2120472A632086
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$54,005.00
Original Registration Date:	23 Aug 2012
First Registration Date:	23 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$54,005.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Aug 2022
PARF Rebate Amount:	\$35,103.00

### Intended COE Rebate Details

COE Expiry Date:	22 Aug 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$94,502.00
COE Rebate Amount:	\$34,904.00
<b>Total Rebate Amount:</b>	<b>\$70,007.00</b>

The information contained herein is correct as at 12 Dec 2018

OK

## Nivitha (LKK Auto)

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 10 December 2018 2:45 PM  
**To:** Kuru & Co; MT\_Claim\_SG; assignments@lkkauto.com; Admin-D (LKKAuto)  
**Subject:** Our Ref: TBA RE: I18.1686.CJ.PRI //ACCIDENT INVOLVING SFD 3663A & YN 6966D on 7.12.18 ALONG 171 KAMPONG AMPAT ROAD NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY  
**Attachments:** img-Z10143721.pdf

Without Prejudice  
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input checked="" type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



**From:** Kuru & Co [mailto:kurulegal@yahoo.com.sg]

**Sent:** Monday, 10 December, 2018 2:40 PM

**To:** MT\_Claim\_SG; GERALD POH WEE BIN

**Subject:** l18.1686.CJ.PRI //ACCIDENT INVOLVING SFD 3663A & YN 6966D on 7.12.18 ALONG 171 KAMPONG AMPAT ROAD NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear sirs

**ACCIDENT INVOLVING SFD 3663A & YN 6966D ON 7.12.18  
ALONG 171 KAMPONG AMPAT ROAD  
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **Tang Teng Ting**, whose vehicle registration number **SFD 3663A** was damaged in the above accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

A copy of our client's SAS report is enclosed.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

## Nivitha (LKK Auto)

---

**From:** Kuru & Co <kurulegal@yahoo.com.sg>  
**Sent:** Tuesday, 11 December 2018 11:16 AM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin-D (LKKAuto)  
**Subject:** Re: Our Ref: TBA RE: I18.1686.CJ.PRI //ACCIDENT INVOLVING SFD 3663A & YN 6966D on 7.12.18 ALONG 171 KAMPONG AMPAT ROAD NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear Sirs

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

**KING'S AUTO AIR-CONDITIONING SERVICE**  
**Blk 176 Sin Ming Drive**  
**#02-10 Sin Ming Autocare**  
**Singapore 575721**  
**Tel: 6457 8629**

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Best regards  
Anne  
Kuru & Co

150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**To:** Kuru & Co <kurulegal@yahoo.com.sg>  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Sent:** Tuesday, 11 December 2018, 10:40  
**Subject:** RE: Our Ref: TBA RE: I18.1686.CJ.PRI //ACCIDENT INVOLVING SFD 3663A & YN 6966D on 7.12.18 ALONG 171 KAMPONG AMPAT ROAD NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

WITHOUT PREJUDICE

Dear Anne,

We are objecting to your list of Single Joint Expert and shall appoint LKK Auto Consultants Pte Ltd for the pre-repair survey.

Aside to LKK – Attn :Catherine,/Nivitha  
Please liaise with them for the location and address.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/12/2018 10:45
Date Of Accident	07/12/2018 14:10
Exact Location Of Accident	ALONG 171 KAMPONG AMPAT RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFD3663A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TANG TENG TING
NRIC No	S6802888D
Email Address	LESLIETANG2888@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90923663
Alternative Phone No	OFFICE-90923663

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E 250
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00010797
Cover Note Number	

### Driver

Name of Driver	TANG TENG TING
NRIC No	S6802888D
Date Of Birth	08/01/1968
Occupation	INDOOR
Date Of Driving Pass	06/01/1987
Driving Experience	31 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90923663
Fax Number	
Contact Number	OFFICE-90923663
Email Address	LESLIETANG2888@HOTMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : LING KOCK HAO GENDER: : FEMALE
Passenger 2	NAME: : ZANDER TANG GENDER: : MALE
Passenger 3	NAME: : SITI KHOLIAH GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I SFD3663A just came out from 171 kampong ampat on a two way rd. As I was already make a right turn following the other party YN6966D, suddenly the other party stop his vehicle and started to make a reverse due to he was overshoot to make a left turn into the building on the left. As I sound my horn for a some time due to I can't make any reverse as behind me there were a vehicles waiting behind me, and the other party continues to make a reverse and collided onto my front of my car. I manage to take photos at the scene and exchange particular with the other party, no injuries was involved. There was a witness who see the scene happened and he give me his name card, Mr Seah Kah Jie Contact number 94510672.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	MR SEAH KAH JIE
Phone Number	94510672
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1



Vehicle Registration Number	YN6966D
Vehicle Make/Model/Colour	ISUZU/NPR75UH5A/WHITE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HAN FENG
NRIC/Passport Number	G8003926W
Contact Number	83556382
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the QIA Records Management Centre established by the General Insurance Association of Singapore (QIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
  - (a) I understand, acknowledge, agree and consent that:
    - (i) My insurer, my workshop and the General Insurance Association of Singapore ("QIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured my vehicle(s) involved in this accident (all Insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
      - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
      - (ii) investigating the accident and/or my claims;
      - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
      - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
      - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
    - (b) all Insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
    - (c) my Personal Information may be disclosed by any of the Insurers and/or QIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MUHAMMAD SUMARDI BIN  
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I SFD3663A just came out from 171 kampong ampat on a two way rd. As I was already make a right turn following the other party YN6966D, suddenly the other party stop his vehicle and started to make a reverse due to he was overshoot to make a left turn into the building on the left. As I sound my horn for a some time due to I can't make any reverse as behind me there were a vehicles waiting behind me, and the other party continues to make a reverse and collided onto my front of my car. I manage to take photos at the scene and exchange particular with the other party, no injuries was involved. There was a witness who see the scene happened and he give me his name card, Mr Seah Kah Jie Contact number 94510672.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

8 December 2018 at 10:28 AM

Date/Time:

8 December 2018 at 10:28 AM



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

LONPAC INSURANCE BHD

Ref: CS3/LPC18022251/Gsd3e2

300 BEACH ROAD

Date: 17-12-2018

#17-04/07 THE CONCOURSESINGAPORE 199555



Code: LPC2

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YN 6966D	Veh. Inspected	SFD 3663A
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VC00/021201	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	10/12/2018

### 2. Vehicle Particulars & Condition


Make & Model	MERCEDES BENZ E 250	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDD2120472A632086	Colour	BROWN
Odometer	104307 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/35Z R19	MICHELIN	6 mm
L/H Front Tyre	245/35Z R19	MICHELIN	6 mm
R/H Rear Tyre	245/35Z R19	MICHELIN	6 mm
L/H Rear Tyre	245/35Z R19	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.



### 5. General Information

Accident Date	07/12/2018	Inspect Date / Time	11/12/2018 ( 04:15 PM )
Survey held at	KING'S AUTO AIR-CONDITIONING SERVICE BLK 176 SIN MING DRIVE #02-10 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/LPC18022251/Gsd3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.