

22/03/2002

ASS. REC. BY:

REF

CS3/MSG18022277/Gcd302

Special Instruction:

Surveyor: Quo Quang

ASSIGNMENT (Office)

From (Person): Monica Chung

of

MSG

Date/Time: 11/12/18 @ 2:28pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDN G064E

Insured:

SDG 9978K

at Workshop m/s

Wee Hoo Auto

Tel:

68580019

of

19 Kim Chuan Terrace

Policy No:

28827818QMY

Claim No:

578450

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/12/18

12/12/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

up

Date/Time: 3:11pm @ 11/12/18

Person Contacted:

Kiaf

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction	Estimate
	SDN G064E - NBA / MSG18022267 / y	D.O.A: 10/12/18
	SDG 9978K - NBA / MSG18022267 / y	D.O.A: 10/12/18
	Disassemble: 13/12/2018	

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2018		11 Dec 2018 14:28 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	Khor Poh Hwa, ID: S1852084B		
Main Claimant:	MOO AUTO, Co. Reg. No.: 53373000K		
Vehicle Reg. No.:	SDN6064E	Date of Loss:	10/12/2018 08:00 - :59 [109 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 578450	Policy/Cover Note No.:	28827818QMY (Comprehensive) Coverage: 23/10/2018 - 22/10/2019
Vehicle Reg. No. (Insured):	SDG9978K	Policy No. (Claimant):	
		Excess:	
Repairer:	Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/12/2018]		
Adj Asg. Remarks:	sje disagree appoint lkk. Liability (Non-reporting) pls contact Kiat @ 6858 0019		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3000K
Vehicle Details	
Vehicle No.:	SDN6064E
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4937196
Chassis No.:	MR053ZEE106156613
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	15 Oct 2009
First Registration Date:	15 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2019
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,201.00
COE Rebate Amount:	\$1,354.00
Total Rebate Amount:	\$10,280.00

The information contained herein is correct as at 13 Dec 2018

OK

MNA116158933 / National Assessment Centre Services - Ubl
ENTRY DATE & TIME: 10/12/2018 10:01
SUBMITTED BY: Liew Shan Hul

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 10/12/2018 10:01
Date Of Accident 10/12/2018 08:20
Exact Location Of Accident HOLLAND RD NEAR ESSO
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDN6084E
Insured/Policyholder
Name Of Registered Owner MOO AUTO
Co Reg No 53373000K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-90088701
Vehicle Particulars
Manufacturer TOYOTA
Model COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY
Fleet Policy NO
Policy Number 5097144301
Cover Note Number
Driver
Name of Driver LEW FAN JONG
NRIC No S70016241
Date Of Birth 18/01/1970
Occupation OUTDOOR
Date Of Driving Pass 27/05/1993
Driving Experience 25 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97558835
Fax Number
Contact Number
EMail Address NOEMAIL

Address BLK 353 BUKIT BATOK ST 34 #03-150
 Postcode 650353
 Was driver an employee of the Insured's Company? NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME: : SOPHIA LEE SOK FUN

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG HOLLAND RD ON THE FIRST LANE SOMEWHERE NEAR THE ESSO STATION, ALL OF A SUDDEN, VEH B (BEARING NO SDG9978K) FROM THE SECOND LANE ABRUPTLY CUT INTO MY LANE AND HIT ONTO MY VEH LEFT FRONT PORTION. DUE TO THE IMPACT, MY VEH BEEN PUSH TO THE RIGHT SIDE AND HIT ONTO THE KERB.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SDG9978K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

THIO SHU-MAN CHRISTINA

NRIC/Passport Number

S8007043H

Contact Number


Address

Postcode

Insurance Company Name

Accident Sketch Plan

SKETCH PLAN



W: 50M 1-45
S: 55M 392R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

DECLARATION

I hereby declare that the foregoing particulars are true in every respect.

1. Policyholder's Signature
2. Date & Time:

Other's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2018		11 Dec 2018 14:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Khor Poh Hwa , ID: S1852084B								
Main Claimant:	MOO AUTO , Co. Reg. No.: 53373000K								
Vehicle Reg. No.:	SDN6064E	Date of Loss:	10/12/2018 08:00 - :59 [109 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 578450	Policy/Cover Note No.:	28827818QMY (Comprehensive) Coverage: 23/10/2018 - 22/10/2019						
Vehicle Reg. No. (Insured):	SDG9978K	Policy No. (Claimant):							
		Excess:							
Repairer:	Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 12/12/2018]								
Adj Asg. Remarks:	sje disagree appoint lkk. Liability (Non-reporting) pls contact Kiat @ 6858 0019								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDN6064E (578450)**

[SDG9978K]






































TP





























MOO AUTO

Dec 10 2018 8:00AM

[Khor Poh Hwa]

Wee Hoe Auto Service

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/12/18 14:08	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/12/18 14:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/12/18 14:22	Third Party Accident Report	 Load PDF	
2	11/12/18 14:22	WORKSHOP DETAILS	 Load PDF	
3	11/12/18 14:22	REJECT SURVEYOR LIST GIVEN BY LAWYER	 Load PDF	
4	11/12/18 14:22	PRI	 Load PDF	
5	11/12/18 14:22	sje disagree appoint lkk	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022277/GCD3E2

Date: 18/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28827818QMY

Claimant Vehicle No : SDN6064E

Insured Vehicle No : SDG9978K

Date of Loss: 10/12/2018

Nature of Claim: TP

Claim No: 578450

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDN6064E

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4937196

Reg. Date: 15/10/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106156613

Colour: Silver

Odometer: 242056 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Linglong 5 mm

Rear Left Side:

Linglong 5 mm

Front Right Side: Linglong 5 mm

Rear Right Side:

Linglong 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/12/2018

Date Inspected: 12/12/2018 Inspected At:

Wee Hoe Auto Service (HQ)

19 Kim Chuan Terrace, Singapore 537041

Singapore 537041

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDN6064E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >