

ASS. REC. BY:

REF:

CS3/CT118022279/Jcd302

Special Instruction:

Surveyor

Mehmen

From (Person):

Ahwee Jee  
Cheng Boon Sen

ASSIGNMENT (Office)

of CT1

Date/Time: 11/12/18

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV?CS

To Inspect Vehicle No:

FBH 2883P

Insured:

SKS 6184H

at Workshop m/s

Equity for Brotherhood

Tel:

6384 6939

of

25 kaki Bukit Rd 4 # 03-79 Synergy

Policy No:

DMPCSNI/620721802

Claim No:

SNM18D05721002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/12/18

CA / REV / REP. / REV 24 HRS

hup

H.O.D. Endorsement:

Date/Time:

2:32pm 11/12/18

Person Contacted:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (x) Estimate
	FBH 2883P-X
	SKS 6184H-X
	Dismantle: 12/12/2018

PRS  
Hwee Jie


REF: CT1

ASSIGNMENT

From: Date: 11/12/18  
Estimated Cost:  
OT / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: FBH 2883P  
at Workshop m/s: Equator Brotherhood  
of 25kaki Bkt Rd 4 # 03-79 Synergy  
Insured:  
Policy No:  
Claims No:  
Sum Insured: Excess:  
(Client's Record)  
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS<sup>up</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBH 2883P Yr Regn: 8 May 2013  
Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Yamaha CC: 134  
Colour: white A/C: Insured / Std / NI / NA  
Sp. Reading: 69814 T/Radio: Insured / Std / NI / NA  
Eng/No:  
C/No: MH3S0C003DKS49590  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 70/90 R17  
R: 100/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. - mm L/Bal. - mm  
D.O.A. 5/12/18 D.O.I. 11/12/18  
Survey held at Equator Brotherhood  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftdp or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$1,800-\$2,600  
3 days

17/12/2018

Date/Time, File Pass to?

☐ : Prefi. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

Report Format: PRE.

Lump Sum / I.B.E. (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

TOTAL

150

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Dec 2018		11 Dec 2018 13:58 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	LAI KONG FAI, ID: S1734240A
Vehicle Reg. No.:	FBH2883P
Claim Type:	TP / SNM18D05721C02
Vehicle Reg. No. (Insured):	SKS6184H
Date of Loss:	05/12/2018 19:00 - :59
Policy/Cover Note No.:	DMPCSN1620721802
Policy No. (Claimant):	PNMC2018-00004642
Excess:	S\$0.00
Repairer:	Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/12/2018]

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4240A
<b>Vehicle Details</b>	
Vehicle No.:	FBH2883P
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	YAMAHA
Vehicle Model:	JUPITER MX (HC)
Primary Colour:	White
Secondary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	50C549632
Chassis No.:	MH350C003DK549590
Maximum Power Output:	-
Open Market Value:	\$1,809.00
Original Registration Date:	08 May 2013
First Registration Date:	08 May 2013
Transfer Count:	3
Actual ARF Paid:	\$272.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	07 May 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,909.00
COE Rebate Amount:	\$977.00
<b>Total Rebate Amount:</b>	<b>\$977.00</b>

The information contained herein is correct as at 12 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	06/12/2018 15:44
Date Of Accident	05/12/2018 19:45
Exact Location Of Accident	UPPER EAST COAST RD
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH2883P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LAI KONG FAI
NRIC No	S1734240A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93697025
Alternative Phone No	Office-93697025

**Vehicle Particulars**

Manufacturer	YAMAHA
Model	JUPITER+MX
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

**Insurance Company**

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	PNMC2018-00004642
Cover Note Number	

**Driver**

Name of Driver	LAI RENO
NRIC No	T0031800G
Date Of Birth	20/09/2000
Occupation	INDOOR
Date Of Driving Pass	20/09/2018
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93697025

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 20BEDOL SOUTH RD #04-35

Postcode

460020

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own Vehicle

-  
-  
-

Insurance Company of Driver's Own Vehicle

-  
-  
-**General Information of the Accident**

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLOUDY

Road Surface

WET

**Other Information**

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

Name: : LIM YONG DE

Gender: : Male

**Details of Police Action**

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SKS6184H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

SHAO BAIQING

12/17/2018

E-FILE

NRIC/Passport Number

G545386X

Contact Number

85185360

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LAI RENO

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBH2883P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

LIM YONG DE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBH2883P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Peng  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

[Signature]  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20181206/7010

1 of 4

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20181206/7010

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 06/12/2018 14:42			Vide Report No.:		Station Diary No.:
<b>Informant's Particulars</b>					
Name of Informant: LAI RENO			Address: APT BLK 20 BEDOK SOUTH ROAD #04-35 SINGAPORE 460020		
ID Type / ID No.: NRIC NO / T0031800G			Contact No.: Home/Office: Mobile: 93697025		
Nationality: SINGAPORE CITIZEN			Email: nightlord26@hotmail.com		
Sex: Male	Age: 18	Date of Birth: 20/09/2000	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: 2B		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/12/2018 19:45	Type of Location: Straight Road
Location:  UPPER EAST COAST ROAD				
Weather: Cloudy		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBH2883P	Motorcycle	YAMAHA	Jupiter+MX	White	Slightly Damaged	1
SKS6184H	Car	LEXUS	IS250	Silver	Slightly Damaged	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBH2883P	FWD Singapore Pte. Ltd			

**POLICE REPORT**



**SINGAPORE  
POLICE FORCE**



T/20181206/7010

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4

Report No. T/20181206/7010

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	LAI RENO	ID No.	T0031800G
Related Vehicle	FBH2883P (Motorcycle)	Contact No.	93697025
Hospital/Clinic	CHANGI GENERAL HOSPITAL, WARD 3B @ PARKWAY EAST HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	05/12/2018	Date Discharge	06/12/2018
No. of Days granted Medical Leave	10	Degree of Injury	Slight
<b>Pillion</b>			
Name	Lim Yong De	ID No.	T0014084D
Related Vehicle	FBH2883P (Motorcycle)	Contact No.	83213196
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	05/12/2018	Date Discharge	06/12/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
<b>Driver</b>			
Name	Shao Baiqing	ID No.	G545386X
Related Vehicle	SKS6184H (Car)	Contact No.	85185360
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was travelling straight along upper east coast road (171 Upper East Coast Road) on the left lane when a car from the right lane about few meters ahead of me on the right lane made a sudden left turn without signalling to turn in the condo (The Suites). I tried to brake but the turn made by the car was so abrupt that it caused a collision between the head of my motorcycle and the left front door of the car. My father subsequently drove down and brought me to access medical at 18 Bedok South Road to seek medical assistance and was referred to Changi General Hospital. I sustained several abrasions on my left forearm, lower right back and right foot as well as pain over the right lower back, gluteus area. I was awarded 10 days of medical leave, that is all.

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20181206/7010

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 4

Report No. T/20181206/7010

**CONTINUATION OF REPORT**

**POLICE REPORT**



**SINGAPORE  
POLICE FORCE**



T/20181206/7010

4 of 4

Report No. T/20181206/7010

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
THABAGESH JEYATHESH  
Contact No.: 65476232

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
06/12/2018 14:42

Classification Of Case:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Dec 2018		11 Dec 2018 13:58 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>LAI KONG FAI</b> , ID: S1734240A								
Vehicle Reg. No.:	<b>FBH2883P</b>	Date of Loss:	05/12/2018 19:00 - :59 [66 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D05721C02</b>	Policy/Cover Note No.:	DMPCSN1620721802						
Vehicle Reg. No. (Insured):	<b>SKS6184H</b>	Policy No. (Claimant):	PNMC2018-00004642						
		Excess:	S\$0.00						
Repairer:	<b>Equator Brotherhood (HQ)</b> 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 20/12/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									












## Claim Documents

\*FBH2883P (SNM18D05721C02)  
[SKS6184H]  
TP  
LAI KONG FAI  
Dec 5 2018 7:00PM  
[-]  
Equator Brotherhood

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print					
1	06/12/18 15:58	Accident Statement			Load HTM					
Photos/Images							3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print					
1	06/12/18 15:57	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
2	06/12/18 15:57	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
3	06/12/18 15:57	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
4	06/12/18 15:57	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
5	06/12/18 15:57	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
2	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
3	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
4	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
5	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
6	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
7	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
8	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
9	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
10	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
11	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
12	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
13	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
14	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
15	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
16	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
17	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
18	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
19	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
20	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
21	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
22	12/12/18 09:47	General View			Load JPG		<input checked="" type="checkbox"/>			
23	13/12/18 09:12	Dismantled Parts			Load JPG		<input checked="" type="checkbox"/>			
24	13/12/18 09:12	Dismantled Parts			Load JPG		<input checked="" type="checkbox"/>			
25	13/12/18 09:12	Dismantled Parts			Load JPG		<input checked="" type="checkbox"/>			
26	13/12/18 09:12	Dismantled Parts			Load JPG		<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
27	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	13/12/18 09:12	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/12/18 13:58	PRS CONTACT	 Load PDF	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/12/18 15:57	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	06/12/18 15:57	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	06/12/18 15:57	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	06/12/18 15:57	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	06/12/18 15:57	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	06/12/18 15:57	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	06/12/18 15:58	IC [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	06/12/18 15:58	LC [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print	
1	06/12/18 15:58	Accident Statement	 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print	
1	06/12/18 15:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
2	06/12/18 15:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
3	06/12/18 15:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
4	06/12/18 15:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
5	06/12/18 15:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print	
1	06/12/18 15:57	Sketch Plan	 Load TIF		
2	06/12/18 15:57	Sketch Plan #2	 Load TIF		
3	06/12/18 15:57	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>	
4	06/12/18 15:57	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>	
5	06/12/18 15:57	POLICE REPORT	 Load JPG		



Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print
					<input checked="" type="checkbox"/>
6	06/12/18 15:57	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>
7	06/12/18 15:58	IC		Load JPG	<input checked="" type="checkbox"/>
8	06/12/18 15:58	LC		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18022279/JCD3E2

Date: 31/12/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN1620721802

Claimant Vehicle  
No: FBH2883PInsured Vehicle  
No: SKS6184H

Date of Loss: 05/12/2018

Nature of Claim: TP

Claim  
No: SNM18D05721C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBH2883P

Make &amp; Model: YAMAHA JUPITER 115 Z1, 114cc

Reg. Date: 08/05/2013 (Man. Year: 2013)

Colour: White

Engine Capacity: 134 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: 50C549632

Chassis No: MH350C003DK549590

Odometer: 69814 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 70/90 R17

Front Left Side: Dunlop 6 mm

Front Right Side: 0 mm

Rear Tyre Size: 100/70 R17

Rear Left Side: Dunlop 6 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 11/12/2018

Date Inspected: 11/12/2018 Inspected At:

Equator Brotherhood (HQ)  
25 kaki bukit rd 4 #03-79 synergy @ kb  
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 -\$2,600.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 31 Dec 2018)	
<b>Parts:</b>	N/A	YAMAHA JUPITER 115 Z1 114cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBH2883P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >