

INSURANCE

INS. CASH OWNER:

CC 4/AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

12/11/18

STAGE

DATE / PIC

Non-Reporting Ir (1st):

Non-Reporting Ir (2nd):

Non-Reporting Ir (Final):

Notification Ir (if non-pickup):

Call OE:

After call Ir to OE:

Documentation Check List: Handler Typist

Notification Ir (if non-pickup):

After call Ir to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MED

Repair Cost: PIP S\$ 8,011.38

(4 days)

Reduction:

35 %

Email

Call

FINAL SETTLEMENT

Date/Time: 28-05-19

Confirm with: PRELIMINARY

Confirm by: MED

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 8,512.07

QID REVERSED - THIS PARTIAL TP

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 340.00

(\$ 40 x 6 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 8,934.07

Global Sum S\$:

FINAL PAYMENT

Date/Time: 28-05-19

Confirm with: CTR/QUE

Confirm by: MED

Payee 1:

S\$ 8,934.07

Name 1:

PERFORMANCE MOTORCYCLES

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASSIGNMENT

REF:

C

65756

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SMA 1075 T**

at Workshop n/s **PERFORMANCE**

of

Insured

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: **4** days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMA 1075 T** Yr Regn: **2018 May**
Type: **C** M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **B.M.W 318I**

CC: **1499**

Colour: **WHITE**

A/C: Insured / Std / NI / NA

Sp. Reading: **07721**

T/Rado: Insured / Std / NI / NA

Eng/No:

C.No: **WBABE36000N482160**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: **B** In order / Jammed / Leaked / Burnt or

Brake: **B** In order / Jammed / Leaked / Burnt or

Modi: **C** Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/45R18**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **CONTINENTAL**

Front

Rear

R/Bal: **6** mm

R/Bal: **6** mm

L/Bal: **6** mm

L/Bal: **6** mm

D.O.A: **09/12/18**

D.O: **11/12/18**

Survey held at **PERFORMANCE**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

pp: +8,011.28 CRD: +4,201.87 35%/-

Com/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Com/Time: File Return to?

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.1 (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18022285/R1eb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 11-12-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4854X	Veh. Inspected	SMA 1075T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/12/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
Ea. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Rongong Arang Road
East Coast Centre
Singapore 438186
Tel. 63190889 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

(Car In)

Estimate No. : b1 49404
Date Estimated : 11/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ng Yuan Xin (Huang YuanXin)
61 Lorong Sarhad
#03-07

Singapore 119174

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA1075T	NU82160	28/05/2018	318i	0

DESCRIPTION

To replace frt bumper, frt LH headlamp bracket & all attachments cause by accident.

VALUE
850 / 1,700.00

Painting on frt bumper panel & frt LH side panel

882 / 1,634.00

To check electrical wiring systems at the front section for proper function.

150 / 171.00

To replace left headlight.

408 / 481.00

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

451 / 531.00

To replace tyre and wheel rim including balancing. (1x).

94.00

Sundries. *new*

150.00

Total Labour 1: 4,767.00

DESCRIPTION

BLIND RIVET *m*
ALLOY RIM 8Jx18 DOUBLE SPK 397 *SEA*
FRT BUMPER TOP MOUNT *m*
FRT LH DEFORMATION ELEMENT *m*
FRT LH LOWER DEFORMATION ELEMENT *m*
SUPPORT CENTRAL *m*
MOUNT FOR SUPPORT *m*
INSERT AIR INLET MIDDLE *m*
LH FOG LAMP SUPPORT *m*
FINISHER ROD CENTRE (SPORT) *m*
LH FINISHER ROD (SPORT) *m*
LH AIR INLET FINISHER (SPORT) *m*
FRT SHOCK ABSORBER ECE *m*
LH SPRAY NOZZLE COVER PRIMED *m*
SET MOUNTING PDC/PMA SENSOR FRT *m*

QTY	PRIC	VALUE
2	1.55	3.10
1	1,089.10	1,089.10
1	370.70	370.70
1	99.80	99.80
1	84.70	84.70
1	11.35	11.35
1	6.60	6.60
1	121.95	121.95
1	41.85	41.85
1	53.40	53.40
1	40.20	40.20
1	53.20	53.20
1	53.45	53.45
1	43.25	43.25
1	84.10	84.10



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49404
Date Estimated : 11/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA1075T	NU82160	28/05/2018	318i	0

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
SET MOUNTING PDC/PMA SENSOR FRT <i>AN</i>	1	84.10	84.10
FRT BUMPER PANEL PRIMED (SPORT LINE) <i>DE</i>	1	1,007.30	1,007.30
LH PARTIALLY OPEN GRID (SPORT EDITI) <i>AN</i>	1	88.40	88.40
FRT LH GRILLE (SPORT EDITION) <i>SEA</i>	1	118.55	118.55
LH SUPPORT <i>? bt</i>	1	55.30	55.30
FRT LH WHEEL HOUSING COVER <i>SEA</i>	1	116.55	116.55
LH COVER BOTTOM <i>AN</i>	1	116.55	116.55
DEFLECTOR LIP LH <i>AN</i>	1	52.80	52.80
FANFARE HORN HIGH TONE ELECTRONIC <i>AN</i>	1	94.70	94.70
FANFARE HORN LOW TONE ELECTRONIC <i>? SEA</i>	1	94.70	94.70
LH HEADLIGHT LED TECHNOLOGY <i>SEA</i>	1	3,068.40	3,068.40
DECOUPLING RING PDC TORQUE CONVERTE <i>AN</i>	4	5.05	20.20
PDC SENSOR MINERALWEISS (A96) <i>AN</i>	1	368.80	368.80
(DG/SL) ADHESIVE SET K6 <i>SEA</i>	1	53.05	53.05

Total Parts : 7,496.15

Client's CG / *C* / *Unrecorded Invoice / Direct Settlement*

Regn No. *11/12/18 @ 1600* Client No. _____

Date & Time *11/12/18 @ 1600* Excess CG _____

Surveyor's Name *R/Sue* Sign. _____

Surveyor's Tel *90060068* Authorized Yes / No _____

Authorized Date _____ Time _____

RECEIVED PARTS PHOTO *YES* / *NO* Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended *4 days*

BMW Asset Consultants hereby notify the Register at the following:

- To remove damaged parts from the car
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recorded and is subject to final approval from Insurance Company

Acknowledged by Register

Signature:

Date:

Labour 1	:	4,767.00
Parts	:	7,496.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	858.42
Grand Total	:	13,121.57

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sims Derby Group
Co. Reg. No. 197401559W, GST Reg. No. M3-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49404
Date Estimated : 11/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Ng Yuan Xin (Huang YuanXin)
61 Lorong Sarhad
#03-07

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 119174

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SMA1075T	NU82160	28/05/2018	318i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT LH TOP SUPPORT SIDE PANEL *	18.45	1.00	3.00	17.90
# FRT LH BOTTOM MOUNTING SIDE PANEL *	18.45	1.00	3.00	17.90
# PLAQUE 82MM *	71.25	1.00	3.00	69.11

Total Labour :
Total Parts : 104.91
Total Labour & Parts : 104.91

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-E



FINAL REPORT

Estimate No. : b1 49404
Date Estimated : 11/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Ng Yuan Xin (Huang YuanXin)
61 Lorong Sarhad
#03-07

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 119174

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SMA1075T	NU82160	28/05/2018	318i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, LH fog lamp support, LH support, LH bottom cover include knocking out dents caused by the accident	850.00	10.00	765.00	
To spray paint front bumper	882.00	10.00	793.80	
To check electrical wiring systems at the front section for proper function	150.00	10.00	135.00	
To replace LH LED technology headlight include programming and conducting tests for proper function	408.00	10.00	367.20	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00	10.00	405.90	
To replace wheel rim include balancing (1x)	94.00	10.00	84.60	
Sundries	80.00	0.00	80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BLIND RIVET	1.55	2.00	3.00	3.01
ALLOY RIM 8Jx18 DOUBLE SPK 397	1,089.10	1.00	3.00	1,056.43
# FRT LH TOP SUPPORT SIDE PANEL *	18.45	1.00	3.00	17.90
# FRT LH BOTTOM MOUNTING SIDE PANEL *	18.45	1.00	3.00	17.90
LH FOG LAMP SUPPORT	41.85	1.00	3.00	40.59
FRT SHOCK ABSORBER ECE	53.45	1.00	3.00	51.85
SET MOUNTING PDC/PMA SENSOR FRT	84.10	1.00	3.00	81.58
FRT BUMPER PANEL PRIMED (SPORT LINE	1,007.30	1.00	3.00	977.08
FRT LH GRILLE (SPORT EDITION)	118.55	1.00	3.00	114.99
LH SUPPORT	55.30	1.00	3.00	53.64
LH COVER BOTTOM	116.55	1.00	3.00	113.05
DEFLECTOR LIP LH	52.80	1.00	3.00	51.22
# PLAQUE 82MM *	71.25	1.00	3.00	69.11
FANFARE HORN LOW TONE ELECTRONIC	94.70	1.00	3.00	91.86
LH HEADLIGHT LED TECHNOLOGY (BLACK	2,668.15	1.00	3.00	2,588.11
(DG/SL) ADHESIVE SET K6	53.05	1.00	3.00	51.46

Performance Motors Limited

A member of the Sims-Carby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

SUPPLEMENTARY ITEMS

Total Labour :	2,631.50
Total Parts :	5,379.78
Total Labour & Parts :	8,011.28
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,011.28
GST @7%:	560.79
Grand Total :	8,572.07

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 12 December 2018 5:21 PM
To: PBSP
Cc: Admin A
Subject: RE: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMA1075T & XD4854X ON 09/12/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Wednesday, 12 December 2018 4:52 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: FW: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMA1075T & XD4854X ON 09/12/2018

Dear Caroline,

We refer to the below email.

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 11 December 2018 2:36 PM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMA1075T & XD4854X ON 09/12/2018

Dear Shu Pei,

Smart Claim case.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Tuesday, 11 December, 2018 2:28 PM

To: assignments <assignments@lkkauto.com>

Subject: Fw: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMA1075T & XD4854X ON 09/12/2018

From: PBSP

Sent: Tuesday, 11 December 2018 11:07 AM

To: motor.survey@axa.com.sg

Subject: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMA1075T & XD4854X ON 09/12/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601



MANDATE REQUEST FOR S8M0165R

✓

Type

🔗 Question

Message

Liability: Insured hit third party parked vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$8,372.86 (w/GST) Loss of Use: \$240.00 (4days x \$60) Disbursement: \$200.00 LTA : \$2.00 Total: \$8,814.86 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng
(03/01/2019)

Reply

<< RE: Re:RE: Re:MANDATE REQUEST FOR S8M0165R

Type

 Question

Message

Hi KC, we have uploaded the revised IA with mandate for your approval.

[Reply](#)



Re:RE: Re:RE: Re:MANDATE REQUEST FOR S8M0165R

Type

🔗 Question

Message

PLS PROCEED AS FOLLOWS: COR \$8,572.07 LOU \$360 LTA \$2.00 TOTAL \$8,934.07

Reply

Asher Sng (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 2 May 2019 4:57 PM
To: Asher Sng (LKKAUTO)
Subject: Fw: [SETTLEMENT] AXA / SMA1075T

Follow Up Flag: Follow up
Flag Status: Completed

Dear Asher

Strictly for the purpose of an early and amicable settlement, we have instructions to close the matter at LOU \$60/day and waive ceramic coating charges for this case.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Tuesday, 26 March 2019 8:57 AM
To: PBSP
Subject: RE: [SETTLEMENT] RE: FINAL REPORT / SMA1075T

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Caroline,

We refer to the email below.

Our principal in view that your client ceramic spray coating is more than a month at the time of accident.

Your client's vehicle loss of use under the benchmark is \$50 - \$60.

Our offer to your client's claim @ \$60 per day is fair and reasonable.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 25 March 2019 6:15 PM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: Re: [SETTLEMENT] RE: FINAL REPORT / SMA1075T

Dear Asher

Our customer's mandate for loss of use is \$80/day for 6 days. Our customer wants to know why your Principal disagrees with the ceramic spray coating? Our customer is adamant to claim for the ceramic coating which we are of view that our customer's request is fair and reasonable since he had provided the before and after accident invoice of the ceramic coating he had done.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Sent: Monday, 4 March 2019 11:30 AM
To: PBSP
Subject: [SETTLEMENT] RE: FINAL REPORT / SMA1075T

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

Our principal propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 8,572.07
2. Loss of Use (6 days x \$60)	\$ 360.00
3. LTA/GIA search fee	\$ 2.00
TOTAL	<u>\$ 8,934.07</u>

*Our principal disapproved on the Ceramic spray coating.

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto)

Sent: Thursday, 31 January 2019 4:54 PM

To: 'PBSP' <pml-pbsp@simedarby.com.sg>

Subject: RE: FINAL REPORT / SMA1075T

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi Caroline,

We refer to the above matter.

Our surveyor have finalise COR at \$8,011.28 (exclude gst) 4 days, finalize amount subject to our principal approval.

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

- Please do not send the LOD to our prinicpal for direct settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Thursday, 31 January 2019 9:46 AM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: Re: FINAL REPORT / SMA1075T

Dear Asher

Please see attached surveyor's markings. The labor according to the markings.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: PBSP

Sent: Monday, 28 January 2019 3:37:01 PM

To: Rasul; Asher Sng (LKK Auto)

Subject: FINAL REPORT / SMA1075T

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,631.50

Total Parts : 5,379.78

Total Labour & Parts : 8,011.28

*Separately, please note that owner will be claiming polishing and recoating of \$300 on accident arear. Please refer to attach invoice (before and after accident) submitted by the owner from "AutoPro Chemicals Pte Ltd".

Repair days: 6

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8846975E



Name

NG YUAN XIN
(HUANG YUANXIN)

黄沅欣

Race

CHINESE

Date of birth

23-11-1988

Sex

F

Country of birth

SINGAPORE



3819790

NRIC No: S8846975E



Date of issue

04-10-2004

61 LORONG SARHAD #03-07
SINGAPORE 118174
NRIC No: S8846975E

Date: 08/11/2016

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number
Name

S8846975E

NG YUAN XIN
(HUANG YUANXIN)

Birth Date: 23 Nov 1988

Issue Date: 17 Aug 2010



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 17 Aug 2010



NP 426A

Invoice

26 December 2018

To:
Alvin Lee

Contact:
+6596224923

Ship To
Same as Recipient

Instructions
Avoid heat or sunlight

Bank Details

Bank Code: 7339

Name: Auto Pro
Chemicals Pte Ltd

Swift: OCB CSGSG

Account Number:
550003347301

Bank Address:
65 Chulia Street OCBC
Centre, Singapore
049513

Paypal:
Shopautopro@gmail.com

Quantity	Description	Unit Price	Total
1	Repolish and recoat affected area of accident Model: BMW Make: F30 Color: White VRN: SMA1075T	\$300	\$300
	Subtotal		\$300
	Shipping & Handling		-
	Overnight Shipping		-
	Bank/PayPal Charges		-
	Discount		-
	Total Due		\$300

Due upon receipt

Thank you for your business!

AutoPro Chemicals Pte Ltd

E: shopautopro@gmail.com

T: +6591700700 A: 3018 Bedok North Street 5, Singapore 486132. Unit #03-47



Invoice

23rd June 2018

To:
Alvin Lee

Contact:
+6596224923

Ship To
Same as Recipient

Instructions
Avoid heat or sunlight

Bank Details

Bank Code: 7339

Name: Auto Pro
Chemicals Pte Ltd

Swift: OCBCSGSG

Account Number:
550003347301

Bank Address:
65 Chulia Street OCBC
Centre, Singapore
049513

Paypal:
Shopautopro@gmail.com

Quantity	Description	Unit Price	Total
1	Car paint prepped and ceramic spray coated Model: BMW Make: F30 Color: White VRN: SMA1075T	\$550	\$550
	Subtotal		\$550
	Shipping & Handling		-
	Overnight Shipping		-
	Bank/PayPal Charges		-
	Discount		-
	Total Due		\$550

Due upon receipt

Thank you for your business!

AutoPro Chemicals Pte Ltd

E: shopautopro@gmail.com

T: +6591700700 A: 3018 Bedok North Street 5, Singapore 486132, Unit #03-47





Service Request Details

Claim

S8M0165R

Reference

None

Loss Date

December 9, 2018

Request Date

December 11, 2018

Due Date

December 18, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

11/12/2018 @ 2:29pm

Caroline Whin

Rosal

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SMA1075T

Make

TPVD BMW

Model
318L

Service Address

...

Primary Contact/Insured

VEOLIA ES SINGAPORE PTE LTD
17 TUAS AVENUE 12, 639037, Singapore
66810302
sookchan.ho@veolia.com

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

To: AXA Insurance

I, Ng Guan Xin (S8846975E) would like to verify that
my signature is on the Performance Motors form. The signature on
the Accident Report is by my brother, who represented me ~~as I~~
~~was not a driver~~. Thank you.

Warm Regards,

Ng Guan Xin





(A)

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

"Without Prejudice"

Your Ref

Our Ref

Date

Subject

08 February 2019

ACCIDENT INVOLVING VEHICLES SMA1075T & XD4854X ON 09.12.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	8572.07
Loss of use	:	S\$	480.00 (S\$80.00 x 6 days)
Ceramic Spray Coating	:	S\$	300.00
GIA search fee	:	S\$	2.00
Total	:	S\$	9354.07

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales
6319 0885
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Ceramic Spray Coating slip
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

12 DEC 2018

VEOLIA ES SINGAPORE PTE. LTD.
17 TUAS AVENUE 12
SINGAPORE 639037

Dear Sir/ Mdm

OUR REF : CC4/ASM18022285/R1eb3
YOUR REF : XD 4854X
ACCIDENT INVOLVING XD 4854X AND SMA 1075T ALONG PASIR PANJANG RD
ON 09/12/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s PERFORMANCE MOTORS LTD acting on behalf of the owner of SMA 1075T against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy. We also wish to advise that there is an excess of S\$5,000.00 attached with Third Party Claims.

AXA shall keep you informed of when to make the excess payment, which cheque is to be made in favor of "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to cst@axa.com.sg **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA's Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm (press 1 for GI and option 3 for claims) or cst@axa.com.sg. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SMA 1075T & XD 4854X ON 9/12/18.

I, NG YUAN XIN owner of Vehicle Registration No. SMA 1075T
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:

x

Name : NG YUAN XIN (Date)

NRIC No.: 389467152

In the presence of:

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 119941

Name : (Date)

NRIC No.:



redefining / insurance

CLAIM REF : 88M0682
INSURED : YEDUA. EA SINGAPORE PTE. LTD

DISCHARGE VOUCHER

We/I Ng Yuan Xin, NRIC NO. S8846975E hereby agree to accept the sum of dollars [EIGHT THOUSAND NINE HUNDRED TWENTY FOUR AND SEVEN CENTS] (S\$ 8,939.07) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. X04854X as a result of an accident along Pasir Panjang Road on 9/12/18 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SMA 1075T.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. X04854X in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. X04854X.

Dated this 28 day of 05 2019

Claimant's Signature : [Signature]

NRIC no./ Company Stamp : S8846975E

Occupation/ Business : _____

Address : _____

Telephone No. : _____

Witness's Name : _____

Witness's Signature : [Signature]

Witness's NRIC No. : _____

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190513/538 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1322734

Date IN : 13/12/2018

Cust. Svc. Advisor: Kevin Leong Wai Kit

Page No. : 1 of 2

Invoice Number : 2061943 / WSB

Invoice Date : 31/01/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Ms Ng Yuan Xin (Huang YuanXin)
61 Lorong Sarhad
#03-07

Singapore 119174

- INVOICE TO - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.
SMA1075T

CHASSIS NO.
NU82160

REGN. DATE
28/05/2018

MODEL
318I

MILEAGE
7721

- - - - LABOUR 1 - - - -

To replace front bumper and attachments including to
remove and install body parts in order to carry out painting
job.

To respray front bumper.

To check electrical wiring systems at the front section
for proper function.

To replace left Technology LED headlight.

To check steering geometry and conduct wheel alignment
according to BMW specification

To replace front left wheel rim including balancing.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 9.12.2018. 3RD PARTY CAR : XD4854X.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO
CONSULTANTS PTE LTD ON 11.12.2018 AT 4.00 PM.
AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON
12.12.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$80X6. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

CERAMIC SPRAY COATING - \$300.

GIA SEARCH FEE = \$2.00.

Retail

Price

DISC%

NETT

850.00

10.00

765.00

882.00

10.00

793.80

150.00

10.00

135.00

408.00

10.00

367.20

451.00

10.00

405.90

94.00

10.00

84.60

80.00

0.00

80.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Total Labour 1:

2,631.50

- - - - PARTS - - - -

BLIND RIVET

LH FOG LAMP SUPPORT

FRT SHOCK ABSORBER ECE

SET MOUNTING PDC/PMA SENSOR FRT

FRT BUMPER PANEL PRIMED (SPORT LINE

LH SUPPORT

(DG/SL) ADHESIVE SET K6

FRT LH TOP SUPPORT SIDE PANEL

FRT LH BOTTOM MOUNTING SIDE PANEL

Retail

Qty

Price

DISC%

NETT

2

1.55

3.00

3.01

1

41.85

3.00

40.59

1

53.45

3.00

51.85

1

84.10

3.00

81.58

1

1,007.30

3.00

977.08

1

55.30

3.00

53.64

1

53.05

3.00

51.46

1

18.45

3.00

17.90

1

18.45

3.00

17.90



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/338 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1322734	Page No. : 2 of 2
Date IN : 13/12/2018	Invoice Number : 2061943 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 31/01/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

ALLOY RIM 8Jx18 DOUBLE SPK 397	1	1,089.10	3.00	1,056.43
FRT LH GRILLE (SPORT EDITION)	1	118.55	3.00	114.99
DEFLECTOR LIP LH	1	52.80	3.00	51.22
FANFARE HORN LOW TONE ELECTRONIC	1	94.70	3.00	91.86
LH HEADLIGHT LED TECHNOLOGY (BLACK	1	2,668.15	3.00	2,588.11
LH COVER BOTTOM	1	116.55	3.00	113.05
PLAQUE 82MM	1	71.25	3.00	69.11

Total Parts : **5,379.78**

Labour Charges :	2,551.50	Total Labour & Parts Charges :	S\$ 8,011.28
Parts Charges :	5,379.78	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	80.00	Invoice Total Amount Exclude GST :	S\$ 8,011.28
		GST @ 7% :	S\$ 560.79
		Invoice Total Amount Include GST :	S\$ 8,572.07

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 8,572.07**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-191204

Date of Request: 11/12/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 11/12/2018
Enquiry By Melanie Setiawati
TP Vehicle No. XD4854X
Accident Date 09/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
XD4854X	AXA Insurance Pte Ltd	01/01/2018-31/12/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-191204

Date of Request: 11/12/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 11/12/2018
Enquiry By Melanie Setiawati
TP Vehicle No. XD4854X
Accident Date 09/12/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	XD 4854X (Insd veh)	Model:	B.M.W. 318I
	SMA 1075T (TP veh)		
Date of Accident:	09/12/2018		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	13,233.82
Final Repair Cost	: \$	8,572.07
Loss of Use	: \$	360.00
Rental (if any)	: \$	6days at \$60.00 per day
LTA / GIA Search Fee	: \$	2.00

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	8,934.07

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: 100 _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	PERFORMANCE MOTORS LIMITED	: \$ 8,934.07

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

06/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022285/R1eb3q2

8 SHENTON WAY #24-01

AXA TOWERSINGAPORE 068811

Date : 06-06-2019



ATTN: KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 4854X	Veh. Inspected	SMA 1075T
Policy No.	VFX/P1582555	Coverage (\$)	0.00
Claim No.	S8M0165R	Excess (\$)	0.00
Assign From		Assign Date	11/12/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 318i	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBA8E36000NU82160	Colour	WHITE
Odometer	7721	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/12/2018	Inspection Date	11/12/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 1075T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	80.00
2	BLIND RIVET (SN) (CONSISTENT)	NECESSARY	3.10	3.01
1	ALLOY RIM 8JX18 DOUBLE SPK 397 (SN) (CONSISTENT)	SCRATCHED	1,089.10	1,056.43
1	FRT BUMPER TOP MOUNT (SN) (CONSISTENT)	NOT NECESSARY	370.70	-
1	FRT LH DEFORMATION ELEMENT (SN) (CONSISTENT)	NOT NECESSARY	99.80	-
1	FRT LH LOWER DEFORMATION ELEMENT (SN) (CONSISTENT)	NOT NECESSARY	84.70	-
1	SUPPORT CENTRAL (SN) (CONSISTENT)	NOT NECESSARY	11.35	-
1	MOUNT FOR SUPPORT (SN) (CONSISTENT)	NOT NECESSARY	6.60	-
1	INSERT AIR INLET MIDDLE (SN) (CONSISTENT)	NOT NECESSARY	121.95	-
1	LH FOG LAMP SUPPORT (SN) (CONSISTENT)	CRACKED	41.85	40.59
1	FINISHER ROD CENTRE (SPORT) (SN) (CONSISTENT)	NOT NECESSARY	53.40	-
1	LH FINISHER ROD (SPORT) (SN) (CONSISTENT)	NOT NECESSARY	40.20	-
1	LH AIR INLET FINISHER (SPORT) (SN) (CONSISTENT)	NOT NECESSARY	53.20	-
1	FRT SHOCK ABSORBER ECE (SN) (CONSISTENT)	CUT	53.45	51.85
1	LH SPRAY NOZZLE COVER PRIMED (SN) (CONSISTENT)	NOT NECESSARY	43.25	-
1	SET MOUNTING PDC/PMA SENSOR FRT (SN) (CONSISTENT)	NECESSARY	84.10	81.58
1	SET MOUNTING PDC /PMA SENSOR FRT (SN) (CONSISTENT)	NOT NECESSARY	84.10	-
1	FRT BUMPER PANEL PRIMED (SPORT LINE) (SN) (CONSISTENT)	DEFORMED	1,007.30	977.08
1	LH PARTIALLY OPEN GRID (SPORT EDITI) (SN) (CONSISTENT)	NOT NECESSARY	88.40	-
1	FRT LH GRILLE (SPORT EDITION) (SN) (CONSISTENT)	SCRATCHED	118.55	114.99
1	LH SUPPORT (SN) (CONSISTENT)	BENT	55.30	53.64
1	FRT LH WHEEL HOUSING COVER (SN) (CONSISTENT)	TORN	116.55	113.05
1	LH COVER BOTTOM (SN) (CONSISTENT)	NOT NECESSARY	116.55	-
1	DEFLECTOR LIP LH (SN) (CONSISTENT)	NECESSARY	52.80	51.22
1	FANFARE HORN HIGH TONE ELECTRONIC (SN) (CONSISTENT)	NOT NECESSARY	94.70	-
1	FANFARE HORN LOW TONE ELECTRONIC (SN) (CONSISTENT)	SCRATCHED	94.70	91.86

Report Ref No. CC4/ASM18022285/R1eb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH HEADLIGHT LED TECHNOLOGY (SN) (CONSISTENT)	SCRATCHED	3,068.40	2,588.11
4	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT)	NOT NECESSARY	20.20	-
1	PDC SENSOR MINERALWEISS (A96) (SN) (CONSISTENT)	NOT NECESSARY	368.80	-
1	(DG/SL) ADHESIVE SET K6 (SN) (CONSISTENT)	NECESSARY	53.05	51.48
1	FRT LH TOP SUPPORT SIDE PANEL (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	17.90	17.90
1	FRT LH BOTTOM MOUNTING SIDE PANEL (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	17.90	17.90
1	PLAQUE 82MM (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	69.11	69.11
			7,751.06	5,459.78
	LABOUR			
	TO REPLACE FRT BUMPER ,FRT LH HEADLAMP BRACKET & ALL ATTACHMENTS CAUSE BY ACCIDENT.		1,700.00	765.00
	PAINTING ON FRT BUMPER PANEL & FRT LH SIDE PANEL.		1,634.00	793.80
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION.		177.00	135.00
	TO REPLACE LEFT HEADLIGHTS.		481.00	367.20
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION .		531.00	405.90
	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING.		94.00	84.60
			4,617.00	2,551.50
	GRAND TOTAL		12,368.06	8,011.28
	RECOMMENDED COST OF REPAIRS			8,011.28

Report Ref No. CC4/ASM18022285/R1eb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

```

graph LR
    A[Actions] --> B[Next Step]
    B --> C[Add Invoice]
  
```

Vehicle Information	
Incident Vehicle Registration #	SMA1075T
Make	TPWD BMW
Model	318L
Service Address	















Primary Contact/Insured

VEOLIA ES SINGAPORE PTE LTD
17 TUAS AVENUE 12-659037, Singapore
66810302
sookchan.hu@veolia.com

Claim Handler
CHAN Kian Chuan
658804269
klunchuan.chan@asia.com.sg

Additional Instructions

	Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type	<div> <div>▼</div> <div>Document SubType</div> <div>▼</div> </div>						
<div>+ Upload Documents.</div>							
NAME			TYPE	SUB-TYPE		AUTHOR	DATE UPLOADED
LKX Invoice1 (3).pdf			Invoice	Surveyor/ Assessor expense		LKX AUTO CONSULTANTS PTE LTD (TP)	6 June 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	6 June 2019
 FINAL REPORT - REVISED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 February 2019
 COATING INVOICE (REVISED).pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 February 2019
 Immediate Advice with Mandate - REVISED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 February 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 January 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 January 2019

