

22/03/2002

ASS. REC. BY:

REF:

CS/GAI18022299/Usd3ct

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Kelvyna Ngian

of

GAI

Date/Time:

11/12/18 @ 3:08pm

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE625Y

Insured:

at Workshop m/s

NPH Auto

Tel:

6784 0663

of

Blk9005 tumpines st. 93 # 01-246/254

Policy No:

Claim No:

CHMOMVC000003575

Sum Insured:

Excess:

\$ 600.00

Make of Veh:

D.O.A.

01/12/2018

(Client's Record)

if consistent.

☒ CA / REV / REP. / REV 24 HRS

12/12/2018

H.O.D. Endorsement:

Date/Time:

3:40pm @ 11/12/18

Person Contacted:

peggy

Vehicle

☒ IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBE625Y-X

13/12/18

@ 16:50 p.m.: revised PA to Kelvyna via email.

REF: GAI

ASSIGNMENT

From: Date: 12/12/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBE 625 Y

at Workshop n/s: NPH Auto

of: Blk 9005, Tampines St. 93 # 01-246/

Insured: 254

Policy No.

Claims No.

Sum Insured: Excess: \$ 600.00

(Client's Record)

Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 45k.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PB Seen: 2 Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

☒ if consistent
CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted: L7A 2P188

Veh No: GBE 625 Y Yr Regn: 8 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Cn /

Make: NISSAN NV350 C.C. 2488

Colour: white A/C Insured / Std / NI / NA

Sp. Reading: 16/200 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1MC2E2620004807

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NIP / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 12/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rear w/screens shattered

The U/C / Chassis frame / Body Structure affected due to collision.

14/12/18 confirmed L/S \$ 4500 with MANG.

14/12/18 Confirmed L/S \$ 4,500/- @ 5 days with Marcus
(\$ 1,356.20 - Red - 23%)

14/12/2018

RECEIVED 14 DEC 2018

Date/Time, File Pass to?

14/12/18

1) Typ: SF

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 4,500/- HS

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

250

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

250

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1373W
Vehicle Details	
Vehicle No.:	GBE625Y
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	YD25376155A
Chassis No.:	JN1MC2E26Z0004807
Maximum Power Output:	-
Open Market Value:	\$22,176.00
Original Registration Date:	27 Aug 2015
First Registration Date:	27 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$1,109.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,045.00
COE Rebate Amount:	\$28,188.00
Total Rebate Amount:	\$28,188.00

The information contained herein is correct as at 12 Dec 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



15-16 DEC
DOWNTOWN EAST
CARPARK B

- ◆ Largest Fleet of Near-
- ◆ Massive Savings from
- ◆ Low Interest Rate of 1
- ◆ Minimum 12 Months V

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A



2.88% P.A. Lowest Interest @ GV
Cars Financing \$2000
Downpayment Monthly From
\$638
GV Credit Pte Ltd StarAd



click here to view
our **PRISTINE USED**
at GREAT

Browse by Category






Sort by Date Posted

7 vehicles

nv350

Advanced Search



	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	nv350		Any	Any	2015	Any	Any	Any
	Nissan NV350 2.5A		\$50,800	\$7,270 /yr	07-Dec-2015	2,488 cc	38,087 km	Van
	Fuel Type: Diesel Original Paintwork, Excellent Condition, Authentic Low Mileage Done, Well Taken Care By Previous Owner, 100% Loan Available, High Trade In Accident-Free, Call Our Sale Consultant For Appointment... ABWIN (1994) Pte Ltd Posted: 11-Dec-2018 Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan							
	Nissan NV350 2.5M		\$44,800	\$7,130 /yr	23-Mar-2015	2,488 cc	82,000 km	Van
	Fuel Type: Diesel SMS Only. Ridiculous Offers Will Be Ignored. Posted: 08-Dec-2018 Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan							
	Nissan NV350 2.5M		\$48,800	\$7,230 /yr	10-Sep-2015	2,488 cc	-	Van
	Fuel Type: Diesel Previous Owner Retired So Need Sell This Van, Normally Carry Light Goods Only, High COE Value, Low Miles, Super Good Condition Like Brand New No Need Repairs Anything, Regular Servicing Done, Price Negotiable... ABWIN Bus Pte Ltd Posted: 03-Dec-2018 Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan							
	Nissan NV350 2.5M		\$52,800	\$7,510 /yr	21-Dec-2015	2,488 cc	-	Bus
	Fuel Type: Diesel Cheapest PA Bus In The Market! Make Appointment To View This Beauty Before It Is Gone! Posted: 29-Nov-2018 Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan							
	Nissan NV350 van to be launched Nissan will launch the all-new NV350 van at the upcoming Tokyo Motor Show, and the van will go on sale by the middle of next year Read this article							
	Nissan NV350 2.5A		\$64,900	\$10,050 /yr	28-May-2015	2,488 cc	63,627 km	Bus
	Fuel Type: Diesel 10 Seaters Excursion Bus In Excellent Condition. Well Maintained And Regularly Serviced. Call Now For Viewing Appointment! Posted: 15-Nov-2018 Tags: 2015 Nissan NV350, 2015 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan							

Compare

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 13 December 2018 4:50 PM
To: 'Ngian, Kelvyna'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: CLMOMVC000003575 ACCD INLVG OD GBE625Y ON 01/12/2018
Attachments: GBE 625Y - Preli Advise.pdf

Dear Kelvyna,

Enclosed preliminary revised of vehicle GBE 625Y
Date of survey: 12/12/2018
Number of days : 5 days

We have authorise repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 11 December 2018 4:02 PM
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CLMOMVC000003575 ACCD INLVG OD GBE625Y ON 01/12/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 12/12/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]
Sent: Tuesday, 11 December 2018 3:08 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Subject: CLMOMVC000003575 ACCD INLVG OD GBE625Y ON 01/12/2018

Hi team

OD survey, authorize if consistent. Excess \$600.00

Nivitha (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Tuesday, 11 December 2018 3:08 PM
To: Admin-D (LKKAuto); 'Admin A'
Subject: CLMOMVC000003575 ACCD INLVG OD GBE625Y ON 01/12/2018
Attachments: SKMBT_C224e18121109160.pdf

Hi team

OD survey, authorize if consistent. Excess \$600.00

Thanks
Kelvyna

From: peggy <nphauto@pacific.net.sg>
Sent: Tuesday, December 11, 2018 9:21 AM
To: Motor Claims <MotorClaims@sg.gaig.com>
Subject: [External] ACCD INLVG GBE625Y ON 01/12/2018

Dear Sir,

We refer to the above matter and claiming OWN DAMAGE.

Attach documents and please arrange your surveyor to survey the vehicle.

REGARDS

PEGGY FOO
NPH AUTO SERVICE
Email : peggy@nphauto.com
TEL; 67840663
FAX: 67840692

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVC000003575

Date: 13 December 2018

Our Ref: CS/GAI18022299/Usd3

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 625Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/12/2018 at the premises of M/s NPH Auto Service and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,856.20</u> .
Revised Estimate Amount	: S\$ <u>5,672.57</u> .
"Check" Items Amount	: S\$ _____ .
Total	: S\$ <u>5,672.57</u> .
Market Value	: S\$ <u>45,000.00</u> .
LTA Reimbursement Value	: S\$ <u>28,188.00</u> .
Nett Value	: S\$ <u>16,812.00</u> .

Description of Damage:

The vehicle sustained damages at the rear portion & rear windscreen shattered.



Comments/ Present Status:

Damages Consistent.
Repair cost economical, we have authorise repair
Repair days: 5 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2018 12:59
Date Of Accident	01/12/2018 18:10
Exact Location Of Accident	OUR TAMPINES HUB 1 TAMPINES WALK LOADING BAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE625Y
Insured/Policyholder	
Name Of Registered Owner	TRANSPEED CARGO (S) PTE LTD
Co Reg No	00 198501373W
Email Address	ALAN.TEO@TRANSPEED.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65420044

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVC000007910-0-000
Cover Note Number	

Driver

Name of Driver	VEDHARETHINAM SENTHILKUMAR
Passport No/FIN	G6265493M
Date Of Birth	29/05/1984
Occupation	OUTDOOR
Date Of Driving Pass	16/05/2012
Driving Experience	6 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91205910
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	NO
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS AT THE TAMPINES HUB 1 TAMPINES WALK LOADING BAY. IT WAS RAINING HEAVILY AND I WAS DRIVING GBE625Y. AS VISION WAS POOR I REVERSED AND HIT ONTO THE PILLAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	PILLAR
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1/12/18, at 18 10 hrs. at Our Tampines Hub. 1 Tampines Walk Loading bay. It was raining heavily & I was driving GBE625Y. As vision was poor, I reversed & hit a pillar. Nobody was injured. I was with a colleague named Malick.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

v. Sankar
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : OD0087/12/18 Date : 12/12/2018

OWN DAMAGE CLAIM

M/S : GREAT AMERICAN INSURANCE CO
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBE625Y - NISSAN NV350
INSURED : TRANSPEED CARGO (S) PTE LTD ENGINE# :
DATE OF ACCIDENT : 01/12/2018 CHASSIS# :
POLICY NO : MOMVC000007910

1/5 \$4500

*Authorised
Lark
12/12/18
5 day*

Excess \$600

*1/5 \$4500/L
Lark P. A. H. H. H.*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	%MarkUp	U/Price	Total
		\$		\$	\$
<u>Replacement of Parts</u>					
1 rear boot <i>so 1/5 20</i>	1	1350.00	15	1552.50	1,552.50
2 rear windscreen <i>shaded</i>	1	780.00	15	897.00	897.00
3 rear NISSAN logo <i>scr</i>	1	48.00	15	55.20	55.20
4 rear boot NV350 emblem <i>neu</i>	1	50.00	15	57.50	57.50
5 rear boot URVAN emblem <i>neu</i>	1	35.00	15	40.25	40.25
6 rear number plate chrome moulding <i>one</i>	1	280.00	15	322.00	322.00
7 rear bumper <i>DD</i>	1	290.00	15	333.50	333.50
8 rear bumper side retainer RH <i>3rd</i>	2	7.50	15	8.63	17.25
9 rear boot inner finisher <i>De/ty</i>	1	210.00	15	241.50	241.50
10 rear boot rubber <i>tu/</i>	1	120.00	15	138.00	138.00
11 rear step panel <i>DD/ant</i>	1	155.00	15	178.25	178.25
12 rear end panel (outer) <i>Body DD</i>	1	155.00	15	178.25	178.25
Total Material					\$4,011.20

Special Nett Items

9 rear windscreen sealant <i>neu</i>	1	40.00		40.00	40.00 ✓
10 rear boot 70KM/H sticker <i>neu</i>	1	15.00		15.00	15.00 10
11 rear boot 8 PAX sticker <i>neu</i>	1	15.00		15.00	15.00 10
12 rear bumper parking sensor <i>shaded</i>	1	200.00		200.00	200.00 ✓
Total S/Nett					\$270.00

Labour & Misc

1 Remove & install rear windscreen.					120.00 ✓
-------------------------------------	--	--	--	--	----------



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : OD0087/12/18

Page : 2/2
Date : 12/12/2018

OWN DAMAGE CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	%MarkUp	U/Price	Total
		\$		\$	\$
2 Remove & install r/boot, r/boot lamp, r/mirror, r/bumper, r/lamp assy, knock bumper inner lower panel, floorboard panel and restraighten body & chassis.					650.00 620
3 Spray painting.					700.00 600
4 Check wiring system.					25.00 20
5 Remove & install r/boot carpet and rear boot finishder.					80.00 50
Total Labour					\$1,575.00
Nett before GST					5,856.20

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-3488
+ 152
4011.20

S.N 260.00
10km 1410.00
5681.20
1655 2073
4544




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18022299/Usd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 19-12-2018		
		Code : GAI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	GBE 625Y	
Policy No.	MOMVC000007910-0-000	Coverage (\$)	0.00	
Claim No.	CLMOMVC000003575	Excess (\$)	0.00	
Assign From	KELVYNA NGIAN	Assign Date	11/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (M)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1MC2E26Z0004807	Colour	WHITE	
Odometer	161200	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2018	Inspection Date	12/12/2018	
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839			
5a. Remarks				
A)THE MARKET VALUE IS S\$45,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 625Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT (WCP)	BADLY DENTED	1,350.00	1,350.00
1	REAR WINDSCREEN (WCP)	SHORTED	780.00	780.00
1	REAR NISSAN LOGO (WCP)	SCRATCHED	48.00	48.00
1	REAR BOOT NV350 EMBLEM (WCP)	NECESSARY	50.00	50.00
1	REAR BOOT URAVN EMBLEM (WCP)	NECESSARY	35.00	35.00
1	REAR NUMBER PLATE CHROME MOULDING (WCP)	CRACKED	280.00	280.00
1	REAR BUMPER (WCP)	DENTED	290.00	290.00
2	REAR BUMPER SIDE RETAINER RH @\$7.50 (WCP)	BENT	15.00	15.00
1	REAR BOOT INNER FINISHER (WCP)	DEFORMED / TWISTED	210.00	210.00
1	REAR BOOT RUBBER (WCP)	TWISTED	120.00	120.00
1	REAR STEP PANEL (WCP)	DENTED / BENT	155.00	155.00
1	REAR END PANEL (OUTER) (WCP)	BADLY DENTED	155.00	155.00
	COST PLUS 15%		523.20	523.20
			4,011.20	4,011.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR BOOT 70KM/H STICKER (SN)	NECESSARY	15.00	10.00
1	REAR BOOT 8 PAX STICKER (SN)	NECESSARY	15.00	10.00
1	REAR BUMPER PARKING SENSOR (SN)	SHORTED	200.00	200.00
			270.00	260.00
<u>LABOUR</u>				
	REMOVE & INSTALL REAR WINDSCREEN.		120.00	120.00
	REMOVE & INSTALL R/BOOT,R/BOOT LAMP,R/MIRROR,R/BUMPER,R/LAMP ASSY,KNOCK BUMPER INNER LOWER PANEL,FLOORBOARD PANEL AND RESTRAIGHTEN BODY & CHASSIS.		650.00	620.00
	SPRAY PAINTING.		700.00	600.00
	CHECK WIRING SYSTEM.		25.00	20.00

Report Ref No. CS/GAI18022299/Usd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & INSTALL R/BOOT CARPET AND REAR BOOT FINISHDER.		80.00	50.00
			1,575.00	1,410.00
GRAND TOTAL			5,856.20	5,681.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00
LESS EXCESS			-600.00
NETT LIABILITY			3,900.00

Report Ref No. CS/GAI18022299/Usd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.