

ASS. REC. BY:

REF:

3
COLMSG18022312/GCD302

Special Instruction:

Surveyor:

Meinen

From (Person):

Quo Dong
Pauline Thom

ASSIGNMENT (Office)

of

MSIG

Date/Time:

11/12/18 4:21pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

SLT 6649S

Insured:

SKR 9286H

at Workshop m/s

Teamwork Garage

Tel:

68442475

of

53 Ubi Ave 1 # 01-24

Policy No:

A80460901QMX

Claim No:

578267

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/12/2018

CA / REV / REP. / REV 24 HRS

kps

12/12/18

H.O.D. Endorsement:

Date/Time:

5pm 11/12/18

Person Contacted:

Damen

Vehicle:

IN/OUT

Date/Time

Action/Instruction (x) Estimate

SLT 6649S - NA/INC18021996/24

DUA: 5/12/18

SKR 9286H - NA/INC18021996/24

DUA: 5/12/18

Dismantle: 13/12/2018

Xhl

REF: MS1G

47695 /

PRS (Menimen)

ASSIGNMENT

From: Date: 12/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLT 6649S
at Workshop n/s: Teamwork Garage
of: 53 Ubi Ave 1 #01-24

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$25K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLT 6649S Yr Regn: 19 Feb 2016

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry C.C. 1998

Colour: Silver A/C Insured / Std / NI / NA

Sp. Reading: 153739 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053BK 410 7055 250

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / M/B or

Tyre Size: F: 215 / 60 R16
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A.

D.O.I. 12/12/18

Survey held at

w/s

12:50pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$7000 - \$8000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + RS. SI

) Photos

) Other

TOTAL

Report Format: PRE

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2018		11 Dec 2018 16:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KOH KAR KHEE, ID: S7026494C, Tel: +6594870803, Email: NOEMAIL			
Main Claimant:	T ISVARI D/O P TIRUPPATHY, ID: S2644769J			
Vehicle Reg. No.:	SLT6649S	Date of Loss:	05/12/2018 14:00 - :59 [105 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 578267	Policy/Cover Note No.:	A80460901QMX (Comprehensive) Coverage: 18/09/2018 - 17/09/2019	
Vehicle Reg. No. (Insured):	SKR9286H	Policy No. (Claimant):		
		Excess:	S\$600.00	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/12/2018]			
Driver/Custodian (Insured):	KOH KAR KHEE (48 / Male), NRIC: S7026494C, Tel: +6594870803			
Adj Asg. Remarks:	liability 100% on OI (Bola 28) Assign LKK CONSULTANCY (called ws to ask) Contact : 68442475			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4769J
Vehicle Details	
Vehicle No.:	SLT6649S
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	1AZE164404
Chassis No.:	MR053BK4107055250
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$26,443.00
Original Registration Date:	19 Feb 2010
First Registration Date:	19 Feb 2010
Transfer Count:	3
Actual ARF Paid:	\$26,443.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Feb 2020
PARF Rebate Amount:	\$14,543.00
Intended COE Rebate Details	
COE Expiry Date:	18 Feb 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$23,180.00
COE Rebate Amount:	\$2,737.00
Total Rebate Amount:	\$17,280.00

The information contained herein is correct as at 13 Dec 2018

OK

► Camry Used Vehicle List (8 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Camry 2.0A	\$25,800	\$11,270 /yr	12-Jan-2010	1,998 cc	154,000 km	Juzt Carz Auto	Available
Powerful And Responsive Yet Fuel Economical Performance. New Paint Work, Immaculate Condition. Ideally For Short Term Ride, Or Renew COE At End Of Drive. See To Believe. Trade In Available. Major Bank... Office No. - 63383813 Joey Lim - 97898277 James Li - 88588866 Shawn Zheng - 97520620 Philip Koh - 82338484							
Toyota Camry 2.4A	\$25,800	\$9,680 /yr	08-Feb-2010	2,362 cc	124,850 km		Available
Good Condition, Viewing Welcome, In House Loan Of Up To \$20000 Available. Office No. - - Lien Chong Enterprises - 96175005							
Toyota Camry 2.4A	\$26,500	\$9,870 /yr	26-Feb-2010	2,362 cc	163,278 km	Juzt Carz Auto	Available
High OMV Of \$29264! Drive Away This Best Selling Japanese Luxury Sedan, Fantastic Condition Inside Out, Must View To Believe, Easy Loan And Trade In Available, Accident Free. Call Or SMS To Enquire. Office No. - 63383813 Shawn Zheng - 83373788 Joey Lim - 96229169 James Li - 88588866 Phillip Koh - 82338484							
Toyota Camry 2.0A	\$26,800	\$12,130 /yr	14-Jan-2010	1,998 cc	106,000 km	High Speed Motor	Available
6 Months Road Tax Till Jan'19, Excellent Short Term Usage And Also Can Be Considered For COE Renewal, No Repairs Needed, Famed For Its Powerful Yet Fuel Economical Performance, 100% Accident Free, Spa... Office No. - 64568190 Harjinder Singh - 93386317 Manjit Singh - 98581265							
Toyota Camry 2.4A	\$27,500	\$9,660 /yr	30-Apr-2010	2,362 cc	-	GD Motoring	Available
New 6 Months Road Tax! 10 Years COE At \$61,000! No Repairs Needed! Smooth Ride! Your Best Choice Selection With Us! 90% Loan Financing, Lowest Interest Rate, 100% Accident-Free, Best Quality Purchase ... Office No. - - Vins Goh - 83835833 Mr Koh - 88626325							
Toyota Camry 2.4A	\$28,900	\$10,020 /yr	02-Jun-2010	2,362 cc	128,123 km	Mayfair Motoring	Available
Reliable Luxury Car! High Scrap And Body Value! Excellent For Short Term Usage, Reliability, Comfort And Practicality All In One! High And Flexible Loan Options Available! Call For A Viewing Appointment... Office No. - 64792220 Richard Ho - 98625691 Terry Cheah - 84840005 Kohji - 97327889 Kenny Toh - 91871230							
Toyota Camry 2.0A	\$29,900	\$8,750 /yr	09-Nov-2010	1,998 cc	-	Carro	Available
Well Maintained By The Previous Owner. Factory Fitted Interior. Accident Free. No Repairs Needed. Best Deal In Town. Buy With A Peace Of Mind. High Loan Available! Schedule A Test Drive Today. Viewing... Office No. - 67146652 Jace - 81394200 Betty - 96215746							
Toyota Camry 2.0A	\$31,300	\$9,810 /yr	18-Oct-2010	1,998 cc	97,200 km	Gen Capital Pte Ltd	Available
Passed With 120 Points Inspection. No Repairs Needed, Low Mileage, Excellent Condition, Low Maintenance Cost, 1 x Free Servicing And 6 Months Warranty Will Be Provided. Buy With A Peace Of Mind! Hurry... Office No. - - Ken - 93378983 Jord - 87978998							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or station wagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news (

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/12/2018 16:22
Date Of Accident	05/12/2018 14:00
Exact Location Of Accident	CTE TWDS CITY AFTER YIO CHU KANG RD EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLT6649S
Insured/Policyholder	
Name Of Registered Owner	T ISVARI D/O P TIRUPPATHY
NRIC No	S2644769J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90304336
Alternative Phone No	OFFICE-90304336
Vehicle Particulars	
Manufacturer	TOYOTA
Model	CAMRY 2.0 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096223974
Cover Note Number	
Driver	
Name of Driver	KURUMBIAN S/O VIJAENDIAN
NRIC No	S9535422Z
Date Of Birth	30/09/1995
Occupation	OUTDOOR
Date Of Driving Pass	08/08/2014
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90304336
Fax Number	
Contact Number	OFFICE-90304336
EMail Address	NOEMAIL

Address	BLK 535 ANG MO KIO AVENUE 5 #09-4078
Postcode	560535
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4519999 - FAX NO: 65535679
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20181206/2005.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR9286H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH
NRIC/Passport Number	S7026494C
Contact Number	94870803
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLR8295B
Vehicle Make/Model/Colour	HARRIER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO CHOON HUAT JEFFERY
NRIC/Passport Number	S7925620Z
Contact Number	97979883
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	KURUMBIAN S/O VIJAENDIAN
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLT6649S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling at Cte towards City after Vio Chu Kung exit, When the Vehicle in front of me came to stop I also came to a stop without any contact with the vehicle in front of me. Suddenly I felt a huge impact from the rear portion of my vehicle. When I got down of my vehicle, I felt very dizzy and realised that I was involved in a accident

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GLARAC Form 1 (Rev. 1/2019)

Police Report



**SINGAPORE
POLICE FORCE**



T/20181206/2005

1 of 4

Report No. T/20181206/2005

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/12/2018 01:36	Vide Report No.: F/20181205/0124	Station Diary No.: 18
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: KURUMBIAN S/O VIJAENDIAN			Address: APT BLK 535 ANG MO KIO AVENUE 5 #09-4078 SINGAPORE 560535	
ID Type / ID No.: NRIC NO / S9535422Z			Contact No.: Home/Office: Mobile: 90304336	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 23	Date of Birth: 30/09/1995	Type of Informant: Driver	
Race: Indian			Language:	Institution / School Name:
Occupation: NAVY REGULAR			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/12/2018 14:20	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY (AYE) 15KM				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKR9286H	Car					0
SLR8295B	Car					0
SLT6649S	Car					0

Police Report



**SINGAPORE
POLICE FORCE**



T/20181206/2005

2 of 4

Report No. T/20181206/2005

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KOH	ID No.	S7026494C
Related Vehicle	SKR9286H (Car)	Contact No.	94870803
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TEO CHOON HUAT JEFFERY	ID No.	S7925620Z
Related Vehicle	SLR8295B (Car)	Contact No.	97979883
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	KURUMBAN S/O VJAENDIAN	ID No.	S9535422Z
Related Vehicle	SLT6649S (Car)	Contact No.	90304336
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	05/12/2018	Date Discharge	05/12/2018
No. of Days granted Medical Leave	01	Degree of Injury	NIL

Brief Details.

On 05/12/18 at about 1422hours, my vehicle(SKR9286H) was travelling at first lane, I saw there was tree pruning ahead, and filtered to the 2nd lane. While filtering into 2nd lane, a vehicle who was behind me when I was at 1st lane sped past me and other few other vehicles and cut into 2nd lane in front of us. Due to that, vehicles in front of me applied jam brake as well as myself. Behind me there was another vehicle(SKR9286H) driver who managed to jam brake on time however vehicle(SLR 8295B) driver who was behind vehicle(SKR9286H) did not managed to stop on time and due to that vehicle (SLR8295B) hit onto vehicle(SKR9286H). Vehicle(SKR9286H) then surged forward and hit onto my vehicle. My vehicle suffered damages, I do not know which part as I was being conveyed to Hospital by ambulance. Due to

Police Report



**SINGAPORE
POLICE FORCE**



T/20181205/2005

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

3 of 4

Report No. T/20181205/2005

CONTINUATION OF REPORT

the accident, I suffered sprained thumb and was given 1 day MC

I wish to state that traffic police and ambulance was at scene.

I am lodging this report as requested by the Traffic Police and for my insurance claims.

Police Report



SINGAPORE
POLICE FORCE



T/20181206/2005

4 of 4

Report No. T/20181206/2005

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /
Sgt 2 ELAINE ONG EE LING

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

06/12/2018 01:36

Officer In Charge Of Case:

TP / GIT /
Sr Staff Sgt NOR FAIZAL BIN YAHYA
Contact No.: 65476202

Classification Of Case:

Authentication Stamp
NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)



CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2018		11 Dec 2018 16:21 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KOH KAR KHEE , ID: S7026494C, Tel: +6594870803, Email: NOEMAIL									
Main Claimant: T ISVARI D/O P TIRUPPATHY , ID: S2644769J									
Vehicle Reg. No.: SLT6649S		Date of Loss: 05/12/2018 14:00 - :59 [105 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 578267		Policy/Cover Note No.: A80460901QMX (Comprehensive) Coverage: 18/09/2018 - 17/09/2019							
Vehicle Reg. No. (Insured): SKR9286H		Policy No. (Claimant): Excess: S\$600.00							
Repairer: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 12/12/2018]									
Driver/Custodian (Insured): KOH KAR KHEE (48 / Male) , NRIC: S7026494C, Tel: +6594870803									
Adj Asg. Remarks: liability 100% on OI (Bola 28) Assign LKK CONSULTANCY (called ws to ask) Contact : 68442475									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT6649S (578267)
[SKR9286H]
TP
T ISVARI D/O P TIRUPPATHY
Dec 5 2018 2:00PM
[KOH KAR KHEE]
Teamwork Garage Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print
1	10/12/18 10:35	Accident Statement From:SC - Reg. No: SKR9286H, Claimant: KOH KAR KHEE						Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
2	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
3	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
4	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
5	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
6	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
7	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
8	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
9	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
10	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
11	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
12	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
13	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
14	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
15	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
16	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
17	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
18	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
19	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
20	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
21	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
22	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
23	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
24	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
25	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
26	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
27	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
28	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
29	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
30	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
31	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
32	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>
33	17/12/18 13:53	General View						Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/12/18 13:53	General View		<input checked="" type="checkbox"/>
35	17/12/18 13:53	General View		<input checked="" type="checkbox"/>
36	17/12/18 13:53	General View		<input checked="" type="checkbox"/>
37	17/12/18 13:53	General View		<input checked="" type="checkbox"/>
38	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
56	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
57	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
58	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
59	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
60	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
61	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
62	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
63	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
64	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
65	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
66	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
67	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
68	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
69	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
70	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
71	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
72	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
73	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
74	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
75	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
76	17/12/18 13:53	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/12/18 10:35	SLT6649S GIA REPORT From: SC - Reg. No: SKR9286H, Claimant: KOH KAR KHEE		<input type="checkbox"/>
2	10/12/18 10:38	PRI Request SLT6649S		<input type="checkbox"/>
3	11/12/18 13:52	TP AGREE MSIG IHS EMAIL		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022312/GCD3E2

Date: 17/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80460901QMX

Claimant Vehicle No : SLT6649S

Insured Vehicle No : SKR9286H

Date of Loss: 05/12/2018

Nature of Claim: TP

Claim No: 578267

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT6649S

Make & Model: TOYOTA CAMRY, 2.0 (A)

Engine No: 1AZE164404

Reg. Date: 19/02/2010 (Man. Year: 2010)

Chassis No: MR053BK4107055250

Colour: Silver

Odometer: 153739 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/12/2018

Date Inspected: 12/12/2018 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial
Park
Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT6649S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >