

ASS. REC. BY:

REF:

CS3/MSG18022314/Gcd31

Special Instruction:

Surveyor:

Minimen

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Pauline them

of

MNG

Date/Time:

11/12/2018 @ 4:16pm.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 4565A

Insured:

GBD 3616J

at Workshop m/s

Team Autopro

Tel:

90927279

of

Stucki St Ave 1 # 06-21 premier

Policy No:

B29096489MKF

Claim No:

578283

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/12/18

CA / REV / REP. / REV 24 HRS

kup?

H.O.D. Endorsement:

12/12/18

Date/Time:

5:02pm @ 11/12/18

Person Contacted:

Alan

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLM 4565A-CS/CTI18011520/Ards

Burr: 22/06/2018

GBD 3616J-X

Dismantle: 13/12/2018.

11/12/18

Xhl.

REF: MSIG

Menmen (PRS)

# ASSIGNMENT

From: Date: 12/12/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: STM 1565A

at Workshop n/s Tecum Autopro

of 8 kaki Bkt Ave 4 # 06-21 premier

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 2M4565A Yr Regn: Mar / 17

Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda vessel C.C. 1496

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 158274 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU3121 85 89

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 25/60 R16  
R: 11

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A.

D.O.I.

Survey held at

w/s

12-12-18

4:55 pm

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: PRS-

Lump Sum / I.B.I. (\$)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

120

10

130

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2018		11 Dec 2018 16:16 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CROWN EQUIPMENT (SINGAPORE) PTE. LTD., Co. Reg. No.: 197800704G		
Main Claimant:	KIRALY AUTOMOBILE PRIVATE LIMITED, Co. Reg. No.: 201436970K		
Vehicle Reg. No.:	SLM4565A	Date of Loss:	05/12/2018 08:00 - :59 [20 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 578283	Policy/Cover Note No.:	B29096489MKF (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
Vehicle Reg. No. (Insured):	GBD3616J	Policy No. (Claimant):	
		Excess:	
Repairer:	Team Autopro Pte Ltd (KAKI BUKIT) No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/12/2018]		
Driver/Custodian (Insured):	ANPALAGAN A/L PATCHYMUTHU (), NRIC: F1412856P, Tel: +6598004382		
Adj Asg. Remarks:	SJE DISAGREE APPOINT LKK. LIAB IS CLEAR. PLS CONTACT Mr. Alan Koh/Frederick Lim at 9092 7279/9674 6635		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLM4565A		
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	VEZEL HYBRID 1.5X AUTO		
Chassis No. :	RU31218589		
Propellant :	Petrol-Electric		
Engine No. :	LEB5918599		
Motor No. :	H12322566		
Engine Capacity :	1496 cc		
Power Rating :	22.0 kW		
Maximum Power Output :	112.0 kW ( 150 bhp)		
Maximum Laden Weight :	1555 kg		
Unladen Weight :	1280 kg		
Year Of Manufacture :	2016		
Original Registration Date :	30 Mar 2017		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$54,000.00		
COE Expiry Date :	29 Mar 2027		
Road Tax Expiry Date :	29 Mar 2019		
PARF Eligibility Expiry Date :	29 Mar 2027		
Inspection Due Date :	29 Mar 2020		
Intended Transfer Date :	17 Dec 2018		
CO2 Emission :	94.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$26,279.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	6970K
<b>Vehicle Details</b>	
Vehicle No.:	SLM4565A
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	LEB5918599
Chassis No.:	RU31218589
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$28,056.00
Original Registration Date:	30 Mar 2017
First Registration Date:	30 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2027
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$44,724.00
<b>Total Rebate Amount:</b>	<b>\$48,474.00</b>

The information contained herein is correct as at 17 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/12/2018 15:45
Date Of Accident	05/12/2018 08:30
Exact Location Of Accident	TUAS AVENUE 7 CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM4565A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KIRALY AUTOMOBILE PRIVATE LIMITED
Co Reg No	201436970K
Email Address	NKF.BEN@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-64921785

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5A HYBRID
Exact Purpose for which vehicle was being used at time of accident	PTE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	LOOK JUN HONG
NRIC No	S8384401I
Date Of Birth	19/10/1983
Occupation	OUTDOOR
Date Of Driving Pass	17/12/2008
Driving Experience	9 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87428028
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 817 JURONG WEST STREET 81#06-40
Postcode	690817
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY CAR SLM4565A WAS PARKED IN A PARKING LOT . UPON COLLECTION OF MY CAR , THE DRIVER'S OF GBD3616J HAD APPROACHED ME AND INFORMED ME THAT HIS VAN HAD COLLIDED ONTO THE FRONT PORTION (RH) OF MY CAR WHILE HE WAS REVERSING.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD3616J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ANPALAGAN A/L PATCHYMUTHU
NRIC/Passport Number	F1412856P
Contact Number	98004382
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*R*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*Jack*

*Andy*


Reporting Centre Personnel's Signature  
Name:  
NRIC/HN No.:





# Accident Sketch Plan

## SKETCH PLAN





## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 5/12/18 @ 0830 hr, my car SLM4565A was parked in a parking lot. Upon collection of my car, the driver's of GBD 3616 J had approached me and informed me that his van had collided onto the front portion (RH) of my car while he was reversing.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2018		11 Dec 2018 16:16 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>CROWN EQUIPMENT (SINGAPORE) PTE. LTD.,</b> Co. Reg. No.: 197800704G								
Main Claimant:	<b>KIRALY AUTOMOBILE PRIVATE LIMITED,</b> Co. Reg. No.: 201436970K								
Vehicle Reg. No.:	<b>SLM4565A</b>	Date of Loss:	05/12/2018 08:00 - :59 [20 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 578283</b>	Policy/Cover Note No.:	B29096489MKF (Comprehensive) Coverage: 01/10/2018 - 30/09/2019						
Vehicle Reg. No. (Insured):	<b>GBD3616J</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Team Autopro Pte Ltd (KAKI BUKIT)</b> No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Pauline Tham</b> - 6594 2545]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 12/12/2018]								
Driver/Custodian (Insured):	ANPALAGAN A/L PATCHYMUTHU (), NRIC: F1412856P, Tel: +6598004382								
Adj Asg. Remarks:	SJE DISAGREE APPOINT LKK. LIAB IS CLEAR. PLS CONTACT Mr. Alan Koh/Frederick Lim at 9092 7279/9674 6635								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLM4565A (578283)  
[GBD3616J]  
TP  
KIRALY AUTOMOBILE PRIVATE LIMITED  
Dec 5 2018 8:00AM  
[CROWN EQUIPMENT (SINGAPORE) PTE. LTD.]  
Team Autopro Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/12/18 11:34	<b>Accident Statement</b> From: SC - Reg. No: GBD3616J, Claimant: CROWN EQUIPMENT (SINGAPORE) PTE. LTD.	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/12/18 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	17/12/18 13:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/12/18 13:38	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	17/12/18 13:38	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	17/12/18 13:38	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	17/12/18 13:38	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	17/12/18 13:38	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/12/18 11:34	<b>TP SLM4565A E-REPORT</b> From: SC - Reg. No: GBD3616J, Claimant: CROWN EQUIPMENT (SINGAPORE) PTE. LTD.	Load PDF	
2	10/12/18 16:01	<b>SJE DISAGREE APPOINT LKK</b>	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer  
 Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022314/GCD3E2

Date: 17/12/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29096489MKF

Claimant Vehicle No : SLM4565A

Insured Vehicle No : GBD3616J

Date of Loss: 05/12/2018

Nature of Claim: TP

Claim No: 578283

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLM4565A

Make &amp; Model: HONDA VEZEL, 1.5 HYBRID (A)

Engine No: LEB5918599

Reg. Date: 30/03/2017 (Man. Year: 2016)

Chassis No: RU31218589

Colour: Brown

Odometer: 158274 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 11/12/2018

Date Inspected: 12/12/2018 Inspected At:

Team Autopro Pte Ltd (KAKI BUKIT)  
No.8 Kaki Bukit Avenue 4, #06-21  
Premier@ Kaki Bukit (Gate 2)  
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM4565A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >