

Putra

CC 4, III 180 22323, Tiga 3/4

ASSIGNMENT

Sinsayon:

Taufan

DOI:

16/11/19

Date / Time:

11/12/18

Registered in Merimen:

11/12/18

Pre-assign / CCU / FTE

SHA 6925 S



Insured Vehicle No.:

C7PL

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

09/12/18

Place of Accident:

Woodland Centre

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SLA 1322M



INSRS:

WSP:

Tel:

Liability:

RMKS:

CH



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

29/11
2018SLA 1322M X;
SHA 6925 S - 06/11/19 25187 / Ayb3p ; 009 41/11/19
- 05/11/19 15435 (G24030) ; 009 41/11/19

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

X

After call ltr to OI:

X

Authorisation To Act:

X

Release Voucher:

X

Final Repair Bill:

X

Car Rental Invoice:

X

Towing Invoice:

X

LTA / GIA:

X

Medical Bill:

X

PIR:

X

Mandate/Reject Instruction:

X

LOD

X

Payment Breakdown Form:

X

Post-Repair Photos:

X

Others:

X

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Taufan

Repair Cost:

PIP

SS 3706.00

(3 days)

Reduction: \$2441-

% 40

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

ATM

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

29

If NO or B 28, Ass. Lia:

Repair Cost:

(W/ GST)

SS 3965.42

Loss of Rental (LOR):

SS 535.00

(5 days)

x \$107

(W/ GST)

Loss of Use (LOU):

SS -

(\$ x days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350/-

Total:

SS 4500.42

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

SS 4500.42

Name 1:

Cyndi Zi Cavnage Fia Pte Ltd

Payee 2 (Strike if N.A.):

SS -

Name 2:

Payee 3 (Strike if N.A.):

SS -

Name 3:

2016 Feb

Rent

→ 3 repair days + 2 PRS + 1 Sunday = 6 days

--	--



Exceptional Journeys

INSURANCE CO. : INDIA

Supplementary Parts For Registration No.: SLA 1332 M

Materials

Cost (\$)

- 1 Emblem K3
- 2 Forte Emblem

15.00 ✓ *KE*
40.00 ✓ *NOL*

Total Materials

55.00

Labour

Cost (\$)

- 1 Repair Boot lid
- 2 Respray boot lid

550.00 ✓ *[Signature]*
420.00 ✓ *[Signature]*

Total Labour

970.00

Taxable Amount

1,025.00

7% GST

71.75

Grand total

1,096.75

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

[Signature]
LOI AI TING
CUSTOMER SERVICE ADVISOR
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

#6155

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR AZLAN BIN BAHAROM BLK 304 WOODLANDS ST 31 #04-117 SINGAPORE 730304 Contact No Mobile: 96499234	Cust No/Name /MR AZLAN BIN BAHAROM Reg No/Reg Date SLA1332M / 23/02/201 Date In/Mileage / 0 Chassis No KNAFZ411MF5534218 Engine No G4FGFH799593 Make/Model KIA/FORTE K3 1.6 A SX ADQ Colour/Trim SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CSM00081	Cash	10/12/2018/ 17:20		465 / Tay Jian Ye	40523	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000		TO RENEW REAR BUMPER, LWR BUMPER CTR, REPAIR REAR END PANEL				✓ 550 1650.00
E PNT98000		PAINT WORK SPRAY REAR BUMPER , END PANEL				✓ 420 1260.00
E PNT88000		TO TRANSFER REAR PARKING SENSOR TO NEW PART				✓ - 60.00
A 54900099		TO CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ - 30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ - 200.00
M SUNDRY		SUNDRIES				✓ - 20.00
M STAY-RR BUMPER LH			1.00	75.00	00.00	RM X 75.00
M STAY-RR BUMPER RH			1.00	75.00	00.00	RM X 75.00
M BEAM-RR BUMPER			1.00	365.00	00.00	RM X 365.00
M BRACKET-RR BEAM LWR MTG			2.00	5.00	00.00	RM X 10.00
M BRACKET-RR BEAM LWR,CTR			1.00	5.00	00.00	RM X 5.00
M COVER-RR BUMPER			1.00	791.00	00.00	RM X 791.00
M COVER-RR BUMPER,UPR			1.00	245.00	00.00	RM X 245.00
M ULTRASONIC SENSOR ASSY-FBWS			1.00	172.00	00.00	RM X 172.00
M ULTRASONIC SENSOR ASSY-FBWS			1.00	172.00	00.00	RM X 172.00

Estimate

SURVEYOR NAME: Tanpin 974952459

SURVEYOR SIGNATURE: [Signature]

DATE: 16/1/19 3:50 pm WP

REMARKS: Reming before paint
surellianto in
03 days

SURVEYOR NAME: Tay Jian Ye 974957409

SURVEYOR SIGNATURE: [Signature]

DATE: 16/1/19 3:50 pm WP

REMARKS: Resurvey before paint

sure 1/1/19 to 16/1/19

03 days

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

7% GST on
Total Payable
5,130.00
359.10
5,489.10

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Surveyor : TAUFIKH LKK
 Company : TP INDIA
 Emailed : 17/04/19, 4.30pm
 Date survey : 16.01.2019

VEHICLE NO : SLA 1332 M
 MODEL : KIA FORTE K3 1.6 A SX
 WIP : 40523

Material	:	\$	<u>1,456.00</u>
Labour	:	\$	<u>2,250.00</u>
Sub-Total	:	\$	<u>3,706.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>3,706.00</u>
GST 7%	:	\$	<u>259.42</u>
Grand Total	:	\$	<u>3,965.42</u>
Finalise By/Date	:	<u>LOI / 17/04/2019</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 3 WORKING DAYS + 2 Days (1) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 5

☒ TP claim SHA6925S

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE P/L	Cust No/Name /MR AZLAN BIN BAHAROM
64 CECIL STREET	Reg No/Reg Date SLA1332M / 23/02/2016
#04/05 IOB BUILDING	Date In/Mileage 17/01/2019/ 42569
SINGAPORE 049711	Chassis/Package KNAFZ411MF553421E /KC17
Contact No	Engine No G4FGFH799593
16/01/	Make/Model KIA/FORTE K3 1.6 A SX ADQ
	Colour/Trim SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	16/04/2019/ 15:03	TLT	260 / AiTing	40523

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, LOWER BUMPER CENTRE, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 550.00
E PNT98000 RESPRAY ON REAR BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 420.00
E PNT88000 TRANSFER REAR PARKING SENSOR TO NEW PANEL				✓ 60.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 200.00
M SUNDRY SUNDRIES				✓ 20.00
E PNT88000 REPAIR BOOT LID → Supp.				✓ 550.00
E PNT98000 RESPRAY BOOT LID → Supp.				✓ 420.00
X BEAM-RR BUMPER	1.00	? 365.00	00.00	365.00
X COVER-RR BUMPER	1.00	✓ 791.00	00.00	791.00
X COVER-RR BUMPER,UPR	1.00	✓ 245.00	00.00	245.00
X EMBLEM K3	1.00	15.00	00.00	15.00
X FORTE EMBLEM } Supp.	1.00	40.00	00.00	40.00
Z TEXT TP CLAIM INDIA SHA69255 DOA : 09.12.18 SURVEYOR TAUFIKH LKK 16.01.19 REPAIR 03 DAYS				

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	1,456.00	Nett	3,706.00
Labour	2,230.00	7% GST on	259.42
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	3,965.42
Diagnostics Job	0.00		
Sundry/Others	20.00		
Total(w/o GST)	3,706.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 11 December 2018 9:43 AM
To: Tay Jian Ye; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Manivel Priyadarshini
Subject: RE: TP INDIA CLAIM SLA1332M AGAINST YOUR INSURE SHA69255
Attachments: [Untitled].pdf; WhatsApp Image 2018-12-10 at 16.56.37.jpeg; WhatsApp Image 2018-12-10 at 16.56.38(1).jpeg; WhatsApp Image 2018-12-10 at 16.56.38.jpeg

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLA1332M and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee

64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

-----Original Message-----

From: Tay Jian Ye [mailto:jianye.tay@cyclecarriage.com.sg]
Sent: 11 December, 2018 9:30 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: TP INDIA CLAIM SLA1332M AGAINST YOUR INSURE SHA69255
Importance: High

Dear Gabriel,

I will choose LKK for survey, can I have the liability

Best Regards,

Tay Jian Ye
Advisor- Customer Service

Cycle & Carriage Singapore * 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 * F: +65 6565 1240 * H: +65 81680997 * www.cyclecarriage.com.sg

q'sqam@11/12/18
vni yet
Tay jian ye

-----Original Message-----

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: Tuesday, 11 December, 2018 9:18 AM

To: Tay Jian Ye

Subject: RE: TP INDIA CLAIM SLA1332M AGAINST YOUR INSURE SHA6925S

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- * LKK Auto Consultants Pte Ltd

- * Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

-----Original Message-----

From: Tay Jian Ye [mailto:jianye.tay@cyclecarriage.com.sg]

Sent: 10 December, 2018 7:44 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Don Bong Kiong Hua

<kionghua.bong@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Edwin Abcede Caina

<edwin.caina@cyclecarriage.com.sg>

Subject: TP INDIA CLAIM SLA1332M AGAINST YOUR INSURE SHA6925S

Importance: High

To Officer In charge,

My client who is driving SLA1332M want to claims against SHA6925S which was insured by you.

Attach is the SAS report and repair quotation for your reference.

Please let me know the liability

Best Regards,

Tay Jian Ye

Advisor- Customer Service

-----Original Message-----

From: PGMFP06@cyclecarriage.com.sg [mailto:PGMFP06@cyclecarriage.com.sg]

Sent: Monday, 10 December, 2018 6:13 PM

To: Tay Jian Ye

Subject:

DISCLAIMER:-

This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message.

Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

19th November 2019

LKK Ref: SHA6925S

Ms Suwanna Te-Uttarung (Motor Claims Department)
LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
#02-25 Ubi Avenue 1
Singapore 408933

Dear Madam,

Discharge Voucher for Accident Involving Vehicles SLA1332M and SHA6925S on
09/12/2018

Attached is the signed Discharge Voucher.

Kindly process for payment to, Cycle & Carriage Kia Pte Ltd, the soonest possible.

Appreciate your assistance.

Yours Sincerely,



Loi Ai Ting
Senior Officer-Admin

Print Received Message

This mail is associated with :

***SLA1332M (MCT18120253)**
[SHA6925S]

TP

AZLAN BIN BAHAROM

Dec 9 2018 12:00AM

[-]

Cycle & Carriage KIA Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/11/2019 10:21 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4500.42) - SLA1332M - Claim Handler: Priya

Approved:4500.42:Request TP WS to issue Tax Invoice for Repairs in III's favour

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2018 Edit Reg		11 Dec 2018 00:00 Edit Adj Rpt	\$43,706.00 Edit Estimates	\$43,706.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	AZLAN BIN BAHAROM, ID: S1598128H								
Vehicle Reg. No.:	SLA1332M	Date of Loss:	09/12/2018 00:00 - :59 [33 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18120253	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA6925S	Policy No. (Claimant):	2100452086						
		Excess:							
Repairer:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 20/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (11/11/2019): Alert - Adj Mandate Approved (\$4500.42) - SLA1332M - Claim Handler: Priya III_SG (08/11/2019): Alert - Adj Mandate Maintained - SLA1332M - Claim Handler: Priya III_SG (24/12/2018): Alert - Adj Mandate Approved (\$40.00) - SLA1332M - Claim Handler: Priya 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA1332M (MCT18120253)
[SHA6925S]
TP
AZLAN BIN BAHAROM
Dec 9 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Cycle & Carriage KIA Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
2	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
3	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
4	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
5	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
6	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
7	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
8	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
9	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
10	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
11	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
12	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
13	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
14	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
15	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
16	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
17	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
18	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
19	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
20	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
21	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
22	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
23	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
24	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
25	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
26	16/10/19 17:27	General View		Load JPG	<input checked="" type="checkbox"/>					
							1 per page		<input checked="" type="checkbox"/>	
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	11/12/18 19:53	ACKNOWLEDGEMENT EMAIL TO III DD 11.12.2018		Load PDF						
2	11/12/18 21:22	TP GIA REPORT		Load PDF						
3	22/01/19 09:24	TP ESTIMATE - MARKED		Load PDF						
4	16/10/19 17:26	LOD AND OTHER DOCUMENTS		Load PDF						
5	06/11/19 13:57	WORKSHOP INVOICE		Load PDF						
6	06/11/19 13:57	RENTAL RECEIPT		Load PDF						
7	06/11/19 13:57	LOD		Load PDF						
8	05/12/19 08:30	AUTHORISATION TO ACT FORM		Load PDF						
9	05/12/19 08:30	DISCHARGE VOUCHER		Load PDF						
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print					
1	12/12/18 09:08	Singapore Accident Statement		Load PDF						

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18022323/T1GA3Q2

Date: 05/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant
Vehicle No : SLA1332M **Insured Vehicle No :** SHA6925S
Date of Loss: 09/12/2018 **Nature of Claim:** TP **Claim No:** MCT18120253

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA1332M
Make & Model: KIA FORTE K3, 1.6 SX (A) **Engine No:** G4FGFH799593
Reg. Date: 23/02/2016 (Man. Year: 2015) **Chassis No:** KNAFZ411MF5534218
Colour: White **Odometer:** 42569 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 **Rear Tyre Size:** 215/45 R17
Front Left Side: Roadstone 6 mm **Rear Left Side:** Roadstone 6 mm
Front Right Side: Roadstone 6 mm **Rear Right Side:** Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,985.00	1,476.00	509.00	25.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	2,230.00	1,940.00	46.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,155.00	3,706.00	2,449.00	39.79
+ GST 7.00/7.00% (S\$)	430.85	259.42	171.43	39.79
Nett Amount (S\$)	6,585.85	3,965.42	2,620.43	39.79
+ Car Rental (5.0 x S\$107.00/day) (S\$)		535.00		
	Nett Liability (S\$)	4,500.42		

INSPECTION

Date of Assignment: 11/12/2018
Date Inspected: 16/01/2019 **Inspected At:** Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2019)
Parts: 143	KIA FORTE K3 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLA1332M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*STAY -RR BUMPER LH	Not Necessary	75.00 FS	*- FS
3	1		*STAY -RR BUMPER RH	Not Necessary	75.00 FS	*- FS
4	1		*BEAM -RR BUMPER	Cracked	365.00 FS	*365.00 FS
5	2		*BRACKET -RR BEAM LWR MTG	Not Necessary	10.00 FS	*- FS
6	1		*EMBLEM K3	Necessary	15.00 FS	*15.00 FS
7	1		*FORTE EMBLEM	Necessary	40.00 FS	*40.00 FS
8	1		*BRACKET -RR BEAM LWR ,CTR	Not Necessary	5.00 FS	*- FS
9	1		*COVER-RR BUMPER	Deformed	791.00 FS	*791.00 FS
10	1		*COVER -RR BUMPER ,UPR	Deformed	245.00 FS	*245.00 FS
11	1		*ULTRASONIC SENSOR ASSY -FBWS	Not Necessary	172.00 FS	*- FS
12	1		*ULTRASONIC SENSOR ASSY -FBWS	Not Necessary	172.00 FS	*- FS

F=Franchise part, S=SpcNett.

Total Parts (\$\$)	1,985.00	1,476.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR BOOT LID	New	550.00	550.00
2	RESPRAY BOOT LID	New	420.00	420.00
3	TO RENEW REAR BUMPER ,LWR BUMPER CTR ,REPAIR REAR END PANEL	New	1,650.00	550.00
4	PAINT WORK SPRAY REAR BUMPER ,END PANEL	New	1,260.00	420.00
5	TO TRANSFER REAR PARKING SENSOR TO NEW PART	New	60.00	60.00
6	TO CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
Gross Labour Cost (S\$)			4,170.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >