

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 10/12/2018

LONPAC

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 07/12/2018 @ 09:30

VRN : SJS3492A

MODEL : TOYOTA ALTIS 1.6

TP VRN : XE8080E

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER	1	\$ 510.00	\$ 510.00	
2 FRONT BUMPER CLIPS	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER OUTER BRACKET R/L	2	\$ 55.00	\$ 110.00	
4 FRONT REINFORCEMENT	1	\$ 345.00	\$ 345.00	
5 FRONT CENTER GRILLE	1	\$ 315.00	\$ 315.00	
6 FRONT BUMPER LOGO	1	\$ 75.00	\$ 75.00	
7 BONNET HINGE R/L	2	\$ 60.00	\$ 120.00	
8 FRONT LOWER GRILLE	1	\$ 105.00	\$ 105.00	
9 HEADLAMP R/L	2	\$ 715.00	\$ 1,430.00	
10 SUPPORT PANEL	1	\$ 721.00	\$ 721.00	
11 FRONT BRACE PANEL	1	\$ 115.00	\$ 115.00	
12 CONDENSER	1	\$ 1,507.00	\$ 1,507.00	
13 CONDENSER SUCTION	1	\$ 375.00	\$ 375.00	
14 CONDENSER DISCHARGE	1	\$ 435.00	\$ 435.00	
15 RADIATOR	1	\$ 1,984.00	\$ 1,984.00	
16 RADIATOR TOP COWLING	1	\$ 105.00	\$ 105.00	
17 WIPER TANK	1	\$ 145.00	\$ 145.00	
18 FRONT FENDER LOGO "VVT-I" R/L	2	\$ 40.00	\$ 80.00	
19 CHASSIS RH	1	\$ 600.00	\$ 600.00	
20 RADIATOR FAN COWLING	1	\$ 240.00	\$ 240.00	
21 RADIATOR FAN MOTOR	1	\$ 463.00	\$ 463.00	
22 RADIATOR FAN BLADE	1	\$ 160.00	\$ 160.00	
			\$ 9,995.00	
Discount -25%			\$ 2,498.75	
			\$ 7,496.25	

Special Nett

23 COOLANT	1	\$	42.00	\$	42.00
				\$	42.00
24 FRONT FENDER RH	Repair				
25 FRONT FENDER LH	Repair				
26 FRONT DOOR RH	Repair				
27 BONNET	Repair				

PARTS TOTAL \$ 7,538.25

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	\$	2,750.00
Putty, Blend And Spray Paint on FRONT Affected Area	\$	2,250.00
Check Wiring, Re-align Headlamps, and Ensure Proper Functioning	\$	80.00
Remove and Replace A/C Condenser, Pipes and Radiator, Vacuum A/C System and Refill Gas	\$	180.00
Towing Charge	\$	100.00
Remove and Replace Front RH Door Window Glass to Facilitate Repair and Spray Painting	\$	100.00
Dismantle and Transfer Front RH Door Fittings & Mechanisms to Facilitate Repair	\$	180.00
Re-align/Repair Chassis Member	\$	600.00

LABOURS TOTAL \$ 6,240.00

Grand Total : \$ 13,778.25
Add 7% GST : \$ 964.48
***Nett Total* : \$ 14,742.73**

No. of repair days: 20

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/12/2018 16:50
Date Of Accident	07/12/2018 09:30
Exact Location Of Accident	TELOK BLANGAH GREEN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS3492A
Insured/Policyholder	
Name Of Registered Owner	CHAM KOK KIANG
NRIC No	S7603563F
Email Address	CKOKKIANG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97867935
Alternative Phone No	OFFICE-97867935

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01013904
Cover Note Number	

Driver

Name of Driver	CHAM KOK KIANG
NRIC No	S7603563F
Date Of Birth	03/02/1976
Occupation	INDOOR
Date Of Driving Pass	09/05/1994
Driving Experience	24 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97867935
Fax Number	
Contact Number	OFFICE-97867935
Email Address	CKOKKIANG@GMAIL.COM

Address	BLK 268C BOON LAY DRIVE #16-550
Postcode	643268
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR SIM
Phone Number	93865245
Email Address	

Details of Witness 2

Name	SOH ZE BIN
Phone Number	81121156
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE8080E
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ANG TIAN SEE
NRIC/Passport Number	S0213047E

Contact Number	94273701
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7 Dec 2018, about 09:30 hrs, I was driving SJS3492A along Telok Blangah Green. The lorry (XE8080E) in front me stopped so I also stopped. Suddenly the lorry start reversing. I honked at him but he still continue to reverse and pushed back my vehicle. No injury involved. Mr Sim saw how the accident happened and willing to be my witness. He can be contacted @ 93865245.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	3563F

Vehicle Details

Vehicle No.:	SJS3492A
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4920596
Chassis No.:	MR053ZEE106151692
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	13 Aug 2009
First Registration Date:	13 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$17,853.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2019
PARF Rebate Amount:	\$8,926.00

Intended COE Rebate Details

COE Expiry Date:	12 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$892.00
Total Rebate Amount:	\$9,818.00

The information contained herein is correct as at 07 Dec 2018

OK