

INS. CASE OWNER: PRVA CC 3, 111 180 22333, Rihab LKK: IDAC

Surveyor: KASUL DOI: 07/01/19 Date / Time: 12/12/18 Registered in Merimen: 12/12/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 34352 Claim No. : MOT 18120209  
 Name of Insured : OTM Policy No. : \_\_\_\_\_  
 Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_ Make / Model : \_\_\_\_\_  
 Excess Sec II :SS D.O.A : 7/12/18 Place of Accident : T junction of Dughatel & Margaret Dr  
 Is driver the owner? (YES/NO) Nature of Accident : \_\_\_\_\_  
 If NO, Driver Name / Age : OTM KAMEL FEE OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO  
 Driver Tel No. : 93742129 (V/L: YES/NO) Insured Liability : % Final ? Yes / No

SCE 1336M → → → → →

INSRS: WSP: PMU Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRS: WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRS: WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRS: WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
<u>13/12</u>	Non-Reporting ltr (1st)	
	Non-Reporting ltr (2nd)	
	Non-Reporting ltr (Final)	
	Notification ltr (if non-pickup)	
	Call OI	
	After call ltr to OI	
	Documentation Check List: Handler Typist	
<u>16/12/18</u>	Notification ltr (if non-pickup)	
	After call ltr to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA :	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
<u>14/12/18</u>	Notification ltr (if non-pickup)	
	After call ltr to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA :	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
<u>17/10/19</u>	Notification ltr (if non-pickup)	
	After call ltr to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA :	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
<u>8/5/19</u>	Notification ltr (if non-pickup)	
	After call ltr to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA :	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
<u>09/05/19</u>	Notification ltr (if non-pickup)	
	After call ltr to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA :	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: PIR \$S 9,789.85 ( 5 days) Reduction: 36 % Email  Call

FINAL SETTLEMENT Date/Time: 03/06/19 Confirm with: CHARLINE Email  Call

Final Liability: % 100 (Assess / Assessed) BOLA S/N No. : 27 If NO or B 28, Ass. Lia : COLD RATE-ENDED TP

Repair Cost: (20/000) \$S 10,475.14 Loss of Rental (LOR): \$S 750.00 ( 5 days) x 150

Loss of Use (LOU): \$S — ( 5 x days) Loss of Income (LOI): \$S — ( 5 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  (Tick only one)

GIA/LTA Search: \$S — Medical: \$S — Disbursement: \$S — (e.g. Tow/ Independent )

Legal Cost: \$S — Total: \$S 11,225.14 Global Sum SS: —

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$S 11,225.14 Name 1: PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.) \$S — Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$S — Name 3: \_\_\_\_\_

Passive

ASSIGNMENT

From: \_\_\_\_\_ Date: 07/01/2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SCE 1336M

at Workshop with: Performance

of: 303 Alexandra Rd

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Kevin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 100k

IDAC Accident Report: Consistent? Yes or No


GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: SCE 1336M Yr Regn: 2014 P60

Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: B.M.W X3 XDRIVE 20I cc 1997

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 77008 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/N: WBAW X32030B28575

Gen. Cond: Good /  Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18 R: -

BS:  DUP / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear
R/Bal: 6 mm		R/Bal: 6 mm
L/Bal: 6 mm		L/Bal: 6 mm
D.O.A: 07/12/18		D.O.I: 07/01/19

Survey held at: PERFORMANCE

Des. of Damages: Frt /  Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	P/P \$9,789.85
	CRD: \$5,268.95 (55%)

Date/Time, File Pass to?  : Prel. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_\_ S+RS \$ \_\_\_\_\_

Photos \_\_\_\_\_

Other \_\_\_\_\_

\_\_\_\_\_

TOTAL \_\_\_\_\_

Add Fee:  Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

BMW Dealer

# Performance Motors Limited

A member of the Stone Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Stone Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampong Krang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449777

115, Alexandra Road  
Stone Darby Business Centre  
Singapore 159944  
Tel. 63190328 (AfterSales)  
63190333/230 (Motorsrad)  
Fax. 64794601 (AfterSales)  
64794634 (Motorsrad)

INDIA



GST REG. NO : M2 - 0020081 - X

11 DEC 2018

## ESTIMATE

Estimate No. : b1 49397	Page No. : 1 of 5
Date Estimated : 10/12/2018	
Prepared By : Kevin Leong Wai Kit	

<p>- ESTIMATE REPAIR FOR - Maria Lin Wong 15J Lim Tua Tow Road  Singapore 547747</p>	<p>- ACCOUNT - 219 India Int'L Insurance Pte Ltd 64 Cecil Street #04-05 IOB Building Singapore 049711</p>
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCE1336M	0B28575	28/02/2014	X3 xDrive20i	0

DESCRIPTION	VALUE
To replace rear bumper, rear tailgate, reinforcement & all attachments cause by accident.	1700 <del>3400.00</del>
Painting on rear bumper & rear tailgate	1805 <del>2,000.00</del>
To conduct water leak tests.	75 68 <del>78.00</del>
To supply and install rear windscreen solar film.	574 451 ? 531.00
To check electrical wiring systems at the rear section for proper function.	150 <del>172.00</del>
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451 <del>531.00</del>
To carry out body cavity preservation. (Per panel) Tailgate	100 <del>130.00</del>
Sundries.	80 / ? 150.00

Total Labour 1: **6,988.00**

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET	5	1.10	5.50
CLAMP	10	1.55	15.50
HEX BOLT	8	1.45	11.60
BOOTLID	1	1,852.40	1,852.40
LH TRUNK LID HINGE	1	66.25	66.25
RH TRUNK LID HINGE	1	76.45	76.45
SET TRIM TOWING LUG	2	71.60	143.20
Set of mount	1	35.10	35.10
RR BUMPER CARRIER ECE	1	756.50	756.50
MOUNT BUMPER REAR LH	1	192.15	192.15
MOUNT BUMPER REAR RH	1	192.15	192.15

# Performance Motors Limited

A member of the Simo Darby Group  
 Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



101, Alexandra Road  
 Simo Darby Performance Centre  
 Singapore 119941  
 Tel. 43190130 (Sales & Admin)  
 43190111 (AfterSales)  
 Fax. 44747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438188  
 Tel. 43190888 (AfterSales)  
 Fax. 43449773

215, Alexandra Road  
 Simo Darby Business Centre  
 Singapore 119944  
 Tel. 43190528 (AfterSales)  
 43190531/330 (Motorrad)  
 Fax. 44794801 (AfterSales)  
 44794824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 49397  
 Date Estimated : 10/12/2018  
 Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCE1336M	0B28575	28/02/2014	X3 xDrive20i	0

DESCRIPTION	QTY	PRIC	VALUE
COVERING BOTTOM REAR ? } xsu	1	81.80	81.80
RR BUMPER LH MIDDLE MOUNT ? } xsu	1	142.55	142.55
RR BUMPER RH MIDDLE MOUNT ? } xsu	1	142.55	142.55
COVER TRIM REAR BLACK (PDC) DE -	1	202.25	202.25
RR BUMPER (PRIMED) DE -	1	1,375.90	1,375.90
RR W/SCREEN (try to replace) xsu	1	1,063.05	1,063.05
DEFLECTOR LIP REAR LH ? } xsu	1	12.95	12.95
BOOTLID GASKET X	1	145.30	145.30
REAR LH REFLECTOR X } xsu	1	36.10	36.10
REAR RH REFLECTOR X } xsu	1	36.10	36.10
THIRD STOPLAMP xsu	1	239.45	239.45
DECOUPLING RING PDC TORQUE CONVERTE xsu	4	5.05	20.20
BUMPER PDC SENSOR (SCHWARZ) ? xsu lw (1P)	2	236.85	473.70
(DG) CLEANER R1 (100ML) xsu	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) xsu	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) xsu	1	27.85	27.85

four

Total Parts : 7,635.80

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
 Date & Time 07/01/19 @ 10:55 Excess S\$ \_\_\_\_\_  
 Surveyor's Name RABU Sign \_\_\_\_\_  
 Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_  
 Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PVL Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Estimated 5 days

Resury SF paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Labour 1	:	6,988.00
Parts	:	7,635.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,023.67
<b>Grand Total</b>	:	<b>15,647.47</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
 \*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

15,058.80

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559N. GST Reg. No. M3-0020091-X



## FINAL REPORT

Estimate No. : b1 49397  
Date Estimated : 10/12/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Maria Lin Wong  
15J Lim Tua Tow Road

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Singapore 547747

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SCE1336M	0B28575	28/02/2014	X3 xDrive20i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid and attachments include knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint rear bumper and boot lid	1805.00		1,805.00	
* To conduct water leak tests	75.00		75.00	
* To remove and install rear windscreen glass to facilitate repairs	574.00		574.00	
To check electrical wiring systems at the rear section for proper function.	150.00		150.00	
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	
To carry out body cavity preservation (Per panel)	100.00		100.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BLIND RIVET	1.10	10.00		11.00
CLAMP	1.55	10.00		15.50
HEX BOLT	1.45	10.00		14.50
BOOTLID	1,852.40	1.00		1,852.40
SET TRIM TOWING LUG	71.60	1.00		71.60
COVER TRIM REAR BLACK (PDC)	210.25	1.00		210.25
RR BUMPER (PRIMED)	1,430.20	1.00		1,430.20
# EMBLEM GROMMET *	0.80	2.00		1.60
# MODEL LETTERING X3 *	64.10	1.00		64.10
# TRUNK LID BADGE *	71.25	1.00		71.25
# BUMP STOP *	3.50	10.00		35.00
# EXPANDING RIVET *	1.35	20.00		27.00
THIRD STOPLAMP	239.45	1.00		239.45

# Performance Motors Limited

A member of the Stone Carby Group  
Co. Reg. No. 191401559W. GST Reg. No. M3-0020081-1



## FINAL REPORT

DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00	20.20
# BUMPER PDC SENSOR (SCHWARZ) *	236.85	1.00	236.85
BUMPER PDC SENSOR (SCHWARZ)	236.85	1.00	236.85
(DG) CLEANER R1 (100ML)	26.15	1.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	27.85

### # SUPPLEMENTARY ITEMS

Total Labour :	4,935.00
Total Parts :	4,854.85
Total Labour & Parts :	<u>9,789.85</u>
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,789.85
GST @7%:	685.29
Grand Total :	<u>10,475.14</u>

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W; GST Reg. No. M2-0028081-4



## SUPPLEMENTARY

Estimate No. : b1 49397  
Date Estimated : 10/12/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Maria Lin Wong  
15J Lim Tua Tow Road

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Singapore 547747

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SCE1336M	0B28575	28/02/2014	X3 xDrive20i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EMBLEM GROMMET *	0.80	2.00		1.60
# MODEL LETTERING X3 *	64.10	1.00		64.10
# TRUNK LID BADGE *	71.25	1.00		71.25
# BUMP STOP *	3.50	10.00		35.00
# EXPANDING RIVET *	1.35	20.00		27.00
# BUMPER PDC SENSOR (SCHWARZ) *	236.85	1.00		236.85

Total Labour :  
Total Parts : 435.80  
Total Labour & Parts : 435.80



BMW X3 xDrive20i

\$96,888

\$14,430 /yr

19-Feb-2014

1,997 cc

79,000 km

SUV

Available

One Owner Unit. Well Taken Care Of By Previous Owner. Powerful And Luxurious SUV With BMW Renowned Twin Power Turbo Engine Mated To Auto 8-Speed Transmission. Flexible Finance Package Available. Exten...

Cars 88 Pte Ltd

Posted: 20-Dec-2018 Tags: 2014 BMW X3, 2014 bmw x3, BMW X3, bmw x3, BMW, X3, x3, Used BMW



BMW X3 xDrive20i

\$100,000

\$15,220 /yr

25-Feb-2014

1,997 cc

58,000 km

SUV

Available

Offering \$10K Driveway Scheme! Comes With 6 Months Warranty & Full Vehicle Polishing Including Engine Bay! Complimentary BMW Logo Car Mats Including Boot! Single Owner! Lowest Mileage For Its Age! La...

Posted: 19-Dec-2018 Tags: 2014 BMW X3, 2014 bmw x3, BMW X3, bmw x3, BMW, X3, x3, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Status

For old advertisements, view [Expired ads](#)

20  results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used BMW X3, BMW X3 Singapore, used BMW X3 Singapore, used BMW X3, used vehicles Singapore or even buy used BMW X3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare



BMW Dealer

**Performance Motors Limited**A member of the Gine Darby Group  
Co. Reg. No. 191401559W GST Reg. No M2-0020081-x103, Alexandra Road  
Gine Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773119, Alexandra Road  
Gine Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/330 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

INDIA



GST REG. NO : M2 - 0020081 - X

11 DEC 2018

**E S T I M A T E**Estimate No. : b1 49397  
Date Estimated : 10/12/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

**- ESTIMATE REPAIR FOR -**Maria Lin Wong  
15J Lim Tua Tow Road

Singapore 547747

**- ACCOUNT - 219**India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCE1336M	0B28575	28/02/2014	X3 xDrive20i	0

DESCRIPTIONVALUE

To replace rear bumper, rear tailgate, reinforcement &amp; all attachments cause by accident

1700 ~~3,400.00~~

Painting on rear bumper &amp; rear tailgate

1805 ~~2,000.00~~

To conduct water leak tests.

68 ~~78.00~~

To supply and install rear windscreen solar film.

451 ? 531.00

To check electrical wiring systems at the rear section for proper function.

150 ~~177.00~~

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 ~~531.00~~To carry out body cavity preservation.  
(Per panel) Tailgate100 ~~118.00~~

Sundries.

? 150.00

Total Labour 1: **6,988.00**DESCRIPTIONQTYPRICVALUEBLIND RIVET *gn*

5

1.10

5.50

CLAMP *gn*

10

1.55

15.50

HEX BOLT *gn*

8

1.45

11.60

BOOTLID *gn*

1

1,852.40

1,852.40

LH TRUNK LID HINGE *gn*

1

66.25

66.25

RH TRUNK LID HINGE *gn*

1

76.45

76.45

SET TRIM TOWING LUG *gn*

1

71.60

143.20

Set of mount *gn*

1

35.10

35.10

RR BUMPER CARRIER ECE *gn*

1

756.50

756.50

MOUNT BUMPER REAR LH *gn*

1

192.15

192.15

MOUNT BUMPER REAR RH *gn*

1

192.15

192.15

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Karpang Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190333/330 (Motorrad)  
Fax. 64786601 (AfterSales)  
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 49397  
Date Estimated : 10/12/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCE1336M	0B28575	28/02/2014	X3 xDrive20i	0

DESCRIPTION	QTY	PRIC	VALUE
COVERING BOTTOM REAR ?	1	81.80	81.80
RR BUMPER LH MIDDLE MOUNT ?	1	142.55	142.55
RR BUMPER RH MIDDLE MOUNT ?	1	142.55	142.55
COVER TRIM REAR BLACK (PDC) DE ✓	1	202.25	202.25
RR BUMPER (PRIMED) DE ✓	1	1,375.90	1,375.90
RR W/SCREEN ? (try to reuse)	1	1,063.05	1,063.05
DEFLECTOR LIP REAR LH ?	1	12.95	12.95
BOOTLID GASKET X	1	145.30	145.30
REAR LH REFLECTOR X	1	36.10	36.10
REAR RH REFLECTOR X	1	36.10	36.10
THIRD STOPLAMP re ✓	1	239.45	239.45
DECOUPLING RING PDC TORQUE CONVERTE re ✓	4	5.05	20.20
BUMPER PDC SENSOR (SCHWARZ) ?	2	236.85	473.70
(DG) CLEANER R1 (100ML) re ✓	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) re ✓	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) ✓ ✓	1	27.85	27.85

Total Parts : 7,635.80

Claims OD / Third Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date&amp;Time 07/01/19 @ 10:55 Excess S\$ \_\_\_\_\_

Surveyor's Name RASUL Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days 5 days

Resur SF print

Labour 1	:	6,988.00
Parts	:	7,635.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,023.67
<b>Grand Total</b>	:	<b>15,647.47</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## Print Received Message

This mail is associated with :

**\*SCE1336M (MCT18120209)**  
**[SHC3435Z]**

TP

MARIA LIN WONG

Dec 7 2018 5:00PM

[-]

Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 09/05/2019 11:00 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$11225.14) - SCE1336M - Claim Handler: Priya

Approved:11225.14.

AXA INSURANCE PTE LTD  
8 Shepton Way, #24-01  
AXA Tower, Singapore 068811  
Customer Service Centre #B1-01  
Tel:(65)63387288 Fax:(65)63382522  
Website:www.axa.com.sg  
GST Registration Number: 199903512M  
customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

* Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) * Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 * Road Transport Act, 1987 (Malaysia) * Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)		
CERTIFICATE NO.	: VPA/P1718187	Account No. : 11615
Coverage	: Comprehensive	
Sum Insured	: Market Value At The Time Of Loss	
Name of Policy Holder	: MARIA LIN WONG	
Vehicle Registration No.	: SCE1336M	
Period of Insurance	: From 28/02/2017 To 27/02/2018 (Both Dates Inclusive)	
<b>PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*</b>		
(a) The Policyholder The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner		
(b) Any other person who is driving on the Policyholder's order or with his permission Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
<b>LIMITATIONS AS TO USE*</b>		
Use only for social, domestic and pleasure purposes and for the Policyholder's business The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.		
(01)		
<b>Basic Own Damage Excess</b>	: SGD 500.00	
An Additional Excess is applicable as follows: S\$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver. S\$5,000.00 for Undeclared Young and Inexperienced Driver. (Please refer to your policy on the terms & conditions)		
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOVKRS2 on 22/02/2017

**IMPORTANT :**  
Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189)).  
The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

**REPUBLIC OF SINGAPORE DRIVING LICENCE**



Licence Number: **S22051671**  
 Name:  
**MARIA LIN WONG**  
 Birth Date: **21 Dec 1953**  
 Issue Date: **22 Dec 2003**

001058758F



**REPUBLIC OF SINGAPORE**  
**IDENTITY CARD NO. S22051671**




Name:  
**MARIA LIN WONG**  
**王蓮**  
 Race:  
**CHINESE**  
 Date of birth:  
**21-12-1953** Sex:  
**F**

Country/Place of Birth:  
**HONG KONG**

S22051671

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	29 Jan 1980

NP 428A



930966



S22051671



Nationality:  
**CHINESE**  
 Date of issue:  
**30-05-2013**

Address

**15J LIM TUA TOW ROAD**  
**SINGAPORE 547747**

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401159W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190180 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/330 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

INDIA



GST REG. NO : M2 - 0020081 - X

11 DEC 2018

## ESTIMATE

Estimate No. : b1 49397  
Date Estimated : 10/12/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

### - ESTIMATE REPAIR FOR -

Maria Lin Wong  
15J Lim Tua Tow Road

Singapore 547747

### - ACCOUNT - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCE1336M	0B28575	28/02/2014	X3 xDrive20i	0

#### DESCRIPTION

To replace rear bumper, rear tailgate, reinforcement & all attachments cause by accident

1700 ~~3400.00~~

Painting on rear bumper & rear tailgate

1805 ~~2,000.00~~

To conduct water leak tests.

68 ~~78.00~~

To supply and install rear windscreen solar film.

451 ? 531.00

To check electrical wiring systems at the rear section for proper function.

150 ~~177.00~~

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 ~~531.00~~

To carry out body cavity preservation.  
(Per panel) Tailgate

100 ~~118.00~~

Sundries.

? 150.00

Total Labour 1: **6,988.00**

#### DESCRIPTION

BLIND RIVET *MA*  
CLAMP *MA*  
HEX BOLT *MA*  
BOOTLID *MA*  
LH TRUNK LID HINGE *MA*  
RH TRUNK LID HINGE *MA*  
SET TRIM TOWING LUG *MA*  
Set of mount *MA*  
RR BUMPER CARRIER ECE *MA*  
MOUNT BUMPER REAR LH *MA*  
MOUNT BUMPER REAR RH *MA*

QTY	PRIC	VALUE
5	1.10	5.50
10	1.55	15.50
8	1.45	11.60
1	1,852.40	1,852.40
1	66.25	66.25
1	76.45	76.45
2	71.60	143.20
1	35.10	35.10
1	756.50	756.50
1	192.15	192.15
1	192.15	192.15

**PERFORMANCE MOTORS LIMITED**A member of the Sime Darby Group  
Co. Reg. No. 197401159W QOT Reg. No M2-0020081-X303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190828 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**Estimate No. : **b1 49397**  
Date Estimated : **10/12/2018**  
Prepared By : **Kevin Leong Wai Kit**Page No. : **2 of 5**REGN. NO. : **SCE1336M** CHASSIS NO. : **0B28575** REGN. DATE : **28/02/2014** MODEL : **X3 xDrive20i** MILEAGE : **0**

DESCRIPTION	QTY	PRIC	VALUE
COVERING BOTTOM REAR ?	1	81.80	81.80
RR BUMPER LH MIDDLE MOUNT ?	1	142.55	142.55
RR BUMPER RH MIDDLE MOUNT ?	1	142.55	142.55
COVER TRIM REAR BLACK (PDC) DE	1	202.25	202.25
RR BUMPER (PRIMED) DE	1	1,375.90	1,375.90
RR W/SCREEN (try to reuse)	1	1,063.05	1,063.05
DEFLECTOR LIP REAR LH ?	1	12.95	12.95
BOOTLID GASKET X	1	145.30	145.30
REAR LH REFLECTOR X	1	36.10	36.10
REAR RH REFLECTOR X	1	36.10	36.10
THIRD STOPLAMP new	1	239.45	239.45
DECOUPLING RING PDC TORQUE CONVERTE new	4	5.05	20.20
BUMPER PDC SENSOR (SCHWARZ) ?	2	236.85	473.70
(DG) CLEANER R1 (100ML) new	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) new	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) new	1	27.85	27.85

Total Parts : **7,635.80**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date&Time 07/01/19 @ 10:55 Excess S\$ \_\_\_\_\_

Surveyor's Name R Paul Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR. Yes / No PML Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days 5 days

Resurvey SF print

Labour 1	:	6,988.00
Parts	:	7,635.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,023.67
<b>Grand Total</b>	:	<b>15,647.47</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



(Vic) ✓

India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
Attention: Motor Claims

**"Without Prejudice"**

Your Ref:

Our Ref:

Date:

Subject:

08 April 2019

**ACCIDENT INVOLVING VEHICLES SCE1336M & SHC3435Z ON 07.12.2018**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$ 10475.14
Car Rental	: S\$ 750.00
Total	: S\$ 11225.14

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Car Rental bill & Car Rental Agreement & Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel Aftersales  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel Aftersales  
6319 0527  
Fax 6479 6634

290  
Kampong Arang Rd  
East Coast Centre  
Singapore 436190  
Tel Aftersales  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No.  
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours sincerely

Cresendo Lagman  
Customer Service Manager, Body & Paint



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SCE 1336M & SHL 34 352 ON 7/12/18.

I, Maria Lin Wong owner of Vehicle Registration No. SCE 1336M hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Maria Lin Wong

Name: MARIA LIN WONG (Date) 10.12.2018  
NRIC No.: S 2205167 (1)

In the presence of:

[Signature]  
KEVIN LEONG WAI KIT  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Name: \_\_\_\_\_ (Date) 10/12/18  
NRIC No.: \_\_\_\_\_

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: NOT10120209  
Claimant Ref: SCE1336M

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd Mr. Rasul from LKK Auto Consultants P/L (name of Surveyor) with respect to the amount claimed for S\$10475.14 (repair cost), S\$750.00 (loss of ~~rental~~ rental), S\$ - (search fee), vehicle no. SCE1336M that was damaged pursuant to the accident which occurred on 7-12-18 (date) at Tanglin Road (location) involving vehicle no. 91CJ457 (insured vehicle). This is pursuant to the inspection conducted on 7-1-19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Maria Lin Wong ("the third party claimant") of vehicle no. SCE1336M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SCE1336M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$11,225.14 to PERFORMANCE MOTORS LIMITED

Dated this 03 day of 06 2019

CLAIMANT:

Signature:

[Signature]  
Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

**KEVIN LEONG WAI KIT**  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

WITNESS:

Signature:

[Signature]  
Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:



**LKK AUTO CONSULTANTS P/L**  
51 Ubi Ave 1, #01-25  
Paya Ubi Industrial Park  
Singapore 489333  
Tel: 6256 3561

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559M GST Reg. No M2-0020061-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159943  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63443773

311, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)



## SERVICE TAX INVOICE

Repair Order No. : B1 1328284	Page No. : 1 of 2
Date IN : 07/01/2019	Invoice Number : 2083202 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 02/04/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

### - CUSTOMER INFORMATION -

Mdm Maria Lin Wong  
15J Lim Tua Tow Road

Singapore 547747

- INVOICE TO - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO. SCE1336M	CHASSIS NO. 0B28575	REGN. DATE 28/02/2014	MODEL X3 XDRIVE20I	MILEAGE 77008
-----------------------	------------------------	--------------------------	-----------------------	------------------

	NETT
<b>--- LABOUR ---</b>	<b>1,700.00</b>
To replace rear bumper and attachments, rear boot lid and attachments etc including to remove and install body parts in order to carry out painting job.	1,805.00
To respray rear bumper and rear boot lid.	75.00
To conduct water leak tests.	574.00
To remove and install rear windscreen glass to facilitate the repair job.	150.00
To check electrical wiring systems at the rear section for proper function.	451.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	100.00
To carry out body cavity preservation.	80.00
Sundries.	0.00
INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT. DATE OF ACCIDENT : 7.12.2018. 3RD PARTY CAR : SHC3435Z. YOUR REF NO : NIL. VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 7.1.2019. AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK ON 14.12.2018 VIA E-MAIL. PROPOSE CAR RENTAL = \$750.00 THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
Total Labour 1:	<b>4,935.00</b>

### --- PARTS ---

	Qty	Retail Price	NETT
BLIND RIVET	10	1.10	11.00
CLAMP	10	1.55	15.50
HEX BOLT	10	1.45	14.50
RR BUMPER (PRIMED)	1	1,430.20	1,430.20
THIRD STOPLAMP	1	239.45	239.45
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
BUMPER PDC SENSOR (SCHWARZ)	1	236.85	236.85
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 418100  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190523/538 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)



## SERVICE TAX INVOICE

Repair Order No. : <b>B1 1328284</b>	Page No. : <b>2 of 2</b>
Date IN : <b>07/01/2019</b>	Invoice Number : <b>2083202 / WSB</b>
Cust. Svc. Advisor: <b>Kevin Leong Wai Kit</b>	Invoice Date : <b>02/04/2019</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
BOOTLID	1	1,852.40	1,852.40
COVER TRIM REAR BLACK (PDC)	1	210.25	210.25
BUMPER PDC SENSOR (SCHWARZ)	1	236.85	236.85
EXPANDING RIVET	20	1.35	27.00
BUMP STOP	10	3.50	35.00
TRUNK LID BADGE	1	71.25	71.25
EMBLEM GROMMET	2	0.80	1.60
MODEL LETTERING X3	1	64.10	64.10
SET TRIM TOWING LUG	1	71.60	71.60
	<b>Total Parts :</b>		<b>4,854.85</b>

--- LABOUR 2 ---

	NETT
	0.00
<b>Total Labour 2:</b>	<b>0.00</b>

Labour Charges :	<b>4,855.00</b>	Total Labour & Parts Charges :	<b>S\$ 9,789.85</b>
Parts Charges :	<b>4,854.85</b>	Less Insurance Excess :	<b>S\$ 0.00</b>
Lubricant/Misc :	<b>80.00</b>	Invoice Total Amount Exclude GST :	<b>S\$ 9,789.85</b>
		GST @ 7% :	<b>S\$ 685.29</b>
		Invoice Total Amount Include GST :	<b>S\$ 10,475.14</b>

Computer generated invoice. No signature is required. Amount Payable Include GST : **S\$ 10,475.14**

All amounts are in Singapore Dollars.  
Work was carried out subject to the Company's Terms and Conditions of Service.  
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
For credit purchases, interest @1% per month will be debited on overdue amounts.



# CHANS & SONS ENTERPRISE

363 Sembawang Road, Goodlink Park,  
Singapore 758379  
Tel: 67532536 Fax: 67567565  
GST Reg No: 51-936900-M

**chan's**  
www.chans.com.sg

Hirer:

**MARIA LIN WONG**

## OFFICIAL RECEIPT

DESCRIPTION		AMOUNT (SGD)	
Official Receipt No	: 201901-0083		
Account of	: MARIA LIN WONG		
Date Issued	: 11/01/2019		
Vehicle Reg No.	: SKH3353P		
Rental Dates	: 07/01/2019		
Amount Received	: S\$ 750.00		
Payment Type:	: MASTER	M101071	S\$ 750.00
Payment for Invoice	: AR1901-0140		
Comments	:		
<b>TOTAL AMOUNT RECEIVED</b>		<b>S\$</b>	<b>750.00</b>

\* This is a computer generated document. No signature is required.

## RENTAL AGREEMENT

2019 01 - 0077

Hirer's Name <b>Maria Lin Wong</b>		Date of Birth <b>21/12/53</b>	Passport/ Nric No. <b>S2205167/I</b>	Nationality
Address <b>155 Lim Tua Tow Road</b>		Occupation	Driving Licence No. <b>As Above</b>	Date of Expiry <b>Life.</b>
	Postal Code <b>547747</b>	Contact No	Mobile Phone No. <b>96891112</b>	
Joint Hirer's / Guarantor's Name		Date of Birth	Passport/ Nric No.	Nationality
Address		Occupation	Driving Licence No	Date of Expiry
	Postal Code	Contact No	Mobile Phone No.	

### CHECK OUT

Date <b>7.1.19</b>	Time <b>9.55am</b>	Mileage <b>10.35km</b>	E <b>1/4</b> 1/2 3/4 F
Date <b>11.1.19</b>	Time <b>4pm</b>	Mileage <b>11</b>	

### CHECK IN

- IMPORTANT NOTES:-**
- Car is restricted to SINGAPORE use. See clause 1(f) for non-compliance.
  - No refund will be given for vehicle that returns early.
  - Own Damage Liability - First \$1500 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
  - Third Party Liability - First \$2000 for any Third Party Accident Claim.
  - Additional Excess of \$3000 for drivers under 24yrs old or above 70yrs and/or less than 2yrs driving experience.
  - Hirer is responsible for all parking fines & traffic summons.
  - Extension:- One day's advance notice is required otherwise no extension will be allowed.
  - Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
  - Vehicle returned after office hour will be charged to the next working day.
  - Hourly extension is charged at 1/5 of the daily rate.
  - As preventive maintenance, please check water & engine oil daily.
  - Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings after the vehicle is returned.
  - For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge of \$200 will be imposed for smoky, smelly or dirty vehicle.
  - Carrying of PASSENGERS in commercial vehicle is strictly prohibited. Only WORKERS covered under hirer's workmen compensation are allowed.

	UNIT	RATE (\$)	TOTAL (\$)
RATE	5	150	
DISCOUNT			
GST @ 7%			
TOTAL			750
EXTENSION			
PML/K			
SCE1336M			
DEPOSIT (refundable) S\$			
CHANGED OVER FROM VEH.		DATE	

*We have read and agree to the terms and conditions of the rental agreement above and as set overleaf.  
 We declare that all information given on this form is true and accurate.*

**Masha H.**  
 Hirer's Signature

Joint Hirer's/ Guarantor's Signature

**Chan's**  
 for CHAN'S & SONS ENTERPRISE

VEHICLE NO. <b>SKH 3353P</b>	MODEL
FROM	RETURN

\*Estimate Date. For actual return see CHECK IN

# CHAN'S & SONS ENTERPRISE

363 Sembawang Road  
Singapore 758379  
Tel: 67532536 Fax: 67567565  
GST Reg No: 51-936900-M

# chan's

www.chans.com.sg

## TAX INVOICE

**MARIA LIN WONG**  
NO. 15J  
LIM TUA TOW ROAD  
SINGAPORE 547747

ATTN : MARIA LIN WONG

INVOICE : AR1901-0140  
DATE : 11/01/2019  
TERMS : C.O.D  
STAFF ID : AMIRA  
AGREEMENT NO. : HA201901-0077

DESCRIPTION	AMOUNT (SGD)
Vehicle Reg No : SKH3353P	700.93
Make / Model :	
Rental Dates : Rental Billing From 07/01/2019 To 11/01/2019 (incl)	
Period : 5 days	
Rental Rate : S\$ 150.00 Per Day (Including GST)	
Reference No : SCE1336M	

AMOUNT : S\$	NON-TAXABLE VALUE :	0.00
SEVEN HUNDRED FIFTY DOLLARS ONLY	TAXABLE VALUE :	700.93
	GST 7% :	49.07
	<b>TOTAL S\$ :</b>	<b>750.00</b>

Please make your cheques payable to : **CHAN'S & SONS ENTERPRISE**



For Official Use Only

Payment Date :	F / Amt
CS / CC / CH :	
CS / CC / CH :	

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2018 <a href="#">Edit Reg</a>		07 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$9,789.85</b> <a href="#">Edit Estimates</a>	<b>S\$9,789.85</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Main Claimant:	<b>MARIA LIN WONG</b> , ID: S2205167I								
Vehicle Reg. No.:	<b>SCE1336M</b>	Date of Loss:	07/12/2018 17:00 - :59 [57 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT18120209</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SHC3435Z</b>	Policy No. (Claimant):	P1718187						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Priya</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 21/12/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (09/05/2019): Alert - Adj Mandate Approved (S\$11225.14) - SCE1336M - Claim Handler: Priya</li> <li>III_SG (14/12/2018): Alert - Adj Mandate Approved (S\$0.00) - SCE1336M - Claim Handler: Priya</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SCE1336M (MCT18120209)  
[SHC3435Z]

TP

MARIA LIN WONG

Dec 7 2018 5:00PM

[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View	View in Browser <input type="button" value="v"/>	
<b>Photos/Images</b>			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/04/19 10:01	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	02/04/19 10:01	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
4	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
5	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
6	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
7	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
8	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
9	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
10	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
11	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
12	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
13	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
14	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
15	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
16	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
17	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
18	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
19	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
20	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
21	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
22	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
23	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
24	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
25	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
26	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
27	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
28	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
29	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
30	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
31	02/04/19 10:01	General View		Load JPG	<input checked="" type="checkbox"/>
32	02/04/19 10:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	02/04/19 10:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	02/04/19 10:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	02/04/19 10:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	02/04/19 10:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	02/04/19 10:02	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/04/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	02/04/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	02/04/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/18 08:59	TP ESTIMATE + TP GIA REPORT	 Load PDF	
2	10/01/19 13:21	TP ESTIMATE - MARKED	 Load PDF	
3	29/04/19 13:53	WORKSHOP INVOICE	 Load PDF	
4	29/04/19 13:53	RENTAL RECEIPT	 Load PDF	
5	29/04/19 13:53	LOD	 Load PDF	
6	11/06/19 09:27	DISCHARGE VOUCHER	 Load PDF	
7	11/06/19 09:27	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/12/18 09:06	Singapore Accident Statement	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III18022333/R1HA3Q2  
**Date:** 11/06/2019

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b> SCE1336M	<b>Insured Vehicle No :</b>	SHC3435Z
Date of Loss: 07/12/2018	Nature of Claim:	TP
		Claim No: MCT18120209

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SCE1336M</b>	Engine No:	A2260614N20B20A
Make & Model:	BMW X3, 2.0 xDrive20i (A)	Chassis No:	WBAWX320300B28575
Reg. Date:	28/02/2014 (Man. Year: 2013)	Odometer:	77008 km
Colour:	Red		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,292.30	4,934.85	3,357.45	40.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,881.00	4,855.00	2,026.00	29.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,173.30</b>	<b>9,789.85</b>	<b>5,383.45</b>	<b>35.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,062.13</b>	<b>685.29</b>	<b>376.84</b>	<b>35.48</b>
<b>Nett Amount (S\$)</b>	<b>16,235.43</b>	<b>10,475.14</b>	<b>5,760.29</b>	<b>35.48</b>
<b>+ Car Rental (5.0 x S\$150.00/day) (S\$)</b>		<b>750.00</b>		
	<b>Nett Liability (S\$)</b>	<b>11,225.14</b>		

#### INSPECTION

Date of Assignment:	07/01/2019	
Date Inspected:	07/01/2019	Inspected At: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD RASUL

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2019)	
<b>Parts:</b> M1-SUV	BMW X3 2.0 xDrive20i (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b> (Unsubmitted, no print-code for SCE1336M)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	5		*BLIND RIVET	Necessary	11.00 FS	*11.00 FS
3	10		*CLAMP	Necessary	15.50 FS	*15.50 FS
4	1		*HEX BOLT (8 PCS)	Necessary	14.50 FS	*14.50 FS
5	1		*BOOTLID	Bent	1,852.40 FS	*1,852.40 FS
6	1		*LH TRUNK LID HINGE	Serviceable	66.25 FS	*- FS
7	1		*RH TRUNK LID HINGE	Serviceable	76.45 FS	*- FS
8	2		*SET TRIM TOWING LUG	Cut (1 PCS ONLY)	143.20 FS	*71.60 FS
9	1		*SET OF MOUNT	Not Necessary	35.10 FS	*- FS
10	1		*RR BUMPER CARRIER ECE	Serviceable	756.50 FS	*- FS
11	1		*MOUNT BUMPER REAR LH	Serviceable	192.15 FS	*- FS
12	1		*MOUNT BUMPER REAR RH	Serviceable	192.15 FS	*- FS
13	1		*COVERING BOTTOM REAR	Serviceable	81.80 FS	*- FS
14	1		*RR BUMPER LH MIDDLE MOUNT	Serviceable	142.55 FS	*- FS
15	1		*RR BUMPER RH MIDDLE MOUNT	Serviceable	142.55 FS	*- FS
16	1		*COVER TRIM REAR BLACK (PDC)	Deformed	210.25 FS	*210.25 FS
17	1		*RR BUMPER (PRIMED)	Deformed	1,430.20 FS	*1,430.20 FS
18	1		*RR W/SCREEN	Serviceable	1,063.05 FS	*- FS
19	1		*DEFLECTOR LIP REAR LH	Serviceable	12.95 FS	*- FS
20	1		*BOOTLID GASKET	Serviceable	145.30 FS	*- FS
21	1		*REAR LH REFLECTOR	Serviceable	36.10 FS	*- FS
22	1		*REAR RH REFLECTOR	Serviceable	36.10 FS	*- FS
23	1		*THIRD STOPLAMP	Necessary	239.45 FS	*239.45 FS
24	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20 FS	*20.20 FS
25	1		*BUMPER PDC SENSOR (SCHWARZ) (2 PCS)	Not Working (1 PCS ONLY)	473.70 FS	*236.85 FS
26	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
27	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
28	1		*(DG/SL) GLASS PRIMER 30 ML(VP 206)	Necessary	27.85 FS	*27.85 FS
29	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
30	1		*MODEL LETTERING X3	Necessary	64.10 FS	*64.10 FS
31	1		*TRUNK LID BADGE	Necessary	71.25 FS	*71.25 FS
32	10		*BUMP STOP	Necessary	35.00 FS	*35.00 FS
33	20		*EXPANDING RIVET	Necessary	27.00 FS	*27.00 FS
34	1		*BUMPER PDC SENSOR (SCHWARZ)	Not Working	236.85 FS	*236.85 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	8,292.30	4,934.85

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER ,REAR TAILGATE ,REINFORCEMENT & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	3,400.00	1,700.00
2	PAINTING ON REAR BUMPER & REAR TAILGATE	New	2,006.00	1,805.00
3	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
4	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	574.00	574.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) TAILGATE	New	118.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>6,881.00</b>	<b>4,855.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >