

◀ Service Request Details

Claim S8M0167N
Reference CS/ASM18022339/R1vd3s2 ✎
Loss Date December 6, 2018
Request Date December 12, 2018
Due Date
Vendor Name LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss Own Damage
Services Accelerated workshop survey

Actions

Next Step Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle SKA8808Z
Registration #

Make MERCEDES

Model C180

Service Address

...

Primary Contact/Insured

WONG WEI SHENG WILSON
 435C FERNSVALE ROAD, #18-222, 793435,
 Singapore

MIRACLE_BOI87@HOTMAIL.COM

Claim Handler

ANG Yvonne
 6568804461
 yvonne.ang@axa.com.sg

Additional Instructions EXCESS 1600 PENDING INVESTIGATION

[Messages](#)
[Invoices](#)
[History](#)
[Documents](#)
[Assessment](#)
[Metrics](#)
[Notes](#)

Document Type Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
OD PRI FROM WORKSHOP	Letters and Correspondence	Workshop	DHIWAR Namrata	
LKKInvoice1[2].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (OD)	December 26, 2018
LTA REBATE.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	December 26, 2018
LETTER.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	December 26, 2018
GIA RPT.pdf	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (OD)	December 26, 2018
IA.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	December 13, 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 REPAIRER ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	December 13, 2018
 SURVEY REPORT.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	December 13, 2018
 SKA8808Z INSD GIA.pdf	Reports & Statement	GIA Report	DHIWAR Namrata	December 11, 2018
 OD PRI FROM WORKSHOP .pdf	Letters and Correspondence	Workshop	DHIWAR Namrata	December 11, 2018