

22/03/2003

ASS. REC. BY:

REF:

CS3 | FWD18022347 / Jcd36

Special Instruction:

Surveyor: Hwee See  
Munim

ASSIGNMENT (Office)

From (Person): Kronel Tan

of

FWD

Date/Time: 11/12/18 @ 5:14pm

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SCV1234J

Insured:

FBM 35742

at Workshop m/s

Kim Service Station

Tel:

93839008

of

No. 4 Sungai Kedut Ave

Policy No:

PNMC2018-00004412

Claim No:

1201800018220

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/12/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

9:06am @ 12/12/18

Person Contacted:

Ah hue

Vehicle  IN  OUT

| Date/Time | Action/Instruction ( x ) Estimate |
|-----------|-----------------------------------|
|           | <u>SCV1234J - X</u>               |
|           | <u>FBM35742 - X</u>               |
|           | <u>Dismantle: 14/12/2018</u>      |
|           |                                   |
|           |                                   |
|           |                                   |
|           |                                   |

PRS

REF: FWD

Huee Jie

ASSIGNMENT

From: Date: 12/12/18

Estimated Cost

OD  WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SCV 1234J

at Workshop n/s: Kim service station

of: No. 4 Sungai kadut Ave

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Ah hoo @ 93839008

Veh No: SCV 1234J Yt Regn: 25 Sep 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes CLA 200 C.C. 1595

Colour: white A/C Insured / Std / NI / NA

Sp. Reading: 107709 T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: WDD1173432N022258

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil /  Rrim / STD A/Rim or

Tyre Size: F: 225/40R18

R: -

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

BS / DUN / EXNOVA / GY / FS / LIZA /  MMS / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 10/12/18

Survey held at Kim Service

Des. of Damages: Frt /  Rear / O/S / N/S / UIC / Rooftop or

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Date: Person Contacted: Vehicle: IN / OUT


Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 12/12/18

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction  |
|-------------|---|
|             | Range: \$4,800 - \$6,000<br>5 days  |
|             | <br>19/12/2018 |

Date/Time, File Pass to?  : Prel. Report

1)  : Final Report

Date/Time, File Return to?

2)

Report Format: PRS

Lump Sum / I.B.I: (\$)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: 80

Transportation: 50

S + RS: \$

Photos

Others

TOTAL: 130

**Nivitha (LKK Auto)**

---

**From:** motorclaims.sg@fwd.com  
**Sent:** Tuesday, 11 December 2018 5:14 PM  
**To:** assignments@lkkauto.com; sur@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com  
**Subject:** FW: 2ND PRS - Notice to conduct Pre-Prepair Survey - Your Ref: PNMC2018-00004412 and our ref: SCV 1234J/KM/jp/cl  
**Attachments:** 2nd PRS (reject) - 10.12.18.pdf

Hi

Please attend to attached TP PRS notice.

Indicate our Policy Number PNMC2018-00004412 in Merimen.

Regards,  
Lionel

---

**From:** Motor Claims SG - SG Common  
**Sent:** Tuesday, December 11, 2018 9:48 AM  
**To:** Accident@kscgp.com  
**Cc:** jiapei@kscgp.com; Motor Claims SG - SG Common  
**Subject:** RE: 2ND PRS - Notice to conduct Pre-Prepair Survey - Your Ref: PNMC2018-00004412 and our ref: SCV 1234J/KM/jp/cl

**WITHOUT PREJUDICE**

Dear Sir/ Madam

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK AUTO CONSULTANTS PTE LTD**, to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

Regards,  
Lionel

**From:** [Accident@kscgp.com](mailto:Accident@kscgp.com) [<mailto:Accident@kscgp.com>]  
**Sent:** Monday, December 10, 2018 7:27 PM  
**To:** Motor Claims SG - SG Common  
**Cc:** [jiapei@kscgp.com](mailto:jiapei@kscgp.com)  
**Subject:** 2ND PRS - Notice to conduct Pre-Prepair Survey - Your Ref: PNMC2018-00004412 and our ref: SCV 1234J/KM/jp/cl

Dear Josey,

Please find enclosed our 2nd PRS for your attention.

Thank you.

Wishing you a Merry Christmas and a Happy New Year! 🎄

Regards,  
Calshie LIM  
for and on behalf of Mr Gurdeep Singh Sekhon  
KSCGP Juris LLP  
10 Hoe Chiang Road  
#13-03A Keppel Towers  
Singapore 089315  
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708  
Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

**From:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com) [mailto:[motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)]

**To:** [Accident@kscgp.com](mailto:Accident@kscgp.com)

**Cc:** [jiapei@kscgp.com](mailto:jiapei@kscgp.com), [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)

**Sent:** Mon, 10 Dec 2018 10:21:17 +0000

**Subject:**

**WITHOUT PREJUDICE**

Dear Calshie,

We refer to your letter dated 10 December 2018 of the PRI Notice of your client's vehicle SCV1234J.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

***\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.***

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E [josey.loh@fwd.com](mailto:josey.loh@fwd.com)

W fwd.com.sg



**From:** [Accident@kscgp.com](mailto:Accident@kscgp.com) [<mailto:Accident@kscgp.com>]

**Sent:** Monday, 10 December, 2018 4:21 PM

**To:** Motor Claims SG - SG Common

**Cc:** [jiapei@kscgp.com](mailto:jiapei@kscgp.com)

**Subject:** 1ST PRS - Notice to conduct Pre-Prepair Survey - Your insured's vehicle: FBM 3574Z and our ref: SCV 1234J/KM/jp/cl

Dear Sirs,

Please find enclosed our 1st PRS Notice to conduct Pre-Prepair Survey for your attention and necessary action.

Thank you.

Regards,

Calshie LIM

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not

use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Your Ref : PNMC2018-00004412

Our Ref : SCV 1234J/KM/jp/cl

Date : 10 December 2018

Fax : 6538 3708

Tel : 3152 0982

Email : [accident@kscgp.com](mailto:accident@kscgp.com)

FWD SINGAPORE PTE. LTD.

BY EMAIL ONLY

**DATE OF ACCIDENT: 10 DECEMBER 2018**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email dated 10 December 2018.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

| S/no. | Name of Surveyor | Company Name                  |
|-------|------------------|-------------------------------|
| 1.    | Errol Tan        | Pro Plus Automobile Engineers |
| 2.    | Dave Chang       | Sincere Appraisal Services    |
| 3.    | Lee Kok Weng     | Lee Automobile Services       |

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Kim Service Station  
No. 4 Sungei Kadut Avenue  
Singapore 729641

Contact Person/Tel : Ah Hoe / 6367 6063 / 9383 9008

Yours faithfully,

*CL*

Your Ref : PNMC2018-00004412

Our Ref : SCV 1234J/KM/jp/cl

Date : 10 December 2018

**Acknowledgement**

This is to confirm that I \_\_\_\_\_ *[Full Name of Surveyor]* of \_\_\_\_\_ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(c) Re-inspection of new replacement part (part by part) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(d) Post – Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

| <b>Vehicle Owner Particulars</b>    |                          |
|-------------------------------------|--------------------------|
| Owner ID Type:                      | Singapore NRIC           |
| Owner ID:                           | 8572H                    |
| <b>Vehicle Details</b>              |                          |
| Vehicle No.:                        | SCV1234J                 |
| Vehicle to be Exported:             | No                       |
| Intended Deregistration Date:       | 12 Dec 2018              |
| Vehicle Make:                       | MERCEDES BENZ            |
| Vehicle Model:                      | CLA 200 (R18 SR)         |
| Primary Colour:                     | White                    |
| Manufacturing Year:                 | 2013                     |
| Engine No.:                         | 27091030209551           |
| Chassis No.:                        | WDD1173432N022258        |
| Maximum Power Output:               | 115.0 kW (154 bhp)       |
| Open Market Value:                  | \$29,551.00              |
| Original Registration Date:         | 25 Sep 2013              |
| First Registration Date:            | 25 Sep 2013              |
| Transfer Count:                     | 0                        |
| Actual ARF Paid:                    | \$23,372.00              |
| <b>Intended PARF Rebate Details</b> |                          |
| PARF Eligibility:                   | Yes                      |
| PARF Eligibility Expiry Date:       | 24 Sep 2023              |
| PARF Rebate Amount:                 | \$16,360.00              |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date:                    | 24 Sep 2023              |
| COE Category:                       | A - Car (1600cc & below) |
| COE Period(Years):                  | 10                       |
| QP Paid:                            | \$77,304.00              |
| COE Rebate Amount:                  | \$36,977.00              |
| <b>Total Rebate Amount:</b>         | <b>\$53,337.00</b>       |

The information contained herein is correct as at 12 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |   |
|----------------------------|---|
| Date Of Report             | 10/12/2018 14:52                        |
| Date Of Accident           | 10/12/2018 10:05                        |
| Exact Location Of Accident | JUNCTION OF BT BATOK EAST AVE 6 & AVE 2 |
| Country/State of Loss      | SINGAPORE                               |

### DETAILS OF OWN VEHICLE

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SCV1234J |
|-----------------------------|----------|

#### Insured/Policyholder

|                          |                      |
|--------------------------|----------------------|
| Name Of Registered Owner | CHAI HUEL LENG       |
| NRIC No                  | S7208572H            |
| Email Address            | NOEMAIL              |
| Mobile Phone No          | (LOCAL) +65-98521234 |
| Alternative Phone No     | OFFICE-98521234      |

#### Vehicle Particulars

|              |                      |
|--------------|----------------------|
| Manufacturer | MERCEDES-BENZ        |
| Model        | CLA200-1.6 (R18) (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

#### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5067679659-04 (CLASSIC)                |
| Cover Note Number         |  |

#### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | CHAI CHON YEN         |
| NRIC No              | S2017976G             |
| Date Of Birth        | 16/10/1948            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 20/05/1968            |
| Driving Experience   | 50 YEARS AND 6 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-98521234  |
| Fax Number           |                       |
| Contact Number       | OFFICE-98521234       |
| Email Address        | NOEMAIL               |

|   |                           |
|---|---------------------------|
| Address   | 167 PETIR ROSD<br>#11-134 |
| Postcode  | S670167                   |
| Was driver an employee of the Insured's Company     | NO                        |
| If No, Relationship of the Driver with the Insured  | CHILDREN                  |
| Vehicle Registration Number of Driver's Own Vehicle | -                         |
|   | -                         |
|   | -                         |
| Insurance Company of Driver's Own Vehicle           | -                         |
|   | -                         |
|   | -                         |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |                               |
|---|-------------------------------|
| Was any foreign vehicle involved in this accident?  | NO                            |
| Number of vehicles involved in the accident   |                               |
| Was any body injured in the Accident?   | YES                           |
| Was any injured conveyed to hospital by ambulance?  | YES                           |
| Was any other material or property damaged?   | YES                           |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                            |
| Number of Passengers (Including Driver)   | 2                             |
| Passenger 1   | NAME: : -<br>GENDER: : FEMALE |

#### Details of Police Action

|   |   |
|---|---|
| Was the accident reported to the police?  | YES   |
| If Yes, Please state which Police Station |   |
| Police Station Name                       | BUKIT TIMAH NEIGHBOURHOOD POLICE POST   |
| Police Station Address                    | <b>ROAD:</b> BLK 1 TOH YI DRIVE , <b>POSTCODE:</b> 590001 , <b>COUNTRY:</b> SINGAPORE |
| Police Station Contact                    | <b>TEL NO:</b> 1800-4689999 - <b>FAX NO:</b> 64623782                                 |
| Was notice of intended Prosecution given? | NO  |
| If Yes, against whom?                     |   |

#### Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT

#### Attachment(s)

|   |             |
|---|-------------|
| Are accident photos available for attachment? | YES         |
| Was there any video captured by Car Camera?   | YES         |
| Remarks/ Reasons:                             | TAKEN BY TP |
| Was there any audio recorded?                 | NO          |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |            |
|-----------------------------|------------|
| Vehicle Registration Number | FBM3574Z   |
| Vehicle Make/Model/Colour   | M/CYCLE    |
| Details Of Properties       |            |
| Vehicle Category            | MOTORCYCLE |
| Name of Driver              | MR NG      |
| NRIC/Passport Number        |            |
| Contact Number              | 87800884   |

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

RIDER

Approximate Age

Injuries Sustain

REFER TO POLICE REPORT

Injured person in which vehicle?

FBM3574Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time: :



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

10 DEC 2018

IDAC BUKIT BATOK (VAC)  
511 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







**SINGAPORE  
POLICE FORCE**



T/20181210/2065

Police Station Of Origin:  
Bukit Timah NPP  
1 Toh Yi Drive #01-139 SINGAPORE 591501  
Tel No: 1800-4689999

2 of 4

Report No. T/20181210/2065

## CONTINUATION OF REPORT

| Details of Person Involved        |                |  |                                   |
|-----------------------------------|----------------|--|-----------------------------------|
| Any Pedestrian Involved: No       |                |  |                                   |
| No. of Pedestrians Injured: NIL   |                | Use of Pedestrian Crossing: NA         |                                   |
| Driver                            |                |  |                                   |
| Name                              | CHAI CHON YEN  | ID No.                                 | S2017976G                         |
| Related Vehicle                   | SCV1234J (Car) | Contact No.                            | 98521234                          |
| Hospital/Clinic                   | NIL            | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL   |
| Date Treatment                    | NIL            | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL            | Degree of Injury                       | NIL                               |
| Passenger                         |                |  |                                   |
| Name                              | LEW MOY FAH    | ID No.                                 | S2118835B                         |
| Related Vehicle                   | SCV1234J (Car) | Contact No.                            | 96871234                          |
| Hospital/Clinic                   | NIL            | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL            | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL            | Degree of Injury                       | NIL                               |

**Brief Details.**

On 10/12/2018 at about 1005hrs, I was driving my car SCV1234J and was travelled along Bukit Batok East Ave 6 towards junction of Bukit Batok East Ave 2. As I approaching to the said junction, my car was on the 2nd lane from the right of 3 lanes. There was a road work on the 1st lane and controlled by the cisco officer. As my car was near to the said junction, suddenly there was a vehicle in front of me jammed brake and I also braked, after which I felt an impact from the left rear. I then stepped out from my car to check and discovered a rider with a motorcycle FBM3574Z fell to the ground. I observed the rider was injured at his right hand was bleeding and he was conscious. Someone called for the ambulance.

Shortly, the ambulance and traffic police came to the incident location. After the paramedic render treatment to the rider and conveyed the rider to the hospital (unknown).

I wish to state that I only managed to take down the rider particular namely Mr Ng HP: 87800884.

I did not managed to take down the in front vehicle number who caused the jammed out sudden when the traffic light was green.

I also wish to state that my wife and I were not injured.

The traffic police handle the incident and my memory card was seized by the traffic police officer at the scene for camera footage purpose.



**SINGAPORE  
POLICE FORCE**



T/20181210/2065

Police Station Of Origin:  
Bukit Timah NPP  
1 Toh Yi Drive #01-139 SINGAPORE 591501  
Tel No: 1800-4689999

3 of 4

Report No. T/20181210/2065

**CONTINUATION OF REPORT**

The incident number is J/20181210/0069 in-charge TP IO Ridzwan.

I was advised by the traffic police officer to make a traffic police report at any police station.



**SINGAPORE  
POLICE FORCE**



T/20181210/2065

Police Station Of Origin:  
Bukit Timah NPP  
1 Toh Yi Drive #01-139 SINGAPORE 591501  
Tel No: 1800-4689999

4 of 4

Report No. T/20181210/2065

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

|   |
|---|
| Signature Of Officer Recording The Report:<br>D /<br>Sgt 3 ZAMBREE BIN SA'AT                            |
| Signature Of Interpreter:<br>Not applicable   |
| Officer In Charge Of Case:<br>TP / GIT /<br>Sgt 3 MUHAMMAD RIZWAN/BIN KAMALUDIN<br>Contact No: 65476185 |

|                                |
|--------------------------------|
| Signature Of Informant:        |
| Date/Time:<br>10/12/2018 13:46 |
| Classification Of Case:        |

SINGAPORE  
Authentication Stamp  
NP168

SM 33

SIGNATURE

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |             |   |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 12 Dec 2018<br><a href="#">Edit Reg</a> |               | 11 Dec 2018<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference  | Claim Details          | Documents  | Show All |         |             |              |            |       |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>   |  |                        |  |          |         |             |              |            |       |
| Insured:  | <b>Ng Tzin Pern Darryl</b> , ID: S8719427B   |                        |  |          |         |             |              |            |       |
| Main Claimant:  | <b>CHIA HUEL LENG</b> , ID: S7208572H  |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SCV1234J</b>  | Date of Loss:          | 10/12/2018 00:00 - :59<br>[62 Months and 15 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | <b>TP / 1201800018220</b>  | Policy/Cover Note No.: | PNMC2018-00004412  |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>FBM3574Z</b>  | Policy No. (Claimant): |  |          |         |             |              |            |       |
|   |  | Excess:                |  |          |         |             |              |            |       |
| Repairer:   | <b>Kim Service Station (HQ)</b> 4 SUNGEI KADUT AVENUE, 729641 Sungei Kadut - Tel: 9383 9008                                    |                        |  |          |         |             |              |            |       |
| Handling Insurer:   | <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Josey Loh</b> ]  |                        |  |          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 21/12/2018] |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |  |                        |  |          |         |             |              |            |       |
| There are no mail for this case.  |  |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |  |                        |  |          |         |             |              |            |       |
| Due Date  | Priority   | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |  |                        |  |          |         |             |              |            |       |

## Claim Documents

\*SCV1234J (1201800018220)  
 [FBM3574Z]  
 TP  
 CHIA HUEL LENG  
 Dec 10 2018 12:00AM  
 [Ng Tzin Pern Darryl]  
 Kim Service Station

| Upload Documents     |                 | Upload Photos                     |  | Compose New Letter |  | View <input type="button" value="View in Browser"/>  |                                     |                                     |
|----------------------|-----------------|-----------------------------------|--|--------------------|--|--|-------------------------------------|-------------------------------------|
| <b>Photos/Images</b> |                 |                                   |  |                    |  |  | 3 per page                          | <input checked="" type="checkbox"/> |
| No                   | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  |                    |  | Thumbnail  | Print                               |                                     |
| 1                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 2                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 3                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 4                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 5                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 6                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 7                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 8                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 9                    | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |                                     |
| 10                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 11                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 12                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 13                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 14                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 15                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 16                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 17                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 18                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 19                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 20                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 21                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 22                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 23                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 24                   | 12/12/18 14:06  | General View                      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 25                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 26                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 27                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 28                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 29                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 30                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 31                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 32                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 33                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 34                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 35                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 36                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |
| 37                   | 17/12/18 13:20  | Photographs of Damaged Parts      |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |                                     |

| Photos/Images |                 |                                   | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 38            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 39            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 40            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 41            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 17/12/18 13:20  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |

| Documentation |                |                              | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|------------------------------|------------|-------------------------------------|
| No            | Finalized On   | FWD Singapore Pte. Ltd. (HQ) | Thumbnail  | Print                               |
| 1             | 21/12/18 12:18 | PH GIA                       | Load PDF   |                                     |

### Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>   |       |      |       |
| <div style="border: 1px solid black; padding: 5px;"> <div style="border: 1px solid black; height: 30px; width: 100%;"></div> </div>                |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/FWD18022347/JCD3E2  
**Date:** 31/12/2018

#### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2018-00004412  
**Claimant Vehicle No :** SCV1234J **Insured Vehicle No :** FBM3574Z  
 Date of Loss: 10/12/2018 Nature of Claim: TP Claim No: 1201800018220

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCV1234J**  
 Make & Model: MERCEDES-BENZ CLA200, 1.6 (R18) (A) Engine No: 27091030209551  
 Reg. Date: 25/09/2013 (Man. Year: 2013) Chassis No: WDD1173432N022258  
 Colour: White Odometer: 107709 km  
 Engine Capacity: 1595 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

#### INSPECTION

Date of Assignment: 11/12/2018  
 Date Inspected: 12/12/2018 Inspected At: Kim Service Station (HQ)  
 4 SUNGEI KADUT AVENUE  
 Singapore 729641  
 Estimated Period of Repair: 5.0 days

**Adjuster:** ONG HWEE JIE

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,800.00 -\$6,000.00

## REPAIR DETAILS

### Reference

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 31 Dec 2018)  |
| <b>Parts:</b> 143          | MERCEDES-BENZ CLA200 1.6 (R18) (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SCV1234J)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >