

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: e-mail only

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI: BULK

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: DO FORM

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 146

SS 6,350.00 (9 days) Reduction: 53 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 24/08/19

Confirm with: LC

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. 1 is:

Repair Cost:

SS 6,350.00

COIP Kante-bayad TP

Loss of Rental (LOR):

SS 1,500.00 (10 days) X \$150.00

Loss of Use (LOU):

SS - (\$ x days)

Loss of Income (LOI):

SS - (\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS -

(e.g. Tow/Independent)

2) Report Format:

Legal Cost

SS -

3) Survey fee: \$350.00

Total:

SS 7,857.45

Global Sum SS: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 7,857.45

Name 1:

GUAN HIN MOTOR WORKSHOP

Payee 2: (Strike if N/A)

SS -

Name 2:

Payee 3: (Strike if N/A)

SS -

Name 3:

ASS. REC. BY:

REF:

AAA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

832k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Soon:

Consistent?: Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/12

File pass to Carphone, GIA not ready
Workshop don't agree on rate less 50% on 6/Rep.
L/G 26,350.00
CRSD: 27,220.00 (68%)

Veh No:

SJC 1186G

Yr Regn:

01, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

c.c.

1.794

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

125276

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

7NE10

0384038

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / Std Rim / STD A/Rim or

Tyre Size:

F:

215/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

11/12/18

D.O.I.

12/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Parking

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Kh

GUAN HIN MOTOR WORKSHOP

Page 1 / 2

NO 10 ANG MO KIO INDUSTRIAL PARK 2A
#02-03 AMK AUTOPOINT 568047
Tel No. : 64837111 Fax No. : 64837221
E-Mail : guanhinmotor@yahoo.com
Buss. Reg. No. : 06035200X

ISMATH EUNOON

Attention : Motor Claim Department

Not Authorised
1/12/18 8 6350h
Remy After Pain
9 days

Estimate : ES000844

Date : 11/12/2018
Vehicle Num. : SJC 1186 G
Make/Model : TOYOTA WISH 1.8-2007
Chassis/Eng# : ZNE100384038/1ZZ2978610
Accident Date : 11/12/2018
Claim No. :
Reference :
Policy No. : (31/01/2008)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS		
2.	2	REAR BOOT LID		
3.	2	REAR BOOT LID HINGE	80.00	
4.	1	REAR BOOT DAMPER	105.00	
5.	1	REAR BOOT INNER TRIM BOARD TOP		
6.	1	REAR BOOT INNER TRIM BOARD LOWER		
7.	1	REAR BOOT LOCK		
8.	1	REAR BOOT HANDLE		
9.	1	REAR BOOT EMBLEM		
10.	1	REAR WIPER MOTOR		
11.	1	REAR WIPER ARM		
12.	1	REAR WIPER BLADE		
13.	2	REAR WIPER BLADE COVER		
14.	1	REAR NO PLATE LAMP	70.00	
15.	1	REAR LH FENDER		
16.	1	REAR LH FENDER INNER TRIM BOARD		
17.	1	REAR WEALTHSTRIP		
18.	1	LH TAIL LAMP		
19.	1	REAR END PANEL (INNER)		
20.	1	REAR END PANEL REINFORCEMENT		
21.	1	REAR END PANEL GARNISH		
22.	1	REAR BUMPER		
23.	1	REAR BUMPER SIDE RETAINER LH		
24.	1	REAR BUMPER REFLECTOR		
25.	2	REAR FENDER SHIELD		
26.	1	REAR BUMPER BRACKET		
27.	1	REAR WINDSCREEN		
		REAR WINDSCREEN MOULDING		

List Total S\$:

SPECIAL NETT ITEMS :
REVERSER SENSOR

1. 1

1,273.30
160.00
210.00
205.00
350.00
57.00
165.00
25.00
170.00
140.00
45.00
15.00
140.00
859.00
230.00
311.30
605.00
519.80
230.00
605.00
490.20
50.00
56.50
95.00
100.00
913.50
60.00
8,080.60
200.00
350.00

CONTINUE / ...

LHK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

GUAN HIN MOTOR WORKSHOP

Page 2 / 2

NO 10 ANG MO KIO INDUSTRIAL PARK 2A
#02-03 AMK AUTOPOINT 568047
Tel No. : 64837111 Fax No. : 64837221
E-Mail : guanhinmotor@yahoo.com
Buss. Reg. No. : 05035200X

ISMATH EUNOON

Attention : Motor Claim Department

Estimate : ES000844

Date : 11/12/2018
Vehicle Num. : SJC 1186 G
Make/Model : TOYOTA WISH 1.8-2007
Chassis/Eng# : ZNE100384038/1ZZ2978610
Accident Date : 11/12/2018
Claim No. :
Reference :
Policy No. : (31/01/2008)

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REAR WINDSCREEN SEALANT		50.00
3.	1	VIEW CAMERA	395.65	250.00
		Special Nett Total S\$:		650.00
		LABOUR :		
		LABOUR CHARGE FOR CUTTING & WELDING REAR END PANEL, STRAIGHTEN REAR CHASSIS ,FLOOR BOARD REPAIRING WHEEL-HOUSE AND REPLACEMENT OF PARTS		2,500.00
		REMOVE & FIX BACK CUSHION & UPHOLSTERY		150.00
		REMOVE & FIX BACK FENDER WINDSCREEN AND FIXING REAR BOOT WINDSCREEN		280.00
		TO SPRAY PAINTING		1,200.00
		TO CHECK REAR LIGHTING ,THIRD BRAKE LIGHT WIRING		80.00
		TO REMOVE & INSTALL REAR TAILGATE LOCK ANTI RUST PROOFING ACCIDENT AFFECTED AREA		60.00
		TO REMOVE AND REFIX REAR BOOT ACCESS		200.00
		TO REMOVE & INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR		100.00
		TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOT LID,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE		180.00
		REMOVE & FIX BACK REAR REVERSE SENSOR		120.00
		Labour Total S\$:		5,050.00

E & O E

Total S\$: 13,780.60

for GUAN HIN MOTOR WORKSHOP

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7022J
Vehicle Details	
Vehicle No.:	SJC1186G
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	1ZZ2978610
Chassis No.:	ZNE100384038
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,313.00
Original Registration Date:	31 Jan 2008
First Registration Date:	31 Jan 2008
Transfer Count:	2
Actual ARF Paid:	\$17,945.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jan 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,136.00
COE Rebate Amount:	\$21,583.00
Total Rebate Amount:	\$21,583.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Dec 2018

OK

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

ISMATH EUNOON

Attention : Motor Claim Department

*Not Notarised**1/18/8?**Recovery After Point
9 days*

Estimate : ES000844

Date : 11/12/2018

Vehicle Num. : SJC 1186 G

Make/Model : TOYOTA WISH 1.8-2007

Chassis/Eng# : ZNE100384038/1ZZ2978610

Accident Date : 11/12/2018

Claim No. :

Reference :

Policy No. : (31/01/2008)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :		
1.	1	REAR BOOT LID		
2.	2	REAR BOOT LID HINGE		
3.	2	REAR BOOT DAMPER		
4.	1	REAR BOOT INNER TRIM BOARD TOP		
5.	1	REAR BOOT INNER TRIM BOARD LOWER		
6.	1	REAR BOOT LOCK		
7.	1	REAR BOOT HANDLE		
8.	1	REAR BOOT EMBLEM		
9.	1	REAR WIPER MOTOR		
10.	1	REAR WIPER ARM		
11.	1	REAR WIPER BLADE		
12.	1	REAR WIPER BLADE COVER		
13.	2	REAR NO PLATE LAMP		
14.	1	REAR LH FENDER		
15.	1	REAR LH FENDER INNER TRIM BOARD		
16.	1	REAR WEALTHSTRIP		
17.	1	LH TAIL LAMP		
18.	1	REAR END PANEL (INNER)		
19.	1	REAR END PANEL REINFORCEMENT <i>inner</i>		
20.	1	REAR END PANEL GARNISH		
21.	1	REAR BUMPER		
22.	1	REAR BUMPER SIDE RETAINER L/H		
23.	1	REAR BUMPER REFLECTOR		
24.	1	REAR FENDER SHIELD		
25.	2	REAR BUMPER BRACKET		
26.	1	REAR WINDSCREEN		
27.	1	REAR WINDSCREEN MOULDING		

List Total S\$:

SPECIAL NETT ITEMS :
REVERSER SENSOR

1. 1

	<i>B1</i>	1,273.30	✓
80.00	<i>R</i>	160.00	X
105.00	<i>R</i>	210.00	X
		205.00	?
	<i>D1</i>	350.00	✓
	<i>Red</i>	57.00	✓
	<i>CM</i>	165.00	✓
	<i>R</i>	25.00	✓
		170.00	?
	<i>R</i>	140.00	X
	<i>R</i>	45.00	X
	<i>R</i>	15.00	X
70.00	<i>R</i>	140.00	X
	<i>R</i>	859.00	✓
	<i>CM</i>	230.00	✓
	<i>Red Lt</i>	311.30	50% ✓
	<i>CR</i>	605.00	✓
	<i>R</i>	519.80	✓
	<i>R</i>	230.00	✓
	<i>R</i>	605.00	✓
	<i>CM</i>	490.20	✓
	<i>D1</i>	50.00	✓
	<i>CM</i>	56.50	✓
	<i>R</i>	95.00	X
50.00		100.00	?
	<i>Section</i>	913.50	✓
	<i>R</i>	60.00	✓

8,080.60

*200%
R* 350.00

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

ISMATH EUNOON

Estimate : ES000844

Date : 11/12/2018

Vehicle Num. : SJC 1186 G

Make/Model : TOYOTA WISH 1.8-2007

Chassis/Eng# : ZNE100384038/1ZZ2978610

Accident Date : 11/12/2018

Claim No. :

Reference :

Policy No. : (31/01/2008)

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REAR WINDSCREEN SEALANT		50.00
3.	1	VIEW CAMERA		250.00
		Special Nett Total S\$:		650.00
		LABOUR :		
		LABOUR CHARGE FOR CUTTING & WELDING REAR END PANEL,		1400
		STRAIGHTEN REAR CHASSIS ,FLOOR BOARD		2,500.00
		REPAIRING WHEEL-HOUSE AND REPLACEMENT OF		
		PARTS		
		REMOVE & FIX BACK CUSHION & UPHOLSTERY		150.00
		REMOVE & FIX BACK FENDER WINDSCREEN AND FIXING REAR		280.00
		BOOT WINDSCREEN		180.00
		TO SPRAY PAINTING		1000
		TO CHECK REAR LIGHTING ,THIRD BRAKE LIGHT WIRING		80.00
		TO REMOVE & INSTALL REAR TAILGATE LOCK		60.00
		ANTI RUST PROOFING ACCIDENT AFFECTED AREA		200.00
		TO REMOVE AND REFIX REAR BOOT ACCESS		100.00
		TO REMOVE & INSTALL REAR INNER GARNISH AND TRIM TO		180.00
		FACILITATE THE REPAIR		
		TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOT		120.00
		LID,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND		
		WATER SEEPAGE		
		REMOVE & FIX BACK REAR REVERSE SENSOR		180.00
		Labour Total S\$:		5,050.00
		E. & O.E.	Total S\$:	13,780.60

for GUAN HIN MOTOR WORKSHOP



Re:<MANDATE IA> S8M0169U

Type

🔗 Question

Message

Approved

Reply

ISMATH EUNOON
C/O 10 ANG MO KIO IND. PARK 2A
#02-03 AMK AUTOPOINT
SINGAPORE 568047

13/3/2019

YOUR REF: PA8481Y

M/S AXA LIFE INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Attn: MOTOR CLAIMS DEPARTMENT

VEHICLE REPAIR CHARGES DUE TO ACCIDENT

I would like to inform you that my vehicle SJC1186G
was involved in an accident with PA8481Y
on 11/12/2018 has been repaired.

The charges for the repair caused are as following :

1	Final Repair Bill		\$	6,350.00
2	LTA Search Fee		\$	7.45
3	Rental	<u>10DAYS X@150</u>	\$	<u>1,500.00</u>
			\$	<u><u>7,857.45</u></u>

Yours faithfully.



Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 2 May 2019 11:55 AM
To: alexng@kimsingapore.com.sg
Subject: ACCIDENT INVOLVING PA8481Y AND SJC1186H ALONG BEACH ROAD TOWARDS JAVA ROAD ON 11/12/2018 [YOUR DRIVER: TEO HAN SOON]

KIM TRANSPORT SOLUTIONS PTE LTD
48 TOH GUAN RD EAST
#05-97
ENTERPRISE HUB
SINGAPORE 608586

Attn: Mr. Alex Ng

Dear Sir/Madam,

OUR REF : CC4/ASM18022354/Kha3
YOUR REF : PA8481Y
ACCIDENT INVOLVING PA8481Y [AXA] AND SJC1186H ALONG BEACH ROAD TOWARDS JAVA ROAD ON 11/12/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/S GUAN HIN MOTOR WORKSHOP, acting on behalf of the owner of **SJC1186H** against your motor insurance policy.

Based on the accident report and accident scenario, we are of the opinion that this is a conflicting version based on words against each driver unless one can prove otherwise.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

There is an excess of **\$ 1,500.00** on Third Party claims under your policy. Please make a cheque payment of **\$ 1,500.00** payable to "AXA Insurance Singapore Pte Ltd" with your vehicle registration number and the date of accident indicated on the back of your cheque and mail to AXA Insurance Singapore Pte Ltd.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to khanchna@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorization Letter for the Driver to drive the vehicle

- Driver's Vocational license
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at khanchna@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

ISMATH EUNOON
BLK 10 ANG MO KIO IND, PARK 2A
#02-03
SINGAPORE 568047

18/12/2018

YOUR REF:PA8481Y

M/S AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01
Singapore 068811

ATTN: MOTOR CLAIM DEPARTMENT

Dear Sir/Mdm,

Re: Traffic accident on 11/12/2018 involving vehicle SJC1186G AND PA8481Y

I hereby authorise my claims payment direct issue to my repairer name:

GUAN HIN MOTOR WORKSHOP
10 ANG MO KIO IND PARK 2A
#02-03 AMK AUTOPOINT
SINGAPORE 568047


signature of vehicle owner



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	PA8481Y (Insd veh)	Model: <u>Toyota wish - 1794cc</u>
	SJC1186G (TP veh)	
Date of Accident/ Time:	11/12/2018 @ 1125HRS	

Repair Estimate	: \$	<u>12,380.00</u>	
Final Repair Cost	: \$	<u>6,350.00</u>	
Loss of Use	: \$		days at \$ per day
Rental (if any)	: \$	<u>1,500.00</u>	10 days at \$ 150 per day
LTA / GIA Search Fee	: \$	<u>7.45</u>	
Others:	: \$		
Final Settlement Sum	: \$	<u>7,857.45</u>	
Payee Name: <u>GUAN HIN MOTOR WORKSHOP</u>			
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability <u>100</u> (%)	
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____	
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			



NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All documents are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are *not received within 7 days* of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and/or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 Signature of workshop representative / Workshop stamp Name of Representative: <u>L. C. Ng</u> Date: <u>24/5/2019</u>	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: _____ Date: <u>24/5/19</u>
 Signature of AXA's surveyor/Representative: Name of AXA's surveyor/Representative: _____ Date: <u>28/5/19</u>	

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

ISMATH EUNOON

BLK 309B ANCHORVALE ROAD

#04-65 SINGAPORE 542309

Attention : Motor Claim Department

Contact : 81013135

Final Repair Bill : TI043244

Date : 21/12/2018

Vehicle Num. : SJC 1186 G

Make/Model : TOYOTA WISH 1.8-2007

Chassis/Eng# : ZNE100384038/1ZZ2978610

Accident Date : 11/12/2018

Claim No. :

Reference :

Policy No. : (31/01/2008)

Amount S\$

LUMPSUM REPAIR

6,350.00

E. & O.E.

Total S\$:

6,350.00



for GUAN HIN MOTOR WORKSHOP

B 萬豐利汽車服務

BAN HONG LEE MOTOR SERVICES

Blk 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)
Singapore 569538 Tel: 6482 5577 (3 Lines) Fax: 6482 5000
Reg. No: 263102/00M
TOWING SERVICE: 6058 4067 (After 10.30pm)

Truck Rental
Motor Repair
Motor Insurance Claims
Insurance Agent
Dealer in Used Car
Authorised Control Service Centre

命甲及羅羅出租
汽車修理
保險服務
代運保險
買賣汽車
維修服務中心



車輛出租合同 VEHICLE RENTAL AGREEMENT

Date: 11/12/18
Owner: BAN HONG LEE MOTOR SERVICES ("the owner")
Hirer: ISMATH EUNOON
Address: BLK 309B ANCHORVALE ROAD #104-65 S 542309
NRIC / Co. Reg. No: S7427022J
Tel: Fax: H/P: 81015135

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle, described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SKU4167K		Agreement No.: 139570	
Driver's Particulars		Odometer: _____	
Name: _____		Date & Time Out: 11/12/18 12:45PM	
Address: _____		Date & Time In: 24/12/18 9:30A	
VC No: _____	Dr/Licence No: _____	Hour @\$ _____	
of Issue: _____	Occupation: _____	10 Days @\$ 150 ✓	
Date of Birth: _____	Tools: Old	Wks @\$ _____	
	Spare Tyre: New	Mths @\$ _____	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive), Hirer unconditionally agrees to pay Owner S\$ 5000/ ✓ comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first \$ 3000/ ✓ excess for collision/damage to first party, (i.e.) BAN HONG LEE MOTOR SERVICES (including windscreen) plus loss of earning while damaged vehicle is under repair.

Authorised Driver

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable): _____

Sub-Total: _____

Balance To Pay: 81500/ ✓

PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

BAN HONG LEE MOTOR SERVICES

Authorised Signature

Hirer's Signature

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 11 Dec 2018 / 15:22:52

Receipt Date/Time : 11 Dec 2018 / 15:22:52

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181211-002123

Previous Receipt No. :

S/N Item Description/

Business Transaction Reference

No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - PA8481Y

As at 11 Dec 2018/11:25:00

Insurance Co: AXA INSURANCE PTE LTD

1 Insurance Enquiry - PA8481Y

Enquiry Fee

20181211152202193693

7.00 0.49 7.49

Sub-Total 7.00 0.49 7.49

Total Before Rounding 7.00 0.49 7.49

Rounding Difference 0.04

Total Amount Payable 7.45

Paid By

20181211152219790	Direct Debit: eNETS Debit (Internet Banking)	7.45
-------------------	---	------

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	PA 8481Y (Insd veh)	Model:	TOYOTA WISH (A)
	SJC 1186G (TP veh)		
Date of Accident:	11/12/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	13,780.60
Final Repair Cost	:	\$	6,350.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,500.00 10 days
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	7,857.45

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ___ 100 ___ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____ _____			

Payment Instruction: Payee's Breakdown			
1)	GUAN HIN MOTOR WORKSHOP	:	\$ 7,857.45

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

14/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18022354/Kha3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH			Date : 14-06-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PA 8481Y	Veh. Inspected	SJC 1186G	
Policy No.	P1927356	Coverage (\$)	0.00	
Claim No.	S8M0169U	Excess (\$)	0.00	
Assign From		Assign Date	12/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	ZNE100384038	Colour	METALLIC DARK WHITE	
Odometer	125276	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45Z R17	DUNLOP	7 mm	
L/H Front Tyre	215/45Z R17	DUNLOP	7 mm	
R/H Rear Tyre	215/45Z R17	DUNLOP	7 mm	
L/H Rear Tyre	215/45Z R17	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2018	Inspection Date	12/12/2018	
Survey held at	GUAN HIN MOTOR WORKSHOP BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 1186G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID (CONSISTENT)	BENT	1,273.30	1,273.30
2	REAR BOOT LID HINGE @\$80.00 (CONSISTENT)	TO REPAIR SEE LABOUR	160.00	-
2	REAR BOOT DAMPER @\$105.00 (CONSISTENT)	SERVICEABLE	210.00	-
1	REAR BOOT INNER TRIM BOARD TOP (CONSISTENT)	SERVICEABLE	205.00	-
1	REAR BOOT INNER TRIM BOARD LOWER (CONSISTENT)	DISTORTED	350.00	350.00
1	REAR BOOT LOCK (CONSISTENT)	DENTED	57.00	57.00
1	REAR BOOT HANDLE (CONSISTENT)	CRACKED	165.00	165.00
1	REAR BOOT EMBLEM (CONSISTENT)	NECESSARY	25.00	25.00
1	REAR WIPER MOTOR (CONSISTENT)	SERVICEABLE	170.00	-
1	REAR WIPER ARM (CONSISTENT)	SERVICEABLE	140.00	-
1	REAR WIPER BLADE (CONSISTENT)	SERVICEABLE	45.00	-
1	REAR WIPER BLADE COVER (CONSISTENT)	SERVICEABLE	15.00	-
2	REAR NO PLATE LAMP @\$70.00 (CONSISTENT)	SERVICEABLE	140.00	-
1	REAR LH FENDER (CONSISTENT)	BUCKLED	859.00	859.00
1	REAR LH FENDER INNER TRIM BOARD (CONSISTENT)	CRACKED	230.00	230.00
1	LH TAIL LAMP (CONSISTENT)	CRACKED	605.00	387.40
1	REAR END PANEL (CONSISTENT)	BENT	519.80	519.80
1	REAR END PANEL INNER (CONSISTENT)	BENT	230.00	230.00
1	REAR END PANEL GARNISH (CONSISTENT)	BUCKLED	605.00	374.45
1	REAR BUMPER (CONSISTENT)	CRACKED	490.20	490.20
1	REAR BUMPER SIDE RETAINER L/H (CONSISTENT)	DISTORTED	50.00	50.00
1	REAR BUMPER REFLECTOR (CONSISTENT)	CRACKED	56.50	56.50
1	REAR FENDER SHIELD (CONSISTENT)	SERVICEABLE	95.00	-
2	REAR BUMPER BRACKET @\$50.00 (CONSISTENT)	TO REPAIR SEE LABOUR	100.00	-
1	REAR WINDSCREEN (CONSISTENT)	SHATTERED	913.50	913.50
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	60.00	60.00
	LESS 25% DISCOUNT		-	-1,510.29
			7,769.30	4,530.86

Report Ref No. CC4/ASM18022354/Kha3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WEALTHSTRIP (CONSISTENT) (SN) (50%)	DENTED / CUT	311.30	155.65
1	REVERSE SENSOR (SN)(CONSISTENT)	DENTED	350.00	200.00
1	REAR WINDSCREEN SEALANT (SN)(CONSISTENT)	NECESSARY	50.00	40.00
1	VIEW CAMERA (SN)(CONSISTENT)	SERVICEABLE	250.00	-
			961.30	395.65
	<u>LABOUR</u>			
	LABOUR CHARGE FOR CUTTING & WELDING REAR END PANEL, STRAIGHTEN REAR CHASSIS, FLOOR BOARD REPAIRING WHEEL-HOUSE AND REPLACEMENT OF PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT LID HINGE AND REAR BUMPER BRACKET .		2,500.00	1,400.00
	REMOVE & FIX BACK CUSHION & UPHOLSTERY.)		150.00	100.00
	TO REMOVE & INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.)		180.00	-
	REMOVE & FIX BACK FENDER WINDSCREEN AND FIXING REAR BOOT WINDSCREEN.		280.00	180.00
	TO SPRAY PAINTING.		1,200.00	1,000.00
	TO CHECK REAR LIGHTING ,THIRD BRAKE LIGHT WIRING.		80.00	20.00
	TO REMOVE & INSTALL REAR TAILGATE LOCK.		60.00	60.00
	ANTI RUST PROOFING ACCIDENT AFFECTED AREA.		200.00	90.00
	TO REMOVE AND REFIX REAR BOOT ACCESS.		100.00	60.00
	TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOT LID ,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.		120.00	60.00
	REMOVE & FIX BACK REAR REVERSE SENSOR .		180.00	50.00
			5,050.00	3,020.00
	GRAND TOTAL		13,780.60	7,946.51
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,350.00

Report Ref No. CC4/ASM18022354/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S0M0169U
Reference	CC4/ASM18022254/K0A3qZ
Loss Date	11 December 2018
Report Date	12 Dec 2018 8:51:04 AM
Request Date	30 May 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Print Invoice

Vehicle Information	
Incident Vehicle Registration #	SJC1186G
Make	TPWD
Model	TOYOTA
Service Address	

Primary Contact/Insured

KIM TRANSPORT SOLUTIONS PTE LTD
48 TOH GUAN ROAD EAST, #05-97 ENTERPRISE HUB, 608586, Singapore
62701311

Claim Handler

KH HONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

NON REPORTED

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Martine	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LUKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LKKAdj(adjustment).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
TP ESTIMATE - MARKED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
TP LOI.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
LKK REINSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
EMAIL TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 MANDATE VA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
 Vocational Licence Status.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 OLD DL VL.pdf	Forms / Claim Documents	Driver's License / IDP	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 REPLY FROM WORKSHOP.png	Forms / Claim Documents	Others	KUMAR Shalindra	12 December 2018
 PRI FROM WORKSHOP.png	Forms / Claim Documents	Others	KUMAR Shalindra	12 December 2018
 TP GUA REPORT PDF	Reports & Statement	GIA Report	LOH Cynthia	12 December 2018
 P1927356_EN_00007_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	LOH Cynthia	12 December 2018
 P1927356_CI_00007_0001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	LOH Cynthia	12 December 2018