

LKK:
IDAC

Surveyor:

DOI:

Date / Time : _____

Registered in Merimex:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age: Wong Y1 Wuen (Hoi Y1 Wuen)

Driver Tel No. :

(V/L: YES/NO)

Claim No.

Policy No.

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :	%	Final ? Yes / No
1. General Liability		
2. Professional Liability		
3. Directors and Officers Liability		
4. Employment Practices Liability		
5. Fidelity and Bonding		
6. Commercial Automobile		
7. Marine		
8. Aviation		
9. Umbrella		
10. Other		



INSRS:
WSP:
Tel :
Liability
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
10/11/18	Non-Reporting ltr (1st):	
11/11/18	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
01.12.19	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
PRELIMINARY ADVICE	Date/Time:	Post-Repair Photos: <input checked="" type="checkbox"/> <input type="checkbox"/>
	Sent By:	Others: <input type="checkbox"/> <input type="checkbox"/>

FINALIZATION		Date/Time: 4/2/19	Confirm with: SUSAN	Confirm by: CES
Repair Cost:	\$6,650	(7 days) Reduction:	84 %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time: 2-04-19	Confirm with: SUSAN	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	36	If NO or B 28, Ass. Lia :
Repair Cost:	\$6,650.00	DID NOT CORRECT TIR TP.		
Loss of Rental (LOR):	\$ -	(days)		
Loss of Use (LOU):	\$ 720.00	(\$ 80 x 9 days)		
Loss of Income (LOI):	\$ -	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	\$ 2.00			
Medical:	\$ -	1) Claim status: Normal/Reject/Private Settle		
Disbursement:	\$ -	(e.g. Tow/ Independent)	2) Report Format:	
Legal Cost	\$ -	3) Survey fee:		
Total:	\$ 7,372.00	Global Sum \$:		
FINAL PAYMENT		Date/Time: 12-04-19	Confirm with: SUSAN	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$ 7,372.00	Name 1:	Liu's BROTHER AUTO ENGINEERING WORKSHOP	
Payee 2: (Strike if N.A.)	\$ -	Name 2:		
Payee 3: (Strike if N.A.)	\$ -	Name 3:		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18022362/Ueb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 12-12-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 4773G	Veh. Inspected	GBE 7685C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/11/2018	Inspection Date	12/12/2018	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7685C181122

Estimate

Customer

Name: Lompac Insurance Berhad

Address: Motor Claims Department

300 Beach Road #17-04 / 07

The Concourse

Singapore 199555

Date:

11-12-18

Vehicle No: GBE7685C

Model/Make: Toyota Hiace

Van Turbo 5

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front h Bonnet	\$ 872.90	
2	Bonnet "Toyota" Motif	\$ 75.00	
3	Bonnet Hinge 02 pcs (@ S\$295.30)	\$ 590.60	X
4	Head Lamp	\$ 930.70	X
5	Head Lamp clips 1 set	\$ 65.00	X
6	Head Lamp Cover Garnish (Accessories)	\$ 180.00	X
7	Bumper	\$ 796.80	X
8	Bumper Clips 1 set	\$ 50.00	X
9	Bumper Beam	\$ 409.10	X
10	Bumper Lower Skirting (Spoiler)	\$ 580.00	X
11	Bumper Side Holder	\$ 139.00	X
12	Corner Panel	\$ 376.50	X
13	Door	\$ 1,632.50	X
14	Door Hinges 02 pcs (@ S\$115.00)	\$ 230.00	X
15	Door Checker	\$ 152.00	X
16	Door Rubber	\$ 245.70	X
17	Door Outer Pillar	\$ 622.60	X
18	Door Inner Lock	\$ 554.40	X
19	Door View Mirror	\$ 1,142.80	X
20	Door Outer Carbon Garnish (Accessories)	\$ 450.00	X
21	Door Outer Handle Lower Carbon Garnish (Accessories)	\$ 180.00	X
22	Door Visor	\$ 120.00	X
23	Door Wire Harness	\$ 269.20	X
24	Door Inner Trim Board	\$ 645.10	X
25	Door Inner Trim Board Clips 1 set	\$ 52.00	X
26	Door "ROC" Sticker	\$ 80.00	X
27	Step Garnish	\$ 372.80	X
28	Step Garnish Clips 1 set	\$ 30.00	X
29	Step Panel	\$ 248.10	X
30	Wheel Arch Panel	\$ 516.20	X
31	Air Cleaner	\$ 649.70	X
	To check all wiring & electrical component for proper function	\$ 50.00	X
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 120.00	X
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc...	\$ 280.00	X
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 80.00	X
	To check and re-adjust wheel alignment	\$ 80.00	X
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 100.00	X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	X
	To putty & spray painting & including touch up paint on accident affected ar	\$ 1,500.00	X

Total Parts & Labour of estimate for damaged vehicle

\$ 16,668.70



M/s Liu's Brother Auto Engrg Wks

Not Authorized

2/5 6650

12/12/18

Today.

P-6628.37

25%

4971.27

S.N 1380

Labour 1980

8331.27

6665



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-191536

Date of Request: 11/12/2018

Your Ref No:

Online Purchase

LIU'S BROTHER AUTO WORKSHOP

1 Kaki Bukit Ave 6 #01-01

Auto Bay@Kaki Bukit

Singapore 417883

Dear Sir/Madam,

Enquiry Date: 11/12/2018

Enquiry By: Susan Low Siew Yian

TP Vehicle No: GZ4773G

Accident Date: 22/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GZ4773G	Lonpac Insurance Bhd	14/09/2018-13/09/2020	+65 62507388

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-191536

Date of Request: 11/12/2018

Your Ref No:

Online Purchase

LIU'S BROTHER AUTO WORKSHOP

1 Kaki Bukit Ave 6 #01-01

Auto Bay@Kaki Bukit

Singapore 417883

Dear Sir/Madam,

Enquiry Date: 11/12/2018

Enquiry By: Susan Low Siew Yian

TP Vehicle No: GZ4773G

Accident Date: 22/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GZ4773G	Lonpac Insurance Bhd	14/09/2018-13/09/2020	+65 62507388

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 12 December 2018 8:48 AM
To: Jasmine Low; Susan Low; MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)
Subject: RE: Our Ref: 18/18/18/VC00/021152 RE: Request for 3rd party claims survey GBE7685C Claims against GZ4773G

9.23am @ 12/12/18
person @ jasmine
vehicle in

Without Prejudice


Dear Jasmine

Thank you for your reply.

Dear Catherine/Nivitha

Please arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Jasmine Low [mailto:liusbrojasmine@yahoo.com]
Sent: Tuesday, 11 December, 2018 6:14 PM
To: ONG LI LI; Susan Low; MT_Claim_SG
Subject: Re: Our Ref: 18/18/18/VC00/021152 RE: Request for 3rd party claims survey GBE7685C Claims against GZ4773G

Hi All,

We like to choose No 7 (Marcus Chua)

Thank You

Regards

Jasmine

On Tuesday, 11 December 2018, 17:34, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice
Save as to Costs


Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Susan Low [mailto:liusbro@gmail.com]
Sent: Tuesday, 11 December, 2018 5:20 PM
To: MT_Claim_SG; GERALD POH WEE BIN
Cc: liusbrojasmine@yahoo.com
Subject: Request for 3rd party claims survey GBE7685C Claims against GZ4773G

Accident on 22/11/2018 Along BKE Towards Woodlands
Involving GBE7685C and GZ4773G

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :- _____


Shu Pei (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 13 December 2018 5:48 PM
To: Shu Pei (LKKAuto)
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAuto)
Subject: RE: Our Ref: 18/18/18/VC00/021152 RE: Request for 3rd party claims survey GBE7685C
Claims against GZ4773G
Attachments: SAS2510559 (1).PDF

Dear Shu Pei

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 13 December, 2018 5:22 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAuto)
Subject: RE: Our Ref: 18/18/18/VC00/021152 RE: Request for 3rd party claims survey GBE7685C Claims against GZ4773G

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBE 7685C at M/s Liu's Brother Auto Engineering Workshop on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that preliminary advice is not ready yet.

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 12 December 2018 10:48 AM

To: 'ONG LI LI' <long@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 18/18/18/VC00/021152 RE: Request for 3rd party claims survey GBE7685C Claims against GZ4773G

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:long@lonpac.com>]

Sent: Wednesday, 12 December 2018 8:48 AM

To: Jasmine Low <liusbrojasmie@yahoo.com>; Susan Low <liusbro@ymail.com>; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: RE: Our Ref: 18/18/18/VC00/021152 RE: Request for 3rd party claims survey GBE7685C Claims against GZ4773G

Without Prejudice

Dear Jasmine

Thank you for your reply.

Dear Catherine/Nivitha

Please arrange TP survey.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Jasmine Low [mailto:liusbrojasmine@yahoo.com]

Sent: Tuesday, 11 December, 2018 6:14 PM

To: ONG LI LI; Susan Low; MT_Claim_SG

Subject: Re: Our Ref: 18/18/18/VC00/021152 RE: Request for 3rd party claims survey GBE7685C Claims against GZ4773G

Hi All,

We like to choose No 7 (Marcus Chua)

Thank You

Regards

Jasmine

On Tuesday, 11 December 2018, 17:34, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice

Save as to Costs


Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input checked="" type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Susan Low [mailto:liusbro@gmail.com]
Sent: Tuesday, 11 December, 2018 5:20 PM
To: MT_Claim_SG; GERALD POH WEE BIN
Cc: liusbrojasmine@yahoo.com
Subject: Request for 3rd party claims survey GBE7685C Claims against GZ4773G

Accident on 22/11/2018 Along BKE Towards Woodlands
Involving GBE7685C and GZ4773G

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :- _____



This email has been checked for viruses by AVG antivirus software.
www.avg.com




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18022362/Ueb3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 02-05-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 4773G	Veh. Inspected	GBE 7685C	
Policy No.	Z/18/VC00/102415	Coverage (\$)	0.00	
Claim No.	18/18/18/VC00/021152	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	12/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFHT02P500191474	Colour	WHITE	
Odometer	66099	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	DUNLOP	6 mm	
L/H Front Tyre	195 R15	DUNLOP	6 mm	
R/H Rear Tyre	195 R15	DUNLOP	6 mm	
L/H Rear Tyre	195 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2018	Inspection Date	12/12/2018	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 7685C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	DENTED / BENT	872.90	872.90
1	FRONT BONNET "TOYOTA" MOTIF	NECESSARY	75.00	75.00
2	FRONT BONNET HINGE @ \$295.30	NOT NECESSARY	590.60	-
1	FRONT HEAD LAMP O/S	CRACKED	930.70	766.50
1	SET FRONT HEAD LAMP CLIPS	NOT NECESSARY	65.00	-
1	FRONT BUMPER	DISTORTED	796.80	597.97
1	FRONT BUMPER BEAM	BENT	409.10	409.10
1	FRONT BUMPER SIDE HOLDER	CRACKED	139.00	139.00
1	FRONT CORNER PANEL	DENTED	376.50	376.50
1	FRONT DOOR	DENTED / BENT	1,632.50	1,415.30
2	FRONT DOOR HINGES @ \$115.00	SERVICEABLE	230.00	-
1	FRONT DOOR CHECKER	NOT NECESSARY	152.00	-
1	FRONT DOOR RUBBER	NOT NECESSARY	245.70	-
1	FRONT DOOR OUTER PILLAR	DENTED / BENT	622.60	622.60
1	FRONT DOOR INNER LOCK	NOT NECESSARY	554.40	-
1	FRONT DOOR VIEW MIRROR	TO REPAIR SEE LABOUR	1,142.80	-
1	FRONT DOOR WIRE HARNESS	CRACKED	269.20	269.20
1	FRONT DOOR INNER TRIM BOARD	NOT NECESSARY	645.10	-
1	FRONT STEP GARNISH	CUT	372.80	186.50
1	FRONT STEP PANEL	BENT	248.10	248.10
1	FRONT WHEEL ARCH PANEL	TO REPAIR SEE LABOUR	516.20	-
1	FRONT AIR CLEANER BOX	CRACKED	649.70	649.70
	LESS 25% DISCOUNT		-	-1,657.09
			11,536.70	4,971.28
<u>SPECIAL NETT ITEMS</u>				
1	FRONT HEAD LAMP COVER GARNISH (ACCESSORIES) (SN)	BROKEN	180.00	120.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER SKIRTING (SPOILER) (SN)	DISTORTED	580.00	580.00

Report Ref No. CC4/LPC18022362/Ueb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR OUTER CARBON GARNISH (ACCESSORIES) (SN)	CUT / NECESSARY	450.00	400.00
1	FRONT DOOR OUTER HANDLE LOWER CARBON GARNISH (ACCESSORIES) (SN)	NECESSARY	180.00	150.00
1	FRONT DOOR VISOR (SN)	NECESSARY	120.00	50.00
1	SET FRONT DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	52.00	-
1	FRONT DOOR "ROC" STICKER (SN)	NECESSARY	80.00	30.00
1	SET FRONT STEP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
			1,722.00	1,380.00
	LABOUR			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		50.00	20.00
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		120.00	100.00
	REMOVE & INSTALL DASHBOARD, METER INSTRUMENTS, DISCONNECT WIRING & ETCS.		280.00	200.00
	TO REMOVE, REPLACE AND TRANSFER DOOR PANEL, FITTING AND MECHANISMS.		80.00	60.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES.	NOT NECESSARY	100.00	-
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF FRONT DOOR VIEW MIRROR AND FRONT WHEEL ARCH PANEL.		1,200.00	800.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		1,500.00	800.00
			3,410.00	1,980.00
GRAND TOTAL			16,668.70	8,331.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,650.00

Report Ref No. CC4/LPC18022362/Ueb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.