

22/03/2002

ASS. REC. BY:

REF: CS/MSG18022378/ Kvd301 Special Instruction

Surveyor:
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Manichung

of

MSG

Date/Time:

12/12/02 2.26pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

SLS8878P

Insured:

SJS1688R

at Workshop m/s

Ophman Werkz

Tel:

G4811522

of

9A Serangoon North Ave 5

Policy No:

228858628MF

Claim No:

578461

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/12/18

CA / REV / REP. / REV 24 HRS

lup

18.12.2018 @ 2 pm under writing

H.O.D. Endorsement

Date/Time:

4:17pm @ 12/12/18

Person Contacted:

Sharon

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SLS8878P - CC6 / AIG17024282 / Kpb392

DUA: 19/12/17

SJS1688R - CC4 / AIG17007319 / Khb392

DUA: 10/4/17

19/12/18

Send preli revised via merimen

4/1/19

@ 3:37pm Sharon said vehicle send in next week

31/1/19

@ 4pm Sharon said vehicle will send in repair after CNY

REF: MSG

ASSIGNMENT

From: _____ Date: 18/12/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLS 8878P

at Workshop n/s Optima Werkz

of 9A Serangoon North Ave S

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 2pm owner meeting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLS 8878P Yr Regn: 08 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Honda 'A' Free C.C. 1496

Colour: M. P. White A/C Insured / Std / NI / NA

Sp. Reading: 26450 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GB7 1030047

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: R/Bal. 3 mm

Rear: R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 7/12/18 D.O.I. 18/12/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rec d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/12	15h pass to Car home
28/12/19	8 22 ok

28/12/19 @ 303pm Lily said vehicle has not send in for repair

RECEIVED 01 MAR 2019

Date/Time, File Pass to?

☒: Preli. Report

Days Of Repair: 1

1)

☐: Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee: 150

2) 28/12 - typist

Add Fee: ☐: Site Insp (\$)

Transportation:

) S + RS. SI

Report Format: merimen

☐: Interview (\$)

) Photos

Lump Sum / I.B.I: (\$)

☐: Tech. Invs (\$)

) Others

☐: Weekend (\$)

TOTAL

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Dec 2018		12 Dec 2018 14:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Ng Chin Siong, ID: S1435153A		
Main Claimant:	KWA IVAN, ID: S7721647B		
Vehicle Reg. No.:	SLS8878P	Date of Loss:	07/12/2018 21:00 - :59 [15 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 578461	Policy/Cover Note No.:	28885862SMF (Comprehensive) Coverage: 23/02/2018 - 22/02/2019
Vehicle Reg. No. (Insured):	SJS1688R	Policy No. (Claimant):	
		Excess:	
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/12/2018]		
Adj Asg. Remarks:	SJE AGREE LKK. Liability (Non-reporting) PLS CONTACT SHARON TEN @ 6481 1522		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Monica Chung Pei Zhen	Date: 19 Dec 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: SJS1688R	Accident Date	: 07/12/2018
TP Vehicle No	: SLS8878P	Assignment Date	: 12/12/2018
Make	: HONDA FREED	Est. Duration of Repair	: 1.00
Date of Inspection	: 18/12/2018		
Inspection At	: OPTIMA WERKZ PTE LTD (HQ) 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	530.00
Revised Amount	:S\$	220.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	220.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1647B
Vehicle Details	
Vehicle No.:	SLS8878P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	LEB5556031
Chassis No.:	GB71030047
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$26,295.00
Original Registration Date:	16 Aug 2017
First Registration Date:	16 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	15 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$42,968.00
Total Rebate Amount:	\$46,718.00

The information contained herein is correct as at 10 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/12/2018 14:24
Date Of Accident	07/12/2018 21:10
Exact Location Of Accident	BUKIT BATOK EAST COMMUNITY CENTRE (FRONT PORCH)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLS8878P
Insured/Policyholder	
Name Of Registered Owner	KWA IVAN
NRIC No	S7721647B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96988887
Alternative Phone No	OFFICE-96988887
Vehicle Particulars	
Manufacturer	HONDA
Model	FREED-1.5 G (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700036592
Cover Note Number	
Driver	
Name of Driver	KWA IVAN
NRIC No	S7721647B
Date Of Birth	12/07/1977
Occupation	INDOOR
Date Of Driving Pass	29/06/1996
Driving Experience	22 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96988887
Fax Number	
Contact Number	OFFICE-96988887
Email Address	NOEMAIL

Address	BLK 454 CHOA CHU KANG AVE 4 #07-117
Postcode	680454
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	MOHD EFFENDY
Phone Number	98905992
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS1688R
Vehicle Make/Model/Colour	B
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 08/12/2018
1130 hrs


Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: Kenneth
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/12/2018 at 2110 hrs, I parked my car, SLS 8878P, at Bukit Batok East Community Centre front porch handicap lot. Thereafter, I went to level 3 of the community centre to fetch my daughter. I returned to my car with my daughter about 1 min later. The community centre security guard on duty namely, Mr Mohd Effendy Bin Mohd Ja'apar, asked me whether there was something wrong with my car. I made a check and discovered my car's right side rear bumper was dented and had a long scratch. The guard informed me that a few minutes ago, he heard a loud bang and a white car had hit onto my car. The ~~young~~ young female driver came out of her car to make a check while waiting for an older female passenger just behind my car. The older female passenger denied any wrongdoings when the guard questioned about the accident. They then drove off. I have viewed my car camera footage and extracted it out as verification. There is also CCTV at Bukit Batok NPC directed at the front porch handicap lot.

Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS** CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

	- Reporting Only
	- Claim OD
	- Claim TP
✓	- Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature

Date & Time 08/12/2018
1130 hrs

Driver's Signature

(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature

Name: Kenneth

Nric/Fin No.



**SINGAPORE
POLICE FORCE**



T/20181207/2176

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

1 of 3

Report No. T/20181207/2176

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/12/2018 21:41	Vide Report No.:	Station Diary No.: 89
--	------------------	--------------------------

Informant's Particulars

Name of Informant: KWA IVAN			Address: APT BLK 454 CHOA CHU KANG AVENUE 4 #07-117 SINGAPORE 680454		
ID Type / ID No.: NRIC NO / S7721647B			Contact No.: Home/Office: Mobile: 96988887		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 41	Date of Birth: 12/07/1977	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: STOCK BROKER			Driving Licence Information: Class: 2B,3,4,5		
			Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 07/12/2018 21:10	Type of Location: front porch handicap lot
Location: Along Road 1 BUKIT BATOK EAST AVENUE 4 Bukit Batok East Community Centre, front porch handicap lot				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLS8878P	Car	HONDA	FREED HYBRID 1.5G AUTO	White	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS8878P	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700036592-01	16/08/2018	15/08/2019



**SINGAPORE
POLICE FORCE**



T/20181207/2176

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 3

Report No. T/20181207/2176

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KWA IVAN	ID No.	S7721647B
Related Vehicle	SLS8878P (Car)	Contact No.	96988887
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 07/12/2018 at about 2110hrs, I parked my car, SLS8878P, at Bukit Batok East Community Centre, front porch handicap lot. I then went to level 3 of the community centre to fetch my daughter. I returned to the car with my daughter about 1 minute later.

The community centre security guard namely, Mohd Effendy Bin Mohd Ja'apar, asked me whether there was something wrong with my car. I made a check and discovered that the right side of the rear bumper was dented and had scratches. The community centre security guard informed that earlier on he heard a loud bang and a white car had hit onto my car. The young female driver and the older female passenger came out of the car to make a check. The older female passenger denied any wrongdoing when the security guard asked about the accident. They then drove off.

My car is equipped with in car camera at front and back. I will view the footage later. There is also CCTV at Bukit Batok NPC which is co-located with Bukit Batok East community centre. That CCTV is directed at the handicap lot.



**SINGAPORE
POLICE FORCE**



T/20181207/2176

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3



Report No. T/20181207/2176

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Staff Sgt MOHAMED NASRUDIN BIN SHAHUL HAMEED	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 07/12/2018 21:41
Officer In Charge Of Case: TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No: 65476079	Classification Of Case:
Authentication Stamp NP168 	

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	10 DECEMBER 2018	Third Party Insurer:	MSIG INSURANCE (S)
Vehicle No:	SLS8878P		PTE LTD
Model:	HONDA FREED HYBRID 1.5G AUTO	Third Party Veh No:	SJS1688R
Chassis:	GB71030047 – 2017	Date of Accident:	7 DECEMBER 2018

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

na \$200.00 X

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

2201
\$250.00

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

na \$80.00 X

LABOUR TOTAL	\$530.00
--------------	----------

PEI TING

TOTAL	\$530.00
-------	----------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Dec 2018		12 Dec 2018 14:26 Edit Adj Rpt	S\$220.00 Edit Estimates	S\$220.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Ng Chin Siong , ID: S1435153A								
Main Claimant:	KWA IVAN , ID: S7721647B								
Vehicle Reg. No.:	SLS8878P	Date of Loss:	07/12/2018 21:00 - :59 [15 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 578461	Policy/Cover Note No.:	28885862SMF (Comprehensive) Coverage: 23/02/2018 - 22/02/2019						
Vehicle Reg. No. (Insured):	SJS1688R	Policy No. (Claimant):							
		Excess:							
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/01/2019]								
Adj Asg. Remarks:	SJE AGREE LKK. Liability (Non-reporting) PLS CONTACT SHARON TEN @ 6481 1522								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS8878P (578461)
[SJS1688R]
TP
KWA IVAN
Dec 7 2018 9:00PM
[Ng Chin Siong]
Optima Werkz Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/12/18 14:17	Video - AccidentTP1	Load MP4	
2	17/12/18 14:17	Video - AccidentTP2	Load MP4	
3	17/12/18 14:17	Video - AccidentTP3	Load MP4	
4	17/12/18 15:50	Video - Accident_ORIGINALFRONTVIEW	Load AVI	
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/12/18 14:18	Non Reporting Letter to OI	Load HTM	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/18 12:22	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 15:27	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/02/19 15:27	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/02/19 15:27	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/02/19 15:27	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/02/19 15:27	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/02/19 15:27	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/02/19 15:27	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/12/18 12:40	TP SLS8878P E-REPORT	Load PDF	
2	12/12/18 14:16	SJE AGREE LKK	Load PDF	
3	17/12/18 14:22	SLS8878P	Load PDF	
4	17/12/18 14:23	SJS1688R	Load PDF	

Documents Checklist

Reset Save Print
<p>DOCUMENTS CHECKLIST</p> <p>There are no document checklists configured.</p>
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> <p> Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> </p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18022378/KVD3E2

Date: 04/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28885862SMF

Claimant Vehicle No : SLS8878P

Insured Vehicle No : SJS1688R

Date of Loss: 07/12/2018

Nature of Claim: TP

Claim No: 578461

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS8878P

Make & Model: HONDA FREED, 1.5 G (A)

Engine No: LEB5556031

Reg. Date: 16/08/2017 (Man. Year: 2017)

Chassis No: GB71030047

Colour: Metallic Pearl White

Odometer: 26450 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17

Rear Tyre Size: 205/45 R17

Front Left Side: Bridgestone 3 mm

Rear Left Side: Bridgestone 3 mm

Front Right Side: Bridgestone 3 mm

Rear Right Side: Bridgestone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	530.00	220.00	310.00	58.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	530.00	220.00	310.00	58.49
+ GST 7.00/7.00% (S\$)	37.10	15.40	21.70	58.49
Nett Amount (S\$)	567.10	235.40	331.70	58.49

INSPECTION

Date of Assignment: 12/12/2018

Date Inspected: 18/12/2018

Inspected At:

Optima Werkz Pte Ltd (HQ)
9A Serangoon North Ave 5
Singapore 554500

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIR.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2019)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS8878P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	200.00	0.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	250.00	220.00
3	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	New	80.00	0.00
Gross Labour Cost (\$\$)			530.00	220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >