

ASS. REC. BY:

REF: CS/FCI18022424/Ktd3 ⁿ² Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): CWS Keiren Ten of FCI Date/Time: 13/12/18 @ 10.29am

Estimated Cost: _____ Bill to: _____

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: S2201CD Insured: SHC 8826x

at Workshop m/s Poon Siang Jew Tel: 96169634

of Bik 160 Sin Ming Drive # 05-13

Policy No: _____ Claim No: D18008796MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 11/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (Ds) H.O.D. Endorsement: _____

Date/Time: 10:38am @ 13/12/18 Person Contacted: Albert Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>S2201CD - CS/TK1000/420/vxx</u> D.O.A: <u>12/8/2009</u>
	<u>SHC 8826x - CI/TPD17022963/Zn</u> D.O.A: <u>-</u>
<u>11/12/2018 @ 3:51pm</u>	<u>Revised via email preli advise</u>
<u>2/1/12</u>	<u>L1 Lny 812, 600 email & confirm (Red: 7519.92; 37%)</u>

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: NA

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S 2201 CD Yr Regn: 1 15

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Avdi ABL c.c. 2995

Colour: M. D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 44986 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WACU 888 414 XFN 030312

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 255/45R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 11/12/18

Survey held at _____

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 13/12/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/12	File pass to Catherine

RECEIVED 24 DEC 2018

Date/Time, File Pass to?

1) 21/12/18

Date/Time, File Return to?

2) _____

: Prell. Report

: Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

13x15=195

Survey Fee:

Transportation: 50

S + RS: 50

Fixtos: OSP 24

Others: 21/12/18

TOTAL

489

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$)

2,000



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008796MFSH

Date: 17/12/2018

Our Ref: CS/FCI18022424/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. S 2201CD

Please be informed that we had conducted the inspection of the abovementioned vehicle 13/12/2018 at the premises of M/s Poon Siang Seow have the following to report: -

Workshop Estimate Amount	: <u>S\$ 20,119.92</u>
Revised Estimate Amount	: <u>S\$ 3,769.53</u>
"Check" Items Amount	: <u>S\$ 1,692.00</u>
Market Value	: <u>S\$ _____</u>
LTA Reimbursement Value	: <u>S\$ _____</u>
Nett Value	: <u>S\$ _____</u>

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-12-2018	Our Ref No. D18008796MFSH
Accident Date	11-12-2018	Claim Type. Third Party
Insured Vehicle	SHC8826X	Third Party Vehicle. S2201CD
Survey Location	BLK 160 SIN MING DRIVE #05-13	
Contact Person.	ALBERT	
Contact No.	64537511/ 96169634	Fax No. 64538046
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	POON SIANG SEOW	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 17 December 2018 3:51 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008796MFSH/1
Attachments: PRELI ADVISED S 2201CD.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **S 2201CD**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 13 December 2018 10:52 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008796MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 13 December 2018 10:28 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008796MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

QBE Insurance (Singapore) Pte Ltd

A member of the worldwide QBE Insurance Group - Unique Entity No: 198401361C

1 Raffles Quay, #20-10 South Tower, Singapore 048583
Tel: 65 6224 6633 Fax: 65-6533 3270
GST Registration No.: M200644018
www.qbe.com.sg

Date of issue 13/01/2018

Page 1 of 2

**PRIVATE CAR
RENEWAL NOTICE**AUSTRALIAN HIGH COMMISSION
25 NAPIER ROAD
AUSTRALIAN HIGH COMMISSION
SINGAPORE 258507Policy Number
8-V0010140-MVA-R003Period of Insurance
25/03/2018 to 24/03/2019
(Both Dates Inclusive)Account Number
09L00173
QBE-DIRECT ACCOUNT

Your insurance will expire soon. Kindly review the Policy to ensure that it is in line with your intentions. When reviewing your policy we will be assuming that your original policy submission is still correct and complete at the time for renewal except for those matters that you have already notified us of. If this is not the case or if you have not notified us prior to renewal of any occurrence that could give rise to a claim we reserve the right to terminate the renewed policy or amend its terms provided we give you notice of such action within a reasonable time afterwards. Subject to the above, all terms and conditions will be as per your existing policy.

The Insured : AUSTRALIAN HIGH COMMISSION**Risk Details****Private Motor****Risk No 0001****Business/Occupation**

HIGH COMMISSION

Cover

Third Party Only

Registration No.

S2201CD

Make & Model

AUDI A8L 3.0 TFSI

Cubic Capacity

2995

Type of Body

Saloon

Chassis No.

WALZZZ4H XFN030312

Year of Manufacture

2015

Engine No.

CRE026677

No Claims Discount

50.00

Safe Driver Discount

0.00



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Australian High Commission
25 Napier Road
Singapore 258507


Not Authored
L1 Sup 8/12, 800g
Respray After Paint
7 days

Dear sir
Estimate cost of repair to vehicle no. S 2201 CD
To supply

1. Rear bumper		Bul/nd	2,236.45	—
2. Rear bumper chrome		Mu	180.00	—
3. Rear fender	4450.40	Bt	5,807.67	—
4. Rear fender glass		sn	580.00	X
5. Rear door	4850	Bt	5,622.90	—
6. Rear door window motor and gear		R	850.00	X
7. Rear door rubber		Mu	345.00	—
8. Rocker panel garish		Del	980.80	—
9. Rocker panel garish chrome		Del	480.00	—
10. Wheel rim		Del	1,500.00	—
11. Tyre		Sn	450.00	X
12. Rivet X20	108	Mu	80.00	—

Labour charge

Penal beating	2,500.00	1100L
Spray painting	1,500.00	1000L
To remove and refit w/s glass and fender	450.00	1800L
Total	20,119.92	23562.82

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022424/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-12-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8826X	Veh. Inspected	S 2201CD
Policy No.		Coverage (\$)	0.00
Claim No.	D18008796MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	13/12/2018
2. Vehicle Particulars & Condition			
Make & Model	AUDI A8L (A)	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WAUZZZ4HXFN030312	Colour	METALLIC DARK BLUE
Odometer	44986	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/45 R19	PIRELLI	9 mm
L/H Front Tyre	255/45 R19	PIRELLI	9 mm
R/H Rear Tyre	255/45 R19	PIRELLI	9 mm
L/H Rear Tyre	255/45 R19	PIRELLI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/12/2018	Inspection Date	13/12/2018
Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. S 2201CD

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED / DENTED	2,236.45	2,236.45
1	REAR BUMPER CHROME	NECESSARY	180.00	180.00
1	REAR FENDER	BENT	5,807.67	4,450.40
1	REAR FENDER GLASS	SERVICEABLE	580.00	-
1	REAR DOOR	BENT	5,622.90	4,850.00
1	REAR DOOR WINDOW MOTOR AND GEAR	TO REPAIR SEE LABOUR	850.00	-
1	REAR DOOR RUBBER	NECESSARY	345.00	345.00
1	ROCKER PANEL GARISH	DENTED	980.80	980.80
1	ROCKER PANEL GARISH CHROME	DENTED	480.00	480.00
1	WHEEL RIM	DENTED	1,500.00	1,500.00
1	TYRE	SERVICEABLE	450.00	-
20	RIVET	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-1,510.27
			19,112.82	13,592.38
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR WINDOW MOTOR AND GEAR.		2,500.00	1,100.00
	SPRAY PAINTING.		1,500.00	1,000.00
	TO REMOVE AND REFIT W/S GLASS AND FENDER.		450.00	160.00
			4,450.00	2,260.00
	GRAND TOTAL		23,562.82	15,852.38
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,600.00

Report Ref No. CS/FC118022424/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.