

ASS. REC. BY:

REF:

CS3/LCR18022428/God30

Special Instruction:

Surveyor:
Menmen

Guo Chang

ASSIGNMENT (Office)

From (Person):

Chin lee Ying

of

LCR

Date/Time:

13/12/18 @ 11:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJE7877X

Insured:

SLL9530Y

at Workshop m/s

Motor Intel

Tel:

8838 3318

of

13 kaki Bukit Rd 4 #01-20

Policy No:

0999994827

Claim No:

1871230253SG.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/12/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:11am @ 13/12/18

Person Contacted:

Wilson

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJE7877X-X

SLL9530Y-X.

REF: 7270f (-2008)

REF: 7270f (-2008)

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

at Workshop m/s Motor Intel

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt. Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 15 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 55151E7877X Regn: 08 May 2008

Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Jancer 1.5 c.c. 1495

Colour: Red A/C Insured / Std / NI / NA

Sp. Reading: 170685 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM YSRC Y2A 8400 6661

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rip / STD A/Rim or

Tyre Size: F: 215 / 60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 0 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.L. 13-12-18

Survey held at: W/S 12:15 pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

\$9000 - \$1000

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 15

Resurvey No. of Trip: -

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

Report Format : DAR

Lump Sum / I.B.I: (\$)

180

20

200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 13/12/2018 11:28:36 AM
Attachments:  [tmp1391.tif](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: SLL 9530Y

Our Ref: AL.INS.2018.SJE7877X

13 December 2018

PDX Intercompany Exchange Pte Ltd



010808613133

FROM Allister Lim & Thrumurgan

PDX Box No. 8144

AIG ASIA PACIFIC INSURANCE PTE. LTD. BY PDX & FAX; 6835 7416
78, Shenton Way
AIG Building, #08-16
Singapore 079120

Dear Sirs,

**ACCIDENT INVOLVING SJE 7877X & SLL 9530Y ALONG DUNEARN ROAD
BEFORE TURF CLUB AVENUE ON 11 DECEMBER 2018 AT ABOUT 1950
HOURS**

We act for the owner of vehicle no. SJE 7877X

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

MOTOR INTEL AUTOMO PTE LTD
13 Kaki Bukit Road 4
#01-20 Bartley Biz Centre
Singapore 417807
Person In-Charge: Wilson / Tinie
Mobile Number: 8838 3318 / 6281 0087

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jeremy Peh at 6438 3303 or email us at jeremypeh@alt.sg for future correspondences.

Yours faithfully

ALLISTER LIM

ALLISTER LIM & THRUMURGAN

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7270F
Vehicle Details	
Vehicle No.:	SJE7877X
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Dec 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLS 4A/T
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	4A910081910
Chassis No.:	JMYSRCY2A8U006661
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,142.00
Original Registration Date:	08 May 2008
First Registration Date:	08 May 2008
Transfer Count:	0
Actual ARF Paid:	\$18,857.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,096.00
COE Rebate Amount:	\$16,791.00
Total Rebate Amount:	\$16,791.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Dec 2018

▶ Lancer Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Mitsubishi Lancer EX 1.5A GLS (COE till 04/2023)	\$26,888	\$6,250 /yr	03-Apr-2008	1,499 cc	109,000 km	JDM Cars	Available
Free 1 Servicing Upon Purchase! 1 Year Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! Low Down Payment Available! No Gimmicks! Trade In Welcome! Priced Lowest In Th...							
Office No. - 62994111 John - 90105163 William - 96463854 Yang - 92981269 Patrick - 93865066							
Mitsubishi Lancer 1.6M GLX (COE till 04/2028)	\$40,500	\$4,350 /yr	03-Apr-2008	1,584 cc	156,000 km	Carro	Available
Drift Racing Exhaust Full System, LTA Passed Cert, New CS5 Grill, BC Coil Over, Newly Replace Aircon Compressor (early This Year), Regular 8k Servicing. Schedule A Test Drive Today. Viewing Is Stric...							
Office No. - 67146652 Jace - 81394200 Betty - 96215746							
Mitsubishi Lancer EX 1.5A GLS (COE till 04/2023)	\$42,800	\$9,930 /yr	07-Apr-2008	1,499 cc	-	Car Search	Available
Consignment Unit. Viewing By Appointment Only!							
Office No. - 62620728 Kelvin - 97593539 Louise - 93295018							
Mitsubishi Lancer EX 1.5A GLS (COE till 06/2023)	\$32,800	\$7,330 /yr	06-Jun-2008	1,499 cc	130,000 km	Tay Motor & Credit Pte Ltd	Available
Low Down Payment \$5K For Well Maintained. Superb Condition With Worn Out Parts Replaced. Low Mileage! Bank Or In House Loan Available! High Trade In Are Welcome! Call Our Friendly Sales Person For App...							
Office No. - - Ben Poh - 90602520 Eric Kwan - 93630202 Jason Loh - 81001755							
Mitsubishi Lancer EX 1.5A GLS (COE till 06/2023)	\$32,800	\$7,280 /yr	16-Jun-2008	1,499 cc	123,000 km	Tay Motor & Credit Pte Ltd	Available
Original Car Paint Work! Extremely Well Maintained! Low Mileage Done. Accident Free. Don't Miss This Chance. Kindly Call Our Friendly Sales Person For Viewing The Car Now.							
Office No. - - Ben Poh - 90602520 Jason Loh - 81001755 Eric Kwan - 93630202							
Mitsubishi Lancer 1.6A GLX (COE till 07/2028)	\$44,000	\$4,580 /yr	21-Jul-2008	1,584 cc	82,000 km	360 VR Cars	Available
Viewing By Appointment.							
Office No. - 69310005 Belinda Lim - 90588558 James Tan - 90700005							
Mitsubishi Lancer EX 1.5A GLS (COE till 07/2023)	\$33,800	\$7,300 /yr	01-Aug-2008	1,499 cc	-	Car Guru.Com Pte Ltd	Available
Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Bef...							
Office No. - 67639595 Lawrence - 92228747 Jimmy - 90079944							
Mitsubishi Lancer EX 1.5A GLS (COE till 08/2023)	\$34,800	\$7,490 /yr	06-Aug-2008	1,499 cc	-	Car Guru.Com Pte Ltd	Available
Smooth Engine, Easy To Maintained Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now B...							
Office No. - 67639595 Lawrence - 92228747 Jimmy - 90079944							
Mitsubishi Lancer EX 1.5A GLS (COE till 08/2023)	\$34,800	\$7,460 /yr	14-Aug-2008	1,499 cc	-	Car Guru.Com Pte Ltd	Available

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2018 17:11
Date Of Accident	11/12/2018 19:50
Exact Location Of Accident	DUNEARN RD BEFORE TURF CLUB AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE7877X
Insured/Policyholder	
Name Of Registered Owner	TANG HAY YIU
NRIC No	S2207270F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91895887
Alternative Phone No	OTHERS-91895887
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER 1.5 MIVEC GLS 4A/T
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	TANG HAY MING
NRIC No	S2199322J
Date Of Birth	04/05/1969
Occupation	INDOOR
Date Of Driving Pass	26/08/1996
Driving Experience	22 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91895887
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 24 JALAN KHAMIS SPORE 577870
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SIBLING
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : LEONG SEOK MEI
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ,
POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLL9530Y
Vehicle Make/Model/Colour HONDA GRACE 1.5 DX HYBRID CVT ABS D/AIRBAG 2WD
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TANG HAY MING

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJE7877X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name LEONG SEOK MEI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJE7877X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

It was noted apertly the details of the accident to speed up the claims process.

¹² This form must be completed by the Policyholder and/or the Authorised Driver.

Information provided must be as truthful and accurate as possible. 4% will be fined without being allowed to sue. In 1986, 480 insurance companies repudiated policy liability.

¹⁶ The 10% and all other rights figure by Insurance Companies is not an estimate; it is based on actual experience.

Any false reporting may be referred to the Police for investigation

The report will be forwarded by the officers of the G4 Funds Management Centre to the relevant authorities in Singapore (SIA) for archiving and the copies of this report will be forwarded to the relevant authorities.

☐ Consent under the Personal Data Protection Act (PDPA)

While I don't always agree, agree and consent that

[illegible]

Understanding, managing and resolving issues relating to the claims, including the settlement of the claims, and the investigations relating to the claims.

c. Investigating the subject's account of the crime.

© 2011 Blackwell Publishing Ltd *Journal of Internal Medicine* 270: 103–111

which could involve disclosure of certain personal data about not to be using what drivers on the national river of environmental packages, and/or

12. Comparing with spot table as in administering, processing, and 2. ing and in doing a more

(b) a "master(s)" who have created, updated, modified, deleted, or archived the "data(s)" and the "data(s)" owner(s) who may, at their sole discretion, use, disclose and/or process the Personal Information for one or more of the purposes set forth in (a).

Mr. Perkins informed me that he collected the bulk of the material used in the book from the public domain, including the following: (1) the various deeded tracts of land outside of Singapore for the purpose of

124 The firm's information will also be collected and used by Google, which is storing the information to improve its advertising and management of content and all future users.

* This information is intended to be a general guide only. It is not intended to be used as a basis for a specific investment decision.

It is at this time that any other third parties may want to be setting themselves up as a business partner, law enforcement and government agencies to ensure they are in the system.

is a free normal subgroup with $\text{rank}(\text{Im}(\phi)) = 1$ under the regularity assumption on ϕ and ϕ is surjective.

2017年11月15日
 2017年11月15日

Driver's Signature _____
 Date & Time _____

Reporting Officer's Signature
Name: S. G. M.
MUNICIPALITY: S. G. M.

Sketch Plan #2

SKETCH PLAN



VEH A > STE 3877K

VEH B > NLL 9530Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/13/2018 at about 1950hrs, I was traveling along Dunsmuir Rd towards city direction just before ~~my car~~ took over the on the extreme lane. Traffic was moderate, and a sudden vehicle B hit on the rear of my vehicle A. The impact was so strong that my vehicle A lost its control and went up the bank and hit onto the bushes.

DECLARATION

I declare that the foregoing particulars are true and correct.

[Signature]
Deponent's Signature
Date & Time

[Signature]
Driver's Signature
If driver is not the deponent
Date & Time

[Signature]
Witnessing Officer's Signature
Name: S. L. [unclear]
No. 104/10: 10401021

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	QIS
1137	993626	Rear Number Plate	BT	✓	
1138	993627	Rear Number Plate Base	GR	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	BE	✓	2
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	MIS	✓	
1146	992341	Rear Bumper Clips	DES	✓	
1147	992976	Rear Bumper Bracket	BT	✓	2
1148	993068	Rear Bumper Side Retainer	BE	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CRA	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	CRA	✓	2
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	DI	✓	
1160	993339	Rear End Panel Top Garnish	CRA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	BUC	✓	
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	BUC	✓	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NLC	✓	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	CRA	✓	
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BUC	✓	
1178	990377	Bootlid Rubber	BT	✓	
1179	990382	Bootlid Hinge	BT	✓	2
1180	993877	Bootlid Spoiler	DIS	✓	
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Vehicle No: **SJE787X**

NAC	INC	Item	CON	AC	QIS
1202	993784	Spare Tyre Board	CRA	✓	
1203	994328	Spare Tyre Panel	DD	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			?
1211	990532	Centre Exhaust Mounting			?
1212	993364	Rear Exhaust Pipe	BT	✓	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting	DIS	✓	
1215	993358	Rear Exhaust Heat Shield	BT	✓	
1216	995223	Rear LH Chassis Member	BUC	✓	R
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	BT	✓	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel	BUC	✓	R
1221	993431	Rear LH Fender Inner Trim	TN	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	TN	✓	
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			?
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			?
1228	993456	Rear RH Fender	BT	✓	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel	BT	✓	R
1231	993431	Rear RH Fender Inner Trim			?
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield	TN	✓	
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			?
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			?
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding	NEL	✓	
1247	993955	Rear Windscreen Sealant	NEL	✓	
1248	994729	Third Brake Light	BT	✓	
1249	993385	Rear Fender Air Grille	CRA	✓	2
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			?
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			
		Bootlid Inner Board	DIS	✓	
		Bootlid Damper			2

Left Portion

[illegible]

Vehicle No: 5JE7877X

[illegible]

No of Items: _____ Assessor: _____

Claim Documents

***SJE7877X (1871230253SG)
[SLL9530Y]**

TP

Dec 11 2018 12:00AM

[LCRF Pte Ltd]

Motor Intel Automo Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page ☐	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/12/18 16:46	Accident Statement From: OD - Reg. No: SLL9530Y, Claimant: LCRF PTE LTD	Load HTML	
Photos/Images			3 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/12/18 14:59	General View	Load JPG	☒
2	17/12/18 14:59	General View	Load JPG	☒
3	17/12/18 14:59	General View	Load JPG	☒
4	17/12/18 14:59	General View	Load JPG	☒
5	17/12/18 14:59	General View	Load JPG	☒
6	17/12/18 14:59	General View	Load JPG	☒
7	17/12/18 14:59	General View	Load JPG	☒
8	17/12/18 14:59	General View	Load JPG	☒
9	17/12/18 14:59	General View	Load JPG	☒
10	17/12/18 14:59	General View	Load JPG	☒
11	17/12/18 14:59	General View	Load JPG	☒
12	17/12/18 14:59	General View	Load JPG	☒
13	17/12/18 14:59	General View	Load JPG	☒
14	17/12/18 14:59	General View	Load JPG	☒
15	17/12/18 14:59	General View	Load JPG	☒
16	17/12/18 14:59	General View	Load JPG	☒
17	17/12/18 14:59	General View	Load JPG	☒
18	17/12/18 14:59	General View	Load JPG	☒
19	17/12/18 14:59	General View	Load JPG	☒
20	17/12/18 14:59	General View	Load JPG	☒
21	17/12/18 14:59	General View	Load JPG	☒
22	17/12/18 14:59	General View	Load JPG	☒
23	17/12/18 14:59	General View	Load JPG	☒
24	17/12/18 14:59	General View	Load JPG	☒
25	17/12/18 14:59	General View	Load JPG	☒
26	17/12/18 14:59	General View	Load JPG	☒
27	17/12/18 14:59	General View	Load JPG	☒
28	17/12/18 14:59	General View	Load JPG	☒
29	17/12/18 14:59	General View	Load JPG	☒
30	17/12/18 14:59	General View	Load JPG	☒
31	17/12/18 14:59	General View	Load JPG	☒
32	17/12/18 14:59	General View	Load JPG	☒
33	17/12/18 14:59	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	17/12/18 14:59	General View	 Load JPG	☒
35	17/12/18 14:59	General View	 Load JPG	☒
36	17/12/18 14:59	General View	 Load JPG	☒
37	17/12/18 14:59	General View	 Load JPG	☒
38	17/12/18 14:59	General View	 Load JPG	☒
39	17/12/18 14:59	General View	 Load JPG	☒
40	17/12/18 14:59	General View	 Load JPG	☒
41	17/12/18 14:59	General View	 Load JPG	☒
42	17/12/18 14:59	General View	 Load JPG	☒
43	17/12/18 14:59	General View	 Load JPG	☒
44	17/12/18 14:59	General View	 Load JPG	☒
45	17/12/18 14:59	General View	 Load JPG	☒
46	17/12/18 14:59	General View	 Load JPG	☒
47	17/12/18 14:59	General View	 Load JPG	☒
48	17/12/18 14:59	General View	 Load JPG	☒
49	17/12/18 14:59	General View	 Load JPG	☒
50	17/12/18 14:59	General View	 Load JPG	☒
51	17/12/18 14:59	General View	 Load JPG	☒
52	17/12/18 14:59	General View	 Load JPG	☒
53	17/12/18 14:59	General View	 Load JPG	☒
54	17/12/18 14:59	General View	 Load JPG	☒
55	17/12/18 14:59	General View	 Load JPG	☒
56	17/12/18 14:59	General View	 Load JPG	☒
57	17/12/18 14:59	General View	 Load JPG	☒
58	17/12/18 14:59	General View	 Load JPG	☒
59	17/12/18 14:59	General View	 Load JPG	☒
60	17/12/18 14:59	General View	 Load JPG	☒
61	17/12/18 14:59	General View	 Load JPG	☒
62	17/12/18 14:59	General View	 Load JPG	☒
63	17/12/18 14:59	General View	 Load JPG	☒
64	17/12/18 14:59	General View	 Load JPG	☒
65	17/12/18 14:59	General View	 Load JPG	☒
66	17/12/18 14:59	General View	 Load JPG	☒
67	17/12/18 14:59	General View	 Load JPG	☒
68	17/12/18 14:59	General View	 Load JPG	☒
69	17/12/18 14:59	General View	 Load JPG	☒
70	17/12/18 14:59	General View	 Load JPG	☒
71	17/12/18 14:59	General View	 Load JPG	☒
72	17/12/18 14:59	General View	 Load JPG	☒
73	17/12/18 14:59	General View	 Load JPG	☒
74	17/12/18 14:59	General View	 Load JPG	☒
75	17/12/18 14:59	General View	 Load JPG	☒
76	17/12/18 14:59	General View	 Load JPG	☒
77	17/12/18 14:59	General View	 Load JPG	☒
78	17/12/18 14:59	General View	 Load JPG	☒
79	17/12/18 14:59	General View	 Load JPG	☒
80	17/12/18 14:59	General View	 Load JPG	☒
81	17/12/18 14:59	General View	 Load JPG	☒
82	17/12/18 14:59	General View	 Load JPG	☒
83	17/12/18 14:59	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
84	17/12/18 14:59	General View		Load JPG ☒
85	17/12/18 14:59	General View		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR18022428/GCD3E2

Date: 31/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994827

Claimant Vehicle
No: SJE7877X

Insured Vehicle No: SLL9530Y

Date of Loss: 11/12/2018

Nature of Claim: TP

Claim No: 1871230253SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE7877X

Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)

Engine No: 4A910081910

Reg. Date: 08/05/2008 (Man. Year: 2008)

Chassis No: JMYSRCY2A8U006661

Colour: Red

Odometer: 170685 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/12/2018

Date Inspected: 13/12/2018 Inspected At:

Motor Intel Automo Pte Ltd (HQ)
13 Kaki Bukit Road 4, #01-20, Bartley Biz
Centre
Singapore 417807

Estimated Period of Repair: 15.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*- F
3	2		*REAR NUMBER PLATE LAMP	Broken	0.00 F	*- F
4	1		*REAR BUMPER	Dented	0.00 F	*- F
5	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
6	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
7	2		*REAR BUMPER BRACKET	Bent	0.00 F	*- F
8	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
9	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
10	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
11	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
12	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
13	1		*REAR END PANEL	Dented	0.00 F	*- F
14	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
15	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
16	1		*REAR LH TAILLAMP PANEL	Buckled	0.00 F	*- F
17	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
18	1		*REAR RH TAILLAMP PANEL	Buckled	0.00 F	*- F
19	1		*BOOTLID	Dented	0.00 F	*- F
20	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
21	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
22	1		*BOOTLID LAMP RH	* Check	0.00 F	*- F
23	1		*BOOTLID LOCK	Buckled	0.00 F	*- F
24	1		*BOOTLID RUBBER	Bent	0.00 F	*- F
25	2		*BOOTLID HINGE	Bent	0.00 F	*- F
26	1		*BOOTLID SPOILER	Distorted	0.00 F	*- F
27	1		*SPARE TYRE BOARD	Cracked	0.00 F	*- F
28	1		*SPARE TYRE PANEL	Dented	0.00 F	*- F
29	1		*CENTRE EXHAUST PIPE ASSY	* Check	0.00 F	*- F
30	1		*CENTRE EXHAUST MOUNTING	* Check	0.00 F	*- F
31	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
32	1		*REAR EXHAUST MOUNTING	Distorted	0.00 F	*- F
33	1		*REAR EXHAUST HEAT SHIELD	Bent	0.00 F	*- F
34	1		*REAR LH CHASSIS MEMBER	Repair	0.00 F	*- F
35	1		*REAR LH FENDER	Bent	0.00 F	*- F
36	1		*REAR LH FENDER INNER PANEL	Repair	0.00 F	*- F
37	1		*REAR LH FENDER INNER TRIM	Torn	0.00 F	*- F
38	1		*REAR LH FENDER INNER SHIELD	Torn	0.00 F	*- F
39	1		*REAR LH WHEEL RIM	* Check	0.00 F	*- F
40	1		*REAR LH TYRE	* Check	0.00 F	*- F
41	1		*REAR RH FENDER	Bent	0.00 F	*- F
42	1		*REAR RH FENDER INNER PANEL	Repair	0.00 F	*- F
43	1		*REAR RH FENDER INNER TRIM	* Check	0.00 F	*- F
44	1		*REAR RH FENDER INNER SHIELD	Torn	0.00 F	*- F
45	1		*REAR RH WHEEL RIM	* Check	0.00 F	*- F
46	1		*REAR RH TYRE	* Check	0.00 F	*- F
47	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
48	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
49	1		*THIRD BRAKE LIGHT	Broken	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*REAR FENDER AIR GRILLE	Cracked	0.00 F	*- F
51	1		*FUEL NECK	* Check	0.00 F	*- F
52	1		*BOOTLID INNER BOARD	Distorted	0.00 F	*- F
53	2		*BOOTLID DAMPER	* Check	0.00 F	*- F
54	1		*FRT NUMBER PLATE	Cut	0.00 F	*- F
55	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*- F
56	1		*FRT BUMPER	Dented	0.00 F	*- F
57	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
58	2		*FRT BUMPER SIDE RETAINER L & R	Broken	0.00 F	*- F
59	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
60	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
61	1		*FRT BUMPER GRILLE	Broken	0.00 F	*- F
62	1		*FRT BUMPER LOWER SPOILER RH	Missing	0.00 F	*- F
63	1		*FRT LH BUMPER FOG LAMP COVER	* Check	0.00 F	*- F
64	1		*FRT RH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
65	1		*FRT LH BUMPER FOG LAMP	* Check	0.00 F	*- F
66	1		*FRT RH BUMPER FOG LAMP	* Check	0.00 F	*- F
67	1		*FRT GRILLE	Cracked	0.00 F	*- F
68	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
69	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
70	1		*FRT SUPPORT PANEL TOP GARNISH COVER	* Check	0.00 F	*- F
71	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F
72	1		*FRT RH HEADLAMP ASSY	Cut	0.00 F	*- F
73	1		*BONNET	Repair	0.00 F	*- F
74	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
75	1		*RADIATOR	* Check	0.00 F	*- F
76	1		*FRT LH FENDER	Repair	0.00 F	*- F
77	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
78	1		*FRT LH WHEEL RIM	* Check	0.00 F	*- F
79	1		*FRT LH TYRE	* Check	0.00 F	*- F
80	1		*FRT RH FENDER	Repair	0.00 F	*- F
81	1		*FRT RH FENDER INNER SHIELD	Torn	0.00 F	*- F
82	1		*FRT RH WHEEL RIM	* Check	0.00 F	*- F
83	1		*FRT RH TYRE	* Check	0.00 F	*- F
84	1		*FRT LH DOOR	Dented	0.00 F	*- F
85	1		*FRT LH DOOR HINGE	* Check	0.00 F	*- F
86	1		*FRT LH DOOR GLASS OUTER MOULDING	Bent	0.00 F	*- F
87	1		*FRT LH DOOR GLASS REGULATOR	* Check	0.00 F	*- F
88	1		*FRT LH DOOR RUBBER	* Check	0.00 F	*- F
89	1		*FRT LH DOOR OUTER HANDLE	Cut	0.00 F	*- F
90	1		*REAR LH DOOR	Dented	0.00 F	*- F
91	1		*REAR LH DOOR RUBBER	* Check	0.00 F	*- F
92	1		*FRT RH DOOR	Repair	0.00 F	*- F
93	1		*REAR RH DOOR	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >