

ASS. REC. BY:

REF:

CSB/AIG18022430/Ged302

Special Instruction:

Surveyor:
Munim

Guo Qiang

ASSIGNMENT (Office)

(From (Person):

Chin ke Ying

of

AIG

Date/Time:

13/12/18 @ 10:30am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 90482

Insured:

SJS 3974B

at Workshop m/s

88 Motorz

Tel:

98111555

of

25 kaki Bkf Rd 4 # 05-34 Synergy

Policy No:

0999994481

Claim No:

724929757536

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/12/18

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

1041am @ 13/12/18

Person Contacted:

James

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SME 90482 - X

SJS 3974B - NBA / INC 16007069/Y

JDA: 18/02/2016

PHS
Xcel.

REF: ALG

32348 /

ASSIGNMENT

From: Date: 13/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SME 90482

at Workshop m/s 88 Motorz

of 25 Kelki Bukit Rd 4 # 05-34

Insured: Synergy

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$63K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SME 90482 Regn: 01 Oct 2012

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: merce C180 C.C. 1595

Colour: Brown A/C Insured / Std / NI / NA

Sp. Reading: 71662 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDN 2040312-A 768142

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Altim or

Tyre Size: F: 225 / 45 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

~~\$9000~~ \$10K

RECEIVED 17 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: -

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

Report Format : DAR

Lump Sum / I.B.I. (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

180

20

200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJS3974B AND SME9048Z ON 07/12/...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 13/12/2018 10:30:46 AM
Attachments: SME9048Z GIA.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Pri [mailto:pri@satwantlaw.com.sg]

Sent: Wednesday, December 12, 2018 6:05 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJS3974B AND SME9048Z ON 07/12/2018

Without Prejudice

Dear Sir/Mdm,

ACCIDENT INVOLVING SME9048Z & SJS3974B ALONG PIE (CHANGI) PAYA LEBAR FLYOVER ON 11/12/2018 @ 22:35

We refer to your letter dated 12 December 2018 confirming your intention to conduct a pre-repair survey on our client's vehicle SME9048Z.

We have instructions to reject your surveyor and propose to engage Andrew from Prominent Appraisal.

Please be informed that said vehicle can be inspected at:

Workshop:

Address:

Contact Person:

88 Motorz (SG) Pte Ltd

25 Kaki Bukit Road 4 #05-34 Synergy @ KB

Singapore 417800

James (HP: 9811 1555) / Ryan (HP: 9733 6635)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence

For Surveyor: To initial after Completion

1st Inspection
Appointed surveyor
(Name & Siganature)
Date & Time

2nd Inspection
Appointed surveyor
(Name & Siganature)
Date & Time

3rd Inspection
Appointed surveyor
(Name & Siganature)
Date & Time

aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran
singh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Hor, Yinrul
Baljit.Kaur@aig.com>
ICLE SJS3974B AND SME9048Z ON 07/12/2018

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่

UUUUU

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-12-19 10:23 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

*** Please note that all our email addresses now end with @satwantlaw.com.sg.

Satwant & Associates

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

450 Lorong 6 Toa Payoh #02-03, Singapore 319394 | tel: 6221 6114 | fax: 6266 6925

The information contained in this communication is confidential and may be legally privileged. It is intended solely for the use of the individual or entity to whom it is addressed and others authorised to receive it. If you are not the intended recipient you are hereby notified that any disclosure, copying, distribution or taking any action with respect to the content of this information is strictly prohibited and may be unlawful, and kindly inform the sender via email or call SATWANT & ASSOCIATES at (65) 6299 9470 immediately and destroy all copies. SATWANT & ASSOCIATES is neither liable for the proper and complete transmission of the information contained in this communication nor for any delay in its receipt.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3234F
Vehicle Details	
Vehicle No.:	SME9048Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 BLUEEFFICIENCY
Primary Colour:	Brown
Manufacturing Year:	2012
Engine No.:	27491030015615
Chassis No.:	WDD2040312A768142
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$30,160.00
Original Registration Date:	01 Oct 2012
First Registration Date:	01 Oct 2012
Transfer Count:	2
Actual ARF Paid:	\$30,160.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Sep 2022
PARF Rebate Amount:	\$19,604.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$68,656.00
COE Rebate Amount:	\$26,051.00
Total Rebate Amount:	\$45,655.00
Message	

The information contained herein is correct as at 14 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 13:42
Date Of Accident	07/12/2018 22:35
Exact Location Of Accident	PIE (CHANGI) PAYA LEBAR FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME9048Z
Insured/Policyholder	
Name Of Registered Owner	LAU WEE KIM
NRIC No	S7973234F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96162813
Alternative Phone No	OFFICE-96162813
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104891540
Cover Note Number	
Driver	
Name of Driver	LAU WEE KIM
NRIC No	S7973234F
Date Of Birth	25/03/1979
Occupation	INDOOR
Date Of Driving Pass	05/02/2002
Driving Experience	16 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96162813
Fax Number	
Contact Number	OFFICE-96162813
Email Address	NOEMAIL

Address BLK 476 TAMPINES ST 44 #04 -185
 Postcode 520476
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 07/12/2018 AT 10.35PM, I WAS DRIVING MY CAR A ALONG PIE (PAYA LEBAR FLYOVER). VEHICLE B SLOWED DOWN AND CAME TO A COMPLETE STOP. I BRAKED AND STOP MY VEHICLE AS WELL. SUDDENLY, I HEARD A LOUD BANG. MY CAR MOVED FORWARD AND COLLIDED ONTO VEHICLE B. I ALIGHTED AND CHECKED, VEHICLE C COLLIDED ONTO MY REAR. I FELT PAIN ON MY BODY AND HEAD AND WENT TO SEE A DOCTOR.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJS3974B
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver KOH KOK HWEE
 NRIC/Passport Number
 Contact Number 96162813
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLE6640U
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LAU WEE KIM
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SME9048Z
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

88 MOTORZ

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/12/18 at 10:35pm, I was driving my car (A) along P112 paya Lebar Expressway, vehicle (B) slow down and came to a complete stop. I braked and stop my vehicle as well. Suddenly I heard a loud bang, my car move forward and collid onto vehicle (B). I alighted and checked vehicle (C) collided onto my rear. I felt pain on my body and head and went to see doctor.

DECLARATION

I/We declare the foregoing particulars are true and correct to the best of my/our knowledge.

Signature of the
Accident Holder's Signature
Date & Time

Signature of the
Accident Holder's Signature
Date & Time

10/12/18 at 11:45AM
Reporting Centre Personnel's Signature
Name
ARCC/MSD

MOTOR CAR (Frt)

ACCUH1651

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

11/12/18

SME 90482

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	CRA	✓	
1006	991325	Frt Bumper Bracket	NEC	✓	
1007	991462	Frt Bumper Side Retainer		?	
1008	991433	Frt Bumper Reinforcement		?	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector	IN	✓	
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille		?	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler	NEC	✓	2
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem	CRA	✓	
1023	991799	Frt Grille Chrome Moulding	CRA	✓	
1024	991222	Frt Apron Panel	CUT	✓	
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA	✓	
1030	991821	Frt RH Headlamp Assy	CUT	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem	IT	R	
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990039	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990234	Battery Cover			

17/12/18

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992112	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994453	Steering Wheel Airbag			
1128	994455	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991809	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (P)
 (4) Not Consistent (NC)


Aug 2005

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CR4	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	MIS	✓	
1146	992341	Rear Bumper Clips		?	
1147	992976	Rear Bumper Bracket		?	
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement		?	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	CUT	✓	
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor		?	
1159	993327	Rear End Panel		?	
1160	993339	Rear End Panel Top Garnish		?	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	RD	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock		?	
1178	990377	Bootlid Rubber		?	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Vehicle No: SME 90482

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe	CUT	✓	
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		AT Headrest Retainer Kit			2


 17/12/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING




















Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2018 Edit Reg		13 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: 88 RENTAL PTE LTD , Co. Reg. No.: -									
Main Claimant: LAU WEE KIM , ID: S7973234F									
Vehicle Reg. No.: SME9048Z		Date of Loss: 07/12/2018 22:00 - :59 [74 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7249297575SG		Policy/Cover Note No.: 0999994481 (Comprehensive)							
Vehicle Reg. No. (Insured): SJS3974B		Policy No. (Claimant):							
		Excess:							
Repairer: 88 Motorz (sg) Pte Ltd (HQ) 25 Kaki Bukit Road 4 Synergy @ KB #05-34, 417800 Kaki Bukit - Tel: 82200338									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/12/2018]									
Claimant's Solicitor: SATWANT & ASSOCIATES - Tel: 62216114									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (14/12/2018): rEQUEST FOR tp gia rEPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SME9048Z (7249297575SG)**
[SJS3974B]
TP
LAU WEE KIM
Dec 7 2018 10:00PM
[88 RENTAL PTE LTD]
88 Motorz (sg) Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)					Thumbnail	Print	
1	14/12/18 16:43	Accident Statement From: SC - Reg. No: SJS3974B, Claimant: 88 RENTAL PTE LTD					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
2	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
3	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
4	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
5	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
6	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
7	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
8	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
9	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
10	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
11	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
12	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
13	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
14	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
15	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
16	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
17	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
18	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
19	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
20	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
21	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
22	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
23	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
24	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
25	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
26	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
27	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
28	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
29	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
30	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
31	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
32	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	
33	17/12/18 14:34	General View					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/12/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022430/GCD3E2

Date: 18/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994481
Claimant Vehicle No : SME9048Z **Insured Vehicle No :** SJS3974B
 Date of Loss: 07/12/2018 Nature of Claim: TP Claim No: 7249297575SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME9048Z**
 Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491030015615
 Reg. Date: 01/10/2012 (Man. Year: 2012) Chassis No: WDD2040312A768142
 Colour: Brown Odometer: 71662 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/12/2018
 Date Inspected: 13/12/2018 Inspected At: 88 Motorz (sg) Pte Ltd (HQ)
 25 Kaki Bukit Road 4 Synergy @ KB #05-34
 Singapore 417800
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Crumpled	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	* Check	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	Torn	0.00 F	*- F
6	1		*FRT BUMPER GRILLE	* Check	0.00 F	*- F
7	2		*FRT BUMPER MOULDING	Necessary	0.00 F	*- F
8	1		*FRT GRILLE	Cracked	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Cracked	0.00 F	*- F
10	1		*FRT GRILLE CHROME MOULDING	Cut	0.00 F	*- F
11	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
12	1		*FRT RH HEADLAMP ASSY	Cut	0.00 F	*- F
13	1		*BONNET	Repair	0.00 F	*- F
14	1		*REAR BUMPER	Crumpled	0.00 F	*- F
15	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
16	1		*REAR BUMPER BRACKET	* Check	0.00 F	*- F
17	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
18	1		*REAR BUMPER MOULDING	Cut	0.00 F	*- F
19	1		*REVERSE SENSOR	* Check	0.00 F	*- F
20	1		*REAR END PANEL	* Check	0.00 F	*- F
21	1		*REAR END PANEL TOP GARNISH	* Check	0.00 F	*- F
22	1		*BOOTLID	Dented	0.00 F	*- F
23	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
24	1		*BOOTLID LOCK	* Check	0.00 F	*- F
25	1		*BOOTLID RUBBER	* Check	0.00 F	*- F
26	1		*REAR EXHAUST CHROME PIPE	Cut	0.00 F	*- F
27	2		*FRT HEADREST RETAINER KIT	Damaged	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >