

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBJ1970S		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	CBR1000RR		
Chassis No. :	JH2SC59A6DK501047		
Propellant :	Petrol		
Engine No. :	SC59E2410919		
Engine Capacity :	999 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	379 kg		
Unladen Weight :	200 kg		
Year Of Manufacture :	2013		
Original Registration Date :	24 Jan 2014		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$2,704.00		
COE Expiry Date :	23 Jan 2024		
Road Tax Expiry Date :	23 Jan 2019		
Inspection Due Date :	23 Jan 2019		
Intended Transfer Date :	13 Dec 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 23 Jan 2019. You may renew the road tax from 24 Oct 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 23 Jan 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 24 Jan 2019 to 23 Jul 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	126.00	-	126.00
Total Amount Payable :			151.00
Amount Payable (From 24 Jan 2019 to 23 Jan 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	252.00	-	252.00
Total Amount Payable :			277.00

You may print this page for reference.

[OK](#)
[Print](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/12/2018 10:18
Date Of Accident	30/11/2018 19:30
Exact Location Of Accident	ECP TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ1970S
Insured/Policyholder	
Name Of Registered Owner	PRITPAL SINGH
NRIC No	S8319529J
Email Address	PRITALSAINI@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-82056256
Alternative Phone No	OFFICE-82056256

Vehicle Particulars

Manufacturer	HONDA
Model	CBR1000RR-998CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MC/00512733
Cover Note Number	

Driver

Name of Driver	PRITPAL SINGH
NRIC No	S8319529J
Date Of Birth	18/06/1983
Occupation	INDOOR
Date Of Driving Pass	27/05/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82056256
Fax Number	
Contact Number	OFFICE-82056256
Email Address	PRITALSAINI@HOTMAIL.COM

Address	BLK 9 SELEGIE ROAD #18-23
Postcode	180009
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	SLIGHT DAMP

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NATASHA DUTTA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ORCHARD NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 KILLINEY ROAD , POSTCODE: 239572 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7359999 - FAX NO: 67331934
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE TRAFFIC ACCIDENT REPORT NO. T/20181201/2143 ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	NATASHA DUTTA
Phone Number	90039751
Email Address	NATASHAAGEL@GMAIL.COM

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX439A
Vehicle Make/Model/Colour	MITSUBISHI / OUTLANDER / SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	SEAH SHEAU MING
NRIC/Passport Number	S7139007A
Contact Number	93877385
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKS4070R
Vehicle Make/Model/Colour	PEUGEOT / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	PRITPAL SINGH
Approximate Age	35
Injuries Sustain	
Injured person in which vehicle?	FBJ1970S
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 9 SELEGIE ROAD #18-23
Postcode	180009

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 3/12/18

1736 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name: Tan Chua Lok

NRIC/FIN No.: 67715735R



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Traffic Accident NO. T/20181201/2143

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: 03/12/16
1736

GLAMC SketchPlanForm_V3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Tan Chou Lok
NRIC/FIN No.: G7715735W

NRIC/FIN No.: 677152354





**SINGAPORE
POLICE FORCE**



T/20181201/2143

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

1 of 4

Report No. T/20181201/2143

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/12/2018 20:05		Vide Report No.:		Station Diary No.: 142
Informant's Particulars				
Name of Informant: PRITPAL SINGH		Address: APT BLK 9 SELEGIE ROAD #18-23 SINGAPORE 180009		
ID Type / ID No.: NRIC NO / S8319529J		Contact No.: Home/Office: Mobile: 82056256		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 35	Date of Birth: 18/06/1983	Type of Informant: Vehicle Owner	
Race: Sikh		Language: English	Institution / School Name:	
Occupation: Business development manager		Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/11/2018 19:30	Type of Location: Straight Road
Location: Along Road 1 EAST COAST EXPRESSWAY				
Travelling along ECP towards Changi				
Weather: Clear		Road Surface: slight Damp	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBJ1970S	Motorcycle	HONDA		Multi-Colored	Seriously Damaged	1
SKS4070R	Car	PEUGEOT		Black	Seriously Damaged	0
SLX439A	Car	MITSUBISHI		Silver	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181201/2143

2 of 4

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No. T/20181201/2143

CONTINUATION OF REPORT

Vehicle 1			
Name	PRITPAL SINGH	ID No.	S8319529J
Related Vehicle	FBJ1970S (Motorcycle)	Contact No.	82056256
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	30/11/2018	Date Discharge	30/11/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver 1			
Name	One Chinese female driver	ID No.	NIL
Related Vehicle	SKS4070R (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Vehicle 2			
Name	Seah Sheau Ming	ID No.	S7139007A
Related Vehicle	SLX439A (Car)	Contact No.	93877385
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

-On 30/11/2018 at about 7.30pm, I was travelling together with my wife, namely Natasha Dutta along East Coast Expressway toward Changi. Before the accident took place, I was travelling between lane 1 and lane 2. I then noted that there was an accident happened at lane 1 from my right as such I slow down with hazard light on. At that point, I decided to travel at Lane 2 instead. I noticed vehicle registration number SLX439A (Silver / Mitsubishi) has his hazard light one together with his signal light but hesitant on whether to stop or turn left.

As my vehicle still moving straight on lane 2 suddenly, the said vehicle SLX439A decided to turn left and causes me to hit the rear of the said vehicle who then come to a stopped. Due to that, my wife and I fall off from the motorcycle after the stopped. I could felt pain as such ambulance came and convey me to Changi General Hospital.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999



T/20181201/2143

3 of 4

Report No. T/20181201/2143

CONTINUATION OF REPORT

I wish to state that I could see when the said vehicle making a left turn, the driver had graze the left rear of vehicle SKS4070R (Black / Peugeot) which cause some damages. I wish to state that due to the accident my front of my vehicle is seriously damage. It was then tow by Traffic police as informed by them. Lastly, there was Traffic police at scene that attended to the accident. That's all.



**SINGAPORE
POLICE FORCE**



T/20181201/2143

4 of 4

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No. T/20181201/2143

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sr Staff Sgt SITI AISYAH BINTI NANI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/12/2018 20:05
Officer In Charge Of Case: TP / GIT / SI THABAGESH JEYATHESH Contact No.: 65476232	Classification Of Case: TN 172
Authentication Stamp NP168	SIGNATURE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-192215

Date of Request: 12/12/2018

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 12/12/2018
Enquiry By Tan Chok Lok
TP Vehicle No. SLX439A
Accident Date 30/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLX439A	AIG Asia Pacific Insurance Pte. Ltd.	06/03/2018-05/03/2020	65-6419-3000
SLX439A	AIG Asia Pacific Insurance Pte. Ltd.	14/03/2018-13/03/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-192215

Date of Request: 12/12/2018

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 12/12/2018
Enquiry By Tan Chok Lok
TP Vehicle No. SLX439A
Accident Date 30/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33355

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 12/12/2018
CLAIM NO. : 11219
POLICY NO. : MC/00512733
FROM : RAYMOND

VEHICLE NO. : FBJ1970S
MAKE/MODEL : HON / CBR1000RR

(Page 1 of 3)

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
1	BOLT P/N: 50534	REPLACE	4.00	\$9.00	36.00
2	CAP BOOST	REPLACE	1.00	\$0.00	0.00
3	CAP CRANKCASE COVER 45MM	REPLACE	1.00	\$39.00	39.00
4	CLIP NUT P/N: 50536	REPLACE	2.00	\$7.00	14.00
5	COVER AIR DUCT LH	REPLACE	1.00	\$32.00	32.00
6	COVER AIR DUCT RH	REPLACE	1.00	\$32.00	32.00
7	COVER COWLING LAYER LH	REPLACE	1.00	\$95.00	95.00
8	COVER COWLING LAYER RH	REPLACE	1.00	\$95.00	95.00
9	COVER COWLING MIDDLE	REPLACE	1.00	\$52.00	52.00
10	COVER CRANKCASE COMP.	REPLACE	1.00	\$575.00	575.00
11	COVER INTAKE	REPLACE	1.00	\$52.00	52.00
12	COVER LAYER LH	REPLACE	1.00	\$18.00	18.00
13	COVER LAYER RH	REPLACE	1.00	\$18.00	18.00
14	COVER MIRROR INNER RH	REPLACE	1.00	\$213.00	213.00



CERT NO.: 2002-1-0303
ISO 9001:2015

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
15	COVER MIRROR OUTER LH	REPLACE	1.00	\$48.00	48.00
16	COVER MIRROR OUTER RH	REPLACE	1.00	\$48.00	48.00
17	COVER SIDE RH	REPLACE	1.00	\$1,105.00	1,105.00
18	COWLING MIDDLE	REPLACE	1.00	\$892.00	892.00
19	COWLING MIDDLE INNER LH	REPLACE	1.00	\$52.00	52.00
20	COWLING MIDDLE LH	REPLACE	1.00	\$1,105.00	1,105.00
21	DAMPER MIRROR	REPLACE	2.00	\$9.00	18.00
22	DUCT AIR LH	REPLACE	1.00	\$145.00	145.00
23	DUCT AIR RH	REPLACE	1.00	\$145.00	145.00
24	HEADLAMP ASSY	REPLACE	1.00	\$1,445.00	1,445.00
25	HORN	REPLACE	1.00	\$182.00	182.00
26	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	16.00	\$35.00	560.00
27	MUDGUARD FRONT	REPLACE	1.00	\$405.00	405.00
28	NUT PLASTIC (WINDSHIELD) P/N: 30543	REPLACE	1.00	\$8.00	8.00
29	NUT PLASTIC (WINDSHIELD) P/N: 30543	REPLACE	8.00	\$8.00	64.00
30	NUT RUBBER	REPLACE	2.00	\$8.50	17.00
31	O-RING (48.1X3.6) P/N: 36668	REPLACE	1.00	\$12.00	12.00
32	PROTECTOR EXHAUST	REPLACE	1.00	\$488.00	488.00
33	RIVET P/N: 40901	REPLACE	11.00	\$9.00	99.00
34	RUBBER COVER SEAL DUCT LHRUBBER COVER SEAL DUCT	REPLACE	1.00	\$49.00	49.00
35	RUBBER COVER SEAL DUCT RH	REPLACE	1.00	\$49.00	49.00



S/N	Description	Action	Qty	Unit Price	Amount
36	SCREW SMALL BOX P/N: 29943	REPLACE	6.00	\$7.50	45.00
37	STAY COWLING P/N: 50539	REPLACE	2.00	\$18.00	36.00
38	STAY HEADLAMP	REPLACE	1.00	\$383.00	383.00
39	STAY VACUUM TANK	REPLACE	1.00	\$22.00	22.00
40	TANK VACUUM COMP.	REPLACE	1.00	\$65.00	65.00
41	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 P/N: 45836 - FOR COLLECTION OF ACCIDENT BIKE.		1.00	\$55.00	55.00
42	WASHER	REPLACE	4.00	\$7.00	28.00
43	WINDSCREEN SET	REPLACE	1.00	\$235.00	235.00
44	WIRE HARNESS METER	REPLACE	1.00	\$405.00	405.00

SUB TOTAL

\$9,481.00

GST @ 7 %

\$663.67

GRAND TOTAL

\$10,144.67

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

CERT NO.: 2002-1-0383
ISO 9001 : 2015