

22/03/2002

ASS. REC. BY:

REF: CS/CTL18022437 / TT+bez

Special Instruction:

Surveyor  
Mehmen

**ASSIGNMENT (Office)**

From (Person): Chong Boon Sen of CTL Date/Time: 13/12/08 3:08pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: SDZ 3911S Insured: GBH 9984K

at Workshop m/s Wearnes Tel: 9818 7217

of 75 Leng Kee Rd

Policy No: DMCVSN 1837651800 Claim No: SNM/BD05768 C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 06/12/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 13/12/08 3:30pm Person Contacted: Derek Vehicle IN / OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SDZ 3911S - X
	GBH 9984K - X
	Part by Part \$4,095.60 (Red: 8631.70; 67%)

Signature: *Tamper*

REF: CTI

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: 2DZ3911C  
 at Workshop m/s Wearnes Automotive  
 of 209 Alexandra Rd  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

16/1/2019 Morning  
(Policy Condition)

/	
N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : **Yes** or **No**  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes** or **No**  
 Est. Repairs: \_\_\_\_\_ days Res.: **Yes** or **No**  
 Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SDZ3911S Yr Regn: 2018 / June -  
 Type: M Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Volvvo 560 C.C. 1969  
 Colour: Green A/C: Insured / Std / NI / NA  
 Sp. Reading: 1442 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: 9V1FS42LDJ2467879  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/50R17  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front Rear  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 16/1/19  
 Survey held at Wearnes Automotive  
 Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or  
Frnt O/S  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

RECEIVED 30 JAN 2019

Date/Time, File Pass to?  Preli. Report  
 Final Report  
 1) 30/1 Typist  
 Date/Time, File Return to?

Days Of Repair: 3  
 Resurvey No. of Trip: -

- Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech Invs (\$)  
 Weekend (\$)

Survey Fee:	<u>220</u>
Transportation:	_____
) S + RS	_____
) Photos	_____
) Others	_____
TOTAL	<u>220</u>

Report Format :  
 Lump Sum / I.B.I. (\$) 4095.60

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2018		13 Dec 2018 15:08 Assign				<b>New Assignment</b> Cancel Case

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:				
Main Claimant:	<b>PHUA KOK BOON</b>			
Vehicle Reg. No.:	<b>SDZ3911S</b>	Date of Loss:	06/12/2018 00:00 - :59	
Claim Type:	<b>TP / SNM18D05768C02</b>	Policy/Cover Note No.:	DMCVSN1837651800	
Vehicle Reg. No. (Insured):	<b>GBH9984K</b>	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	<b>Wearnes Automotive Pte Ltd (Leng Kee)</b> 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680			
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]			
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Final Rpt due 24/12/2018</b> ]			
Adj Asg. Remarks:	EST \$13,618.20, CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 30 January 2019 11:33 AM  
**To:** 'Richmond Ho'; Taufikh (LKKAuto); SUR; Admin A  
**Cc:** 'Derek Oh Siong Wee'  
**Subject:** RE: Final Bill For SDZ3911S

Dear Richmond,

Confirm part by part \$4,095.60, 3 Days.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Richmond Ho <[richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)>  
**Sent:** Monday, 28 January 2019 3:32 PM  
**To:** Taufikh (LKKAuto) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Cc:** Derek Oh Siong Wee <[derek.oh@wearnes.com](mailto:derek.oh@wearnes.com)>  
**Subject:** Final Bill For SDZ3911S  
**Importance:** High

Hi,

Please refer to above attachment for the final bill.

**Richmond Ho**  
Senior Service Consultant  
Body & Paint – Insurance Claim



**Wearnes Automotive Pte Ltd**  
249 Alexandra Road Singapore 159935  
D (65) 6430 4890 M (65) 9176 8543  
[www.wearnesauto.com](http://www.wearnesauto.com) [richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

# SINGAPORE ACCIDENT STATEMENT

Code saving 101  
No do LMT holder  
while driving 10 + 10  
storing card + broken

## IMPORTANT NOTICE

1. Complete and submit this Form to Allied World's Authorised Reporting Centre ("ARC") for e-filing.
2. Please report correctly the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorised Driver.
4. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false reporting may be referred to the Traffic Police Department for investigation.

## ACCIDENT STATEMENT

Date and Time of Accident	Date: 06/12/2018 Time: 8:35 am
Exact Location of Accident	Geylang Bahru Hawker Center carpark exit

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	3DZ 3911S
-----------------------------	-----------

## INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (See Insurance Cert.)	PHUA KOK BOON
Personal Identification - NRIC (Singaporean/PR)	S7421253J
- FIN/Passport Number	
- Not Applicable	

## VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model	Manufacturer <u>Volvo</u> Model <u>S60 ?L</u>
Type of Vehicle*	<input checked="" type="checkbox"/> Saloon <input type="checkbox"/> MPV <input type="checkbox"/> CRV <input type="checkbox"/> Van <input type="checkbox"/> Lorry <input type="checkbox"/> Bus <input type="checkbox"/> M/cycle <input type="checkbox"/> Others, _____
Exact Purpose for which vehicle was being used at time of accident	<u>Social</u>
Are you claiming under your own insurance policy for repair to your vehicle?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (If No, Pls select <input checked="" type="checkbox"/> Third Party <input type="checkbox"/> Reporting)
Vehicle Category*	<input checked="" type="checkbox"/> Private <input type="checkbox"/> Commercial <input type="checkbox"/> Motorcycle

## INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company *	<u>AFK</u>
Type of Policy	<input checked="" type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire & Theft <input type="checkbox"/> TP Only
Fleet Policy	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Policy Number	
Motor CI	

## DRIVER

	<input checked="" type="checkbox"/> Same as Insured above
Name of Driver	PHUA KOK BOON
Personal Identification - NRIC (Singaporean/PR)	S7421253J
- FIN/Passport Number	
Date of Birth	05 dd/ 07 mm/ 74 /yy
Driving Date Pass	03 dd/ 07 mm/ 992 /yy
Year of Driving Experience	Year(s) Month(s)
Occupation	<u>Self Employed</u> <input checked="" type="checkbox"/> Indoor <input type="checkbox"/> Outdoor
Gender	<input checked="" type="checkbox"/> Male <input type="checkbox"/> Female
Contact Number / Mobile Phone / Fax No.	90627922

Address of Driver	700 C ANG MO KIO AVE 6 # 11-324	Postcode ( 563700 )
Email Address	no email	
Was driver an employee of the Insured's Company?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
If No, Relationship of the Driver with the Insured	owner	
Vehicle Registration Number of Driver's Own	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Vehicle Registration Number of Driver's Own Vehicle (if applicable)		
Insurance Company of Driver's Own Vehicle (if applicable)		
<b>GENERAL INFORMATION OF THE ACCIDENT</b>		
Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear)	Head to Rear	
Weather Conditions	<input checked="" type="radio"/> Clear <input type="radio"/> Raining <input type="radio"/> Others, _____	
Road Surface	<input checked="" type="radio"/> Dry <input type="radio"/> Wet <input type="radio"/> Others, _____	
<b>OTHER INFORMATION</b>		
Was any foreign vehicle involved in this accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any body injured in the accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any other vehicle or property damaged?	<input checked="" type="radio"/> Yes <input type="radio"/> No	
Was there any video captured by Car Camera?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Number of Passengers (Including Driver)	01	
<b>DETAILS OF POLICE ACTION</b>		
Was the Accident reported to the Police?	<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, please state which Police Station.)	
Police Station Name		
Police Station Address		
Police Station Contact	Tel No.	Fax No.
Was notice of intended Prosecution given?	<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, against whom?)	
<b>DETAILS OF OTHER VEHICLE / PROPERTY 1</b>		
Vehicle Registration Number	GBH 9984 K	
Vehicle Make/ Model/ Colour	Toyota HIACE Silver	
Details of Properties		
Name of Driver	Mr AH LAM	
Personal Identification - NRIC (Singaporean/PR)		
- FIN/Passport Number		
Contact Number	877 88790	
Address		
Name of Insurance Company		
Nature of Damage		
No. of Passenger (Including Driver)	3	
(Note - Please use page 6 if you need to add more vehicles )		

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
\_\_\_\_\_  
Policyholder's Signature / Date & Time

  
\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

**Sketch Plan**

Refer to the attached sketch.

Vehicle A Driver

- ③ While reversing his vehicle, the rear bumper knocked into Vehicle B's right bumper (front).

Google Maps

- ④ There is CCTV at the carpark gantry.

Date: 6 Dec 2018

Time: 8:35 a.m

Location: Geylang Bahru (Driver)


- ① Vehicle A could not exit the car park gantry and reversed his vehicle.
- ② Vehicle B was stationary behind Vehicle A at the point of Accident.



Imagery ©2018 Google, Map data ©2018 Google 5 m

Vehicle A : GGH 9984K

Vehicle B : SDZ 39117



Like Share

Email or Phone Contact Us Password Send Message  
[Input Field] [Input Field] [Input Field] Log In  
Forgotten account?

Light & Lights Pte Ltd  
@lightnlightspteltd

- Home
- Services
- Photos
- Videos
- Posts
- About
- Community
- Info and ads

Create a Page


Services

Electrical & Plumbing

We are offering electrical & plumbing works, which ensure the quality...

See all

Photos



See all

Van GBH 9984K.

Driver Name

Ah Lam 87788790

2 other stuff in car.

Search for posts on this Page

Light & Lights Pte Ltd  
Lighting store in Singapore

Open now

Community

See all

436 people like this

453 people follow this

About

See All



540 Sims Avenue #01-03 Sims Avenue Centre

(4.53 km)

387603 Singapore

Get Directions

6846 0752

lightnlights.com.sg

Lighting store · Electrician

Hours 09:00 - 18:00

Open now

People

436 likes

22 visits

Related Pages

Videos

See more of Light & Lights Pte Ltd on Facebook



The Hardware Shop Pte Ltd  
Hardware shop

Log In

or

Create New Account

Poh Meng Engineering Pte Ltd  
Heating, ventilating & air conditioning service



**Describe Circumstance of the Accident**

On 6 Dec 2018, at about 8:35am, I was driving towards the exit carpark at Geylang Bahru (Hawker Center). There was a van in front of my vehicle (SDZ 3911S). This Van (GBH 9844K) was stationed in front of the exit car park (EPS) barrier. Suddenly, this van reversed his vehicle and knocked into my vehicle (front right bumper), I ~~was~~ tried ~~to~~ applying horns on him but he didn't stopped.


Prior to the above accident event, my vehicle is about 1.5m away.

**IMPORTANT NOTE**


Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

**Declaration**

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate** as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/12/2018 13:19
Date Of Accident	06/12/2018 08:35
Exact Location Of Accident	GEYLANG BAHRU HAWKER CENTER CARPARK EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDZ3911S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PHUA KOK BOON
NRIC No	S7421253J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90627922
Alternative Phone No	OTHERS-90627922

### Vehicle Particulars

Manufacturer	VOLVO
Model	S60-2.0 T5 (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	PHUA KOK BOON
NRIC No	S7421253J
Date Of Birth	05/07/1974
Occupation	INDOOR
Date Of Driving Pass	03/07/1992
Driving Experience	26 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90627922
Fax Number	
Contact Number	OTHERS-90627922
EEmail Address	NOEMAIL

Address	700C ANG MO KIO AVE 6 #11-324
Postcode	563700
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9984K
Vehicle Make/Model/Colour	TOYOTA HIACE / SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	AH LAM
NRIC/Passport Number	
Contact Number	87788790
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3
Passenger 1	NAME: : UNKNOWN
	GENDER: :

Passenger 2

NAME: : UNKNOWN

GENDER: :

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7421253J



Name  
PHUA KOK BOON  
(PAN GUOWEN)  
潘 国 文

Race  
CHINESE

Date of birth 05-07-1974 Sex M

Country of birth  
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7421253J



Name  
PHUA KOK BOON  
(PAN GUOWEN)

Birth Date: 05 Jul 1974

Issue Date: 22 May 2014

002307389J

3629339



NRIC No: S7421253J



Date of issue  
27-10-2004

APT BLK 700C ANG MO KIO AVENUE 6 #11-324  
SINGAPORE 563700

NRIC No: S7421253J Date: 07/04/2016


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 03 Jul 1992

NP 428A

Licence No: S7421253J



in 160119

### SERVICE ESTIMATE

97565 - C00001 SL: SERVICE SALES - PC

Mr Phua Kok Boon

Blk 700C Ang Mo Kio Avenue 6  
#11-324

Singapore 563700

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1  
Inv.date : 07/12/2018  
WIP No. : 42212  
Veh.In/Out: 06/12/2018  
\*Tel.No. : Mobile: 90627922  
Reg.No. : SDZ3911S  
Reg.date : 29/06/2018  
Mileage : 0  
Chassis No: YV1FS40LDJ2467879

Closed by .... : Derek Oh Siong Wee  
Svc Consultant :  
Remarks ..... : Mr Phua Kok Boon

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER,FRT BRACKET,FRT BEAM,FRT HEADLAMP, FRT RH FENDER,ETC	0	3200.00	0		3,200.00 S	800
800	TO PUTTY SPRAY PAINT ON FRT BUMPER,FRT BONNET,FRT LH FENDER,ETC	0	2800.00	0		2,800.00 S	700
280	TO FOCUS HEADLAMP	0	150.00	0		150.00 S	? x nn.
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S	✓✓
	BUMPER COVER FRT SV6	1.0 EA	1519.90	367.91		1,519.90 S	de ✓
	TOW COVER FRT S60 14	1.0 EA	73.90	66.51		73.90 S	cut ✓
	BUMPER BRACKET LHF S	1.0 EA	88.70			88.70 S	x nn ✓
	BUMPER BRACKET RHF V	1.0 EA	88.70	79.83		88.70 S	ner ✓
	BUMPER BRACKET LHF S	1.0 EA	88.70			88.70 S	x nn ✓
	BUMPER BRACKET RHF S	1.0 EA	88.70	79.83		88.70 S	ner ✓
	BUMPER COVER LHF BLA	1.0 EA	105.80			105.80 S	x nn ✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tan Jiah 97495749  
-wp  
16/1/19 e 1230  
Resurvey before paint.  
3 days  
Svc @ lkk auto.com

**SERVICE ESTIMATE**

97565 - C00001 SL: SERVICE SALES - PC

Mr Phua Kok Boon

Blk 700C Ang Mo Kio Avenue 6

#11-324

Singapore 563700

Closed by .... : Derek Oh Siong Wee

Svc Consultant :

Remarks ..... : Mr Phua Kok Boon

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 07/12/2018

WIP No. . : 42212

Veh.In/Out: 06/12/2018

\*Tel.No. . : Mobile: 90627922

Reg.No. . : SDZ3911S

Reg.date. : 29/06/2018

Mileage . : 0

Chassis No: YV1FS40LDJ2467879

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BUMPER COVER RHF BLA	1.0 EA	105.80			105.80	S X NY
	FENDER FRT RH S60 14	1.0 EA	1040.50			1,040.50	S X NY
	FENDER BRACKET FRT S	1.0 EA	11.40			11.40	S X NY
	HEADLAMP HID RH SY60	1.0 EA	1896.00			1,896.00	S ? X NY
	LED LAMP RHF S60 14-	1.0 EA	406.40			406.40	S ? X NY
	BLIND RIVET 4.0*21 P	10.0 EA	3.00		27	30.00	S new
	BUMPER CLIP 8x8,5	10.0 EA	5.40		48.60	54.00	S new ✓
	EXTERIOR ADHESIVE GL	1.0 EA	142.20		127.98	142.20	S new ✓
	BUMPER INSTALLING MT	1.0 EA	83.40		75.06	83.40	S new ✓
	ADHESIVE TUBE CHEMIC	4.0 EA	75.80		272.88	303.20	S new ✓

Gross Total. 12,727.30

Labour Total 6,600.00  
 Parts Total 6,127.30  
 Package Total 0.00

Net..... 12,727.30  
 GST @ 7.0% 890.91  
 Total..... 13,618.20  
 Paid..... 0.00  
 Please Pay.. 13,618.20

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

**SERVICE ESTIMATE**

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)  
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X  
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1  
 #16-00, SPRINGLEAF TOWER Inv.date. : 28/01/2019  
 SINGAPORE 079909 WIP No. . : 49146  
 Veh.In/Out: 16/01/2019 24/01/2019

Closed by .... : Richmond Ho  
 Svc Consultant : ACC  
 Remarks ..... : Mr Phua Kok Boon

\*Tel.No. . : 63896111  
 Reg.No. . : SDZ3911S  
 Reg.date . : 29/06/2018  
 Mileage .. : 14,444  
 Chassis No: YV1FS40LDJ2467879

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER,FRT BRACKET,FRT BEAM,FRT HEADLAMP, FRT RH FENDER,ETC	0	800.00	0		<del>800.00</del>	S
800	TO PUTTY SPRAY PAINT ON FRT BUMPER,ETC	0	700.00	0		<del>700.00</del>	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		<del>450.00</del>	S
	BUMPER COVER FRT SV6	1.0 EA	1519.90	10		1,367.91	S
	TOW COVER FRT S60 14	1.0 EA	73.90	10		66.51	S
	BUMPER BRACKET RHF V	1.0 EA	88.70	10		79.83	S
	BUMPER BRACKET RHF S	1.0 EA	88.70	10		79.83	S
	BLIND RIVET 4.0*21 P	10.0 EA	3.00	10		27.00	S
	BUMPER CLIP 8x8,5	10.0 EA	5.40	10		48.60	S
	EXTERIOR ADHESIVE GL	1.0 EA	142.20	10		127.98	S
	BUMPER INSTALLING MT	1.0 EA	83.40	10		75.06	S
	ADHESIVE TUBE CHEMIC	4.0 EA	75.80	10		272.88	S

Gross Total. 4,095.60

Labour Total 1,950.00  
 Parts Total 2,145.60  
 Package Total 0.00

Net..... 4,095.60  
 GST @ 7.0% 286.69  
 Total..... 4,382.29  
 Paid..... 0.00  
 Please Pay.. 4,382.29

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2018		13 Dec 2018 15:08 <a href="#">Edit Adj Rpt</a>	<b>S\$4,095.60</b> <a href="#">Edit Estimates</a>	<b>S\$4,095.60</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured: -, Co. Reg. No.: -

Main Claimant: **PHUA KOK BOON**

Vehicle Reg. No.: <b>SDZ3911S</b>	Date of Loss: 06/12/2018 00:00 - :59 [5 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type: <b>TP / SNM18D05768C02</b>	Policy/Cover Note No.: DMCVSN1837651800
Vehicle Reg. No. (Insured): <b>GBH9984K</b>	Policy No. (Claimant):
	Excess: S\$0.00

Repairer: **Wearnes Automotive Pte Ltd (Leng Kee)** 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Chong Boon Sen**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MOHD TAUFIKH BIN HAMID**] ... [Final Rpt due 24/12/2018]

Adj Asg. Remarks: EST \$13,618.20, CASE WITH SJE.

---

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS**  [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### Claim Documents

**\*SDZ3911S (SNM18D05768C02)**  
**[GBH9984K]**  
**TP**  
**PHUA KOK BOON**  
**Dec 6 2018 12:00AM**  
**[-]**  
**Wearnes Automotive Pte Ltd**

Upload Documents		Upload Photos	Compose New Letter	<b>View</b> View in Browser	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
2	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
3	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
4	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
5	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
6	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
7	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
8	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
9	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
10	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
11	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
12	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
13	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
14	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
15	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
16	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
17	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
18	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
19	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
20	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
21	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
22	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
23	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
24	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
25	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
26	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
27	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
28	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
29	30/01/19 11:39	General View	Load JPG	<input checked="" type="checkbox"/>	
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	13/12/18 15:08	REPAIR EST WITH TP GIA	Load PDF	<input type="checkbox"/>	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT118022437/T1TBE2

**Date:** 31/01/2019

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1837651800
Claimant Vehicle No :	SDZ3911S	Insured Vehicle No :	GBH9984K
Date of Loss:	06/12/2018	Nature of Claim:	TP
		Claim No:	SNM18D05768C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ3911S	Engine No:	B4204T112533947
Make & Model:	VOLVO S60, 2.0 T5 (A)	Chassis No:	YV1FS40LDJ2467879
Reg. Date:	29/06/2018 (Man. Year: 2018)	Odometer:	14412 km
Colour:	Grey		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,127.30	2,145.60	3,981.70	64.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,600.00	1,950.00	4,650.00	70.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,727.30</b>	<b>4,095.60</b>	<b>8,631.70</b>	<b>67.82</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>890.91</b>	<b>286.69</b>	<b>604.22</b>	<b>67.82</b>
<b>Nett Amount (S\$)</b>	<b>13,618.21</b>	<b>4,382.29</b>	<b>9,235.92</b>	<b>67.82</b>

#### INSPECTION

Date of Assignment:	13/12/2018		
Date Inspected:	16/01/2019	Inspected At:	Wearnes Automotive Pte Ltd (Leng Kee) 45 LENG KEE ROAD SINGAPORE 159103
Estimated Period of Repair:	3.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2019)
<b>Parts:</b> 143	VOLVO S60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SDZ3911S)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT SV6	Deformed	1,519.90 FS	*1,367.91 FS
2	1		*TOW COVER FRT S60 14	Cut	73.90 FS	*66.51 FS
3	1		*BUMPER BRACKET LHF S	Not Necessary	88.70 FS	*- FS
4	1		*BUMPER BRACKET RHF V	Necessary	88.70 FS	*79.83 FS
5	1		*BUMPER BRACKET LHF S	Not Necessary	88.70 FS	*- FS
6	1		*BUMPER BRACKET RHF S	Necessary	88.70 FS	*79.83 FS
7	1		*BUMPER COVER LHF BLA	Not Necessary	105.80 FS	*- FS
8	1		*BUMPER COVER RHF BLA	Not Necessary	105.80 FS	*- FS
9	1		*FENDER FRT RH S60 14	Not Necessary	1,040.50 FS	*- FS
10	1		*FENDER BRACKET FRT S	Not Necessary	11.40 FS	*- FS
11	1		*HEADLAMP HID RH SV60	Not Necessary	1,896.00 FS	*- FS
12	1		*LED LAMP RHF S60 14-	Not Necessary	406.40 FS	*- FS
13	10		*BLIND RIVET 4.0*21 P	Necessary	30.00 FS	*27.00 FS
14	10		*BUMPER CLIP 8X8, 5	Necessary	54.00 FS	*48.60 FS
15	1		*EXTERIOR ADHESIVE GL	Necessary	142.20 FS	*127.98 FS
16	1		*BUMPER INSTALLING MT	Necessary	83.40 FS	*75.06 FS
17	4		*ADHESIVE TUBE CHEMIC	Necessary	303.20 FS	*272.88 FS
<b>Total Parts (S\$)</b>					<b>6,127.30</b>	<b>2,145.60</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER, FRT BRACKET, FRT BEAM, FRT HEADLAMP, FRT RH FENDER, ETC	New	3,200.00	800.00
2	TO PUTTY SPRAY PAINT ON FRT BUMPER, FRT BONNET, FRT LH FENDER, ETC	New	2,800.00	700.00
3	TO FOCUS HEADLAMP	New	150.00	0.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	450.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,600.00</b>	<b>1,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >